

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-1176; Directorate Identifier 2009-CE-062-AD]

RIN 2120-AA64

Airworthiness Directives; Hawker Beechcraft Corporation Model G58 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Hawker Beechcraft Corporation Model G58 airplanes. This proposed AD would require inspecting the installation of stand-off hardware between the heater fuel line and the heater over-temperature sensor wires for minimum clearance and installing acceptable stand-off hardware if stand-off hardware is missing or inadequate. This proposed AD would also require inspecting the brake reservoir line and the fuel heater power wire for damage and minimum clearance, replacing any damaged wires and/or lines, and installing stand-off hardware if minimum clearance is not met. This proposed AD results from reports received of a power wire shorting out on the brake reservoir tube. We are proposing this AD to detect and correct inadequate clearance of the brake reservoir tubing and the heater fuel pump wiring, which could result in chafing and shorting out of the electrical wiring and chafing of the tubing carrying flammable fluids. This condition could lead to a fire in the nose wheel well.

DATES: We must receive comments on this proposed AD by February 1, 2010.

ADDRESSES: Use one of the following addresses to comment on this proposed AD:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor,

Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

• *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Hawker Beechcraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085; telephone: 1 (800) 429-5372 or (316) 676-3140; fax: (316) 676-3340; Internet: <http://hawkerbeechcraft.com>.

FOR FURTHER INFORMATION CONTACT: Kevin Schwemmer, Aerospace Engineer, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4174; fax: (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number, "FAA-2009-1176; Directorate Identifier 2009-CE-062-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive concerning this proposed AD.

Discussion

We have received reports that on a Hawker Beechcraft Corporation Model G58 airplane a power wire shorted out on the brake reservoir tube, resulting in a fire in the nose wheel well. The 0.50-inch minimum clearance requirements may not have been met between the brake reservoir tube and the combustion heater fuel pump power wire below the left side of the nose baggage compartment.

This condition, if not corrected, could result in chafing and shorting out of the

electrical wiring and chafing of the tubing carrying flammable fluids, which could lead to a fire in the nose wheel well.

Relevant Service Information

We have reviewed Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.

The service information describes procedures for:

- Inspecting the installation of stand-off hardware between the heater fuel line and the heater over-temperature sensor wires for minimum clearance;
- Installing acceptable stand-off hardware if stand-off hardware is missing or inadequate;
- Inspecting the brake reservoir line and the fuel heater power wire for damage and minimum clearance;
- Replacing any damaged wires and/or lines; and
- Installing stand-off hardware between the brake reservoir line and the fuel heater power wire if minimum clearance is not met.

FAA's Determination and Requirements of the Proposed AD

We are proposing this AD because we evaluated all information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design. This proposed AD would require inspecting the installation of stand-off hardware between the heater fuel line and the heater over-temperature sensor wires for minimum clearance and installing acceptable stand-off hardware if stand-off hardware is missing or inadequate. This proposed AD would also require inspecting the brake reservoir line and the fuel heater power wire for damage and minimum clearance, replacing any damaged wires and/or lines, and installing stand-off hardware if minimum clearance is not met.

Costs of Compliance

We estimate that this proposed AD would affect 71 airplanes in the U.S. registry.

We estimate the following costs to do the proposed inspection of the heater fuel line, the heater over-temperature sensor wires, the brake reservoir line, and the fuel heater power wire:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
1 work-hour × \$80 per hour = \$80	Not applicable	\$80	\$5,680

We estimate the following costs to do any necessary stand-off hardware installation that would be required

based on the results of the proposed inspection. We have no way of

determining the number of airplanes that may need this installation:

Labor cost	Parts cost	Total cost per airplane
.5 work-hour × \$80 per hour = \$40	\$50	\$90

We estimate the following costs to do any necessary replacement of the brake line that would be required based on the

results of the proposed inspection. We have no way of determining the number

of airplanes that may need this installation:

Labor cost	Parts cost	Total cost per airplane
6 work-hours × \$80 per hour = \$480	\$100	\$580

Hawker Beechcraft Corporation will allow warranty credit as specified in Hawker Beechcraft Mandatory Service Bulletin SB 32–3898, dated November 2008.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket that contains the proposed AD, the regulatory evaluation, any comments received, and other information on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647–5527) is located at the street address stated in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Hawker Beechcraft Corporation: Docket No. FAA–2009–1176; Directorate Identifier 2009–CE–062–AD.

Comments Due Date

(a) We must receive comments on this airworthiness directive (AD) action by February 1, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model G58 airplanes, serial numbers TH–2125 through TH–2172 and TH–2174 through TH–2220, that are certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 32: Landing Gear.

Unsafe Condition

(e) This AD results from reports received of a power wire shorting out on the brake reservoir tube. We are issuing this AD to detect and correct inadequate clearance of the brake reservoir tubing and the heater fuel pump wiring, which could result in chafing and shorting out of the electrical wiring and chafing of the tubing carrying flammable fluids. This condition could lead to a fire in the nose wheel well.

Compliance

(f) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) Inspect the installation of the stand-off hardware between the heater fuel line and heater over-temperature sensor wires for minimum clearance.	Within the next 50 hours time-in-service (TIS) after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first.	Follow Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.
(2) If, during the inspection required in paragraph (f)(1) of this AD, the stand-off hardware is not installed or it does not maintain the minimum clearance, install stand-off hardware as specified in the service information.	Before further flight after the inspection where the missing stand-off hardware and/or inadequate clearance was found.	Follow Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.
(3) Inspect the brake reservoir line and the fuel heater power wire for damage.	Within the next 50 hours TIS after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first.	Follow Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.
(4) If, during the inspection required in paragraph (f)(3) of this AD, damage is found, repair or replace damaged tubing and/or wiring found.	Before further flight after the inspection where damaged tubing and/or wiring was found.	Follow Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.
(5) Inspect the installation of the stand-off hardware between the brake reservoir line and the fuel heater power wire for minimum clearance.	Within the next 50 hours TIS after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first.	Follow Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.
(6) If, during the inspection required in paragraph (f)(5) of this AD, the stand-off hardware is not installed or it does not maintain the minimum clearance, install stand-off hardware as specified in the service information.	Before further flight after the inspection where the missing stand-off hardware and/or inadequate clearance was found.	Follow Hawker Beechcraft Mandatory Service Bulletin SB 32-3898, dated November 2008.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Kevin Schwemmer, Aerospace Engineer, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4174; fax: (316) 946-4107. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(h) To get copies of the service information referenced in this AD, contact Hawker Beechcraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085; telephone: 1 (800) 429-5372 or (316) 676-3140; fax: (316) 676-3340; Internet: <http://hawkerbeechcraft.com>. To view the AD docket, go to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, or on the Internet at <http://www.regulations.gov>.

Issued in Kansas City, Missouri on December 8, 2009.

Margaret Kline,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-29984 Filed 12-16-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

U.S. Customs and Border Protection

19 CFR Parts 123 and 142

[Docket No.: USCBP-2006-0132]

RIN 1651-AA68

Land Border Carrier Initiative Program

AGENCY: Customs and Border Protection, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document proposes to amend U.S. Customs and Border Protection (CBP) regulations by removing the provisions pertaining to the Land Border Carrier Initiative Program (LBCIP). The LBCIP is a voluntary industry partnership program under which participating land and rail commercial carriers agree to enhance the security of their facilities and conveyances to prevent controlled substances from being smuggled into the United States.

Since the promulgation of the LBCIP regulations, CBP has developed a more comprehensive voluntary industry partnership program known as the Customs-Trade Partnership Against Terrorism ("C-TPAT.") C-TPAT builds upon the best practices of the LBCIP, while providing greater border and supply chain security with expanded benefits to approved participants. For this reason, CBP intends to terminate the LBCIP and focus its partnership efforts on the further development of

C-TPAT. Current LBCIP members may participate in the program until a final rule terminating the LBCIP is published in the **Federal Register** and goes into effect.

An LBCIP participant may apply for participation in C-TPAT at any time and, if accepted, will receive the expanded benefits offered under that program. For a more detailed description of C-TPAT, and information regarding eligibility, application criteria, and benefits, CBP directs current LBCIP participants and all other interested parties to the CBP Internet Web site located at <http://www.cbp.gov>.

DATES: Comments must be received on or before February 16, 2010.

ADDRESSES: You may submit comments, identified by *docket number*, by one of the following methods:

- **Federal eRulemaking Portal:** <http://www.regulations.gov>. Follow the instructions for submitting comments via docket number USCBP 2006-0132.

- **Mail:** Border Security Regulations Branch, Customs and Border Protection, 1300 Pennsylvania Avenue, NW. (Mint Annex), Washington, DC 20229.

Instructions: All submissions received must include the agency name and docket number for this rulemaking. All comments received will be posted without change to <http://www.regulations.gov>, including any personal information provided. For detailed instructions on submitting comments and additional information on the rulemaking process, see the "Public Participation" heading of the