

Rules and Regulations

Federal Register

Vol. 75, No. 83

Friday, April 30, 2010

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0328; Directorate Identifier 2008-NE-44-AD; Amendment 39-16161; AD 2010-01-04]

RIN 2120-AA64

Airworthiness Directives; General Electric Company (GE) CF34-1A, CF34-3A, and CF34-3B Series Turbofan Engines; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting airworthiness directive (AD) 2010-01-04, which published in the **Federal Register**. That AD applies to GE CF34-1A, CF34-3A, and CF34-3B series turbofan engines. The docket number is incorrect in all three of its locations. This document corrects those references. In all other respects, the original document remains the same.

DATES: Effective April 30, 2010.

FOR FURTHER INFORMATION CONTACT: John Frost, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7756; fax: (781) 238-7199.

SUPPLEMENTARY INFORMATION: On January 8, 2010 (75 FR 1017), we published a final rule AD, FR Doc. E9-31274, in the **Federal Register**. That AD applies to GE CF34-1A, CF34-3A, and CF34-3B series turbofan engines. We need to make the following correction:

§ 39.13 [Corrected]

On page 1017, in the first column, under 14 CFR Part 39, "Docket No. FAA-2008-0328" is corrected to read "Docket No. FAA-2009-0328".

On page 1018, in the first column, under Comments Invited, starting in the ninth line, "Docket No. FAA-2008-0328" is corrected to read "Docket No. FAA-2009-0328".

On page 1018, in the third column, under § 39.13 [Amended], starting in the eighth line, "Docket No. FAA-2008-0328" is corrected to read "Docket No. FAA-2009-0328".

Issued in Burlington, Massachusetts, on April 23, 2010.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2010-9962 Filed 4-29-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0411; Directorate Identifier 2010-NE-19-AD; Amendment 39-16278; AD 2010-09-13]

RIN 2120-AA64

Airworthiness Directives; Turbomeca Makila 2A Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Some digital engine control units (DECUs) used to control MAKILA 2A and MAKILA 2A1 engines have an ambient pressure (P0) sensor with a measurement accuracy that may be outside the range required for satisfactory functioning of the engines throughout the entire operating envelope. In certain extreme flight conditions, the lack of P0 measurement accuracy could potentially cause an engine flameout if the engine is operating on a replacement fuel.

The issue is limited to a batch of 24 DECUs, of which 23 are known to be still in service. Since 01 January 2010, any such DECU returned to an approved repair centre has had its P0 sensor checked and replaced as necessary.

We are issuing this AD to prevent an uncommanded engine in-flight shutdown which could result in a forced autorotation landing or accident.

DATES: This AD becomes effective May 17, 2010.

We must receive comments on this AD by June 1, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* (202) 493-2251.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is the same as the Mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: kevin.dickert@faa.gov; telephone (781) 238-7117; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD 2010-0068-E (corrected), dated April 13, 2010 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Some DECUs used to control MAKILA 2A and MAKILA 2A1 engines have an ambient pressure (P0) sensor with a measurement accuracy that may be outside the range