

**SUPPLEMENTARY INFORMATION:** On June 29, 2010, the FAA issued AD 2010-14-19, Amendment 39-16364 (75 FR 39814, July 13, 2010), for certain Airbus Model A330-200 and -300 series airplanes, and Model A340-200, -300, -500 and -600 series airplanes. The AD requires replacing or modifying the Halon dual-filter assemblies of the flow metering fire extinguishing system in the forward and bulk cargo compartments, as applicable.

As published, Note 3 of the AD specifies in error Airbus Service Bulletin A340-26-4038. The correct service bulletin is Airbus Service Bulletin A340-26-4030.

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the **Federal Register**.

The effective date of this AD remains August 17, 2010.

#### § 39.13 [Corrected]

■ In the **Federal Register** of July 13, 2010, on page 39817, in the second and third columns, Note 3 of AD 2010-14-19 is corrected to read as follows:

\* \* \* \* \*

**Note 3:** The Halon dual-filter assembly P/N QA06753 is embodied in production through Airbus modification 40041. The Halon dual-filter assembly P/N QA06753-01 is only embodied in service through Airbus Service Bulletin A330-26-3030 or Airbus Service Bulletin A340-26-4030. The Halon dual-filter assembly P/N QA06753-02 is embodied in production through modification 47197 or 47883 or 50108 (BCRC) and 51065 or 51329 (LDCC) or in service through Airbus Service Bulletin A330-26-3030 or Airbus Service Bulletin A340-26-4030.

\* \* \* \* \*

Issued in Renton, Washington, on July 27, 2010.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. 2010-19151 Filed 8-4-10; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2010-0045; Directorate Identifier 2009-NM-085-AD; Amendment 39-16382; AD 2010-16-05]

RIN 2120-AA64

#### **Airworthiness Directives; The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Model 747 airplanes. This AD requires inspecting to verify the part number of the low-pressure flex-hoses of the crew oxygen system installed under the oxygen mask stowage boxes in the flight deck, and replacing the flex-hose with a new non-conductive low-pressure flex-hose if necessary. This AD results from reports of low-pressure flex-hoses of the crew oxygen system that burned through due to inadvertent electrical current from a short circuit in the audio select panel. We are issuing this AD to prevent inadvertent electrical current, which can cause the low-pressure flex-hoses of the crew oxygen system to melt or burn, causing oxygen system leakage and smoke or fire.

**DATES:** This AD is effective September 9, 2010.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of September 9, 2010.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, *Attention:* Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail [me.boecom@boeing.com](mailto:me.boecom@boeing.com); Internet <https://www.myboeingfleet.com>.

#### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527)

is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6457; fax (425) 917-6590.

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to certain Model 747 airplanes. That NPRM was published in the **Federal Register** on January 22, 2010 (75 FR 3658). That NPRM proposed to require inspecting to verify the part number of the low-pressure flex-hoses of the crew oxygen system installed under the oxygen mask stowage boxes in the flight deck, and replacing the flex-hose with a new non-conductive low-pressure flex-hose if necessary.

##### **Comments**

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

##### **Support for the NPRM**

Boeing concurs with the contents of the NPRM, and the Air Line Pilots Association, International (ALPA) supports the intent of the NPRM.

##### **Request To Shorten Compliance Time**

ALPA requests that the 36-month compliance time specified in the NPRM be shortened given the potential consequence of an oxygen-fed fire in the vicinity of the flightcrew station.

We do not agree. In developing an appropriate compliance time, we considered the safety implications, parts availability, and normal maintenance schedules for timely accomplishment of replacement of the fasteners. Further, we arrived at the compliance time with manufacturer concurrence. In consideration of all of these factors, we determined that the compliance time, as proposed, represents an appropriate interval in which the inspections can be done in a timely manner within the fleet, while still maintaining an adequate level of safety. Operators are always permitted to accomplish the requirements of an AD at a time earlier than the specified compliance time; therefore, an operator may choose to do

the inspection before 36 months in order to accomplish the requirements of this AD. If additional data are presented that would justify a shorter compliance time, we may consider further rulemaking on this issue. We have not changed the AD in this regard.

**Conclusion**

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

**Explanation of Change to Costs of Compliance**

Since issuance of the NPRM, we have increased the labor rate used in the Costs of Compliance from \$80 per work-hour to \$85 per work-hour. The Costs of Compliance information, below, reflects this increase in the specified hourly labor rate.

**Costs of Compliance**

We estimate that this AD will affect 211 airplanes of U.S. registry. We also estimate that it will take 1 work-hour per product to comply with this AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this proposed AD to the U.S. operators to be \$17,935, or \$85 per product.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

*For the reasons discussed above, I certify that this AD:*

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new AD:

**2010-16-05 The Boeing Company:**  
Amendment 39-16382. Docket No. FAA-2010-0045; Directorate Identifier 2009-NM-085-AD.

**Effective Date**

(a) This airworthiness directive (AD) is effective September 9, 2010.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes, certificated in any category; line numbers 1 through 1229 inclusive.

**Subject**

(d) Air Transport Association (ATA) of America Code 35: Oxygen.

**Unsafe Condition**

(e) This AD results from reports of low-pressure flex-hoses of the crew oxygen system that burned through due to inadvertent electrical current from a short circuit in the audio select panel. The Federal Aviation Administration is issuing this AD to prevent inadvertent electrical current, which

can cause the low-pressure flex-hoses of the crew oxygen system to melt or burn, resulting in oxygen system leakage and smoke or fire.

**Compliance**

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Inspection**

(g) Within 36 months after the effective date of this AD, do an inspection to determine whether any low-pressure flex-hose of the crew oxygen system installed under the oxygen mask stowage box in the flight deck has a part number identified in Table 1 of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the low-pressure flex-hoses of the crew oxygen system can be conclusively determined from that review.

(1) For any hose having a part number identified in Table 1 of this AD, before further flight, replace the hose with a new or serviceable part, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-35A2101, Revision 1, dated May 15, 2003.

(2) For any hose not having a part number identified in Table 1 of this AD, no further action is required by this paragraph.

TABLE 1—APPLICABLE PART NUMBERS

Boeing specification part No.	Equivalent hydraflow part No.
60B50059-19 .....	38001-19
60B50059-20 .....	38001-20
60B50059-60 .....	38001-60
60B50059-62 .....	38001-62
60B50059-69 .....	38001-69
60B50059-70 .....	38001-70
60B50059-81 .....	38001-81
60B50059-94 .....	38001-94
60B50059-95 .....	38001-95
60B50059-101 .....	38001-101
60B50059-129 .....	38001-129

**Parts Installation**

(h) As of the effective date of this AD, no person may install on any airplane a crew oxygen hose with a part number identified in Table 1 of this AD.

**Alternative Methods of Compliance (AMOCs)**

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6457; fax (425) 917-6590. Or, e-mail information to *9-ANM-Seattle-ACO-AMOC-Requests@faa.gov*.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR

39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD. Material Incorporated by Reference.

**Material Incorporated by Reference**

(j) You must use Boeing Service Bulletin 747-35A2101, Revision 1, dated May 15, 2003 to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail *me.boecom@boeing.com*; Internet *https://www.myboeingfleet.com*.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: *http://www.archives.gov/federal\_register/code\_of\_federal\_regulations/ibr\_locations.html*.

Issued in Renton, Washington, on July 16, 2010.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2010-18619 Filed 8-4-10; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF DEFENSE**

**Department of the Navy**

**32 CFR Part 706**

**Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972**

**AGENCY:** Department of the Navy, DoD.

**ACTION:** Final rule.

**SUMMARY:** The Department of the Navy is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (Admiralty and Maritime Law) has determined that USS RUSSELL (DDG 59) is a vessel of the Navy which, due to its special construction and purpose, cannot fully comply with certain provisions of the 72 COLREGS without interfering with its special function as a naval ship. The intended effect of this rule is to warn mariners in waters where 72 COLREGS apply.

**DATES:** This rule is effective August 5, 2010 and is applicable beginning July 23, 2010.

**FOR FURTHER INFORMATION CONTACT:** Lieutenant Commander Ted Cook, JAGC, U.S. Navy, Admiralty Attorney, (Admiralty and Maritime Law), Office of the Judge Advocate General, Department of the Navy, 1322 Patterson Ave., SE., Suite 3000, Washington Navy Yard, DC 20374-5066, *telephone number:* 202-685-5040.

**SUPPLEMENTARY INFORMATION:** Pursuant to the authority granted in 33 U.S.C. 1605, the Department of the Navy amends 32 CFR part 706.

This amendment provides notice that the Deputy Assistant Judge Advocate General (Admiralty and Maritime Law), under authority delegated by the Secretary of the Navy, has certified that USS RUSSELL (DDG 59) is a vessel of the Navy which, due to its special construction and purpose, cannot fully

comply with the following specific provisions of 72 COLREGS without interfering with its special function as a naval ship: Annex I, paragraph 3(a), pertaining to the horizontal distance between the forward and after masthead lights; and, Rule 21(a) pertaining to the forward masthead light arc of visibility. The Deputy Assistant Judge Advocate General (Admiralty and Maritime Law) has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

**List of Subjects in 32 CFR Part 706**

Marine safety, Navigation (water), and Vessels.

■ For the reasons set forth in the preamble, amend part 706 of title 32 of the Code of Federal Regulations as follows:

**PART 706—CERTIFICATIONS AND EXEMPTIONS UNDER THE INTERNATIONAL REGULATIONS FOR PREVENTING COLLISIONS AT SEA, 1972**

■ 1. The authority citation for part 706 continues to read as follows:

**Authority:** 33 U.S.C. 1605.

■ 2. Section 706.2 is amended in Table Four, Paragraph 16 by revising, in alpha numerical order, by vessel number, an entry for USS RUSSELL (DDG 59):

**§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.**

\* \* \* \* \*

TABLE FOUR—PARAGRAPH 16

Vessel	Number	Obstruction angle relative ship's headings
* * * * *	* * * * *	* * * * *
USS RUSSELL .....	DDG 59 .....	103.66 thru 112.50.°
* * * * *	* * * * *	* * * * *