

Rules and Regulations

Federal Register

Vol. 76, No. 3

Wednesday, January 5, 2011

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0955; Directorate Identifier 2010-NM-013-AD; Amendment 39-16560; AD 2011-01-07]

RIN 2120-AA64

Airworthiness Directives; 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328-100 and -300 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During maintenance on a 328-100 aeroplane, a crack was found on a trim tab fitting assembly. The cause of the cracking was identified as stress corrosion.

This condition, if not corrected, could lead to in-flight failure of the tab fitting, possibly resulting in loss of control of the aeroplane.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective February 9, 2011.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of February 9, 2011.

ADDRESSES: You may examine the AD docket on the Internet at [http://](http://www.regulations.gov)

www.regulations.gov or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on October 1, 2010 (75 FR 60659). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

During maintenance on a 328-100 aeroplane, a crack was found on a trim tab fitting assembly. The cause of the cracking was identified as stress corrosion.

This condition, if not corrected, could lead to in-flight failure of the tab fitting, possibly resulting in loss of control of the aeroplane. To address this unsafe condition, the TC [type certificate] holder has developed new aileron trim tab fittings and rudder spring tab fitting, using a material that is more resistant to stress corrosion. The improved material rudder spring tab fittings were introduced on the production line for the Model 328-300 and for 328-100 aeroplanes with a s/n [serial number] higher than 3098.

For the reasons described above, this AD requires the * * * replacement of [certain] aileron trim tab fittings and [certain] rudder spring tab fitting[s].

You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a Note within the AD.

Costs of Compliance

We estimated that this AD will affect 33 products of U.S. registry. We also estimate that it will take 6 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$2,252 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$91,146, or \$2,762 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

2011-01-07 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt

GmbH): Amendment 39-16560. Docket No. FAA-2010-0955; Directorate Identifier 2010-NM-013-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective February 9, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328-100 and -300 airplanes, certificated in any category, as specified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model 328-100 airplanes, all serial numbers, with part number (P/N) 001B576A2101000 left-hand (LH) or P/N 001B576A2101003 right-hand (RH) aileron trim tab fittings installed, or P/N 001A554A1711000 rudder spring tab fitting installed.

(2) Model 328-300 airplanes, all serial numbers, with P/N 001B576A2101000 (LH) or P/N 001B576A2101003 (RH) aileron trim tab fittings installed.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

During maintenance on a 328-100 aeroplane, a crack was found on a trim tab fitting assembly. The cause of the cracking was identified as stress corrosion.

This condition, if not corrected, could lead to in-flight failure of the tab fitting, possibly resulting in loss of control of the aeroplane.

* * * * *

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) For Model 328-100 airplanes: Within 6 months after the effective date of this AD, replace the aileron trim tab fittings P/N 001B576A2101000 (LH) and P/N 001B576A2101003 (RH) with P/N 001B576A2101004 (LH) and P/N 001B576A2101007 (RH) respectively; and replace the rudder spring tab fitting P/N 001A554A1711000 with P/N 001A554A1711006; in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-27-488, dated August 25, 2009.

(h) For Model 328-300 airplanes: Within 6 months after the effective date of this AD, replace the aileron trim tab fittings P/N 001B576A2101000 (LH) and P/N 001B576A2101003 (RH) with P/N 001B576A2101004 (LH) and P/N 001B576A2101007 (RH) respectively, in accordance with the Accomplishment Instructions of 328 Support Services Service

Bulletin SB-328J-27-237, dated August 25, 2009.

(i) After replacing the fittings as specified in paragraphs (g) and (h) of this AD, do not install P/N 001B576A2101000 (LH) or P/N 001B576A2101003 (RH) aileron trim tab fittings, or P/N 001A554A1711000 rudder spring tab fittings, on any airplane.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave., SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

Related Information

(k) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2009-0266, dated December 17, 2009; and 328 Support Services Service Bulletins SB-328-27-488 and SB-328J-27-

237, both dated August 25, 2009; for related information.

Material Incorporated by Reference

(1) You must use 328 Support Services Service Bulletin SB-328-27-488, dated August 25, 2009; or 328 Support Services Service Bulletin SB-328J-27-237, dated August 25, 2009; as applicable, to do the actions required by this AD, unless the AD specifies otherwise. (The document date is only referenced on the odd-numbered pages of these documents.)

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D-82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; e-mail gsc.op@328support.de; Internet <http://www.328support.de>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on December 17, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-32982 Filed 1-4-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0854; Directorate Identifier 2009-NM-261-AD; Amendment 39-16559; AD 2011-01-06]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A310 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding an existing airworthiness directive (AD) that applies to the products listed above. This AD results from mandatory continuing airworthiness information

(MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During High Time Equipment (HTE) reviews conducted within the scope of the A310 aircraft Design Service Goal (DSG) extension work, Airbus discovered that the splined couplings and the sliding bearings of the flap transmission system could be affected by corrosion and wear, especially when their protective components such as wiper rings and rubber gaiters could become defective.

This condition, if not detected and corrected, could degrade the functional integrity of the flap transmission system.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective February 9, 2011.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 9, 2011.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 23, 2010 (75 FR 57880), and proposed to supersede AD 2007-02-22, Amendment 39-14909 (72 FR 3708, January 26, 2007). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

During High Time Equipment (HTE) reviews conducted within the scope of the A310 aircraft Design Service Goal (DSG) extension work, Airbus discovered that the splined couplings and the sliding bearings of the flap transmission system could be affected by corrosion and wear, especially when their protective components such as wiper rings and rubber gaiters could become defective.

This condition, if not detected and corrected, could degrade the functional integrity of the flap transmission system.

For the reason described above, this AD requires repetitive inspections of the flap transmission system and associated components [for any missing, damaged, or incorrectly installed rubber gaiter, wiper rings and straps], and corrective action(s), depending on findings. [The corrective action is replacing missing, damaged, or incorrectly installed components.]

This [EASA] AD has been revised to correct the compliance time of 400 flight cycles in paragraph (3) into 400 flight hours. In addition, paragraph (4) has been introduced to clarify that the corrective actions do not end the requirement to continue the repetitive inspections, and some editorial changes for reasons of standardization. These do not affect the requirements of this AD as originally intended.

You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comment received.

Request To Clarify Compliance Times in Paragraphs (h)(1) and (h)(2) of the NPRM

FedEx (FedEx) requested that we clarify the compliance times in paragraphs (h)(1) and (h)(2) of the NPRM. FedEx stated that paragraph (h)(1) establishes the deadline for replacing defective components found before the effective date of the AD, and pointed out that paragraph (h)(2) should establish the deadline for replacing the defective components found after the effective date of the AD.

We agree with the commenter. We removed "not" from paragraph (h)(2) of this final rule so that it now establishes the deadline for replacing the defective components after the effective date of the AD.

Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the change described previously. We determined that this change will not increase the economic burden on any operator or increase the scope of the AD.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making