

Accomplishment Instructions of Fokker Service Bulletin SBF50–33–038, dated July 5, 2010; or SBF100–33–023, Revision 1, dated November 4, 2010; as applicable. A review of airplane maintenance records is acceptable in lieu of the inspection in this paragraph if the tritium exit signs and emergency lighting strips can be conclusively determined to have been manufactured in 2003 or earlier, from that review; however, the replacement in this paragraph must be accomplished before further flight after doing the review.

Parts Installation

(h) As of the effective date of this AD, no person may install any tritium exit signs or emergency lighting strips if the manufacturing date is seven years or more before the intended installation date, or if the manufacturing date cannot be determined; unless the tritium exit sign or emergency lighting strip has been inspected in accordance with paragraph (g) of this AD, and does not need replacement.

Credit for Actions Accomplished in Accordance With Previous Service Information

(i) Inspecting and replacing the tritium exit sign or emergency lighting strip in accordance with Fokker Service Bulletin SBF100–33–023, dated July 5, 2010, before the effective date of this AD is acceptable for compliance with the corresponding inspection and replacement required by paragraph (g) of this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1137; fax (425) 227–1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority

(or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(k) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2010–0261, dated December 9, 2010; Fokker Service Bulletin SBF50–33–038, dated July 5, 2010; and Fokker Service Bulletin SBF100–33–023, Revision 1, dated November 4, 2010; for related information.

Issued in Renton, Washington, on September 30, 2011.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011–26108 Filed 10–7–11; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2011–1063; Directorate Identifier 2011–NM–080–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Model 767–200 and –300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Model 767–200 and 767–300 series airplanes. This proposed AD would require installing cargo bulkhead supports, ceiling supports, secondary dam support, drainage tubing, and ceiling panels to the forward lower lobe in the forward cargo compartment. This proposed AD was prompted by reports of water accumulation in the forward lower lobe of the forward cargo compartment. We are proposing this AD to prevent water from accumulating in the forward lower lobe of the forward cargo compartment and entering the adjacent electronic equipment bay, which could result in an electrical short and the potential loss of several functions essential for safe flight.

DATES: We must receive comments on this proposed AD by November 25, 2011.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–

30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; *phone:* 206–544–5000, extension 1; *fax:* 206–766–5680; *e-mail:* me.boecom@boeing.com; *Internet:* <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (*phone:* 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Francis Smith, Aerospace Engineer, Cabin Safety & Environmental Systems Branch, ANM–150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, WA 98057–3356; *phone:* 425–917–6596; *fax:* 425–917–6590; *e-mail:* Francis.Smith@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2011–1063; Directorate Identifier 2011–NM–080–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any

personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received reports of high levels of water accumulation in the forward lower lobe of the forward cargo compartment and the potential for water to enter into the electronic equipment bay adjacent to it. Water coming through the floor panels can accumulate up to 12 gallons at this location and typical aircraft movement may not remove all the water. This condition, if not corrected, could result in water accumulating in the forward lower lobe of the forward cargo compartment and

entering the adjacent electronic equipment bay, which could result in an electrical short and the potential loss of several functions essential for safe flight.

Relevant Service Information

We reviewed Boeing Alert Service Bulletin 767-25A0505, Original Issue, dated January 14, 2011. The service information describes procedures for the installing cargo bulkhead supports, right-side ceiling supports, left-side ceiling supports, secondary dam support, drainage tubing, and ceiling panels in the forward lobe of the forward cargo compartment.

FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 1 airplane of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Installation	16 work-hours × \$85 per hour = \$1,360 per installation ..	Up to \$27,077 ..	Up to \$28,437 ...	Up to \$28,437.

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national

Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2011-1063; Directorate Identifier 2011-NM-080-AD.

Comments Due Date

(a) We must receive comments by November 25, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to The Boeing Company Model 767-200 and 767-300 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 767-25A0505, Original Issue, dated January 14, 2011.

Subject

(d) Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 25: Equipment and Furnishings.

Unsafe Condition

(e) This AD was prompted by reports of water accumulation in the forward lower lobe of the forward cargo compartment. We are issuing this AD to prevent water from accumulating in the forward lower lobe of the forward cargo compartment and entering the adjacent electronic equipment bay, which could result in an electrical short and the potential loss of several functions essential for safe flight.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Retrofit Installation of Drains, Dam, and Support Structure

(g) Within 24 months after the effective date of this AD: Install cargo bulkhead

supports, right-side ceiling supports, left-side ceiling supports, secondary dam support, drainage tubing, and ceiling panels, in accordance with Boeing Alert Service Bulletin 767-25A0505, Original Issue, dated January 14, 2011.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be e-mailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Related Information

(i) For more information about this AD, contact Francis Smith, Aerospace Engineer, Cabin Safety & Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, WA 98057-3356; phone: 425-917-6596; fax: 425-917-6590; e-mail: Francis.Smith@faa.gov.

(j) For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; e-mail: me.boecom@boeing.com; Internet: <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on September 28, 2011.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011-26109 Filed 10-7-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0277; Directorate Identifier 2009-NM-217-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model 767 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for all Model 767 airplanes. That NPRM proposed repetitive inspections to detect fatigue cracking in the wing skin, and corrective actions if necessary. That NPRM was prompted by reports of cracking in the upper wing skin at the fastener holes common to the inboard and outboard pitch load fittings of the front spar which could result in the loss of the strut-to-wing upper link load path and possible separation of a strut and engine from the airplane during flight. This action revises that NPRM by reducing compliance times. We are proposing this supplemental NPRM to correct the unsafe condition on these products. Since these actions impose an additional burden over that proposed in the NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

DATES: We must receive comments on this supplemental NPRM by November 25, 2011.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Berhane Alazar, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW., Renton, Washington 98057-3356; phone: 425-917-6577; fax: 425-917-6590; e-mail: berhane.alazar@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2010-0277; Directorate Identifier 2009-NM-217-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued an NPRM to amend 14 CFR part 39 to include an AD that would apply to Model 767-200, -300, -300F, and -400ER series airplanes. That NPRM was published in the **Federal Register** on March 29, 2010 (75 FR 15357). That NPRM proposed to require repetitive inspections to detect fatigue cracking in the upper wing skin at the fastener holes common to the inboard and outboard pitch load fittings of the front spar, and corrective actions if necessary.

Actions Since Previous NPRM (75 FR 15357, March 29, 2010) Was Issued

Since we issued the previous NPRM (75 FR 15357, March 29, 2010), one