

“General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Cirrus Design Corporation:** Docket No. FAA–2011–1212; Directorate Identifier 2011–CE–034–AD.

#### (a) Comments Due Date

We must receive comments by December 19, 2011.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the following model and serial number airplanes, certificated in any category:

(1) *Group 1 Airplanes:* Cirrus Design Corporation Model SR22T airplanes, serial numbers 0001 through 0169, except 0004, 0019, 0027, 0047, 0097, 0126, 0127, 0135, 0138, 0139, 0144, 0154, 0155, 0157, 0158, 0159, 0160, 0161, and 0163.

(2) *Group 2 Airplanes:* Cirrus Design Corporation Model SR22T airplanes, serial numbers 0004, 0019, 0027, 0047, 0097, 0126, 0127, 0135, 0138, 0139, 0144, 0155, 0157, 0158, 0160, and 0161. These airplanes had the reinforced silicone fiberglass seals installed at the factory but the box flange welds and slots may be incorrectly modified. Therefore, this AD still applies to these airplanes.

#### (d) Subject

Joint Aircraft System Component (JASC) Code 7160, Engine Air Intake.

#### (e) Unsafe Condition

This AD was prompted by reports of partial loss of engine power due to a dislodged rubber gasket/seal being ingested into the turbocharger. We are issuing this AD to inspect and modify the air box flange welds and slots and install induction system air box seals as applicable.

#### (f) Compliance

Comply with this AD following Cirrus Design Corporation SR22T Service Bulletin SB 2X–71–17 R1, dated September 30, 2011, within the compliance times specified, unless already done.

#### (g) Actions

(1) *Group 1 Airplanes:* Within the next 10 hours time-in-service (TIS) after the effective date of this AD, inspect the air box flange welds and slots, make modifications as necessary, and replace the induction air box seals with reinforced silicone fiberglass seals part number 29486–001.

(2) *Group 2 Airplanes:* Within the next 10 hours TIS after the effective date of this AD, inspect the air box flange welds and slots and, as necessary, make modifications.

**Note:** Credit will be given for actions required in paragraphs (g)(1) and (g)(2) of this AD if already done before the effective date of this AD following Cirrus Design Corporation SR22T Service Bulletin SB 2X–71–17, dated July 21, 2011.

#### (h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Chicago Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (i) Related Information

(1) For more information about this AD, contact Michael Downs, Propulsion Engineer, Chicago ACO, FAA, O'Hare Lake Office Center, 2300 East Devon Ave., Des Plaines, Illinois 60018; phone: (847) 294–7870; fax: (847) 294–7834; email: [michael.downs@faa.gov](mailto:michael.downs@faa.gov).

(2) For service information identified in this AD, contact Cirrus Design Corporation, 4515 Taylor Circle, Duluth, Minnesota 55811–1548, phone: (218) 788–3000; fax: (218) 788–3525; email: [fieldservice@cirrusaircraft.com](mailto:fieldservice@cirrusaircraft.com); Internet: <http://www.cirrusaircraft.com>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–1418.

Issued in Kansas City, Missouri, on October 27, 2011.

**John R. Colomy,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2011–28382 Filed 11–1–11; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2011–1166; Directorate Identifier 2010–NM–169–AD]

RIN 2120–AA64

### Airworthiness Directives; Dassault Aviation Model Mystere-Falcon 50 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The Maintenance Procedure (MP) 57–607, related to non destructive check of the flap tracks 2 and 5, has been introduced thru revision 4 (01/2009) of section 5–10 of the Recommended Maintenance Schedules chapter of the Aircraft Maintenance Documentation.

After the implementation of this MP cracks have been detected in service.

\* \* \* \* \*

Cracking of the flap tracks could lead to flap asymmetry and loss of control of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by December 19, 2011.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606; telephone (201) 440-6700; Internet <http://www.dassaultfalcon.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call (425) 227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-1166; Directorate Identifier 2010-NM-169-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2010-0080, dated April 29, 2010 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The Maintenance Procedure (MP) 57-607, related to non destructive check of the flap tracks 2 and 5, has been introduced thru revision 4 (01/2009) of section 5-10 of the Recommended Maintenance Schedules chapter of the Aircraft Maintenance Documentation.

After the implementation of this MP cracks have been detected in service.

\* \* \* \* \*

Cracking of the flap tracks could lead to flap asymmetry and loss of control of the airplane. The required actions include revising the maintenance program to include Dassault Aviation, Falcon 50/50EX Maintenance Manual, Non-Destructive Check of Flap Tracks 2 and 5, 57-607, dated January 2009 (commonly referred to as Dassault Falcon 50/50EX Maintenance Procedure 57-607, Non-Destructive Check of Flap Tracks 2 and 5, of Chapter 5-40 Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011). You may obtain further information by examining the MCAI in the AD docket.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified

of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 250 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$21,250, or \$85 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Dassault Aviation:** Docket No. FAA–2011–1166; Directorate Identifier 2010–NM–169–AD.

### Comments Due Date

(a) We must receive comments by December 19, 2011.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to Dassault Aviation Model Mystere-Falcon 50 airplanes, all serial numbers, certificated in any category.

### Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

The Maintenance Procedure (MP) 57–607, related to non destructive check of the flap tracks 2 and 5, has been introduced thru revision 4 (01/2009) of section 5–10 of the Recommended Maintenance Schedules chapter of the Aircraft Maintenance Documentation.

After the implementation of this MP cracks have been detected in service.

\* \* \* \* \*

Cracking of the flap tracks could lead to flap asymmetry and loss of control of the airplane.

### Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Actions

(g) Within 30 days after the effective date of the AD, revise the maintenance program to include Dassault Aviation, Falcon 50/50EX Maintenance Manual, Non-Destructive Check of Flap Tracks 2 and 5, 57–607, dated January 2009 (commonly referred to as Dassault Falcon 50/50EX Maintenance Procedure 57–607, Non-Destructive Check of Flap Tracks 2 and 5, of Chapter 5–40 Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011). The initial compliance time for doing the check is prior to the accumulation of 7,900 total flight cycles or within 600 flight cycles after the effective date of this AD, whichever occurs later.

### No Alternative Actions or Intervals

(h) After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

### FAA AD Differences

**Note 1:** This AD differs from the MCAI and/or service information as follows:

No difference.

### Other FAA AD Provisions

(i) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to *Attn:* Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; *phone:* (425) 227–1137; *fax:* (425) 227–1149. Information may be emailed to: *9-ANM-116-AMOC-REQUESTS@faa.gov*. Before using any approved AMOC, notify your appropriate principal inspector, or

lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

### Related Information

(j) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2010–0080, dated April 29, 2010; and Dassault Aviation, Falcon 50/50EX Maintenance Manual, Non-Destructive Check of Flap Tracks 2 and 5, 57–607, dated January 2009 (commonly referred to as Dassault Falcon 50/50EX Maintenance Procedure 57–607, Non-Destructive Check of Flap Tracks 2 and 5, of Chapter 5–40 Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011); for related information.

Issued in Renton, Washington, on October 21, 2011.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2011–28362 Filed 11–1–11; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF THE INTERIOR

### Office of Surface Mining Reclamation and Enforcement

### 30 CFR Part 902

[SATS No. AK–007–FOR; Docket ID OSM–2011–0017]

### Alaska Regulatory Program

**AGENCY:** Office of Surface Mining Reclamation and Enforcement, Interior.

**ACTION:** Proposed rule; public comment period and opportunity for public hearing on proposed amendment.

**SUMMARY:** We are announcing receipt of a proposed amendment to the Alaska regulatory program (hereinafter, the “Alaska program”) under the Surface Mining Control and Reclamation Act of 1977 (“SMCRA” or “the Act”). Alaska intends to revise its rules to be consistent with the corresponding Federal regulations and to conform to the drafting manual for the State of Alaska.

This document gives the times and locations that the Alaska program and proposed amendment to that program are available for your inspection, the comment period during which you may