

delay in effective date for these same reasons.

List of Subjects in 10 CFR Part 431

Administrative practice and procedure, Confidential business information, Energy conservation, Household appliances, Imports, Intragovernmental relations, Reporting and recordkeeping requirements, and Small businesses.

Accordingly, part 431 of chapter II, subchapter D, of title 10 of the Code of Federal Regulations, is corrected by making the following correcting amendments:

PART 431—ENERGY EFFICIENCY PROGRAM FOR CERTAIN COMMERCIAL AND INDUSTRIAL EQUIPMENT

- 1. The authority citation for part 431 continues to read as follows:

Authority: 42 U.S.C. 6291–6317.

- 2. Section 431.156 of subpart I is revised to read as follows:

§ 431.156 Energy and water conservation standards and effective dates.

(a) Each commercial clothes washer manufactured between January 1, 2007, and January 8, 2013, shall have—

(1) A modified energy factor of at least 1.26; and

(2) A water consumption factor of not more than 9.5.

(b) Each commercial clothes washer manufactured on or after January 8, 2013, shall have a modified energy factor no less than and a water factor no greater than:

Equipment class	Modified energy factor, cu. ft./kWh/cycle	Water factor, gal./cu. ft./cycle
Top-Loading	1.60	8.5
Front-Loading ...	2.00	5.5

Issued in Washington, DC, on November 1, 2011.

Kathleen B. Hogan,

Deputy Assistant Secretary for Energy Efficiency, Energy Efficiency and Renewable Energy.

[FR Doc. 2011–28920 Filed 11–7–11; 8:45 am]

BILLING CODE 6450–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–27747; Directorate Identifier 2007–CE–030–AD; Amendment 39–16782; AD 2009–10–09 R2]

RIN 2120–AA64

Airworthiness Directives; Cessna Aircraft Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that published in the **Federal Register**. That AD applies to certain Cessna Aircraft Company (Cessna) Models 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FRA150L, FA150M, FRA150M, 152, A152, F152, and FA152 airplanes. There is an error in the compliance instructions. This document corrects that error. In all other respects, the original document remains the same.

DATES: This final rule; correction, is effective November 8, 2011. The effective date for AD 2009–10–09 R2 remains September 12, 2011.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: (800) 647–5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Ann Johnson, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; phone: (316) 946–4105; fax: (316) 946–4107; email: ann.johnson@faa.gov.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive 2009–10–09 R2, Amendment 39–16782 (76 FR 53308, August 26, 2011), currently requires either installing a placard prohibiting spins and other acrobatic maneuvers in the airplane or replacing the rudder stop, the rudder stop bumper, and the attachment hardware with a new rudder

stop modification kit for certain Cessna Models 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FRA150L, FA150M, FRA150M, 152, A152, F152, and FA152 airplanes.

As published, the text in the Procedures column of Table 2 in paragraph (g)(1) of this AD incorrectly states “* * * fabricate the placard required in paragraph (g)(1)(i) of this AD * * *”, and the text should refer to paragraph (g)(1)(ii).

No other part of the preamble or regulatory information has been changed; therefore, only the changed portion of the final rule is being published in the **Federal Register**.

The effective date of this AD remains September 12, 2011.

Correction of Regulatory Text

§ 39.13 [Corrected]

In the **Federal Register** of August 26, 2011, on page 53311, in the 3rd column, Procedures, paragraph (g)(1), Table 2—Actions, Compliance and Procedures, of AD 2009–10–09 R2 is corrected to read as follows:

* * * * *

A person authorized to perform maintenance as specified in 14 CFR 43.3 of the Federal Aviation Administration Regulations (14 CFR 43.3) is required to make the AFM and POH changes, fabricate the placard required in paragraph (g)(1)(ii) of this AD, and make an entry into the aircraft logbook showing compliance with the portion of the AD per compliance with 14 CFR 43.9.

* * * * *

Issued in Kansas City, Missouri, on November 2, 2011.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011–28861 Filed 11–7–11; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2010–1301; Directorate Identifier 2010–SW–008–AD; Amendment 39–16851; AD 2011–22–08]

RIN 2120–AA64

Airworthiness Directives; MD Helicopters, Inc. Model MD900 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.