

(4) Airbus Service Bulletin A320–28–1154, Revision 01, dated April 7, 2008.

(i) Parts Installation

As of the effective date of this AD, no person may install an off-wing slide release cable having P/N L32A319–160–001 on any airplane.

(j) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if installation of off-wing slide release cables having P/N L32A320–180 was done before the effective date of this AD using the applicable service bulletin identified in paragraph (j)(1) through (j)(6) of this AD.

(1) Airbus Service Bulletin A320–53–1227, dated March 24, 2010.

(2) Airbus Service Bulletin A320–28–1132, dated October 13, 2004.

(3) Airbus Service Bulletin A320–28–1132, Revision 01, dated October 12, 2006.

(4) Airbus Service Bulletin A320–28–1132, Revision 02, dated November 12, 2008.

(5) Airbus Service Bulletin A320–28–1132, Revision 03, dated October 5, 2009.

(6) Airbus Service Bulletin A320–28–1145, dated February 28, 2006.

(k) Exception

Provided that off-wing slide release cables have not been replaced with a slide release cable having P/N L32A319–160–001, airplanes having Airbus modification 150811, 26138, 37856, or 39673 installed in production are acceptable for compliance with the requirements of paragraph (g) of this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1405; fax (425) 227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(m) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2011–0015, dated January 31, 2011; and the service information specified in paragraphs (m)(1) through (m)(5) of this AD; for related information:

(1) Airbus Service Bulletin A320–28–1118, Revision 03, including Appendix 1, dated May 12, 2009.

(2) Airbus Service Bulletin A320–28–1132, Revision 04, including Appendices 1 and 2, dated February 1, 2010.

(3) Airbus Service Bulletin A320–28–1145, Revision 01, including Appendix 01, dated April 27, 2007.

(4) Airbus Service Bulletin A320–28–1154, Revision 01, dated April 7, 2008.

(5) Airbus Service Bulletin A320–53–1227, Revision 01, dated May 31, 2010.

Issued in Renton, Washington, on March 1, 2012.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–6465 Filed 3–15–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2009–0288; Directorate Identifier 2008–NM–214–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for certain The Boeing Company Model 737–600, –700, –700C, –800, –900 and –900ER series airplanes. That NPRM proposed to require modifying the fluid drain path in the wing leading edge area, forward of the wing front spar, and doing all applicable related investigative and corrective actions. That NPRM was prompted by a report of leaking fuel from the wing leading edge area at the inboard end of the number 5 leading edge slat. This action revises that NPRM by including installing new seal disks on the latches in the fuel shutoff valve access door as part of the modification and by specifying that certain inspections are detailed inspections. This action also revises the applicability to include additional airplanes. We are proposing this AD to prevent flammable fluids from accumulating in the wing

leading edge, and draining inboard and onto the engine exhaust nozzle, which could result in a fire. Since these actions impose an additional burden over that proposed in the NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

DATES: We must receive comments on this supplemental NPRM by April 30, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; email me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD (74 FR 15683, April 7, 2009), the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Chris Parker, Aerospace Engineer, Propulsion Branch, ANM–140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton,

Washington 98057-3356; phone: 425-917-6496; fax: 425-917-6590; email: chris.r.parker@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2009-0288; Directorate Identifier 2008-NM-214-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued an NPRM to amend 14 CFR part 39 to include an AD that would apply to Model 737-600, -700, -700C, -800, -900 and -900ER series airplanes. That NPRM published in the **Federal Register** on April 7, 2009 (74 FR 15683). That NPRM proposed to require modifying the fluid drain path in the wing leading edge area, forward of the wing front spar, and doing all applicable related investigative and corrective actions.

Actions Since Previous NPRM Was Issued

Since we issued the previous NPRM (74 FR 15683, April 7, 2009), Boeing issued Special Attention Service Bulletin 737-57-1293, Revision 2, dated September 28, 2011, to add actions to the modification of the fluid drain path in the wing leading edge area, forward of the wing front spar. The additional actions are installing new seal disks on the latches in the fuel shutoff valve access door. Boeing Special Attention

Service Bulletin 737-57-1293, Revision 2, dated September 28, 2011, also adds airplanes with line numbers 2438 through 3833 inclusive to the effectivity. The service information also changed the general visual inspection of the countersink diameter for the bonding jumper fastener hole to a detailed inspection.

Comments

We gave the public the opportunity to comment on the previous NPRM (74 FR 15683, April 7, 2009). The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Extend Compliance Time

Air Transport Association, on behalf of its members American Airlines (AAL) and AirTran Airways, requested that we extend the compliance time of the proposed AD (74 FR 15683, April 7, 2009). AAL requested that the proposed compliance time of 24 months be changed to 72 months. AAL stated that the proposed compliance time of 24 months does not integrate into the current operator maintenance program without significant aircraft maintenance planning adjustments and additional costs. AAL stated that a 72-month compliance time would fit within the maintenance review board heavy C-check schedule.

We do not agree with the commenter's request to extend the compliance time. Extending the compliance time to 72 months would result in an unacceptable level of risk for the Model 737-600, -700, -700C, -800, -900, and -900ER fleet. We have determined that the compliance time of 24 months represents the maximum interval of time allowable for the affected airplanes to continue to safely operate before the modification is done. Under the provisions of paragraph (h) of this supplemental NPRM, however, we may consider requests for adjustments to the compliance time if data are submitted to substantiate that such an adjustment would provide an acceptable level of safety. We have not changed the supplemental NPRM in this regard.

Request To Refer to Revised Service Bulletin

Boeing and the Air Transport Association, on behalf of its member AAL, requested that we refer to Boeing Special Attention Service Bulletin 737-57-1293, Revision 1, dated January 11, 2010, in order to incorporate new changes and to prevent issuance of alternative methods of compliance (AMOC).

We disagree with the request to refer to Boeing Special Attention Service Bulletin 737-57-1293, Revision 1, dated January 11, 2010. Since the date of the commenters' requests, Boeing has issued Special Attention Service Bulletin 737-57-1293, Revision 2, dated September 28, 2011 (described previously), which adds more new changes. We have changed paragraphs (c) and (g) of this supplemental NPRM to refer to Boeing Special Attention Service Bulletin 737-57-1293, Revision 2, dated September 28, 2011.

FAA's Determination

We are proposing this supplemental NPRM because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs. Certain changes described above expand the scope of the original NPRM (74 FR 15683, April 7, 2009). As a result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this supplemental NPRM.

Proposed Requirements of the Supplemental NPRM

This supplemental NPRM would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 1,072 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification, Group 1 (734 airplanes)	50 work-hours × \$85 per hour = \$4,250	\$1,262	\$5,512	\$4,045,808
Modification, Group 2 (58 airplanes)	27 work-hours × \$85 per hour = \$2,295	1,262	3,557	206,306
Modification, Group 3 (280 airplanes)	3 work-hours × \$85 per hour = \$255	94	349	97,720

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701:

"General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2009-0288; Directorate Identifier 2008-NM-214-AD.

(a) Comments Due Date

We must receive comments by April 30, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900 and -900ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 737-57-1293, Revision 2, dated September 28, 2011.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of leaking fuel from the wing leading edge area at the inboard end of the number 5 leading edge slat. We are issuing this AD to prevent flammable fluids from accumulating in the wing leading edge, and draining inboard and onto the engine exhaust nozzle, which could result in a fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 24 months after the effective date of this AD, modify the fluid drain path in the wing leading edge area, forward of the wing front spar, and do all applicable related investigative and corrective actions, by accomplishing all applicable actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-57-1293, Revision 2, dated September 28, 2011. Do all applicable related investigative and corrective actions before further flight.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Chris R. Parker, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6496; fax: 425-917-6590; email: chris.r.parker@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; email me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on February 23, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-6468 Filed 3-15-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0036; Directorate Identifier 2009-NM-077-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for certain The Boeing Company Model 737-200, -200C, -300, -400, and -500 series airplanes. That NPRM proposed to require inspections for cracking and corrosion under the number 3 very high frequency (VHF) antenna, and corrective actions if necessary; and, for certain airplanes, replacing bonded skin panels with solid skin panels if not previously accomplished. That NPRM was prompted by reports of cracks in the skin and surrounding structure under the number 3 VHF antenna on the lower external surface of the airplane at buttock line 0.0, aft of the main landing gear wheel well. This action revises that NPRM by adding an optional preventive