

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aerosystems Model 340A (SAAB/SF340A) and SAAB 340B airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 27: Flight Controls.

(e) Reason

This AD was prompted by reports indicating that wear of the elevator pushrods have occurred on some airplanes after extended time in service. We are issuing this

AD to prevent a free elevator from affecting the pitch control authority, which may result in reduced controllability of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection to Determine the Part Number

Within the applicable time specified in table 1 of this AD, inspect each elevator pushrod assembly to determine the part number (P/N).

(1) If a P/N TDF11755 elevator pushrod assembly is installed, or if the part number cannot be determined: Before further flight,

replace the affected elevator pushrod assembly with a P/N R20990 elevator pushrod assembly, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–27–100, dated February 1, 2011.

(2) If P/N 12003–33 or P/N R20990 elevator pushrod assembly is installed: Do a detailed inspection for individual play between the rod end and the pushrod at the locking device and degradation of elevator pushrod assembly (including rod end threads not visible through the inspection hole in the pushrod, and the nut and locking device not properly locked with the lock wire), in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–27–100, dated February 1, 2011.

TABLE 1—Compliance time

Total flight hours accumulated as of the effective date of this AD	Compliance time
For airplanes with 30,000 total flight hours or more	Within 6 months after the effective date of this AD.
For airplanes with 28,000 total flight hours or more, but less than 30,000 total flight hours.	Before the accumulation of 30,000 total flight hours or within 6 months after the effective date of this AD, whichever occurs later.
For airplanes with less than 28,000 total flight hours	Before the accumulation of 30,000 total flight hours.

(h) Corrective Action

If, during the inspection of elevator pushrod assembly required by paragraph (g)(2) of this AD, individual play between the rod end and the pushrod at the locking device, or degradation of the elevator pushrod assembly (including rod end threads not visible through the inspection hole in the pushrod, and the nut and locking device not properly locked with the lock wire) is found: Before further flight, replace the affected elevator pushrod assembly with a new elevator pushrod assembly, P/N R20990, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–27–100, dated February 1, 2011.

(i) Parts Installation

As of the effective date of this AD, no person may install an elevator pushrod assembly with P/N TDF11755, on any airplane.

(j) Reporting Requirement

Submit a report of the findings (both positive and negative) of the inspection and replacement required by paragraphs (g) and (h) of this AD to Saab AB, Support and Services, SE–581 88 Linköping, Sweden; fax +46 13 18 48 74; email saab340.techsupport@saabgroup.com; at the applicable time specified in paragraph (j)(1) or (j)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, FAA, has the authority to

approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to Attn: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1112; fax (425) 227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments

concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(l) Related Information

Refer to MCAI EASA Airworthiness Directive 2011–0078, dated May 5, 2011; and Saab Service Bulletin 340–27–100, dated February 1, 2011; for related information.

Issued in Renton, Washington, on March 23, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–7769 Filed 3–30–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2012–0329; Directorate Identifier 2011–NM–139–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A318–112 and –121 airplanes; Model A319–111, –112, –115, –132, and –133 airplanes; Model A320–

214, -232, and -233 airplanes; and Model A321-211, -212, -213, and -231 airplanes. This proposed AD was prompted by reports of cracked nuts on the fuselage. This proposed AD would require an inspection to determine if certain fuselage nuts are installed, a detailed inspection for cracking of fuselage nuts having a certain part number, and related investigative and corrective actions if necessary. We are proposing this AD to detect and correct cracked nuts on the fuselage which could result in reduced structural integrity of the airplane.

DATES: We must receive comments on this proposed AD by May 17, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer,

International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1405; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2012-0329; Directorate Identifier 2011-NM-139-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2011-0120R1, dated July 13, 2011 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

During structural part assembly in Airbus production line, some nuts Part Number (P/N) ASNA2531-4 were found cracked. Investigations were performed to determine the batches of the affected nuts and had revealed that these nuts have been installed in production on the fuselage of aeroplanes listed in the applicability section of this [EASA] AD.

Static, fatigue and corrosion tests were performed, which demonstrated that no immediate maintenance action is necessary. However, a large number of these nuts are fitted on primary structural elements, which could have long-term consequences.

This condition, if not corrected, could impair the structural integrity of the affected aeroplanes.

For the reasons described above, this [EASA] AD requires [an inspection to determine if certain fuselage nuts are installed,] a detailed inspection [for cracking] of the affected nuts, associated corrective actions, [general visual inspection for scratching of the hole if necessary] depending on findings, and replacement of the affected P/N ASNA2531-4 nuts with new ones, having the same P/N.

* * * * *

Required actions include related investigative and corrective actions if

necessary. Related investigative actions include a general visual inspection for scratching of the hole. Corrective actions include replacing the fastener and installing a new fuselage nut. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued Service Bulletin A320-53-1218, Revision 01, including Appendices 01 and 02, dated June 17, 2010. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 152 products of U.S. registry. We also estimate that it would take about 15 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$193,800, or \$1,275 per product.

In addition, we estimate that any necessary follow-on actions would take about 10 work-hours and require parts costing \$362, for a cost of \$1,212 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Airbus: Docket No. FAA-2012-0329; Directorate Identifier 2011-NM-139-AD.

(a) Comments Due Date

We must receive comments by May 17, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A318-112 and -121 airplanes; Model A319-111, -112, -115, -132, and -133 airplanes; Model A320-214, -232, and -233 airplanes; and Model A321-211, -212, -213, and -231 airplanes; certificated in any category; manufacturer serial numbers 3339, 3340, 3350, 3355, 3360, 3367, 3369, 3372, 3380, 3382, 3385, 3387, 3388, 3390, 3393, 3395, 3397 through 3508 inclusive, 3510 through 3519 inclusive, 3522, 3523, 3525, 3527, 3529, 3530, 3537, 3539, 3542, 3544, 3546, 3548, 3552, and 3555.

(d) Subject

Air Transport Association (ATA) of America Code 53: Fuselage.

(e) Reason

This AD was prompted by reports of cracked nuts on the fuselage. We are issuing this AD to detect and correct cracked nuts on the fuselage which could result in reduced structural integrity of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection and Replacement

Within 72 months since first flight of the airplane or within 90 days after the effective date of this AD, whichever occurs later, do an inspection for nuts having part number (P/N) ASNA2531-4 located in the fuselage. If a nut having P/N ASNA2531-4 is found, before further flight, do a detailed inspection for cracking of the nut, and all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-53-1218, Revision 01, including Appendices 01 and 02, dated June 17, 2010. If any cracking is found, before further flight, repair, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-53-1218, Revision 01, including Appendices 01 and 02, dated June 17, 2010.

(h) Reporting

Submit a report of the findings in accordance with Appendix 01 of the inspection required by paragraph (g) of this AD to Airbus in accordance with Appendix 01 of Airbus Service Bulletin A320-53-1218, Revision 01, including Appendices 01 and 02, dated June 17, 2010, at the applicable time specified in paragraph (h)(1) or (h)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 90 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 90 days after the effective date of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for inspections and replacements required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-53-1218,

including Appendices 01 and 02, dated February 8, 2010.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-227-1405; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591. Attn: Information Collection Clearance Officer, AES-200.

(k) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2011-0120R1, dated July 13, 2011; and Airbus Service Bulletin A320-53-1218, Revision 01, including Appendices 01 and 02, dated June 17, 2010; for related information.

Issued in Renton, Washington, on March 22, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2012-7770 Filed 3-30-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 100

[Docket No. USCG-2012-0169]

RIN 1625-AA08

Special Local Regulation for Marine Events, Chesapeake Bay Workboat Race, Back River, Messick Point, Poquoson, VA

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish a special local regulation during the Chesapeake Bay Workboat Race, a series of boat races to be held on the waters of Back River, Poquoson, Virginia on June 24, 2012. This event will consist of approximately 75 powerboats conducting high-speed competitive races on the waters of the Back River. This regulation is necessary to provide for the safety of life on navigable waters during the event. This action is intended to restrict vessel traffic in portions of the Back River, Messick Point, Poquoson, Virginia during the event.

DATES: Comments and related material must be received by the Coast Guard on or before May 2, 2012.

ADDRESSES: You may submit comments identified by docket number USCG-2012-0169 using any one of the following methods:

(1) *Federal eRulemaking Portal:*
<http://www.regulations.gov>.

(2) *Fax:* 202-493-2251.

(3) *Mail:* Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.

(4) *Hand delivery:* Same as mail address above, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202-366-9329.

To avoid duplication, please use only one of these four methods. See the "Public Participation and Request for Comments" portion of the

SUPPLEMENTARY INFORMATION section

below for instructions on submitting comments.

FOR FURTHER INFORMATION CONTACT: If you have questions on this proposed rule, call or email. If you have questions on this temporary rule, call or email LCDR Christopher O'Neal, Waterways Management Division Chief, Sector Hampton Roads, Coast Guard; telephone 757-668-5581, email *Christopher.A.ONeal@uscg.mil*. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION:

Public Participation and Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related materials. All comments received will be posted without change to <http://www.regulations.gov> and will include any personal information you have provided.

Submitting Comments

If you submit a comment, please include the docket number for this rulemaking (USCG-2012-0169), indicate the specific section of this document to which each comment applies, and provide a reason for each suggestion or recommendation. You may submit your comments and material online (via <http://www.regulations.gov>) or by fax, mail, or hand delivery, but please use only one of these means. If you submit a comment online via www.regulations.gov, it will be considered received by the Coast Guard when you successfully transmit the comment. If you fax, hand deliver, or mail your comment, it will be considered as having been received by the Coast Guard when it is received at the Docket Management Facility. We recommend that you include your name and a mailing address, an email address, or a telephone number in the body of your document so that we can contact you if we have questions regarding your submission.

To submit your comment online, go to <http://www.regulations.gov>, type the docket number (USCG-2012-0169) in the "SEARCH" box and click "SEARCH." Click on "Submit a Comment" on the line associated with this rulemaking. If you submit your comments by mail or hand delivery, submit them in an unbound format, no larger than 8½ by 11 inches, suitable for copying and electronic filing. If you submit comments by mail and would like to know that they reached the

Facility, please enclose a stamped, self-addressed postcard or envelope. We will consider all comments and material received during the comment period and may change the rule based on your comments.

Viewing Comments and Documents

To view comments, as well as documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type the docket number (USCG-2012-0169) in the "SEARCH" box and click "SEARCH." Click on Open Docket Folder on the line associated with this rulemaking. You may also visit the Docket Management Facility in Room W12-140 on the ground floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Privacy Act

Anyone can search the electronic form of comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, labor union, etc.). You may review a Privacy Act notice regarding our public dockets in the January 17, 2008, issue of the **Federal Register** (73 FR 3316).

Public Meeting

We do not now plan to hold a public meeting. But you may submit a request for one using one of the four methods specified under **ADDRESSES**. Please explain why you believe a public meeting would be beneficial. If we determine that one would aid this rulemaking, we will hold one at a time and place announced by a later notice in the **Federal Register**.

For information on facilities or services for individuals with disabilities or to request special assistance at the public meeting, contact LCDR Christopher O'Neal at the telephone number or email address indicated under the **FOR FURTHER INFORMATION CONTACT** section of this notice.

Basis and Purpose

Marine events are frequently held on the navigable waters within the boundary of Fifth Coast Guard District. The water activities that typically comprise marine events include sailing regattas, power boat races, swim races and holiday parades. For a description of the geographical area of each Coast Guard Sector—Captain of the Port Zone, please see 33 CFR 3.25.