

(i) If any crack or corrosion is found: Repair or change the end fitting, as required by paragraph (s) of this AD.

(ii) If no crack or corrosion is found: Apply corrosion inhibiting compound on each end fitting, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, and do detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(A) If any crack or corrosion is found: Repair or change the end fitting, as required by paragraph (s) of this AD.

(B) If no crack or corrosion is found: Apply corrosion inhibiting compound, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009; and repeat the detailed and HFEC inspections of each end fitting for cracks and corrosion, in accordance with Part 6 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(s) New Repair for Group 6 Airplanes

If any crack or corrosion is found during any inspection required by paragraph (r) of this AD: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009.

(t) New Optional Action for Part 4, Part 5, and Part 6 Inspections

In lieu of doing Part 4, Part 5, or Part 6 inspections required by this AD: Repair or change the end fitting, in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009. After accomplishing the repair or change in accordance with Part 7 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2331, dated November 12, 2009, do the applicable actions required by paragraphs (p) and (r) of this AD.

(u) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization

Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 89-15-07, Amendment 39-6267 (54 FR 30009, July 18, 1989), are approved as AMOCs for the corresponding requirements of this AD.

(v) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: (425) 917-6432; fax: (425) 917-6590; email: bill.ashforth@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; email me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on May 18, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-13187 Filed 5-30-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0495; Directorate Identifier 2011-NM-236-AD]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft Industries, Ltd.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Gulfstream Aerospace LP (Type Certificate previously held by Israel Aircraft Industries, Ltd.) Model Galaxy and Gulfstream 200 airplanes. This proposed AD was prompted by reports of degraded brake performance during landing due to improperly-sized wear indicating pins. This proposed AD would require determining the lengths

of the wear indicating pins of all brake assemblies, shortening the pin if the wear indicating pin is too long, inspecting for normal brake wear, and replacing brakes with new brakes if necessary. We are proposing this AD to detect and correct improperly-sized wear indicating pins, which, if not corrected, could result in worn-out brake pads and subsequent loss of braking power, which could result in runway overruns.

DATES: We must receive comments on this proposed AD by July 16, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D-25, Savannah, Georgia 31402-2206; telephone 800-810-4853; fax 912-965-3520; email pubs@gulfstream.com; Internet http://www.gulfstream.com/product_support/technical_pubs/pubs/index.htm. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA,

1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone: (425) 227-1503; fax: (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2012-0495; Directorate Identifier 2011-NM-236-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Civil Aviation Authority of Israel (CAAI), which is the aviation authority for Israel, has issued Israeli Airworthiness Directive 32-11-10-13, dated October 31, 2011 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Two G200 operators experienced degraded brake performance during landing. Subsequent investigation revealed that in both cases the brake wear pins showed remaining life, but the brakes were worn to the minimum pad thickness specified in the Brake Assembly Component Maintenance Manual (CMM). It was found out that pins of incorrect length were installed during brake assembly overhaul. When the brake pads are fully worn without indication, loss of braking power is expected, possibly causing runway overruns. This constitutes an unsafe condition.

The required action is determining the lengths of the wear indicating pins of all brake assemblies, shortening the pin if the wear indicating pin is too long, inspecting for normal brake wear, and replacing brakes with new brakes if necessary. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Gulfstream Aerospace LP has issued Service Bulletin 200-32-389, Revision 1, dated October 27, 2011. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 155 products of U.S. registry. We also estimate that it would take about 16 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$0 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$210,800, or \$1,360 per product.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Gulfstream Aerospace LP (Type Certificate previously held by Israel Aircraft Industries, Ltd.): Docket No. FAA-2012-0495; Directorate Identifier 2011-NM-236-AD.

(a) Comments Due Date

We must receive comments by July 16, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Gulfstream Aerospace LP (Type Certificate previously held by Israel Aircraft Industries, Ltd.) Model Galaxy and Gulfstream 200 airplanes, certificated in any category, serial numbers 004 through 250 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 32: Landing Gear.

(e) Reason

This AD was prompted by reports of degraded brake performance during landing due to improperly-sized wear indicating pins. We are issuing this AD to detect and correct improperly-sized wear indicating pins, which, if not corrected, could result in worn-out brake pads and subsequent loss of braking power, which could result in runway overruns.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Determining and Correcting Pin Length and Inspecting Brake Wear

Within 40 days after the effective date of this AD, determine the length of the wear indicating pins of all the brake assemblies, in accordance with the Accomplishment Instructions of Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011.

(1) If the length of the pins is within the limits specified in Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011, before further flight, perform a normal brake wear inspection in accordance with the Accomplishment Instructions of Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011.

(2) If any wear indicating pin is too long, as specified by the limits in Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011, before further flight, shorten the pin and perform a normal brake wear inspection, in accordance with the Accomplishment Instructions of Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011.

(h) Brake Replacement

If any brake fails the wear inspection required by paragraphs (g)(1) and (g)(2) of this AD, before further flight, replace the affected brakes with new brakes, in accordance with the Accomplishment Instructions of Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011.

(i) Credit for Actions Accomplished in Accordance With Previous Service Information

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the Accomplishment Instructions of Gulfstream Service Bulletin 200-32-389, dated October 20, 2011.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to

approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Groves, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1503; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(k) Related Information

(1) Refer to Israeli Airworthiness Directive 32-11-10-13, dated October 31, 2011; and Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011; for related information.

(2) For service information identified in this AD, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D-25, Savannah, Georgia 31402-2206; telephone 800-810-4853; fax 912-965-3520; email pubs@gulfstream.com; Internet http://www.gulfstream.com/product_support/technical_pubs/pubs/index.htm. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on May 18, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-13194 Filed 5-30-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Saint Lawrence Seaway Development Corporation****33 CFR Part 401**

[Docket No. SLSDC-2012-0001]

RIN 2135-AA30

Seaway Regulations and Rules: Periodic Update, Various Categories

AGENCY: Saint Lawrence Seaway Development Corporation, DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Saint Lawrence Seaway Development Corporation (SLSDC) and the St. Lawrence Seaway Management Corporation (SLSMC) of Canada, under international agreement, jointly publish and presently administer the St. Lawrence Seaway Regulations and Rules (Practices and Procedures in Canada) in their respective jurisdictions. Under agreement with the SLSMC, the SLSDC is amending the joint regulations by updating the Seaway Regulations and Rules in various categories. The proposed changes will update the following sections of the Regulations and Rules: Condition of Vessels; Seaway Navigation; Dangerous Cargo; Information and Reports; General; and, Navigation Closing Procedures. These proposed amendments are necessary to take account of updated procedures and will enhance the safety of transits through the Seaway. Several of the proposed amendments are merely editorial or for clarification of existing requirements.

DATES: Any party wishing to present views on the proposed amendment may file comments with the Corporation on or before July 2, 2012.

ADDRESSES: You may submit comments identified by Docket Number SLSDC 2012-0001 by any of the following methods:

- *Web Site:* <http://www.Regulations.gov>. Follow the online instructions for submitting comments/submissions.
- *Fax:* 1-202-493-2251.
- *Mail:* Docket Management Facility; U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-001.
- *Hand Delivery:* Documents may be submitted by hand delivery or courier to West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-001, between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

Instructions: All submissions must include the agency name and docket number or Regulatory Identification Number (RIN) for this rulemaking. Note that all comments received will be posted without change at <http://www.Regulations.gov> including any personal information provided. Please see the Privacy Act heading under *Regulatory Notices*.

Docket: For access to the docket to read background documents or comments received, go to <http://www.Regulations.gov>; or in person at the Docket Management Facility; U.S.