

composed of several connected networks. The proposed architecture and network configuration may be used for, or interfaced with, a diverse set of functions, including:

1. Flight-safety related control, communication, and navigation systems (aircraft control functions);
2. Airline business and administrative support (airline information services), and;
3. Passenger information and entertainment systems (passenger entertainment services).

#### Discussion

The Model G280 integrated network configuration may allow increased connectivity with external network sources and will have more interconnected networks and systems, such as passenger entertainment and information services, than previous GALP airplane models. This may allow the exploitation of network security vulnerabilities and increased risks potentially resulting in unsafe conditions for the airplane and its occupants. This potential exploitation of security vulnerabilities may result in intentional or unintentional destruction, disruption, degradation, or exploitation of data and systems critical to the safety and maintenance of the airplane. The existing regulations and guidance material did not anticipate these types of system architectures. Furthermore, 14 CFR regulations and current system safety assessment policy and techniques do not address potential security vulnerabilities which could be exploited by unauthorized access to airplane networks and servers. Therefore, these special conditions are being issued to ensure that the security (i.e., confidentiality, integrity, and availability) of airplane systems is not compromised by unauthorized wired or wireless electronic connections between airplane systems and the passenger entertainment services.

#### Applicability

As discussed above, these special conditions are applicable to the Model G280. Should GALP apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special conditions would apply to that model as well.

#### Conclusion

This action affects only certain novel or unusual design features on one model of airplane. It is not a rule of general applicability.

The substance of these special conditions has been subjected to the

notice and comment period in several prior instances and has been derived without substantive change from those previously issued. It is unlikely that prior public comment would result in a significant change from the substance contained herein. Therefore, because a delay would significantly affect the certification of the airplane, which is imminent, the FAA has determined that prior public notice and comment are unnecessary and impracticable, and good cause exists for adopting these special conditions upon issuance. The FAA is requesting comments to allow interested persons to submit views that may not have been submitted in response to the prior opportunities for comment described above.

#### List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

#### The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Gulfstream Aerospace LP, Model Gulfstream G280 airplanes.

1. Isolation or Aircraft Electronic System Security Protection from Unauthorized Internal Access. The applicant must ensure that the design provides isolation from, or airplane electronic system security protection against, access by unauthorized sources internal to the airplane. The design must prevent inadvertent and malicious changes to, and all adverse impacts upon, airplane equipment, systems, networks, or other assets required for safe flight and operations.

2. The applicant must establish appropriate procedures to allow the operator to ensure that continued airworthiness of the aircraft is maintained, including all post type certification modifications that may have an impact on the approved electronic system security safeguards.

Issued in Renton, Washington, on June 7, 2012.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-15913 Filed 6-27-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0034; Directorate Identifier 2011-NM-153-AD; Amendment 39-17105; AD 2012-13-03]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. This AD was prompted by a report of a ground fire which was fed by oxygen escaping from a damaged third crew person oxygen line and had started in the vicinity of an electrical panel. This AD requires replacing and changing the routing of the flexible oxygen hose of the third crew person oxygen line and modifying the entrance compartment assembly. We are issuing this AD to prevent the possibility of damage to the third crew person oxygen line and of an oxygen-fed fire in the airplane.

**DATES:** This AD becomes effective August 2, 2012.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 2, 2012.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

#### FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7318; fax (516) 794-5531.

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on January 23, 2012 (77 FR 3184). That NPRM proposed to correct

an unsafe condition for the specified products. The MCAI states:

An operator has reported a ground fire in the CL-600-2B19 aeroplane. The fire burnt an 18 inch hole through the left upper fuselage skin panel in the cockpit area. The fire started in the vicinity of the Junction Box 1 (JB1) electrical panel, and was fed by oxygen escaping from a damaged third crewman oxygen line.

This [Transport Canada Civil Aviation (TCCA)] Airworthiness Directive (AD) was issued to prevent the possibility of damage to the third crewman oxygen line and an oxygen fed fire in the aeroplane.

You may obtain further information by examining the MCAI in the AD docket.

#### Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comments received.

#### Support for the NPRM (77 FR 3184, January 23, 2012)

Air Line Pilots Association, International (ALPA) stated that the proposed actions will enhance safety and that it supports the intent of the NPRM (77 FR 3184, January 23, 2012).

#### Request To Shorten the Compliance Time and Add an Inspection

The ALPA requested that an initial inspection of the oxygen hose be performed within 500 flight hours after the effective date of the AD and immediate replacement of any damaged hoses. The commenter also requested that the compliance time for the replacement specified in the NPRM (77 FR 3184, January 23, 2012) of “within 4,000 flight hours after the effective date of the AD.” be reduced to “within 2000 flight hours after the effective date of this AD.”

We do not agree to add an inspection to the requirements of this AD. We have determined that accomplishing the replacement required by paragraph (g) of this AD addresses the identified unsafe condition. We have not changed the AD in this regard.

We, also, do not agree with the request for a shorter compliance time. In developing the compliance time, we determined that the compliance time of 4,000 flight hours after the effective date of the AD is appropriate considering the safety implications, the average utilization rate of the affected fleet, the practical aspects of an orderly inspection of the fleet during regular maintenance periods, and the availability of required replacement parts. In addition, the proposed compliance time corresponds with the compliance time of the parallel AD issued by TCCA. Operators may request

approval of an alternative method of compliance (AMOC) under the provisions of paragraph (i)(1) of this AD. We have not changed the AD in this regard.

#### Request To Revise Wording

Air Wisconsin requested that the wording in paragraph (h) of the NPRM (77 FR 3184, January 23, 2012) be changed from “modify” to “discard” as Bombardier Service Bulletin 601R-35-017, Revision A, dated June 9, 2011, states in various places to discard the hose.

We partially agree. The wording in paragraph (h) of the NPRM (77 FR 3184, January 23, 2012) incorrectly implied that both the entrance compartment assembly and the flexible oxygen hose could be modified. We have changed paragraphs (g) and (h) of this AD to clarify that the entrance compartment assembly is “modified” and that the flexible oxygen hose is “replaced with a new flexible oxygen hose.”

#### Conclusion

We reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously—except for minor editorial changes. We have determined that these changes:

- Are consistent with the intent that was proposed in the NPRM (77 FR 3184, January 23, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (77 FR 3184, January 23, 2012).

#### Costs of Compliance

We estimate that this AD will affect 588 products of U.S. registry. We also estimate that it will take about 13 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$108 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$713,244, or \$1,213 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify that this AD:*

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM (77 FR 3184, January 23, 2012), the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

**2012-13-03 Bombardier, Inc.:** Amendment 39-17105. Docket No. FAA-2012-0034; Directorate Identifier 2011-NM-153-AD.

#### (a) Effective Date

This airworthiness directive (AD) becomes effective August 2, 2012.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes; certificated in any category; equipped with entrance compartment assembly having part numbers that begin with A281001, A282001, A283001, A284001, 4591001, 4592001, 4593001, or 4594001.

#### (d) Subject

Air Transport Association (ATA) of America Code 35: Oxygen.

#### (e) Reason

This AD was prompted by a report of a ground fire which was fed by oxygen escaping from a damaged third crew person oxygen line and had started in the vicinity of an electrical panel. We are issuing this AD to prevent the possibility of damage to the third crew person oxygen line and of an oxygen-fed fire in the airplane.

#### (f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### (g) Actions

Within 4,000 flight hours after the effective date of this AD, change the routing and replace the flexible oxygen hose of the third crew person oxygen line with a new flexible oxygen hose and modify the entrance compartment assembly, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-35-017, Revision A, dated June 9, 2011.

#### (h) Parts Installation

As of the effective date of this AD, no person may install an entrance compartment assembly having a part number that begins with A281001, A282001, A283001, A284001, 4591001, 4592001, 4593001, or 4594001, or a flexible oxygen hose having a part number 38027-0260, on any airplane, unless that

entrance compartment assembly has been modified and the flexible oxygen hose has been replaced with a new flexible oxygen hose, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-35-017, Revision A, dated June 9, 2011.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### (j) Related Information

Refer to MCAI Canadian Airworthiness Directive CF-2011-23, dated July 14, 2011; and Bombardier Service Bulletin 601R-35-017, Revision A, dated June 9, 2011; for related information.

#### (k) Material Incorporated by Reference

(1) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51:

(i) Bombardier Service Bulletin 601R-35-017, Revision A, dated June 9, 2011.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this

material at an NARA facility, call 202-741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on June 19, 2012.

**John P. Piccola,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-15602 Filed 6-27-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0330; Directorate Identifier 2011-NM-116-AD; Amendment 39-17103; AD 2012-13-01]

**RIN 2120-AA64**

#### Airworthiness Directives; Saab AB, Saab Aerosystems Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Saab AB, Saab Aerosystems Model 340A (SAAB/SF340A) and SAAB 340B airplanes. This AD was prompted by reports indicating that wear of the elevator pushrods has occurred on some airplanes after extended time in service. This AD requires determining if a certain part number is installed, performing a detailed inspection for individual play between the elevator pushrod assembly and degradation of elevator pushrod assembly, and replacing the affected elevator pushrod assembly with a new elevator pushrod assembly if necessary. We are issuing this AD to prevent a free elevator from affecting the pitch control authority, which may result in reduced controllability of the airplane.

**DATES:** This AD becomes effective August 2, 2012.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 2, 2012.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Shahram Daneshmandi, Aerospace