

comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

### Discussion

On March 29, 2000, we issued AD 2000-07-11, Amendment 39-11665 (65 FR 19305, April 11, 2000). That AD required actions intended to address an unsafe condition on the products listed above.

Since we issued AD 2000-07-11 (65 FR 19305, April 11, 2000), we determined the unsafe condition no longer exists. Review of the Piaggio Model P-180 service history and maintenance requirements shows that regularly scheduled annual inspections address this issue. Therefore, the need to continue to address this subject as an unsafe condition through an AD is not necessary.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued 2012-0095-CN, dated May 31, 2012 (referred to after this as "the MCAI"). The MCAI states:

After a 1999 training session during which conflicting inputs were given to the brake pads between pilot and copilot, a brake system rod was found deflected. The rod, in this bent condition, could possibly wear and damage the tubings connected to the brake valves, with consequent fluid leakage.

Prompted by these findings, PAI issued Service Bulletin (SB) 80-0107, providing instructions for repetitive inspections of the affected rods and tubings. As this was considered to be a potentially unsafe condition, Registro Aeronautico Italiano (RAI), the predecessor of ENAC (Ente Nazionale per l'Aviazione Civile), issued Prescrizione di Aeronavigabilità (PA) No. 1999-219, which required the repetitive inspections as detailed in PAI SB 80-0107 and, depending on findings, replacement of rod or tubing.

Since that AD was issued, the repetitive inspections of SB 80-0107 have been included as regular tasks into the maintenance schedule of both Avanti and Avanti II aeroplanes. In addition, no other cases of brake system bent rods have been reported, nor have any rods been replaced for damage in the P.180 fleet since that occurrence. Based on the available information, this is no longer considered to be an unsafe condition. Prompted by this

determination, PAI issued Revision ZZ of SB 80-0107, which cancels the original SB 80-0107.

For the reasons described above, this Notice is issued to cancel ENAC PA no. 1999-219 dated 03 May 1999.

You may obtain further information by examining the MCAI in the AD docket.

### FAA's Determination

We propose this AD because we evaluated all available information and determined the existing AD is no longer necessary.

### Proposed AD Requirements

This proposed AD would rescind AD 2000-07-11 (65 FR 19305, April 11, 2000).

### Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs", describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed, I certify this proposed regulation:*

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

*Authority:* 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by removing Amendment 39-11665 (65 FR 19305, April 11, 2000), and adding the following new AD:

**Piaggio Aero Industries S.p.A.:** Docket No. FAA-2012-0755; Directorate Identifier 99-CE-65-AD.

#### (a) Comments Due Date

We must receive comments by September 4, 2012.

#### (b) Applicability

This AD applies to Piaggio Aero Industries S.p.A. Model P-180 airplanes, all serial numbers, certificated in any category.

#### (c) Affected ADs

This AD rescinds AD 2000-07-11 (65 FR 19305, April 11, 2000).

#### (d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 32; Landing Gear.

Issued in Kansas City, Missouri, on July 13, 2012.

#### Earl Lawrence,

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-17582 Filed 7-18-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0756; Directorate Identifier 2012-CE-012-AD]

**RIN 2120-AA64**

#### Airworthiness Directives; Piper Aircraft, Inc. Airplanes

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Piper Aircraft, Inc. (type certificate previously held by The New Piper Aircraft Inc.) Models PA-18 and PA-19 airplanes. This proposed AD was prompted by incidents of inadvertent magneto switch shut off in flight. This proposed AD would require moving all magneto switches that are now or are at any time located on the left cabin panel, adjacent to the front seat, to the instrument panel. We are proposing this AD to correct the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by September 4, 2012.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The

street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Gary Wechsler, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5575; fax: (404) 474-5606; email: [gary.wechsler@faa.gov](mailto:gary.wechsler@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2012-0756; Directorate Identifier 2012-CE-012-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

Three forced landings of Piper Aircraft, Inc. Model PA-18 airplanes with magneto switches located on the left cabin panel, adjacent to the front seat, were caused by pilots unknowingly turning off the magneto switches and

causing in-flight engine shutdowns. In each event, the pilot was performing other flight tasks, such as re-trimming the airplane, and the pilot’s arm and/or article of clothing accidentally turned off the magneto switches.

Those parties that may desire an alternative method of compliance (AMOC) are encouraged to work together with pertinent type clubs toward a single global AMOC.

Any Piper Aircraft, Inc. Model PA-18 airplane with the magneto switch currently located away from the left cabin panel, adjacent to the front seat, including those already placed on an airplane’s wing root, is not at a high risk of an inadvertent in-flight engine shutdown and loss of flight control and are not the subject of this proposed AD.

This condition, if not corrected, could result in engine shut down and possible loss of control.

**FAA’s Determination**

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require removing the magneto switch and ignition leads from the left cabin panel adjacent to the front seat and install a key-type ignition switch on the instrument panel.

**Costs of Compliance**

We estimate that this proposed AD affects 295 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Relocate the magneto switch from the port side interior cabin wall to the instrument panel and replace the magneto switch with a keyed switch.	3.5 work-hours × \$85 per hour = \$297.50.	\$125	\$422.50	\$124,637.50

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701:

“General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Piper Aircraft, Inc. (Type Certificate Previously Held by The New Piper Aircraft Inc.):** Docket No. FAA-2012-0756; Directorate Identifier 2012-CE-012-AD.

##### (a) Comments Due Date

We must receive comments by September 4, 2012.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to Piper Aircraft, Inc. (type certificate previously held by The New Piper Aircraft Inc.) Models PA-18, PA-18 “105” (Special), PA-18S, PA-18S “105” (Special), PA-18A, PA-18 “125” (Army L-21A), PA-18S “125”, PA-18AS “125”, PA-18 “135” (Army L-21B), PA-18A “135”, PA-18S “135”, PA-18AS “135”, PA-18 “150”, PA-18A “150”, PA-18S “150”, PA-18AS “150”, PA-19 (Army L-18C), and PA-19S airplanes, all serial numbers, that:

(1) Are certificated in any category; and

(2) Are now or at any time equipped with a magneto switch installed on the left cabin panel, adjacent to the front seat.

**Note 1 to paragraph (c) of this AD:** Model PA-18 airplanes with the magneto switch located away from the left cabin panel, adjacent to the front seat, including those currently placed on an airplane’s wing root,

are not subject to the requirements of this AD.

##### (d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 74, Engine Ignition.

##### (e) Unsafe Condition

This AD was prompted by incidents of inadvertent magneto switch shut off in flight. We are issuing this AD to prevent engine shut down and possible loss of control.

##### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

##### (g) Relocate the Magneto Switch and Replace With Key-Type Ignition Switch

Within the next 12 months after the effective date of this AD, do the following in accordance with FAA Advisory Circular 43.13-2B, Chapter 11, which can be found at <http://rgl.faa.gov/>:

(1) Remove the magneto switch and ignition leads from the left cabin panel, adjacent to the front seat, install either a Piper part number 15302-02, -04 or -05 (or FAA approved equivalent part number) key-type ignition switch on the instrument panel, not adjacent to or below (the height of) the engine fuel primer, attach ignition leads, maintaining shielded or unshielded configuration existing at time of new switch installation, and secure leads following the procedures in FAA Advisory Circular 43.13-2B, Chapter 11, which can be found at <http://rgl.faa.gov/>.

(2) Perform engine run to verify proper engine operation. Following regular run-up procedures, allow the engine to reach operating temperatures and do a normal magneto check.

##### (h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

##### (i) Related Information

For more information about this AD, contact Gary Wechsler, Aerospace Engineer, FAA, Atlanta ACO, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5575; fax: (404) 474-5606; email: [gary.wechsler@faa.gov](mailto:gary.wechsler@faa.gov).

Issued in Kansas City, Missouri, on July 13, 2012.

**Earl Lawrence,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-17589 Filed 7-18-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0721; Directorate Identifier 2012-NM-076-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. This proposed AD was prompted by reports that airplanes with a Class C cargo (baggage) compartment have liners that do not meet flammability requirements. This proposed AD would require replacing the existing cargo compartment liners with liners that comply. We are proposing this AD to prevent inadequate fire protection in the cargo compartment and consequent uncontrolled fire.

**DATES:** We must receive comments on this proposed AD by September 4, 2012.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For Bombardier service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email