

service information referenced above. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. The proposed AD would require inspection of the oil filler plug vent hole at the next scheduled maintenance or within 110 flight hours after the effective date of this AD. If chips are found to be blocking the vent hole, additional corrective action is required before next flight.

Costs of Compliance

We estimate that this proposed AD would affect about 45 engines installed on airplanes of U.S. registry. We also estimate that it would take about 2.5 work-hours per product to comply with this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$30 per engine. Based on these figures, we estimate the cost of the proposed AD to U.S. operators to be \$10,913.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Thielert Aircraft Engines: Docket No. FAA-2012-0885; Directorate Identifier 2012-NE-18-AD.

(a) Comments Due Date

We must receive comments by October 30, 2012.

(b) Affected Airworthiness Directives (ADs)

None.

(c) Applicability

This AD applies to all TAE 125-09-99 and TAE 125-02-114 reciprocating engines.

(d) Reason

This AD was prompted by an in-flight shutdown of an airplane equipped with an TAE 125-02-99 engine. We are issuing this AD to prevent engine in-flight shutdown or power loss, possibly resulting in reduced control of the airplane.

(e) Actions and Compliance

Unless already done, within 110 flight hours after the effective date of this AD, or at the next scheduled maintenance, do the following.

(1) Remove the oil filler plug and check for chips blocking the vent hole in accordance with TAE Service Bulletin (S/B) TM TAE 125-1015 P1, Initial Issue, dated April 27, 2012.

(2) If chips are found during the inspection in paragraph (e)(1) of this AD, disassemble the gearbox and check the radial shaft sealing rings (at the clutch and the propeller shaft) for leakage. If leakage is noted, replace the gearbox before the next flight.

(f) Installation Prohibition

After the effective date of this AD, do not install a gearbox with an S/N listed in TAE S/B TM TAE 125-1015, Initial Issue, dated April 27, 2012, into any engine unless the oil filler plug has passed the inspection required by paragraph (e)(1) of this AD.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19.

(h) Related Information

(1) For more information about this AD, contact Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; email: frederick.zink@faa.gov; telephone (781) 238-7779; fax (781) 238-7199.

(2) Refer to MCAI Airworthiness Directive No. 2012-0112, dated June 22, 2012, and TAE S/B TM TAE 125-1015 P1, Initial Issue, dated April 27, 2012 for related information.

(3) For service information identified in this AD, contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D-09350, Lichtenstein, Germany, telephone: +49-37204-696-0; fax: +49-37204-696-2912; email: info@centurion-engines.com. You may review copies of the referenced service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on August 24, 2012.

Robert G. Mann,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2012-21524 Filed 8-30-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-1222; Directorate Identifier 2010-NM-268-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. That NPRM proposed to require checking the escape slide girt for serviceability, and

replacement if necessary; modifying the cable routing provision; replacing the regulator padding; modifying the aspirator orientation; and modifying the valise. That NPRM also proposed to require, for certain airplanes, modifying or replacing the Vespel piston, modifying the pilot valve regulator, installing a new firing cable and safety pin, and modifying the slide valise. That NPRM was prompted by reports of escape slides failing to deploy from the forward and aft right-hand doors during scheduled maintenance slide deployments. This action revises that NPRM by adding airplanes to the applicability of that NPRM and specifying revised service information. We are proposing this supplemental NPRM to prevent failure of an escape slide to deploy, which could result in the slide being unusable during an emergency evacuation and increased likelihood of injury to passengers or crewmembers due to the difficulty in evacuating the airplane. Since these actions impose an additional burden over that proposed in the NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

DATES: We must receive comments on this supplemental NPRM by October 15, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Goodrich Corporation, Aircraft Interior Products, Attn: Technical Publications, 3414 South Fifth Street, Phoenix, Arizona 85040; phone: 602-243-2270; Internet: <http://www.goodrich.com/TechPubs>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Sarah Piccola, Aerospace Engineer, Cabin Safety & Environmental Systems Branch, ANM-150S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6483; fax: 425-917-6590; email: sarah.piccola@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-1222; Directorate Identifier 2010-NM-268-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued an NPRM to amend 14 CFR part 39 to include an AD that would apply to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. That NPRM published in the **Federal Register** on November 8, 2011 (76 FR 69159). That NPRM proposed to require checking the escape slide girt for serviceability and replacement if necessary, modifying the cable routing provision, the aspirator orientation, the valise, and replacing the regulator padding. That NPRM also proposed to require, for certain airplanes, modifying or replacing the Vespel piston, modifying the pilot valve regulator, modifying the slide valise,

and installing a new firing cable and safety pin.

Actions Since Previous NPRM (76 FR 69159, November 8, 2011) Was Issued

Since we issued the previous NPRM (76 FR 69159, November 8, 2011), new service information has been issued that provides clarifications and minor corrections, and adds data. Additionally, an error was discovered in the part numbers (P/Ns) specified in paragraph (c), "Applicability," of that NPRM. The specification of "P/N 5A3307-1, -3, -5, or -301, S/N BNG0001 through BNG5707 inclusive," is incorrect. The part number should have read "P/N 5A3307-1, -3, -5, or -301, S/N BNG0001 through BNG14499 inclusive." We have changed the supplemental NPRM in this regard.

Comments

We gave the public the opportunity to comment on the previous NPRM (76 FR 69159, November 8, 2011). The following presents the comments received on the NPRM and the FAA's response to each comment.

Requests To Use Revised Service Information

Boeing, United Airlines (United), and Goodrich Corporation (Goodrich) requested that the previous NPRM (76 FR 69159, November 8, 2011) be changed to incorporate revised service information to ensure that operators are incorporating the most current revision of the service information.

We agree that current service information should be incorporated into this supplemental NPRM. Goodrich Service Bulletin 5A3307-25-389, Revision 2, dated May 4, 2012; and Goodrich Service Bulletin 5A3307-25-339, Revision 5, dated May 4, 2012; provide minor corrections, updated pricing, and additional data. The technical content of these documents has not been changed. We have changed paragraphs (g) and (h)(1) of the supplemental NPRM to refer to Goodrich Service Bulletin 5A3307-25-389, Revision 2, dated May 4, 2012; and Goodrich Service Bulletin 5A3307-25-339, Revision 5, dated May 4, 2012; as applicable. We have changed paragraph (i) of the supplemental NPRM to include credit for modifications of the escape slide done before the effective date of the AD using Goodrich Service Bulletin 5A3307-25-339, Revision 3, dated May 8, 2009; or Revision 4, dated October 1, 2011. Modification of the escape slide specified in Goodrich Service Bulletin 5A3307-25-389, Revision 2, dated May 4, 2012, consists of modifying the cable routing provision, replacing the

regulator padding, modifying the aspirator orientation, and modifying the valise. Modification of the escape slide specified in Goodrich Service Bulletin 5A3307-25-339, Revision 5, dated May 4, 2012, consists of modifying the pilot valve regulator P/N 4A3865-2, -3, or -4, as applicable; installing a new firing cable and safety pin; and modifying the slide valise.

Requests To Change Applicability

Goodrich, Boeing, United, AirTran Airways (AirTran), and Southwest Airlines (Southwest) requested that we change or clarify the applicability of the previous NPRM (76 FR 69159, November 8, 2011) to include slide P/N 5A3307-1, -3, -5, or -301, S/Ns BNG0001 through BNG14499 inclusive. Boeing stated that this change "will ensure that all applicable 5A3307 series evacuation slides have been identified for incorporation of the Goodrich Service Bulletin 5A3307-25-389 modifications."

We agree that S/Ns BNG0001 through BNG14499 inclusive should be included in the applicability of this supplemental NPRM as explained previously. We have changed paragraph (c) of the supplemental NPRM to include P/N 5A3307-1, -3, -5, or -301, S/N BNG0001 through BNG14499 inclusive.

Requests To Remove Slide Part Numbers From the NPRM (76 FR 69159, November 8, 2011)

Goodrich, United, and Boeing requested that we remove slide P/N 5A3086-1, -3, or -301, S/Ns B3F001 through B3F611 inclusive; P/N 5A3088-1, -3, or -301, S/Ns B3A001 through B3A685 inclusive; from the NPRM (76 FR 69159, November 8, 2011). Goodrich stated that specification of slide P/N 5A3086-1, -3, or -301, S/Ns B3F001 through B3F611 inclusive; and P/N 5A3088-1, -3, or -301, S/Ns B3A001 through B3A685 inclusive; is inappropriate for the proposed AD, because the unsafe condition that the proposed AD addresses is not an issue for the P/Ns 5A3086 and 5A3088 series slides. Goodrich also stated that the design of the P/Ns 5A3086 and 5A3088 series slides precludes the type of event that has been experienced with the P/N 5A3307 series slides. Goodrich provided detailed information to support its request.

We agree. Including these additional parts is confusing and is not directly related to the unsafe condition addressed by this supplemental NPRM. We have changed paragraph (c) of the supplemental NPRM to remove slide P/N 5A3086-1, -3, or -301, S/Ns B3F001 through B3F611 inclusive; and

P/N 5A3088-1, -3, or -301, S/Ns B3A001 through B3A685 inclusive; from the supplemental NPRM.

Request To Remove Girt Check

Goodrich requested that the girt check be removed from the previous NPRM (76 FR 69159, November 8, 2011). Goodrich stated that the girt condition was not a causative factor in the unsafe condition described in the previous NPRM. The girt condition check is not a configuration requirement of the slide modification, which addresses the slide nondeployment issue. Rather, the girt condition check is included in the Goodrich service information because it falls under the heading of good general maintenance practice. Goodrich stated that the girt check specified in the Goodrich service information was not a causative factor in the unsafe condition described by the previous NPRM and questions the need for it to be called out in the AD.

We agree. The girt condition check is not a configuration requirement of the slide modification, which addresses the slide non-deployment issue. We have removed the girt condition check from paragraph (g) of the supplemental NPRM.

Requests To Remove Parts Installation Restriction

United, American, WestJet, Southwest, Goodrich, and AirTran requested that we remove paragraph (j) of the NPRM (76 FR 69159, November 8, 2011), which prohibits installing certain parts on any airplane after the effective date of the AD. The commenters stated that this prohibition would prevent the use of affected spare slide assemblies (un-modified) during modification of the slide units of the previous NPRM, as well as the removal and reinstallation of the same affected unit on an airplane. The commenters asserted that this requirement could restrict an airline's ability to return an airplane to service due to a shortage of parts.

Boeing requested that we remove paragraphs (j)(1) and (j)(3) from the previous NPRM (76 FR 69159, November 8, 2011). The P/N 5A3086-1, -3, and -301 evacuation slides; and P/N 5A3088-1, -3, and -301 evacuation slides are not affected by Goodrich Service Bulletin 5A3307-25-389, Revision 1, dated October 1, 2011, which is the subject of the previous NPRM. Boeing stated that, once the evacuation slide has been modified as specified in Goodrich Service Bulletin 5A3307-25-389, Revision 1, dated October 1, 2011, into the new P/N 5A3307-7 configuration, the old

regulator and regulator valve padding parts will have been replaced with new parts; therefore, just listing P/N 5A3307-1, -3, -5, and -301 evacuation slides would cover the old regulator and regulator valve padding parts.

We agree with removing the parts installation restriction, since this prohibition could make it difficult for operators to maintain their airplanes. After the effective date of the AD, if the slides are removed for any reason, this prohibition could lead to an airplane with slides having mixed part numbers. We have removed paragraph (j) from the supplemental NPRM, and redesignated subsequent paragraphs accordingly.

Request To Remove Repeated Wording

United requested that we address the need for repeating accomplishment instructions within paragraphs (g) and (h) of the previous NPRM (76 FR 69159, November 8, 2011). United stated that this information is already contained within Goodrich Service Bulletins 5A3307-25-389, Revision 1, dated October 1, 2011; and 5A3307-25-339, Revision 4, dated October 1, 2011; respectively, and by repeating this information, the AD could contain dated information.

We agree that repeating the specifics of the accomplishment instructions in paragraphs (g) and (h) of the supplemental NPRM is unnecessary in this case. We have changed paragraphs (g) and (h) of the supplemental NPRM to require modifying the escape slide in accordance with the applicable service information. We have described the specifics of modifying the escape slide in paragraphs (g) and (h) of the supplemental NPRM in the previous response under comment "Request to Use Revised Service Information." No further change is necessary in this regard.

Request To Remove Certain Part Numbers

United requested that we address repetitive slide part numbers in the previous NPRM (76 FR 69159, November 8, 2011), which have already been subjected to previous AD rulemaking. United stated that including slide part numbers that were subjected to previously issued rulemaking, such as AD 2008-24-08, Amendment 39-15748 (73 FR 72320, November 28, 2008), undermines the rulemaking process and forces operators to demonstrate compliance against certain part numbers for a second time.

We agree and have removed P/Ns 5A3307-1 and 5A3307-3, which were the subject of previous rulemaking (AD 2008-24-08, Amendment 39-15748 (73

FR 72320, November 28, 2008)), from this supplemental NPRM.

FAA’s Determination

We are proposing this supplemental NPRM because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. Certain changes described above

expand the scope of the original NPRM. As a result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this supplemental NPRM.

Proposed Requirements of the Supplemental NPRM

This supplemental NPRM would require accomplishing the actions

specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 557 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modify girt and valise, and replace padding.	2 work-hours × \$85 per hour = \$170	\$223	\$393	\$218,901.
Modify regulator valve, install cable and pin, and modify slide valise.	1 work-hour × \$85 per hour = \$85	Between \$1,749 and \$1,836.	Between \$1,834 and \$1,921.	Between \$1,021,538 and \$1,069,997.
Modify Vespel piston	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$47,345.
Optional Vespel piston replacement.	Up to 1 work-hour × \$85 per hour = \$85	Up to \$612	Up to \$697	Up to \$388,229.

We estimate the following costs to do any necessary replacements that would

be required based on the results of the check of the girt. We have no way of

determining the number of aircraft that might need these replacements.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Girt replacement (Goodrich Service Bulletin 5A3307–25–389, Revision 2, dated May 4, 2012).	1 work-hour × \$85 per hour = \$85	\$942	\$1,027

According to the parts supplier, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition

that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2011–1222; Directorate Identifier 2010–NM–268–AD.

(a) Comments Due Date

We must receive comments by October 15, 2012.

(b) Affected ADs

This AD affects AD 2008–24–08, Amendment 39–15748 (73 FR 72320, November 28, 2008).

(c) Applicability

This AD applies to The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes; certificated in any category; with Goodrich Corporation door escape slide part number (P/N) 5A3307–1, –3, –5, or –301, serial number (S/N) BNG0001 through BNG14499 inclusive.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by reports of escape slides failing to deploy from the forward and aft right-hand doors during scheduled maintenance slide deployments. We are issuing this AD to prevent failure of an escape slide to deploy, which could result in the slide being unusable during an emergency evacuation and increased likelihood of injury to passengers or crewmembers due to the difficulty in evacuating the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Slide Modification

Within 36 months after the effective date of this AD: Modify the escape slide in accordance with the Accomplishment Instructions of Goodrich Service Bulletin 5A3307–25–389, Revision 2, dated May 4, 2012.

(h) Concurrent Requirements

(1) For slide P/N 5A3307–301: Prior to or concurrently with accomplishing the actions required by paragraph (g) of this AD, modify the escape slide in accordance with the Accomplishment Instructions of Goodrich Service Bulletin 5A3307–25–339, Revision 5, dated May 4, 2012.

(2) For slide P/N 5A3307–301 or 5A3307–5: Prior to or concurrently with accomplishing the actions required by paragraph (g) of this AD, modify the Vespel piston in the regulator valves, or replace the Vespel piston with a new or serviceable Vespel piston P/N 3A3566–2 or 3A3832–2, as applicable, in accordance with the Accomplishment Instructions of Goodrich Service Bulletin 25–349, Revision 1, dated January 11, 2010.

(i) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD using Goodrich Service Bulletin 5A3307–25–339, Revision 1, dated September 26, 2003; Revision 2, dated March 31, 2004; Revision 3, dated May 8, 2009; or Revision 4, dated October 1, 2011; which are not incorporated by reference in this AD.

(2) This paragraph provides credit for the modification or replacement of the Vespel piston in the regulator valves required by paragraph (h)(2) of this AD, if those actions were performed before the effective date of this AD using Goodrich Service Bulletin 25–349, dated September 15, 2004, which is not incorporated by reference in this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Sarah Piccola, Aerospace Engineer, Cabin Safety & Environmental Systems Branch, ANM–150S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; phone: 425–917–6483; fax: 425–917–6590; email: sarah.piccola@faa.gov.

(2) For service information identified in this AD, contact Goodrich Corporation, Aircraft Interior Products, ATTN: Technical Publications, 3414 South Fifth Street, Phoenix, Arizona 85040; phone: 602–243–2270; Internet: <http://www.goodrich.com/TechPubs>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, the FAA, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on August 24, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–21556 Filed 8–30–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2012–0661; Airspace Docket No. 09–AWA–4]

RIN 2120–AA66

Proposed Amendment to Class B Airspace; Detroit, MI*Correction*

In proposed rule document 2012–19902, beginning on page 48476–48491 in the issue of Thursday, August 14, 2012, make the following corrections:

1. In the first column titled “Area C”, third paragraph, fifth line, “5-mile arc” should read, “15 mile arc.”

2. In the first column titled “Area C”, third paragraph, eighth line, “5-mile arc” should read, “15 mile arc.”

3. In the first column titled “Area C”, third paragraph, twenty-second line, “5-mile arc” should read, “15 mile arc.”

4. In the first column titled “Area C”, third paragraph, twenty-third line, “5-mile arc” should read, “15 mile arc.”

5. In the second column titled “Area D”, first paragraph, eighth line, “5-mile arc” should read, “15 mile arc.”

6. In the second column titled “Area D”, first paragraph, eleventh line, “5-mile arc” should read, “15 mile arc.”

7. In the second column titled “Area E”, first paragraph, twenty-fourth line, “5-mile arc” should read, “15 mile arc.”

8. In the second column titled “Area E”, first paragraph, twenty-seventh line, “5-mile arc” should read, “15 mile arc.”

[FR Doc. C1–2012–19902 Filed 8–30–12; 8:45 am]

BILLING CODE 1505–01–D

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Parts 91, 121, 125, and 135**

[Docket No. FAA–2012–0752]

Passenger Use of Portable Electronic Devices on Board Aircraft

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of policy; request for comments.

SUMMARY: The FAA seeks comments on current policy, guidance, and procedures that aircraft operators (ranging from pilots of general aviation aircraft up to and including air carrier certificate holders at the major airlines) use when determining if passenger use of portable electronic devices (PEDs)