

Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591. Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency AD 12-053, dated May 25, 2012; and Lindstrand Hot Air Balloons Ltd Service Bulletin No. 12, dated May 10, 2012, for related information. For service information related to this AD, contact Lindstrand Hot Air Balloons Ltd., Maesbury Road, Oswestry, Shropshire SY10 8ZZ, The United Kingdom; telephone: +44 (0) 1691-671717; fax: +44 (0) 1691-671122; email: simon@lindstrand.co.uk; Internet: <http://www.lindstrand.co.uk/>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on October 17, 2012.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-26064 Filed 10-22-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-1105; Directorate Identifier 2012-NM-137-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of Proposed Rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all

Airbus Model A318, A319, and A320 series airplanes. This proposed AD was prompted by fuel system reviews conducted by the manufacturer, which revealed that certain fuel pumps under certain conditions can create an ignition source in the fuel tank. This proposed AD would require modification of the center tank fuel pump control circuit by installation of ground fault interrupters (GFIs). This proposed AD would also require either replacement of the GFI or deactivation of the associated fuel pump following failure of any post-modification operational test of the GFI. We are proposing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by December 7, 2012.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in

the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-227-1405; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2012-1105; Directorate Identifier 2012-NM-137-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued Airworthiness Directive 2012-0198, dated September 26, 2012 (which superseded EASA AD 2012-0133, dated July 18, 2012) (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

* * * The FAA published Special Federal Aviation Regulation (SFAR) 88, and the Joint Aviation Authorities (JAA) published Interim Policy INT/POL/25/12.

In the framework of these requirements, EASA have determined that the electrical power supply circuits of certain fuel pumps, installed on A320 family aeroplanes, for which the canisters become uncovered during normal operation, could, under certain conditions, create an ignition source in the tank vapour space.

This condition, if not corrected, could result in a fuel tank explosion and consequent loss of the aeroplane.

To address this potential unsafe condition, Airbus developed a modification which includes installing Ground Fault Interrupters (GFI) into the centre tank fuel pump control circuit, providing additional system protection by electrically isolating the pump in case of a ground fault condition downstream of the GFI.

Consequently, EASA issued AD 2012-0133 to require modification of the centre tank fuel

pump control circuit by installing GFI and thereafter, in case a GFI failed an operational test, replacement of the faulty GFI, or deactivation of the associated fuel pump in accordance with the provisions of the applicable Master Minimum Equipment List (MMEL).

Since that [EASA] AD was issued, it was noted that, inadvertently, the Applicability of the Final AD was incorrect (the preceding PAD [proposed AD] 12-051 was correct) by excluding aeroplanes on which Airbus modification 150736 has been embodied in production. As a result, the required actions when a GFI fails an operational test did not apply to those aeroplanes.

For the reasons described above, this [EASA] AD retains the requirements [modification of the centre tank fuel pump control circuit by installing GFI] of EASA AD 2012-0133, which is superseded, and expands the Applicability to aeroplanes on which Airbus modification 150736 has been embodied in production.

The required actions also include either replacement of the GFI or deactivation of the associated fuel pump following failure of any post-modification operational test of the GFI. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Airbus has issued Service Bulletin A320-28-1188, dated March 23, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 755 products of U.S. registry. We also estimate that it would take about 11 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$3,360 per product, depending on configuration. Where the service information lists required parts costs that are covered under warranty, we have assumed that

there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$3,242,725, or \$4,295 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Airbus: Docket No. FAA-2012-1105; Directorate Identifier 2012-NM-137-AD.

(a) Comments Due Date

We must receive comments by December 7, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; certificated in any category; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by fuel system reviews conducted by the manufacturer, which revealed that certain fuel pumps under certain conditions can create an ignition source in the fuel tank. We are issuing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Modification

Except as provided by paragraph (h) of this AD: Within 48 months after the effective date of this AD, modify the center tank fuel pump control circuit by installing ground fault interrupters (GFIs), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-28-1188, dated March 23, 2012.

(h) Airplanes Excluded From Modification Requirement

For airplanes on which Airbus modification 150736 has been embodied in production, and on which no GFI has been removed since first flight, the modification specified in paragraph (g) of this AD is not required.

(i) Corrective Action for Failed Post-modification Operational Test

After accomplishment of the modification specified in paragraph (g) or (h) of this AD, each time a GFI fails an operational test, before further flight, replace the GFI or deactivate the associated fuel pump, in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA.

Note 1 to paragraph (i) of this AD:

Guidance on the operational test specified in paragraph (i) of this AD can be found in Task 28.18.00/01, Operational Check of Centre Tank Fuel Pump GFI, of the Airbus A318/A319/A320/A321 Maintenance Review Board Report or Task 281800-710-801, Operational Check of Centre Tank Fuel Pump GFI, of the Airbus A318/A319/A320 Aircraft Maintenance Manual.

Note 2 to paragraph (i) of this AD:

Guidance on the fuel pump deactivation specified in paragraph (h) of this AD can be found in Item 28-21-02, Center Tank Systems, of the FAA Master Minimum Equipment List for Airbus A318/A319/A320/A321.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-227-1405; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(k) Related Information

(1) Refer to MCAI EASA Airworthiness Directive 2012-0198, dated September 26, 2012; and Airbus Service Bulletin A320-28-1188, dated March 23, 2012; for related information.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet

<http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on October 15, 2012.

John P. Piccola,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-26078 Filed 10-22-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2012-0495; Directorate Identifier 2011-NM-236-AD]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft Industries, Ltd.) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Proposed rule; withdrawal.

SUMMARY: The FAA withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD) for certain Gulfstream Aerospace LP (Type Certificate previously held by Israel Aircraft Industries, Ltd.) Model Galaxy and Gulfstream 200 airplanes. The proposed AD would have required determining the lengths of the wear indicating pins of all brake assemblies, shortening the pin if the wear indicating pin is too long, inspecting for normal brake wear, and replacing brakes with new brakes if necessary. Since the issuance of the NPRM, the FAA has received new data that indicates the actions addressing this unsafe condition have been accomplished on the worldwide fleet. Accordingly, the proposed AD is withdrawn.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140,

1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1503; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Discussion**

We proposed to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) with a notice of proposed rulemaking (NPRM) for a new AD for certain Gulfstream Aerospace LP (Type Certificate previously held by Israel Aircraft Industries, Ltd.) Model Galaxy and Gulfstream 200 airplanes. That NPRM was published in the **Federal Register** on May 31, 2012 (77 FR 32069). The NPRM would have required determining the lengths of the wear indicating pins of all brake assemblies, shortening the pin if the wear indicating pin is too long, inspecting for normal brake wear, and replacing brakes with new brakes if necessary. The NPRM resulted from reports of degraded brake performance during landing due to improperly-sized wear indicating pins. The proposed actions were intended to detect and correct improperly-sized wear indicating pins, which, if not corrected, could result in worn-out brake pads and subsequent loss of braking power, which could result in runway overruns.

Actions Since NPRM (77 FR 32069, May 31, 2012) Was Issued

Since we issued the NPRM (77 FR 32069, May 31, 2012), FAA has received new data that indicates the unsafe condition no longer exists. Review of the Gulfstream Aerospace LP Model Galaxy and Gulfstream 200 airplane service history shows that the worldwide fleet is in compliance with the actions specified in Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011. Therefore, the unsafe condition no longer exists.

FAA's Conclusions

Upon further consideration, we have determined that the actions specified in Gulfstream Service Bulletin 200-32-389, Revision 1, dated October 27, 2011, and the Gulfstream Aerospace LP Model Galaxy and Gulfstream 200 airplane service history adequately addressed the identified unsafe condition. Therefore, it is not necessary to issue a final rule. Accordingly, the NPRM (77 FR 32069, May 31, 2012) is withdrawn.

Withdrawal of the NPRM (77 FR 32069, May 31, 2012) does not preclude