

which can degrade the insulation resistance of the ceramic terminal blocks. We are issuing this AD to prevent latent failure of the number 2 fire bottle, which, in the event of an engine fire, could result in failure of the fire bottle to discharge when activated and possibly preventing the flightcrew from extinguishing an engine fire.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection

Within 4,000 flight cycles or 18 months, whichever occurs first after the effective date of this AD, do an insulation resistance test on each terminal block, in accordance with paragraphs 2.C., 2.D., 2.E., and 2.F. of the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin 24-143, Revision 1, dated October 2, 2012.

(h) Replacement

If, during the test required by paragraph (g) of this AD, any terminal block is found to have a value of less than 50 megohms, before next flight, replace it with a new or serviceable terminal block, in accordance with paragraph 2.G. of the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin 24-143, Revision 1, dated October 2, 2012.

(i) Inspection Report Difference

Where BAE Systems (Operations) Limited Inspection Service Bulletin 24-143, Revision 1, dated October 2, 2012, specifies to complete the test result sheets in Appendices 1, 2, 3, and 4 and the inspection report in Appendix 6, and send the information to BAE Systems (Operations) Limited, this AD does not require that action.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using BAE Systems (Operations) Limited Inspection Service Bulletin 24-143, dated September 26, 2011, which is not incorporated by reference in this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Information may be emailed to: 9-

ANM-116-AMOC-REQUESTS@faa.gov.

Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(l) Related Information

(1) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2012-0040, dated March 13, 2012; and Bae Systems (Operations) Limited Inspection Service Bulletin 24-143, Revision 1, dated October 2, 2012; for related information.

(2) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on October 26, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-26897 Filed 11-2-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-1173; Directorate Identifier 2012-CE-038-AD]

RIN 2120-AA64

Airworthiness Directives; Costruzioni Aeronautiche Tecnam srl Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of Proposed Rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Costruzioni Aeronautiche Tecnam srl Model P2006T airplanes. This proposed

AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as multiple cracks found on the outboard aileron hinge support of a P2006T airplane during an inspection. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by December 20, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Costruzioni Aeronautiche TECNAM Airworthiness Office, Via Maiorise—81043 Capua (CE) Italy; telephone: +39 0823 620134; fax: +39 0823 622899; email: m.oliva@tecnam.com or g.paduano@tecnam.com; Internet: www.tecnam.com/it-IT/documenti/service-bulletins.aspx. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901

Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: *albert.mercado@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include "Docket No. FAA-2012-1173; Directorate Identifier 2012-CE-038-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to *http://regulations.gov*, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2012-0146, dated August 6, 2012 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During a 100 hour inspection of a P2006T aeroplane, multiple cracks were detected on the outboard aileron hinge support, part number (P/N) 26-1-1082-1/3.

This condition, if not detected and corrected, could jeopardize the wing structural integrity.

For the reason described above, this AD requires to inspect for crack detection all aileron hinge supports and to accomplish the applicable corrective actions.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Costruzioni Aeronautiche Tecnam srl has issued Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 102-CS-Rev2, dated July 3, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our

bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 7 products of U.S. registry. We also estimate that it would take about .5 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$297.50, or \$42.50 per product.

In addition, we estimate that any necessary follow-on actions would take about 3 work-hours and require parts costing \$460, for a cost of \$715 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Costruzioni Aeronautiche Tecnam srl:

Docket No. FAA-2012-1173; Directorate Identifier 2012-CE-038-AD.

(a) Comments Due Date

We must receive comments by December 20, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Costruzioni Aeronautiche Tecnam srl P2006T airplanes, serial numbers 001/US through 9999/US, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 57, Wings.

(e) Reason

This AD was prompted by multiple cracks found on the outboard aileron hinge support of a P2006T airplane during an inspection. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

(f) Actions and Compliance

Unless already done, do the following actions following Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 102-CS-Rev2, dated July 3, 2012:

(1) At the compliance times below, inspect all aileron hinge supports part numbers (P/N) 26-1-1082-1/3, P/N 26-1-1081-1/3, P/N 26-1-1081-2/4, and P/N 26-1-1082-2/4 for cracks:

(i) For airplanes with 600 or more hours time-in-service (TIS) as of the effective date of this AD: Within 30 days after the effective date of this AD or within the next 25 hours time-in-service (TIS) after the effective date of this AD, whichever occurs first, and repetitively thereafter at intervals not to exceed 100 hours TIS or 12 months, whichever occurs first,

(ii) For airplanes with less than 600 hours TIS as of the effective date of this AD: Within 30 days after accumulating 600 hours TIS or within 25 hours TIS after accumulating 600 hours TIS, whichever occurs first, and thereafter at intervals not to exceed 100 hours TIS or 12 months, whichever occurs first.

(2) If a crack is found during any inspection required by paragraph (f)(1) of this AD, before further flight, replace the applicable hinge support(s) with an airworthy part.

(g) Credit for Actions Accomplished in Accordance With Previous Service Information

This AD provides credit for the actions required in this AD if already done before the effective date of this AD following Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 102-CS-Rev1, dated June 29, 2012; or Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 102-CS-Rev2, dated July 3, 2012.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: albert.mercado@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions,

completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(i) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2012-0146, dated August 6, 2012; and Costruzioni Aeronautiche TECNAM Service Bulletin No. SB 102-CS-Rev2, dated July 3, 2012, for related information. For service information related to this AD, contact Costruzioni Aeronautiche TECNAM Airworthiness Office, Via Maiorise—81043 Capua (CE) Italy; telephone: +39 0823 620134; fax: +39 0823 622899; email: m.oliva@tecnam.com or g.paduan@tecnam.com; Internet: www.tecnam.com/it-IT/documenti/service-bulletins.aspx. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on October 25, 2012.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-26968 Filed 11-2-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF VETERANS AFFAIRS

38 CFR Part 3

RIN 2900-A031

Eligibility of Disabled Veterans and Members of the Armed Forces With Severe Burn Injuries for Financial Assistance in the Purchase of an Automobile or Other Conveyance and Adaptive Equipment

AGENCY: Department of Veterans Affairs.

ACTION: Proposed rule.

SUMMARY: The Department of Veterans Affairs (VA) is amending its adjudication regulation regarding a certificate of eligibility for financial assistance in the purchase of an automobile or other conveyance and adaptive equipment. The amendment is necessary to incorporate statutory changes made by the Veterans' Benefits Act of 2010.

DATES: Written comments must be received on or before January 4, 2013.

Applicability Date: VA would apply this rule to all claims for benefits received on or after October 1, 2011.

ADDRESSES: Written comments may be submitted through

www.Regulations.gov; by mail or hand-delivery to Director, Regulations Management (02REG), Department of Veterans Affairs, 810 Vermont Ave. NW., Room 1068, Washington, DC 20420; or by fax to (202) 273-9026. (This is not a toll-free number.) Comments should indicate that they are submitted in response to RIN 2900-A031 "Eligibility of Disabled Veterans and Members of the Armed Forces with Severe Burn Injuries for Financial Assistance in the Purchase of an Automobile or Other Conveyance and Adaptive Equipment." Copies of comments received will be available for public inspection in the Office of Regulation Policy and Management, Room 1063B, between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday (except holidays). Please call (202) 461-4902 for an appointment. (This is not a toll-free number.) In addition, during the comment period, comments may be viewed online through the Federal Docket Management System (FDMS) at www.Regulations.gov.

FOR FURTHER INFORMATION CONTACT:

Nancy Copeland, Consultant, Regulations Staff (211D), Compensation Service, Veterans Benefits Administration, Department of Veterans Affairs, 810 Vermont Ave. NW., Washington, DC 20420, (202) 461-9487. (This is not a toll-free number.)

SUPPLEMENTARY INFORMATION: Section 803 of Public Law 111-275, the Veterans' Benefits Act of 2010, amended subsection 3901(1)(A) of title 38, United States Code (U.S.C.), by reformatting the statute and adding "severe burn injury (as determined pursuant to regulations prescribed by the Secretary)" as one of the disabilities that VA will consider when making a determination of eligibility for financial assistance in the purchase of an automobile or other conveyance and adaptive equipment. Pursuant to the authority granted to the Secretary in 38 U.S.C. 501(a) and 3901(1)(A)(iv), as added by the Veterans' Benefits Act of 2010, VA proposes to amend 38 CFR 3.808 to define the term "severe burn injury."

The purpose of 38 U.S.C. 3901 and 3902 is to provide an automotive allowance and adaptive equipment to veterans having certain severe disabilities that may impair their ability to operate a standard motor vehicle. Prior to the enactment of the Veterans' Benefits Act of 2010, the automotive allowance was authorized only for the loss or permanent loss of use of one or both hands or feet or for permanent impairment of vision of both eyes. In discussing the proposed extension of this benefit to veterans with severe burn