

TABLE 3—MISCELLANEOUS SERVICES ¹—Continued

(vii) Mass standards calibration and re-verification	94.80
(viii) Special projects	94.80
(4) Foreign travel (hourly fee) ³	94.80
(5) Online customized data service:	
(i) One data file per week for 1 year	568.50
(ii) One data file per month for 1 year	341.10
(6) Samples provided to interested parties (per sample)	3.60
(7) Divided-lot certificates (per certificate)	2.30
(8) Extra copies of certificates (per certificate)	2.30
(9) Faxing (per page)	2.30
(10) Special mailing	Actual Cost
(11) Preparing certificates onsite or during other than normal business hours (use hourly rates from Table 1).	

¹ Any requested service that is not listed will be performed at \$72.90 per hour.

² Regular business hours—Monday through Friday—service provided at other than regular business hours will be charged at 1½ times the applicable hourly rate. (See § 800.0(b)(14) for definition of “business day.”)

³ Foreign travel charged hourly fee of \$94.80 plus travel, per diem, and related expenditures.

Schedule B—Fees for FGIS Supervision of Official Inspection and Weighing Services Performed by Delegated States and/or Designated Agencies in the U.S.

The supervision fee charged by the Service is \$0.011 per metric ton of domestic U.S. grain shipments inspected and/or weighed, including land carrier shipments to Canada and Mexico.

(a) *Registration certificates and renewals.* (1) The nature of your business will determine the fees that your business must pay for registration certificates and renewals:

(i) If you operate a business that buys, handles, weighs, or transports grain for sale in foreign commerce, you must pay \$135.00.

(ii) If you operate a business that buys, handles, weighs, or transports grain for sale in foreign commerce and you are also in a control relationship (see definition in section 17A(b)(2) of the Act) with respect to a business that buys, handles, weighs, or transports grain for sale in interstate commerce, you must pay \$270.00.

(2) If you request extra copies of registration certificates, you must pay \$2.30 for each copy.

(b) *Designation amendments.* If you submit an application to amend a designation, you must pay \$75.00.

(c) If you submit an application to operate as a scale testing organization, you must pay \$250.00.

Larry Mitchell,

Administrator, Grain Inspection, Packers and Stockyards.

[FR Doc. 2013–00455 Filed 1–11–13; 8:45 am]

BILLING CODE 3410-KD-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2012–1114; Directorate Identifier 2012–NE–21–AD]

RIN 2120-AA64

Airworthiness Directives; CFM International, S.A. Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain CFM International, S. A. (CFM) model CFM56–5 and CFM56–5B series turbofan engines. This proposed AD was prompted by corrosion of the delta P valve in the hydromechanical unit (HMU) caused by contaminants in type TS–1 fuel. This proposed AD would require cleaning, inspection and repair of affected HMUs. We are proposing this AD to prevent seizure of the HMU, leading to failure of one or more engines and damage to the airplane.

DATES: We must receive comments on this proposed AD by March 15, 2013.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* 202–493–2251.

For service information identified in this proposed AD, contact CFM International Inc., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; International phone: 1–513–552–3272; USA phone: 877–432–3272; International fax: 1–513–552–3329; USA fax: 877–432–3329; email: geae.aoc@ge.com; or CFM International SA, Customer Support Center, International phone: 33 1 64 14 88 66; fax: 33 1 64 79 85 55; email: snecma.csc@snecma.fr. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (phone: 800–647–5527) is the same as the Mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Martin Adler, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781–238–7157; fax: 781–238–7199; email: martin.adler@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about

this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2012–1114; Directorate Identifier 2012–NE–21–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD.

Discussion

We have received reports over the past 18 months of CFM model CFM56–5 and CFM56–5B series turbofan engines, when operated on type TS–1 fuel, that have experienced an in-flight shutdown resulting from HMU failures. Investigation has determined that these HMU failures were caused by corrosion and seizure of the HMU delta P valve. Fuel samples from event airplanes also contained contaminants and corrosive catalysts. This condition, if not corrected, could result in seizure of the HMU, leading to failure of one or more engines and damage to the airplane.

Relevant Service Information

We reviewed CFM Service Bulletin (SB) CFM56–5 S/B 73–0182, Revision 7, dated September 25, 2012, and CFM SB CFM56–5B S/B 73–0122, Revision 9, dated September 25, 2012. The service information describes procedures for cleaning, inspection, and repair of the affected HMUs.

FAA’s Determination

We are issuing this proposed AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist in other products of the same type design.

Proposed AD Requirements

This proposed AD would require removing, cleaning, inspection, and repair of the affected HMUs.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would not affect any products of U.S. registry. We also estimate that it would take about 4 hours per engine to comply with this proposed AD. The average labor rate is \$85 per hour. Based on these

figures, we estimate the proposed AD to have no cost impact to U.S. operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

CFM International S.A.: Docket No. FAA–2012–1114; Directorate Identifier 2012–NE–21–AD.

(a) Comments Due Date

We must receive comments by March 15, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to CFM International S.A. (CFM) CFM56–5 and CFM56–5B series turbofan engines with any of the hydromechanical unit (HMU) fuel control part numbers (P/Ns) in paragraphs (c)(1) and (c)(2) of this AD, installed:

(1) CFM56–5: CFM P/Ns 1348M79P02; 1348M79P03; 1348M79P04; 1348M79P06; 1348M79P07; 1348M79P08; 1348M79P09; 1348M79P10; 1348M79P11; 1348M79P12; 1348M79P13; and 1348M79P14.

(2) CFM56–5B: CFM P/Ns: 1348M79P08; 1348M79P09; 1348M79P10; 1348M79P11; 1348M79P12; 1348M79P13; and 1348M79P14.

(d) Unsafe Condition

This AD was prompted by corrosion of the delta P valve in the HMU fuel control caused by exposure to type TS–1 fuel. We are issuing this AD to prevent seizure of the HMU, leading to failure of one or more engines and damage to the airplane.

(e) Compliance

Unless already done, do the following:

(f) Record Type TS–1 Fuel Usage

(1) From the effective date of this AD, record all TS–1 fuel usage.

(2) If the HMU never uses TS–1 fuel, no further action is required.

(g) Initial Inspection

If the HMU has operated on TS–1 fuel, inspect the HMU for corrosion as follows:

(1) For an HMU that has operated for less than 8,000 hours since new (HSN) or hours since last overhaul, inspect the HMU before 10,000 HSN or hours since last overhaul, whichever comes later.

(2) For an HMU that has operated for 8,000 or more HSN or hours since last overhaul, inspect the HMU within 24 months or 2,000 hours after the effective date of this AD, whichever comes first.

(3) Use paragraph 3.A(2) of CFM Service Bulletin (SB) CFM56–5 S/B 73–0182, Revision 7, dated September 25, 2012, or CFM SB CFM56–5B S/B 73–0122, Revision 9, dated September 25, 2012, to do the inspection.

(h) Repetitive Inspections

Repeat the inspection required in paragraph (g)(3) of this AD before 10,000 hours since last overhaul if after last overhaul the HMU is exposed to TS-1 fuel.

(i) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(k) Related Information

(1) For more information about this AD, contact Martin Adler, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7157; fax: 781-238-7199; email: martin.adler@faa.gov.

(2) Refer to EASA Airworthiness Directive No. 2012-0123, dated July 9, 2012, and CFM SBs CFM56-5 S/B 73-0182, Revision 7, dated September 25, 2012, and CFM56-5B S/B 73-0122, Revision 9, dated September 25, 2012, for related information.

(3) For service information identified in this AD, contact CFM International Inc., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; International phone: 1-513-552-3272; USA phone: 877-432-3272; International fax: 1-513-552-3329; USA fax: 877-432-3329; email: geae.aoc@ge.com; or CFM International SA, Customer Support Center, International phone: 33 1 64 14 88 66; fax: 33 1 64 79 85 55; email: sneema.csc@sneema.fr.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on January 4, 2013.

Robert J. Ganley,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2013-00529 Filed 1-11-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2012-0966; Airspace Docket No. 12-AWA-5]

RIN 2120-AA66

Proposed Modification of Class B Airspace; Las Vegas, NV

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); Reopening of comment period.

SUMMARY: This action reopens the comment period for an NPRM that was published on October 26, 2012. In that document, the FAA proposed to modify the Las Vegas, NV, Class B airspace area to ensure the containment of large turbine-powered aircraft within Class B airspace.

DATES: The comment period for the NPRM published in the **Federal Register** on October 26, 2012 (77 FR 65332) closed on December 26, 2012, is reopened until February 13, 2013.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-30, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; telephone: (202) 366-9826. You must identify FAA Docket No. FAA-2012-0966 and Airspace Docket No. 12-AWA-5, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace Policy and ATC Procedures Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in

developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2012-0966 and Airspace Docket No. 12-AWA-5) and be submitted in triplicate to the Docket Management Facility (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Nos. FAA-2012-0966 and Airspace Docket No. 12-AWA-5." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Western Service Center, Operations Support Group, Federal Aviation Administration, 1601 Lind Ave. SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Background

In the **Federal Register** of October 26, 2012, the FAA issued a NPRM entitled