

the loss of power to the left and right buses and all systems serviced by these buses. We are issuing this AD to prevent loss of the fixed frequency system, which could lead to loss of a number of the pilot's and co-pilot's flight instruments, in addition to other avionics systems.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Wiring Modifications

Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first: Incorporate the wiring modifications specified in, and in accordance with, the Accomplishment Instructions of Bombardier Service Bulletin 8–24–87, Revision B, dated April 3, 2012.

(h) Airplane Maintenance Program Revision

Within 30 days after the effective date of this AD: Revise the airplane maintenance program by incorporating Task 2420/13, Operational Check of Relays K4, K5, K6, and K7 (Post Modsum 8Q101917), in the applicable temporary revision specified in paragraph (h)(1), (h)(2), or (h)(3) of this AD. The initial compliance time for Task 2420/13 is within 18,000 flight hours after accomplishing the actions specified in paragraph (g) of this AD, or 30 days after the effective date of this AD, whichever occurs later.

(1) For Model DHC–8–102, –103, and –106 airplanes: de Havilland Dash 8 Series 100 Temporary Revision AWL–117, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 100 Maintenance Program Manual, PSM 1–8–7.

(2) For Model DHC–8–201 and –202 airplanes: de Havilland Dash 8 Series 200 Temporary Revision AWL 2–48, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1–82–7.

(3) For Model DHC–8–301, –311, and –315 airplanes: de Havilland Dash 8 Series 300 Temporary Revision AWL 3–118, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1–83–7.

(i) No Alternative Actions or Intervals

After accomplishing the revision required by paragraph (h) of this AD, no alternative actions (e.g., inspections) or intervals may be used, unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (k)(1) of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 8–24–87, dated May 26,

2011; or Bombardier Service Bulletin 8–24–87, Revision A, dated October 5, 2011; which are not incorporated by reference in this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(l) Related Information

Refer to MCAI Canadian Airworthiness Directive CF–2012–09, dated February 15, 2012, and the service information specified in paragraphs (l)(1) through (l)(4) of this AD, for related information.

(1) Bombardier Service Bulletin 8–24–87, Revision B, dated April 3, 2012.

(2) de Havilland Dash 8 Series 100 Temporary Revision AWL–117, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 100 Maintenance Program Manual, PSM 1–8–7.

(3) de Havilland Dash 8 Series 200 Temporary Revision AWL 2–48, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1–82–7.

(4) de Havilland Dash 8 Series 300 Temporary Revision AWL 3–118, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1–83–7.

(m) Material Incorporated by Reference

(1) The Director of the **Federal Register** approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bombardier Service Bulletin 8–24–87, Revision B, dated April 3, 2012.

(ii) de Havilland Dash 8 Series 100 Temporary Revision AWL–117, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 100 Maintenance Program Manual, PSM 1–8–7.

(iii) de Havilland Dash 8 Series 200 Temporary Revision AWL 2–48, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1–82–7.

(iv) de Havilland Dash 8 Series 300 Temporary Revision AWL 3–118, dated April 8, 2011, to Section AWL2—Systems Maintenance, of Part 2, Airworthiness Limitations, of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1–83–7.

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 11, 2013.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013–04006 Filed 3–4–13; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2012–1172; Directorate Identifier 2012–CE–040–AD; Amendment 39–17365; AD 2013–04–08]

RIN 2120–AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Diamond Aircraft Industries GmbH

Model H-36, HK 36 R, HK 36 TS, and HK 36 TTS airplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as installation of an unsuitable self-locking nut on the bell crank of the elevator push rod that can cause failure of the elevator, resulting in loss of control. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective April 9, 2013.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of April 9, 2013.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria, telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: www.diamond-air.at/hk36_super_dimona+M52087573ab0.html. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

FOR FURTHER INFORMATION CONTACT: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on November 5, 2012 (77 FR 66409). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

A HK 36 R aeroplane recently experienced an in-flight elevator control failure after take-off which resulted in an uncontrolled landing. The results of the subsequent investigation revealed that the elevator

control rod had disconnected from the elevator bell crank in the tail section of the fuselage, as a result of installation of a non-suitable self-locking nut.

The subsequent design review of the affected elevator bell crank joint with elevator control rod identified that its current configuration has a failure potential when components such as thin self-securing nuts and bearings are aging and original clearance of the control system cannot be maintained in service. Both the designs of elevator bell crank and elevator control rod are installed in DV 20 aeroplanes.

This condition, if not corrected, could lead to further cases of elevator control failure, likely resulting in reduced control of the aeroplane, consequent damage to the aeroplane and injury to the occupants.

To address this concern, Diamond Aircraft Industries (DAI) published Mandatory Service Bulletin (MSB) 36-108 and MSB 20-061/1 to improve the affected elevator control joint by embodiment of new design which prevents elevator bell crank and push rod disconnection.

For reasons described above, this AD requires replacement of aeroplane elevator bell cranks with improved parts and prohibits installation of any previous design elevator bell crank.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (77 FR 66409, November 5, 2012) or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (77 FR 66409, November 5, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (77 FR 66409, November 5, 2012).

Costs of Compliance

We estimate that this AD will affect 25 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$352 per product.

Based on these figures, we estimate the cost of this AD on U.S. operators to be \$13,050, or \$522 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2013-04-08 Diamond Aircraft Industries GmbH: Amendment 39-17365; Docket No. FAA-2012-1172; Directorate Identifier 2012-CE-040-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective April 9, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the following Diamond Aircraft Industries GmbH models and serial number (S/N) airplanes, certificated in any category: H-36 and HK 36 R airplanes, S/Ns 36.300 through 36.414; HK 36 TS airplanes, S/Ns 36.415 and 36.416; and HK 36 TTS airplane, S/N 36.393.

(d) Subject

Air Transport Association of America (ATA) Code 27: Flight Controls.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as installation of an unsuitable self-locking nut on the bell crank of the elevator push rod that can cause failure of the elevator, resulting in loss of control. We are issuing this AD to prevent disconnection of the elevator bell crank and push rod.

(f) Actions and Compliance

Unless already done, do the following actions following Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 36-108 and Diamond Aircraft Industries GmbH Work Instruction WI-MSB 36-108, both dated February 28, 2012:

(1) Within the next 200 hours time-in-service (TIS) after April 9, 2013 (the effective date of this AD) or within the next 12 months after April 9, 2013 (the effective date of this AD), whichever occurs first, replace each elevator bell crank assembly with part number (P/N) 820-2730-12-00, and replace each elevator bell crank mount with P/N 820-2730-11-00.

(2) After April 9, 2013 (the effective date of this AD), only install on the airplane elevator bell crank assemblies with P/N 820-

2730-12-00 and elevator bell crank mounts with P/N 820-2730-11-00.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2012-0173, dated September 3, 2012; Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 36-108, dated February 28, 2012; and Diamond Aircraft Industries GmbH Work Instruction WI-MSB 36-108, dated February 28, 2012, for related information.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Diamond Aircraft Industries GmbH Mandatory Service Bulletin MSB 36-108, dated February 28, 2012.

(ii) Diamond Aircraft Industries GmbH Work Instruction WI-MSB 36-108, dated February 28, 2012.

(3) For Diamond Aircraft Industries GmbH service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria, telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: www.diamond-air.at/hk36_super_dimona+M52087573ab0.html.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on February 14, 2013.

Earl Lawrence,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-04089 Filed 3-4-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-1159; Directorate Identifier 2012-NM-028-AD; Amendment 39-17368; AD 2013-04-10]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A310-203, -204, -222, -304, -322, and -324 airplanes. This AD was prompted by a design review of the fuel tank access covers and analyses comparing compliance of the access covers to different tire burst models. 'Type 21' panels located within the debris zone revealed that they could not sustain the impact of the tire debris. This AD requires modifying the wing manhole surrounds and replacing certain fuel access panels. We are issuing this AD to prevent a possibility of a fire due to tire debris impact on the fuel access panels.

DATES: This AD becomes effective April 9, 2013.