

unit investment trust that concentrates its investments in an industry, business, single country other than the United States, or bonds of a single State within the United States.

* * * * *

Subpart B—Exemptions Pursuant to 18 U.S.C. 208(b)(2)

■ 3. In § 2640.201, paragraphs (b)(1) and (2) are revised to read as follows:

§ 2640.201 Exemptions for interests in mutual funds, unit investments trusts, and employee benefit plans.

* * * * *

(b) *Sector mutual funds and sector unit investment trusts.* (1) An employee may participate in any particular matter affecting one or more holdings of a sector mutual fund or a sector unit investment trust where the affected holding is not invested in the sector in which the fund or trust concentrates, and where the disqualifying financial interest in the matter arises because of ownership of an interest in the fund or unit investment trust.

(2)(i) An employee may participate in a particular matter affecting one or more holdings of a sector mutual fund or a sector unit investment trust where the disqualifying financial interest in the matter arises because of ownership of an interest in the fund or the unit investment trust and the aggregate market value of interests in any sector fund or funds and any sector unit investment trust or trusts does not exceed \$50,000.

(ii) For purposes of calculating the \$50,000 de minimis amount in paragraph (b)(2)(i) of this section, an employee must aggregate the market value of all sector mutual funds and sector unit investment trusts in which he has a disqualifying financial interest and that concentrate in the same sector and have one or more holdings that may be affected by the particular matter.

* * * * *

■ 4. Section 2640.203 is amended by adding paragraph (m) to read as follows:

§ 2640.203 Miscellaneous exemptions.

(m) *Official participation in nonprofit organizations.* An employee may participate in any particular matter where the disqualifying financial interest is that of a nonprofit organization in which the employee serves (or is seeking or has an arrangement to serve), solely in an official capacity, as an officer, director or trustee.

Note to paragraph (m): Nothing in this paragraph shall be deemed independent authority for an agency to assign an employee

to serve in an official capacity with a particular nonprofit organization. Agencies will make such determinations based on an evaluation of their own statutory authorities and missions. Individual agency decisions to permit (or not permit) an employee to serve in an official capacity necessarily involve a range of legal, policy, and managerial considerations, and nothing in this paragraph is intended to interfere with an agency's discretion to assign official duties and limit such assignments as the agency deems appropriate.

[FR Doc. 2013-05243 Filed 3-5-13; 8:45 am]

BILLING CODE 6345-03-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-1037; Directorate Identifier 2011-NE-30-AD; Amendment 39-17373; AD 2013-05-01]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Turboshift Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are superseding an existing airworthiness directive (AD) for all Turbomeca S.A. Makila 1A2 turboshift engines. That AD currently requires replacement of certain serial number (S/N) N2 sensor harnesses. This AD requires replacement of the same S/N harnesses, and requires replacement of additional S/N N2 sensor harnesses. This AD was prompted by corrosion detected in affected N2 sensor harnesses. We are issuing this AD to prevent inadvertent activation of the 65% N1 back up mode, resulting in N2 speed fluctuation, significant power loss, and emergency landing of the helicopter.

DATES: This AD is effective March 21, 2013.

We must receive any comments on this AD by April 22, 2013.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Turbomeca, 40220 Tarnos, France, phone: +33 (0)5 59 74 40 00; telex: 570 042; fax: +33 (0)5 59 74 45 15; Web site: <http://www.turbomeca-support.com>. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Rose Len, Aerospace Engineer, Engine Certification Office, FAA, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: rose.len@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On November 9, 2011, we issued AD 2011-24-08, Amendment 39-16872 (76 FR 72091, November 22, 2011), for all Turbomeca S.A. Makila 1A2 turboshift engines with certain part number (P/N) N2 sensor harnesses installed. That AD requires replacement of certain S/Ns of the affected N2 sensor harnesses, on the two engines of the helicopter. That AD resulted from mandatory continuing airworthiness information issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. We issued that AD to prevent inadvertent activation of the 65% N1 backup control mode, as a result of defective N2 sensor harness crimps, which could result in engine power loss and emergency landing of the helicopter.

Actions Since AD Was Issued

Since we issued AD 2011-24-08 (76 FR 72091, November 22, 2011), Turbomeca S.A. has determined through investigation that additional S/Ns of the N2 sensor harness, P/N 0 301 52 001 0, are affected and require replacement.

The investigation detected corrosion in the harness inside the cable sheath, at the splices with the sensor coils. This corrosion is attributed to a manufacturing error. We are issuing this AD to include additional S/Ns of the N2 sensor harness.

Relevant Service Information

We reviewed Turbomeca S.A. Alert Mandatory Service Bulletin (MSB) No. A298 77 0821, Version A, dated October 9, 2012, and MSB No. 298 77 0817, Version B, dated August 23, 2011. This service information describes procedures for checking and replacing affected N2 sensor harnesses.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

AD Requirements

This AD requires replacement of certain S/Ns of N2 sensor harnesses, P/N 0 301 52 001 0.

FAA's Justification and Determination of the Effective Date

There are no U.S. operators for this product. Therefore, we find that notice and opportunity for prior public comment are unnecessary and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments before it becomes effective. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket Number FAA-2011-1037; Directorate Identifier 2011-NE-30-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

There are no engines installed on helicopters of U.S. registry that will be affected by this AD. Therefore, we estimate the cost of this AD on U.S. operators to be \$0.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2011-24-08, Amendment 39-16872 (76 FR 72091, November 22, 2011) and adding the following new AD:

2013-05-01 Turbomeca S.A.: Amendment 39-17373; Docket No. FAA-2011-1037; Directorate Identifier 2011-NE-30-AD.

(a) Effective Date

This AD is effective March 21, 2013.

(b) Affected ADs

This AD supersedes AD 2011-24-08, Amendment 39-16872 (76 FR 72091, November 22, 2011).

(c) Applicability

This AD applies to all Turbomeca S.A. Makila 1A2 turboshaft engines with an N2 sensor harness, part number (P/N) 0 301 52 001 0, installed, with:

- (1) A serial number (S/N) 242 through 339, inclusive, or
- (2) A S/N 691 through 705, inclusive, 707 through 728, inclusive, or 813 through 844, inclusive.

(d) Unsafe Condition

This AD was prompted by corrosion detected in affected N2 sensor harnesses. We are issuing this AD to prevent inadvertent activation of the 65% N1 back up mode, resulting in N2 speed fluctuation, significant power loss, and emergency landing of the helicopter.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) For engines listed in paragraph (c)(1) of this AD with an affected N2 sensor harness installed on both engines of the helicopter, do the following:

- (i) Replace one N2 sensor harness with an N2 sensor harness that is eligible for installation within 10 flight hours (FHs) after December 7, 2011, or before the next flight after the effective date of this AD, whichever occurs later, and
- (ii) Replace the second N2 sensor harness with an N2 sensor harness that is eligible for installation within 50 FHs after December 7, 2011, or before the next flight after the effective date of this AD, whichever occurs later.

(2) For engines listed in paragraph (c)(1) of this AD with an affected N2 sensor harness installed on only one engine of the helicopter, replace the affected N2 sensor harness with an N2 sensor harness that is eligible for installation within 50 FHs after December 7, 2011, or before the next flight after the effective date of this AD, whichever occurs later.

(3) For engines listed in paragraph (c)(2) of this AD with an affected N2 sensor harness installed on both engines of the helicopter, do the following:

(i) Replace one N2 sensor harness with an N2 sensor harness that is eligible for installation within 10 FHs after the effective date of this AD, and

(ii) Replace the second N2 sensor harness with an N2 sensor harness that is eligible for installation within 50 FHs after the effective date of this AD.

(4) For engines listed in paragraph (c)(2) of this AD with an affected N2 sensor harness installed on only one engine of the helicopter, replace the affected N2 sensor harness with an N2 sensor harness that is eligible for installation within 50 FHs after the effective date of this AD.

(5) If an affected N2 sensor harness is installed on both engines of the helicopter, one from paragraph (c)(1) of this AD and one from paragraph (c)(2) of this AD, then within 10 FHs after December 7, 2011, or before the next flight after the effective date of this AD, whichever occurs later, replace the N2 sensor harness from paragraph (c)(1) with an N2 sensor harness that is eligible for installation and within 50 FHs after the effective date of this AD, replace the harness from paragraph (c)(2) with an N2 sensor harness that is eligible for installation.

(f) Installation Prohibition

(1) After the effective date of this AD, do not install on any engine any N2 sensor harness, P/N 0 301 52 001 0, with a S/N listed in paragraphs (c)(1) and (c)(2) of this AD, unless the N2 sensor harness has "SB 0815" marked on its identification plate.

(2) After the effective date of this AD, do not install in a helicopter, any engine with an N2 sensor harness, P/N 0 301 52 001 0, installed, with a S/N listed in paragraphs (c)(1) and (c)(2) of this AD, unless the N2 sensor harness has "SB 0815" marked on its identification plate.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures in 14 CFR 39.19 to make your request.

(h) Related Information

(1) For more information about this AD, contact Rose Len, Aerospace Engineer, Engine Certification Office, FAA, 12 New England Executive Park, Burlington, MA 01803; phone: 781-2328-7772; fax: 781-238-7199; email: rose.len@faa.gov.

(2) Turbomeca S.A. Alert Mandatory Service Bulletin (MSB) No. A298 77 0821, Version A, dated October 9, 2012, and MSB No. 298 77 0817, Version B, dated August 23, 2011, pertain to the subject of this AD.

(3) For service information identified in this AD, contact Turbomeca, 40220 Tarnos, France, phone: +33 (0)5 59 74 40 00; telex: 570 042; fax: +33 (0)5 59 74 45 15; Web site: <http://www.turbomeca-support.com>. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

(i) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on February 25, 2013.

Colleen M. D'Alessandro,

Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2013-04996 Filed 3-5-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG-2012-0918]

RIN 1625-AA09

Drawbridge Operation Regulation; Lake Champlain, Swanton, VT

AGENCY: Coast Guard, DHS.

ACTION: Final rule.

SUMMARY: The Coast Guard is changing the drawbridge operation regulation that governs the operation of the New England Central Railroad Bridge across Missisquoi Bay, mile 105.6, at Swanton, Vermont, and removing the regulation for the SR78 highway bridge at mile 105.9. The owner of the New England Central Railroad Bridge has requested to operate the bridge from a remote location, at St. Albans, Vermont. It is expected that this change to the regulations will provide relief to the bridge owner from crewing the bridge while continuing to meet the reasonable needs of navigation.

DATES: This rule is effective April 5, 2013.

ADDRESSES: Comments and related materials received from the public, as well as documents mentioned in this preamble as being available in the docket, are part of docket USCG-2012-0918 and are available online by going to <http://www.regulations.gov>, inserting USCG-2012-0918 in the "Keyword" box, and then clicking "Search." This material is also available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email Mr. John W. McDonald, Project Officer, First Coast Guard District Bridge Branch, 617-223-8364, john.w.mcdonald@uscg.mil. If you have

questions on viewing the docket, call Barbara Hairston, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION:

A. Regulatory History and Information

On November 9, 2012, we published a notice of proposed rulemaking (NPRM) entitled "Drawbridge Operation Regulation; Lake Champlain, Swanton, VT" in the **Federal Register** (77 FR 67319). We received no comments on the proposed rule. No public meeting was requested, and none was held.

B. Basis and Purpose

The New England Central Railroad Bridge, formerly the Central Vermont Railway Bridge, at mile 105.6, across Missisquoi Bay, at Swanton, Vermont, has a vertical clearance in the closed position that ranges between 9.5 feet and zero feet depending on the time of year and other conditions. The waterway users are predominantly seasonal recreational vessels.

The existing drawbridge operation regulations are listed at 33 CFR 117.993(c), which require the draw to operate as follows: From June 15 through September 15, the draw shall open on signal, Monday through Friday between 9 a.m. and 5 p.m. and on Saturday, Sunday, Independence Day, and Labor Day, between 7 a.m. and 11 p.m. At all other times, after at least a two hour notice is given. From September 16 through June 14, on signal after at least a twenty four hour notice is given.

The Coast Guard received a request from the owner of the bridge, New England Central Railroad Inc., to change the drawbridge operation regulations to allow the bridge to be operated remotely from the New England Central Railroad Dispatcher's Office located at St. Albans, Vermont.

The bridge had been operated manually by hand crank since it was constructed in 1912. An operator would be dispatched to the bridge to manually close the draw to facilitate the passage of a train and then crank the draw back into the open position.

The Federal Railroad Administration funded the motorization of the bridge to allow remote operation of the bridge by New England Central Railroad. As a result, in 2012, the operating system was modified by adding electric bridge opening motors to swing the draw open and closed, a standby electric generator to be used in the event of a power outage, local bridge operation controls installed at the tenders building on the bridge to be used to locally operate the draw, LED navigation lights, and