

GmbH Recommended Service Bulletin 40NG-011, dated February 28, 2012, is no longer valid, and any actions following Diamond Aircraft Industries GmbH Recommended Service Bulletin 40NG-011, dated February 28, 2012, are prohibited.

(g) Credit for Actions Accomplished in Accordance With Previous Service Information

If, before May 21, 2013 (the effective date of this AD), you performed the actions in the Accomplishments/Instructions section of Diamond Aircraft Industries GmbH Mandatory Service Bulletin 40NG-018, dated November 22, 2012, you met the requirements of paragraphs (f)(1), (f)(2), and (f)(3) of this AD.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(i) Related Information

Refer to European Aviation Safety Agency (EASA) AD 2013-0018, dated January 21, 2013; and Diamond Aircraft Industries GmbH Mandatory Service Bulletin 40NG-018, dated November 22, 2012, for related information.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Diamond Aircraft Industries GmbH Mandatory Service Bulletin 40NG-018/1, dated November 26, 2012.

(ii) Diamond Aircraft Industries GmbH Work Instruction WI-MSB-40NG-018, Revision 1, dated November 26, 2012.

(3) For Diamond Aircraft Industries GmbH service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Str.5, A-2700 Wiener Neustadt, Austria; telephone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; Internet: <http://www.diamondaircraft.com/contact/technical.php>.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri on April 15, 2013.

Earl Lawrence,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-09431 Filed 4-30-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0951; Directorate Identifier 2007-SW-52-AD; Amendment 39-17437; AD 2013-08-19]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter France (Eurocopter) Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, and AS355N helicopters. This AD requires visual and dye penetrant inspections for cracks in the rear roller support shaft (shaft) and rear fitting

(fitting) of the sliding door, and replacing the shaft or fitting if there is a crack. This AD's actions are prompted by reports of cracks in the shaft and the fitting and are intended to prevent the loss of the sliding door, which could come into contact with the rotor system, leading to damage to the helicopter and loss of helicopter control.

DATES: This AD is effective June 5, 2013.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of June 5, 2013.

ADDRESSES: For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email gary.b.roach@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On October 22, 2009, at 74 FR 54501, the **Federal Register** published our notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 to include an AD that would apply to Eurocopter Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, and AS355N helicopters, with sliding door pre-modification (MOD) 073298 or pre-MOD 073308, installed. The NPRM proposed to require visual and dye

penetrant inspections of the shaft and fitting. If a crack exists in the shaft or fitting, the NPRM proposed replacing the cracked parts with airworthy parts. The proposed requirements were intended to prevent the loss of the sliding door, which could come into contact with the rotor system and lead to damage to the helicopter and loss of helicopter control.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2007-0236, dated August 31, 2007, to correct an unsafe condition for specified Eurocopter model helicopters. EASA issued AD 2006-0251 and its revisions following a case of total failure and a case of a crack discovered on the support shaft of the sliding door rear roller.

Metallurgical and metallographic analyses revealed a nonconformity concerning the heat treatment of the material. Since then, other cases of cracks and failures of the roller support shaft rear attach fitting had been reported. EASA AD No. 2007-0236 supersedes EASA AD No. 2006-0251R2 but retains the requirements for repetitive inspections until replacement of current parts with improved parts. EASA AD No. 2007-0236 also prohibits installation of another roller support fitting part number (P/N) 350A25-1270-22 on any AS350 or AS355 helicopter.

Comments

After our NPRM (74 FR 54501, October 22, 2009) was published, we received comments from one commenter.

Request

One commenter requested that our AD apply to only pre-modified aircraft as stated in the applicability paragraph. We agree.

The commenter also requested a paragraph on terminating action once an aircraft is "modified to a post-mod status" to avoid confusing an owner/operator. We disagree with this request. If an aircraft becomes modified according to modifications 073298 and 073308, the AD is clear that the applicability paragraph no longer applies.

FAA's Determination

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD

because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed, except we have revised the estimated costs of complying with this AD to reflect labor costs of \$85 per hour instead of \$80 per hour.

Differences Between This AD and the EASA AD

This AD differs from EASA AD No. 2007-0236 as follows:

- We use the word "inspect" to describe the actions required by a mechanic. EASA uses the word "check," which is how we describe the actions we allow a pilot to complete.
- We do not require an operator to tell the manufacturer if a crack is found in the shaft.
- We are not including the Model AS 350 BB, because that model is not type certificated in the U.S. We are including Models AS350C and AS350D1 helicopters.

Related Service Information

On July 18, 2006, Eurocopter issued Alert Service Bulletin (ASB) No. 52.00.30 for modifying the AS350 series helicopters and ASB No. 52.00.23 for modifying the AS355 series helicopters. These ASBs contained modifications 073298 and 073308. The following day, Eurocopter issued ASB No. 05.00.45 for the AS355 model helicopters and ASB No. 05.00.47 for the AS350 helicopters. On June 29, 2007, Eurocopter issued Revision 1 to ASB No. 52.00.30 for the AS350 model helicopters and ASB No. 52.00.23 for the AS355 model helicopters to modify the sliding door medium roller pin and the fitting.

Costs of Compliance

We estimate that this AD will affect 725 helicopters of U.S. Registry and that labor costs average \$85 a work-hour. Based on these estimates, we expect the following costs:

Inspecting and modifying the sliding doors will require about 4 work-hours for a labor cost of \$340. Parts will cost about \$7,000 for a total cost of \$7,340 per helicopter, and \$5,321,500 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2013-08-19 Eurocopter France Helicopters:
Amendment 39-17437; Docket No.
FAA-2009-0951; Directorate Identifier
2007-SW-52-AD.

(a) Applicability

This AD applies to Eurocopter France (Eurocopter) Model AS350B, BA, B1, B2, B3, C, D, D1, AS355E, F, F1, F2, and N helicopters, with sliding door pre-modification (MOD) 073298 or pre-MOD 073308, installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in the rear roller support shaft (shaft) or the rear fitting (fitting) of the sliding door. This condition could result in loss of the sliding door, which could come into contact with the rotor system, leading to damage to the helicopter and loss of helicopter control.

(c) Effective Date

This AD becomes effective June 5, 2013.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless accomplished previously.

(e) Required Actions

(1) For a sliding door with less than 90 hours time-in-service (TIS), on or before accumulating a total of 110 hours TIS, conduct the visual and dye penetrant inspections of the shaft and the fitting of the sliding door for a crack by reference to Figure 1 and by following the Operational Procedure, paragraph 2.B.1 and 2.B.2, of Eurocopter Alert Service Bulletin (ASB) No. 05.00.47 dated July 19, 2006, for the Model AS350 helicopters (ASB 05.00.47) or ASB No. 05.00.45 dated July 19, 2006, for the Model AS355 helicopters (ASB 05.00.45), except you are not required to contact the manufacturer.

(i) If no crack is found in the shaft or fitting, reinstall the shaft on the fitting, fit the spring pins, and plug the pin holes by following the Operational Procedure, paragraph 2.B.2. of ASB 05.00.47 or 05.00.45, whichever is appropriate for your model helicopter.

(ii) If you find a crack in the fitting, replace the fitting with an airworthy fitting before further flight.

(iii) If you find a crack in the shaft, replace the shaft with an airworthy shaft before further flight by reference to Figure 1 and by following paragraph 2.B.3. of ASB 05.00.47 or 05.00.45, whichever is appropriate for your model helicopter.

(2) For a sliding door with 90 or more hours TIS, within the next 20 hours TIS, and thereafter at intervals not to exceed 110 hours TIS, conduct the visual and dye penetrant inspections of the shaft and the fitting of the sliding door for a crack by reference to Figure 1 and by following the Operational Procedure, paragraph 2.B.1 and 2.B.2, of ASB 05.00.47 or ASB 05.00.45, whichever is appropriate for your model helicopter, except you are not required to contact the manufacturer.

(i) If no crack is found in the shaft and fitting, reinstall the shaft or fitting, fit the spring pins, and plug the pin holes by following the Operational Procedure, paragraph 2.B.2. of ASB 05.00.47 or 05.00.45, whichever is appropriate for your model helicopter.

(ii) If you find a crack in the fitting, replace the fitting with an airworthy fitting before further flight.

(iii) If you find a crack in the shaft, replace the shaft with an airworthy shaft before further flight by reference to Figure 1 and by following paragraph 2.B.3. of ASB 05.00.47 or 05.45, whichever is appropriate for your model helicopter.

(3) After the effective date of this AD, do not install any of the following parts on any helicopter:

(i) Left-hand sliding door, part number (P/N) 350A25-0030-00XX, 350A25-0120-00XX, and 350AMR-0227-0052;

(ii) Right-hand sliding door, P/N 350A25-0030-01XX, 350A25-0120-01XX, 350A25-0120-03XX, and 350AMR-0227-0051;

(iii) Rail roller pin, P/N 350A25-1275-20; and

(iv) Cast roller support fittings, P/N 350A25-1270-20 and P/N 350A25-1270-22.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email gary.b.roach@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency AD No. 2007-0236, dated August 31, 2007.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 5344, Fuselage Door Hinges.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise:

(i) Eurocopter France Alert Service Bulletin No. 05.00.47, Revision 0, dated July 19, 2006.

(ii) Eurocopter France Alert Service Bulletin No. 05.00.45, Revision 0, dated July 19, 2006.

(3) For Eurocopter France service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052;

telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on April 12, 2013.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2013-09436 Filed 4-30-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0631; Directorate Identifier 2011-SW-021-AD; Amendment 39-17282; AD 2012-25-01]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter France Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with certain Aerazur emergency flotation gear attachment brackets (brackets) installed. This AD requires an initial and recurring inspection of the brackets for a crack, and if there is a crack, replacing the cracked bracket with an airworthy bracket. This AD was prompted by reports of cracks on the brackets. The actions of this AD are intended to prevent failure of the emergency flotation system and loss of float stability in the event of a water landing.

DATES: This AD is effective June 5, 2013.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of June 5, 2013.

ADDRESSES: For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum