

- 10. Amend § 115.35 as follows:
- (a) Revise paragraph (c)(1) as set forth below;
- (b) In paragraph (c)(4), remove “90 days” and add “45 days” in its place.

**§ 115.35 Claims for reimbursement of Losses.**

\* \* \* \* \*

(c) *Claim reimbursement requests.* (1) Claims for reimbursement for Losses which the Surety has paid must be submitted (together with a copy of the bond, the bonded Contract, and any indemnity agreements) with the initial claim to OSO on a “Default Report, Claim for Reimbursement and Report of Recoveries” (SBA Form 994H), within 90 days from the time of each disbursement. Claims submitted after 90 days must be accompanied by substantiation satisfactory to SBA. The date of the claim for reimbursement is the date of receipt of the claim by SBA, or such later date as additional information requested by SBA is received.

\* \* \* \* \*

- 11. Amend § 115.36 paragraph (a)(3) by removing “90 days” and adding “45 days” in its place.
- 12. Amend § 115.67 paragraph (a) by removing “\$50,000” and adding “\$100,000, whichever is less” in its place.
- 13. Revise § 115.69 to read as follows:

**§ 115.69 Imminent Breach.**

(a) *No Prior Approval Requirement.* SBA will reimburse a PSB Surety for the guaranteed portion of payments the Surety makes to avoid or attempt to avoid an Imminent Breach of the terms of a Contract covered by an SBA guaranteed bond. The aggregate of the payments by SBA under this section cannot exceed 10% of the Contract amount, unless the Administrator finds that a greater payment (not to exceed the guaranteed portion of the bond penalty) is necessary and reasonable. The PSB Surety does not need to obtain prior SBA approval to make Imminent Breach payments, except that the PSB Surety may request SBA to approve payments that exceed 10% of the Contract amount prior to the Surety making the payment. In no event will SBA make any duplicate payment under any provision of these regulations in this part.

(b) *Recordkeeping Requirement.* The PSB Surety must keep records of payments made to avoid Imminent Breach.

- 14. Amend § 115.70 paragraph (a) as follows:
- (a) Remove the term “1 year” in the first sentence and add the term “90 days” in its place; and

- (b) Remove the term “90 days” in the third sentence and add “45 days” in its place.

Dated: July 26, 2013.

**Karen G. Mills,**  
Administrator.

[FR Doc. 2013-18530 Filed 7-31-13; 8:45 am]

**BILLING CODE 8025-01-P**

---

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2008-0616; Directorate Identifier 2007-NM-353-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; the Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

**SUMMARY:** We are revising an earlier proposed airworthiness directive (AD) for all The Boeing Company Model 767 airplanes. That NPRM proposed to require repetitive operational tests of the engine fuel suction feed of the fuel system, and other related testing if necessary. That NPRM was prompted by reports of two in-service occurrences on Model 737-400 airplanes of total loss of boost pump pressure of the fuel feed system, followed by loss of fuel system suction feed capability on one engine, and in-flight shutdown of the engine. This action revises that NPRM by proposing to revise the maintenance program to incorporate a revision to the Airworthiness Limitations Section of the maintenance planning data (MPD) document, and to remove airplanes from the applicability. We are proposing this supplemental NPRM to detect and correct failure of the engine fuel suction feed capability of the fuel system, which could result in dual engine flameout, inability to restart the engines, and consequent forced landing of the airplane. Since these actions impose an additional burden over that proposed in the previous NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

**DATES:** We must receive comments on this supplemental NPRM by September 16, 2013.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5280; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, 1601 Lind Avenue SW., Renton, Washington 98057-3352; phone: 425-917-6438; fax: 425-917-6590; email: [suzanne.lucier@faa.gov](mailto:suzanne.lucier@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2008-0616; Directorate Identifier 2007-NM-353-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this

proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

We issued an NPRM to amend 14 CFR part 39 to include an AD that would apply to all The Boeing Company Model 767 airplanes. That NPRM published in the **Federal Register** on June 6, 2008 (73 FR 32252). That NPRM proposed to require repetitive operational tests of the engine fuel suction feed of the fuel system, and other related testing if necessary, according to a method approved by the FAA.

#### Actions Since Previous NPRM (73 FR 32252, June 6, 2008) Was Issued

Since we issued the previous NPRM (73 FR 32252, June 6, 2008), we have received comments from operators indicating a high level of difficulty performing the actions in the previous NPRM during maintenance operations. It is standard practice for operators to revise maintenance tasks to incorporate actions into their individual maintenance manuals as part of the maintenance program. Based on these comments, and a review of the previous NPRM, we determined a revision to the procedures was necessary. In conjunction with Boeing we developed an airworthiness limitation for the engine fuel suction feed system to address this issue.

#### Relevant Service Information

We reviewed Section 9, Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D622T001–9, Revision October 2012 and Revision January 2013, of the Boeing 767 Maintenance Planning Data (MPD) Document. Among other things, Section 9 describes AWL No. 28—AWL—101, Engine Fuel Suction Feed Operational Test, of Section E., AWL—Fuel Systems, which provides procedures for performing repetitive operational tests of the engine fuel suction feed of the fuel system.

#### Comments

We gave the public the opportunity to comment on the previous NPRM (73 FR 32252, June 6, 2008). The following presents the comments received on the previous NPRM and the FAA's response to each comment.

#### Request To Withdraw the Previous NPRM (73 FR 32252, June 6, 2008)

ABX Air asked that we withdraw the previous NPRM (73 FR 32252, June 6, 2008). ABX stated that there have been no incidents recorded in the NTSB or FAA databases for a Model 767 flameout due to the loss of fuel system suction feed capability. ABX added that it does not believe the subject unsafe condition is a critical safety concern.

We do not agree with the request to withdraw the previous NPRM (73 FR 32252, June 6, 2008), because, together with the manufacturer, we have evaluated this issue and determined it to be an important safety concern. Although the fuel system on Model 767 airplanes differs from the Model 737 with respect to the engine fuel feed system design, service data of transport category airplanes indicates that multi-engine flameouts have generally resulted from a common cause, such as fuel mismanagement, crew action that inadvertently shut off the fuel supply to the engines, exposure to common environmental conditions, or engine deterioration on all engines of the same type. Successful in-flight restart of the engines is dependent on adequate fuel being supplied to the engines, solely through engine fuel suction feed. Deterioration of the fuel plumbing system can lead to line (vacuum) losses, reducing the engine fuel suction feed capability; therefore, directed maintenance is necessary to ensure this system is functioning correctly in order to maintain continued safe flight of the airplane. We have not changed the supplemental NPRM in this regard.

#### Request To Incorporate CMR Task Into the Maintenance Program Instead of Issuing an NPRM

ABX, Japan Airlines International (JAL), and Qantas Airways Ltd. asked that a CMR task be developed for incorporation into the maintenance program instead of issuing an NPRM (73 FR 32252, June 6, 2008). The commenters stated that the maintenance program is already in use by operators and the procedures are understood and followed. Qantas added that the task associated with this action will generate an administrative burden for operators, with no benefit.

We do not agree with the requests to develop a CMR task. CMRs are developed by the Certification Maintenance Coordination Committee (CMCC) during the type certification process. The CMCC is made up of manufacturer representatives (typically maintenance, design, and safety engineering personnel), operator

representatives designated by the Industry Steering Committee chairperson, FAA Aircraft Certification Office specialists, and the Maintenance Review Board (MRB) chairperson. CMRs developed during this process become a part of the certification basis of the airplane upon issuance of the type certificate. We do not have a process for convening the CMCC outside of the type certification process; based on this, the CMR is not an option for replacing this AD. Therefore, if the airworthiness limitation items (ALIs) were not in the maintenance program at the time of initial certification, an AD is required to make the ALI task a required action. We have not changed the supplemental NPRM in this regard.

#### Requests To Allow the Use of Later Revisions of the Maintenance Documents

Air New Zealand (ANZ), ABX, Continental Airlines (CAL), and Boeing asked that we allow using later revisions of the referenced maintenance documents, because those documents could be revised over time and would require frequent requests for alternative methods of compliance (AMOCs).

We do not agree with the request. Allowing later revisions of service documents in an AD is not allowed by the Office of the Federal Register regulations for approving materials incorporated by reference. We have made no change to the supplemental NPRM in this regard.

#### Request To Clarify Reason for the Unsafe Condition

Boeing asked that we clarify the reason for the unsafe condition identified in the previous NPRM (73 FR 32252, June 6, 2008). Boeing asked that the AD include the results from a report of in-service occurrences of loss of fuel system suction feed capability on one engine, due to two in-service engine flameout events on a Model 737–400 airplane while operating on suction feed with undetected air leak failures. Boeing stated that there are no known reports of any engine flameout related to events on Model 767 airplanes. Boeing acknowledged that undetected air leaks could exist and that this maintenance procedure is a proactive measure to ensure engine flameout will not occur during suction feed operation.

We agree to clarify the unsafe condition. We have revised the Summary section and paragraph (e) of this supplemental NPRM accordingly.

### Requests for Changes To Certain Maintenance Document References

JAL, ANZ, and Boeing asked that we remove the airplane maintenance manual (AMM) reference to Section 28–22–00 specified in paragraph (f) of the previous NPRM (73 FR 32252, June 6, 2008). The commenters stated that the AMM is covered in Boeing 767 Task Card 28–020–02, and noted that having fewer references included lessens the chance of errors.

We acknowledge and agree with the commenters concerns regarding the maintenance documents referenced in the previous NPRM (73 FR 32253, June 6, 2008). However, these maintenance documents are not FAA-approved and we do not have the publication controls associated with AD-related service documents. We do not agree with the requested changes because we have decided to mandate an FAA-approved document which should eliminate these concerns. We changed paragraph (f) of the previous NPRM (paragraph (g) in this supplemental NPRM) to require revising the maintenance program to incorporate new procedures into the maintenance documents.

### Requests To Extend Repetitive Test Intervals

CAL and Air Canada asked that we extend the repetitive operational test interval specified in paragraph (f) of the previous NPRM (73 FR 32252, June 6, 2008).

CAL stated that a re-evaluation of the proposed repetitive interval limit after doing the initial inspection should be done, since CAL's service history has revealed no reported engine flameout events or related operational discrepancies. CAL asked that the repetitive interval be extended to a normal maintenance 2C-check or within 12,000 flight hours, whichever occurs first.

Air Canada asked that the repetitive interval be extended to a calendar time of 24 months. Air Canada does not understand the logic behind a repetitive frequency of 7,500 flight hours.

We do not agree with the requests that the repetitive intervals be extended. In developing an appropriate compliance time for the actions specified in paragraph (g) of this supplemental NPRM (paragraph (f) of the previous NPRM (73 FR 32252, June 6, 2008)), we considered the safety implications and normal maintenance schedules for the timely accomplishment of the specified actions. We have determined that the proposed compliance time will ensure an acceptable level of safety and allow the actions to be done during scheduled

maintenance intervals for most affected operators. However, affected operators may request an AMOC to request an extension of the repetitive operational test interval under the provisions of paragraph (h) of this supplemental NPRM by submitting data substantiating that the change would provide an acceptable level of safety. We have not changed the supplemental NPRM in this regard.

### Request To Clarify That Engine Fuel Suction Feed Test Is Allowed in Lieu of the Operational Test

JAL asked that we clarify that the engine fuel suction feed test procedure in the Boeing 767 Maintenance Planning Data (MPD) document is an option for performing the operational test in the previous NPRM (73 FR 32252, June 6, 2008). JAL asked that we consider adding the pressure leak check of the fuel lines and fittings procedure as an alternative procedure to performing the operational test specified in Section 28–22–00 of the Boeing 767 Aircraft Maintenance Manual (AMM).

We agree to provide clarification. The pressure leak check is not equivalent to the operational test (Task 28–22–00–710–802) since certain fuel line seal details may function normally under positive pressure, but fail to hold in-line vacuum when under fuel suction feed. Additionally, a fuel suction feed test would be required after reconnecting the fuel line to the manifold to verify final system integrity. Therefore, we have not changed the supplemental NPRM in this regard.

### Request To Include Warning Information

CAL suggested that the Boeing service manuals include a critical design configuration control limitation (CDCCL) warning identification statement to alert maintenance personnel of the importance of regulatory compliance, as well as the configuration control requirement. CAL did not include any justification for this request.

We agree that a CDCCL warning statement would serve as direct communication to maintenance personnel that there is an AD associated with certain maintenance actions. New service information has been added to this supplemental NPRM since issuance of the previous NPRM (73 FR 32252, June 6, 2008), which should eliminate the commenter's concern. The airplane maintenance manual will be a "referred to" document within the AWL task, which gives operators flexibility in developing maintenance programs based on equivalent procedures. We

have made no change to the supplemental NPRM in this regard.

### Request To Include Corrective Action

CAL asked that the related testing language specified in paragraph (f) of the previous NPRM (73 FR 32252, June 6, 2008) be changed. CAL stated that the language should specify correcting discrepancies before further flight if the engine fails the operational test. CAL added that the corrective actions should be done in accordance with the procedures in the "Right (Left) Engine Fails the Suction Feed Test" procedure in the Boeing 767 Fault Isolation Manual (FIM) 28–22–00/101.

We acknowledge and agree with the commenters concern. However, as stated previously, we are issuing this supplemental NPRM to revise the maintenance program to incorporate a revision to the Airworthiness Limitations Section of the MPD document to include the "Engine Fuel Suction Feed Operational Test" procedure. Therefore, the language identified by the commenter has been removed from this supplemental NPRM. We have made no change to the supplemental NPRM in this regard.

### FAA's Determination

We are proposing this supplemental NPRM because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. Certain changes described above expand the scope of the previous NPRM (73 FR 32252, June 6, 2008). As a result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this supplemental NPRM.

### Proposed Requirements of the Supplemental NPRM

This supplemental NPRM revises the previous NPRM (73 FR 32252, June 6, 2008) by proposing to remove the actions in paragraph (f) of the previous NPRM and replace with a revision to the maintenance program to incorporate procedures for the Engine Fuel Suction Feed Operational Test Airworthiness Limitations Section of the MPD document, and to remove airplanes from the applicability.

This AD requires revisions to certain operator maintenance documents to include new actions (e.g., inspections) and/or CDCCLs. Compliance with these actions and/or CDCCLs is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this

AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to

paragraph (i)(1) of this AD. The request should include a description of changes to the required actions that will ensure the continued operational safety of the airplane.

**Costs of Compliance**

We estimate that this proposed AD affects 406 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

| Action                                 | Labor cost                               | Parts cost | Cost per product | Cost on U.S. operators |
|--|--|------------|------------------|------------------------|
| Revise airworthiness limitations ..... | 1 work-hour × \$85 per hour = \$85 ..... | \$0        | \$85             | \$34,510               |

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this proposed regulation:*

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**The Boeing Company:** Docket No. FAA–2008–0616; Directorate Identifier 2007–NM–353–AD.

**(a) Comments Due Date**

We must receive comments by September 16, 2013.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 767–200, –300, –300F, and –400ER series airplanes, certificated in any category, that have received a certificate of airworthiness or foreign export before November 2, 2012.

**Note 1 to paragraph (c) of this AD:** November 2, 2012, is the original publication date of Section 9, Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D622T001–9, Revision October 2012, of the Boeing 767 Maintenance Planning Data (MPD) Document, or Revision January 2013 of the Boeing 767 Maintenance Planning Data (MPD) Document; including Airworthiness Limitations (AWLS)—Fuel Systems of Airworthiness Limitation (AWL) No. 28–AWL–101, Engine Fuel Suction Feed Operational Test.

**(d) Subject**

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 2800, Aircraft Fuel System.

**(e) Unsafe Condition**

This AD results from reports of two in-service occurrences on Model 737–400 airplanes of total loss of boost pump pressure of the fuel feed system, followed by loss of fuel system suction feed capability on one engine, and in-flight shutdown of the engine. We are issuing this AD to detect and correct failure of the engine fuel suction feed capability of the fuel system, which could result in dual engine flameout, inability to restart the engines, and consequent forced landing of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Maintenance Program Revision**

Within 90 days after the effective date of this AD: Revise the maintenance program to incorporate AWL No. 28–AWL–101, Engine Fuel Suction Feed Operational Test, of Section E., AWLS—Fuel Systems of Section 9, AWLs and CMRs, D622T001–9, Revision October 2012 or Revision January 2013, of the Boeing 767 MPD Document.

**(h) No Alternative Actions, Intervals, and/or Critical Design Configuration Control Limitations (CDCCLs)**

After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., tests), intervals, or CDCCLs may be used unless the actions, intervals, or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i) of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

- (1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/  
certificate holding district office.

#### (j) Related Information

(1) For more information about this AD, contact Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, 1601 Lind Avenue SW., Renton, Washington 98057-3352; phone: 425-917-6438; fax: 425-917-6590; email: [suzanne.lucier@faa.gov](mailto:suzanne.lucier@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5280; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on July 21, 2013.

**Stephen P. Boyd,**

*Acting Manager, Transport Airplane  
Directorate, Aircraft Certification Service.*

[FR Doc. 2013-18511 Filed 7-31-13; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2013-0668; Directorate  
Identifier 2013-NM-017-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Airplanes

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking  
(NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A300 B4-600 and A300 B4-600R series airplanes. This proposed AD was prompted by reports of cracks found in the bottom wing skin stringers at rib 14 during full-scale fatigue testing and in service. This proposed AD would require modifying the profile of stringer run-outs at rib 14 of both wings, including a high frequency eddy current inspection of the fastener holes for defects and repair if necessary. We are proposing this AD to prevent cracking in the bottom wing skin stringers, which could result in reduced structural integrity of the wings.

**DATES:** We must receive comments on this proposed AD by September 16, 2013.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2013-0668; Directorate Identifier 2013-NM-017-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the

closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2013-0008R1, dated January 22, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

During full-scale fatigue testing, cracks were detected in the bottom wing skin stringers at rib 14. In addition, A300 aeroplane operators have also reported finding cracks in the same area.

This condition, if not detected and corrected, could impair the structural integrity of the wings.

Additional analysis results showed that the improved design of the stringer run-out is necessary for aeroplanes operating beyond the ESG 1 [extended service goal 1: 42,500 flight cycles].

For the reasons described above, this [EASA] AD requires the removal of the stringer end run-out plate at stringer 19 on the bottom wing skin and the re-profiling modification of the stringers 10, 11, 12, 17 and 19.

\* \* \* \* \*

The modification also includes doing a high frequency eddy current inspection of the fastener holes for defects and repair if necessary. You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Airbus has issued Mandatory Service Bulletin A300-57-6046, Revision 01, dated April 18, 2011. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe