(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2013–0837; Directorate Identifier 2013–NM–112–AD.

(a) Comments Due Date

We must receive comments by November 18, 2013.

(b) Affected ADs

For The Boeing Company Model 737–300, –400, and –500 series airplanes: Certain requirements of AD 2008–09–13, Amendment 39–15494 (73 FR 24164, May 2, 2008), may be affected by certain requirements of this AD.

(c) Applicability

This AD applies to The Boeing Company Model 737–200, –200C, –300, –400, and –500 series airplanes, certificated in any category, without an airstair door cutout, as identified in Boeing Alert Service Bulletin 737–53A1329, dated June 4, 2013.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracking found in the skin at the lower aft corner of the forward entry doorway on airplanes that do not have an airstair door cutout. We are issuing this AD to detect and correct cracking in the lower corners of the forward entry doorway, which could lead to crack progression and consequent rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Except as provided by paragraph (i)(1) of this AD, at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737–53A1329, dated June 4, 2013, do the actions specified in paragraph (g)(1) or (g)(2) of this AD, as applicable.

(1) For Group 1 airplanes, as identified in Boeing Alert Service Bulletin 737–53A1329, dated June 4, 2013: Except as provided by paragraph (i)(2) of this AD, inspect the lower corners of the forward entry doorway for cracking, using a method approved in accordance with the procedures specified in

paragraph (j) of this AD.

(2) For Group 2 and Group 3 airplanes, as identified in Boeing Alert Service Bulletin 737-53A1329, dated June 4, 2013: At the forward entry doorway lower forward and aft corners, as applicable, do an internal detailed inspection of the skin assembly and bear strap, an internal high frequency eddy current (HFEC) inspection of the bear strap, and external detailed and HFEC inspections of the skin assembly for cracking, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1329, dated June 4, 2013. If no cracking is found during any inspection required by this paragraph: Except as provided by paragraph (i)(1) of this AD, repeat the applicable inspections at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1329, dated June 4, 2013.

(h) Repair

(1) If any cracking is found during any inspection required by paragraph (g) of this AD: For Group 3 airplanes with cracking at the aft lower corner of the forward entry doorway, before further flight, repair in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1329, dated June 4, 2013. Accomplishment of this repair terminates the repetitive inspections required by this AD in the area common to the repair for Group 3 airplanes only. For all other cracking found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(2) Installation of a repair approved in accordance with paragraph (j) of this AD terminates the repetitive inspections required by this AD for the repaired area only.

(i) Exceptions to Service Information Specifications

(1) Where Boeing Alert Service Bulletin 737–53A1329, dated June 4, 2013, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Although Boeing Alert Service Bulletin 737–53A1329, dated June 4, 2013, specifies contacting Boeing for information on certain inspections and repairs, this AD requires that those actions be done by using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9–ANM—Seattle–ACO–AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by The Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method

to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: (425) 917–6450; fax: (425) 917–6590; email: alan.pohl@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet https://www.myboeingfleet.com. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on September 25, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2013–24121 Filed 10–1–13; 8:45 am] BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 300

[EPA-HQ-SFUND-1983-0002; FRL-9901-59-Region 2]

National Oil and Hazardous Substances Pollution Contingency Plan; National Priorities List: Deletion of the Ludlow Sand & Gravel Superfund Site

AGENCY: United States Environmental Protection Agency.

ACTION: Proposed rule; notice of intent.

SUMMARY: The Environmental Protection Agency (EPA) Region 2 is issuing a Notice of Intent to Delete the Ludlow Sand & Gravel Superfund Site (Site), located in Paris, New York, from the National Priorities List (NPL) and requests public comments on this proposed action. The NPL, promulgated pursuant to Section 105 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980, as amended, is an appendix of the National Oil and Hazardous Substances Pollution Contingency Plan (NCP). EPA and the State of New York, through the New York State Department of Environmental Conservation, have determined that all appropriate response actions under CERCLA, other than monitoring and maintenance and five-year reviews, have been completed. However, the deletion does not preclude future action under Superfund.

DATES: Comments must be received by November 1, 2013.

ADDRESSES: Submit your comments, identified by Docket ID no. EPA-HQ-SFUND-1983-0002, by one of the following methods:

- http://www.regulations.gov. Follow the on-line instructions for submitting comments.
 - Email: rodrigues.isabel@epa.gov.
- *Fax:* To the attention of Isabel Rodrigues at 212–637–4284.
- Mail: To the attention of Isabel Rodrigues, Remedial Project Manager, Emergency and Remedial Response Division, U.S. Environmental Protection Agency, Region 2, 290 Broadway, 20th Floor, New York, NY 10007–1866.
- Hand Delivery: Superfund Records Center, 290 Broadway, 18th Floor, New York, NY 10007–1866 (telephone: 212–637–4308). Such deliveries are only accepted during the Record Center's normal hours of operation (Monday to Friday from 9:00 a.m. to 5:00 p.m.). Special arrangements should be made for deliveries of boxed information.

Instructions: Direct your comments to Docket ID no. EPA-HQ-SFUND-1983-0002: EPA's policy is that all comments received will be included in the Docket without change and may be made available online at http:// www.regulations.gov, including any personal information provided, unless the comment includes information claimed to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Do not submit information that you consider to be CBI or otherwise protected through http:// www.regulations.gov or via email. The

http://www.regulations.gov Web site is an "anonymous access" system, which means EPA will not know your identity or contact information unless you provide it in the body of your comments. If you send comments to EPA via email, your email address will be included as part of the comment that is placed in the Docket and made available on the Web site. If you submit electronic comments, EPA recommends that you include your name and other contact information in the body of your comments and with any disks or CD-ROMs that you submit. If EPA cannot read your comments due to technical difficulties and cannot contact you for clarification, EPA may not be able to consider your comments. Electronic files should avoid the use of special characters and any form of encryption and should be free of any defects or viruses.

Docket: All documents in the Docket are listed in the http://www.regulations.gov index. Although listed in the index, some information is not publicly available, e.g., CBI or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, will be publicly available only in hard copy. Publicly available Docket materials can be viewed electronically at http://www.regulations.gov or obtained in hard copy at:

U.S. Environmental Protection Agency, Region 2, Superfund Records Center, 290 Broadway, 18th Floor, New York, NY 10007–1866, Phone: 212–637– 4308, Hours: Monday to Friday from 9:00 a.m. to 5:00 p.m., and

Town of Paris, Town Hall, 2580 Sulphur Springs Road, Sauquoit, NY 13456– 0451, Phone: 315–839–5400, Hours: Monday-Thursday from 9:00 a.m. to 4:00 p.m., Friday from 9:00 a.m. to 12:00 p.m., and

NYSDEC Central Office, 625 Broadway, Albany, NY 12233–7016, Phone: 518– 402–9775, Hours: Monday-Friday from 9:00 a.m. to 5:00 p.m., Please call for an appointment, and

NYSDEC Region 6 Sub-Office, State Office Building, 207 Genesee Street, Utica, NY 13501, Phone: 315–793– 2555, Hours: Monday-Friday from 8:30 a.m. to 4:45 p.m., Please call for an appointment.

FOR FURTHER INFORMATION CONTACT:

Isabel Rodrigues, Remedial Project Manager, by mail at Emergency and Remedial Response Division, U.S. Environmental Protection Agency, Region 2, 290 Broadway, 20th floor, New York, NY 10007–1866; telephone at 212–637–4248; fax at 212–637–4284; or email at rodrigues.isabel@epa.gov.

SUPPLEMENTARY INFORMATION: In the "Rules and Regulations" Section of today's **Federal Register**, EPA is publishing a direct final Notice of Deletion of the Site without prior Notice of Intent to Delete because EPA views this as a noncontroversial revision and anticipate no adverse comment. EPA has explained its reasons for this deletion in the preamble to the direct final Notice of Deletion. If EPA receives no adverse comment(s) on this Notice of Intent to Delete or the direct final Notice of Deletion, EPA will proceed with the deletion without further notice on this Notice of Intent to Delete. If EPA receives adverse comment(s), EPA will withdraw the direct final Notice of Deletion and it will not take effect. EPA will, as appropriate, address all public comments in a subsequent final Notice of Deletion based on this Notice of Intent to Delete. EPA will not institute a second comment period on this Notice of Intent to Delete. Any parties interested in commenting must do so at this time.

For additional information, see the direct final Notice of Deletion, which is located in the "Rules" section of this **Federal Register**.

List of Subjects in 40 CFR Part 300

Environmental protection, Air pollution control, Chemicals, Hazardous waste, Hazardous substances, Intergovernmental relations, Penalties, Reporting and recordkeeping requirements, Superfund, Water pollution control, Water supply.

Authority: 33 U.S.C. 1321(c)(2); 42 U.S.C. 9601–9657; E.O. 12777, 56 FR 54757, 3 CFR, 1991 Comp., p. 351; E.O. 12580, 52 FR 2923, 3 CFR, 1987 Comp., p. 193.

Dated: September 20, 2013.

Judith A. Enck,

Regional Administrator, EPA, Region 2. [FR Doc. 2013–24115 Filed 10–1–13; 8:45 am] BILLING CODE 6560–50–P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

42 CFR Part 121

RIN 0906-AB02

Change to the Definition of "Human Organ" Under Section 301 of the National Organ Transplant Act of 1984

AGENCY: Health Resources and Services Administration, HHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice seeks public comment on the proposed change in the definition of "human organ" in section