

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Fort Worth, Texas, on September 27, 2013.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2013-25312 Filed 10-30-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0667; Directorate Identifier 2013-NM-062-AD; Amendment 39-17639; AD 2013-22-07]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-400 series airplanes. This AD was prompted by reports of fasteners missing on an airplane undergoing a passenger-to-freighter conversion. This AD requires doing a general visual inspection of the station 1920 splice clip for correct fastener installation, and related investigative and corrective actions if necessary. We are issuing this AD to detect and correct missing or incorrect fasteners, which can lead to cracking and loss of load carrying capacity, resulting in a possible decompression event.

DATES: This AD is effective December 5, 2013.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 5, 2013.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: bill.ashforth@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to the specified products. The NPRM published in the **Federal Register** on August 1, 2013 (78 FR 46540). The NPRM proposed to require doing a general visual inspection of the station 1920 splice clip for correct fastener installation, and related investigative and corrective actions if necessary.

Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received. The Boeing Company supports the NPRM (78 FR 46540, August 1, 2013).

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this AD as proposed—except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 46540, August 1, 2013) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 46540, August 1, 2013).

Costs of Compliance

We estimate that this AD affects 3 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection for correct fastener installation	2 work-hours × \$85 per hour = \$170	\$0	\$170	\$510

We estimate the following costs to do any necessary repairs that would be

required based on the results of the inspection. We have no way of

determining the number of aircraft that might need these repairs:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Inspections for cracking	3 work-hours × \$85 per hour = \$255	\$0	\$255
Fastener installation	2 work-hours × \$85 per hour = \$170	0	170
Repair	2 work-hours × \$85 per hour = \$170	0	170

According to the manufacturer, some of the costs of this AD may be covered

under warranty, thereby reducing the cost impact on affected individuals. We

do not control warranty coverage for affected individuals. As a result, we

have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2013–22–07 The Boeing Company:
Amendment 39–17639; Docket No. FAA–2013–0667; Directorate Identifier 2013–NM–062–AD.

(a) Effective Date

This AD is effective December 5, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747–400 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of fasteners missing on an airplane undergoing a passenger-to-freighter conversion. We are issuing this AD to detect and correct missing or incorrect fasteners, which can lead to cracking and loss of load carrying capacity, resulting in a possible decompression event.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Except as required by paragraph (h)(1) of this AD, at the times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012: Do a general visual inspection for correct installation of the station 1920 splice clip common to the auxiliary sill web and the tie clip, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012, except as required by paragraph (h)(2) of this AD. Do all applicable related investigative and corrective actions before further flight.

(h) Exceptions to the Service Information

(1) Where Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012, specifies a compliance time "after the original issue date of the service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) If any cracking is found during any inspection required by this AD, and Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012, specifies contacting Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747–53A2844, dated September 15, 2011, except the detailed inspection for cracking of the auxiliary sill outer chord tee and attached parts and all applicable related investigative and corrective actions must be done in accordance with Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012, at the times specified in paragraph (g) of this AD. Boeing Alert Service Bulletin 747–53A2844, dated September 15, 2011, is not incorporated by reference in this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: *9-ANM-Seattle-ACO-AMOC-Requests@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6432; fax: 425–917–6590; email: *bill.ashforth@faa.gov*.

(2) Service information identified in this AD that is not incorporated by reference may be obtained at the addresses specified in paragraphs (i)(3) and (i)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747–53A2844, Revision 1, dated July 30, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial

Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 17, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-25308 Filed 10-30-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0543; Directorate Identifier 2012-NM-202-AD; Amendment 39-17610; AD 2013-20-04]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A318, A319, A320, and A321 series airplanes. This AD was prompted by a determination that certain special washers used in the bearing installation of the retraction jack anchorage fitting in the main landing gear (MLG) were incorrectly manufactured. This AD requires an inspection of the left-hand (LH) and right-hand (RH) bearing assemblies of the MLG retraction jack anchorage fitting to verify that the special washer is seated correctly, and related investigative and corrective actions if necessary. We are issuing this AD to detect and correct installation of incorrectly manufactured special washers, which could lead to a local stress concentration resulting in possible reduction of the fatigue life of the jack fitting, and consequent

reduction of the structural integrity of the affected MLG.

DATES: This AD becomes effective December 5, 2013.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of December 5, 2013.

ADDRESSES: You may examine the AD on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0543>; or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1405; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. The NPRM published in the **Federal Register** on July 1, 2013 (78 FR 39190). The NPRM proposed to correct an unsafe condition for the specified products.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2012-0223, dated October 23, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Airbus identified a batch of special washers, Part Number (P/N) D5725260120000 and P/N D5725664320000, which were incorrectly manufactured and delivered as spares from the supplier

between October 2006 and January 2010. As a result of these manufacturing defects, the affected washers differ geometrically from the design specifications. The results of further analyses on Airbus A318, A319, A320 and A321 aeroplanes demonstrate that the affected washers could be seated incorrectly when installed on aeroplanes, which could affect the main landing gear (MLG) retraction jack anchorage fitting bearing installation.

This condition, if not detected and corrected, could lead to a local stress concentration which may reduce the fatigue life of the jack fitting, possibly reducing the structural integrity of the affected MLG.

For the reasons described above, this [EASA] AD requires a one-time detailed visual inspection of the left-hand (LH) and right-hand (RH) MLG retraction jack anchorage fitting bearing assemblies to verify that the special washer is seated correctly and, depending on findings, the accomplishment of applicable [related investigative action and] corrective actions.

The related investigative action is a detailed inspection of the jack anchorage fitting for damage, corrosion, cracks or other defects. Corrective actions include replacing the special washer with a new special washer and repairing the jack anchorage fitting if there are signs of damage, corrosion, or other defects. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0543-0003>.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comment received. The commenter, Jeremy Schreck, supported the NPRM (78 FR 39190, July 1, 2013).

Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting this AD as proposed—except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 39190, July 1, 2013) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 39190, July 1, 2013).

Costs of Compliance

We estimate that this AD affects 851 airplanes of U.S. registry.

We estimate the following costs to comply with this AD: