

exemption or relieves a restriction; (2) interpretive rules and statements of policy; or (3) as otherwise provided by the agency for good cause found and published with the rule. 5 U.S.C. 553(d). At a minimum, the Bureau believes the amendments fall under the third exception to section 553(d). The Bureau finds that there is good cause to make the amendments effective on January 1, 2014. The amendment in this notice is technical and non-discretionary, and it applies the method previously established in the agency's regulations for automatic adjustments to the threshold.

Regulatory Flexibility Act

Because no notice of proposed rulemaking is required, the Regulatory Flexibility Act does not require an initial or final regulatory flexibility analysis. 5 U.S.C. 603(a), 604(a).

List of Subjects in 12 CFR Part 1026

Advertising, Consumer protection, Credit, Credit unions, Mortgages, National banks, Reporting and recordkeeping requirements, Savings associations, Truth in lending.

Authority and Issuance

For the reasons set forth in the preamble, the Bureau amends Regulation Z, 12 CFR part 1026, as set forth below:

PART 1026—TRUTH IN LENDING (REGULATION Z)

■ 1. The authority citation for part 1026 continues to read as follows:

Authority: 12 U.S.C. 2601, 2603–2605, 2607, 2609, 2617, 5511, 5512, 5532, 5581; 15 U.S.C. 1601 *et seq.*

■ 2. In Supplement I to part 1026—Official Interpretations, under *Section 1026.35—Requirements for Higher-Priced Mortgage Loans*, 35(b)(2) Exemptions, Paragraph 35(b)(2)(iii), paragraph 1.iii is revised.

The revision reads as follows:

Supplement I to Part 1026—Official Interpretations

* * * * *

Subpart E—Special Rules for Certain Home Mortgage Transactions

* * * * *

Section 1026.35—Requirements for Higher-Priced Mortgage Loans

* * * * *

35(b)(2) Exemptions.

* * * * *

Paragraph 35(b)(2)(iii)

1. Requirements for exemption. * * *

* * * * *

iii. As of the end of the preceding calendar year, the creditor had total assets that are less than the asset threshold for the relevant calendar year. For calendar year 2014, the asset threshold is \$2,028,000,000. Creditors that had total assets of less than \$2,028,000,000 on December 31, 2013, satisfy this criterion for purposes of the exemption during 2014. This asset threshold shall adjust automatically each year based on the year-to-year change in the average of the Consumer Price Index for Urban Wage Earners and Clerical Workers, not seasonally adjusted, for each 12-month period ending in November, with rounding to the nearest million dollars. The Bureau will publish notice of the asset threshold each year by amending this comment. For historical purposes, the prior asset threshold was:

A. For calendar year 2013, the asset threshold was \$2,000,000,000. Creditors that had total assets of less than \$2,000,000,000 on December 31, 2012, satisfied this criterion for purposes of the exemption during 2013.

* * * * *

Dated: December 24, 2013.

Richard Cordray,

Director, Bureau of Consumer Financial Protection.

[FR Doc. 2013–31225 Filed 12–26–13; 11:15 am]

BILLING CODE 4810-AM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2013–0370; Directorate Identifier 2013–NM–034–AD; Amendment 39–17711; AD 2013–26–02]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL–600–2C10 (Regional Jet Series 700, 701, & 702), CL–600–2D15 (Regional Jet Series 705), and CL–600–2D24 (Regional Jet Series 900) airplanes. This AD was prompted by a report that traces of oil could be found in the crew oxygen system due to the use of incorrect pressure testing procedures during manufacturing. This AD requires cleaning the crew oxygen system. We are issuing this AD to detect and correct oil contaminants, which could cause an ignition and result in a fire in the oxygen system.

DATES: This AD becomes effective February 3, 2014.

The Director of the Federal Register approved the incorporation by reference

of a certain publication listed in this AD as of February 3, 2014.

ADDRESSES: You may examine the AD on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0370>; or in person at the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE–171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228–7318; fax (516) 794–5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. The NPRM published in the **Federal Register** on May 10, 2013 (78 FR 27314). The NPRM proposed to correct an unsafe condition for the specified products.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF–2013–01, dated January 22, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

It was found that traces of oil could be present in the crew oxygen system due to the use of incorrect pressure testing procedures during manufacturing. Field sampling of nine aeroplanes have confirmed this condition. When the oxygen system is used, oil contaminants can cause an ignition and result in a fire in the oxygen system.

This [Canadian] AD mandates the cleaning of the crew oxygen system to reduce oil contaminants to a safe level.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/>

#!documentDetail;D=FAA-2013-0370-0002.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Request to Revise the NPRM (78 FR 27314, May 10, 2013) Based On New Service Information

ExpressJet requested the NPRM (78 FR 27314, May 10, 2013) be revised due to a new revision of the service information. ExpressJet stated that since the NPRM was issued, Bombardier Service Bulletin 670BA-35-012, Revision B, including Appendix A, dated May 6, 2013, has been released.

We agree with ExpressJet's request to use Bombardier Service Bulletin 670BA-35-012, Revision B, including Appendix A, dated May 6, 2013. We have updated paragraph (g) of this final rule in this regard. We have also added a new paragraph (h) to this final rule to give credit for actions done before the effective date of this AD using

Bombardier Service Bulletin 670BA-35-012, dated August 3, 2012; and Bombardier Service Bulletin 670BA-35-012, Revision A, dated November 26, 2012. Subsequent paragraphs have been redesignated accordingly.

Request to Revise the Compliance Time

The Air Line Pilots Association (ALPA) requested we revise the compliance time. ALPA stated it understands the requirements of the NPRM (78 FR 27314, May 10, 2013) take 51 work-hours per product, but stated that the safety benefit would necessitate a compliance time of between 12 and 24 months.

We do not agree with ALPA's request. We determined that the proposed compliance time of "within 6,600 flight hours or 36 months after the effective date of this AD, whichever occurs first" is appropriate in consideration of the safety implications, the average utilization rate of the affected fleet, and the practical aspects of an orderly cleaning of the crew oxygen system. In

addition, TCCA and Bombardier, Inc., reviewed the risks and found the compliance time to be adequate. We have not changed the final rule in this regard.

Conclusion

We reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 27314, May 10, 2013) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 27314, May 10, 2013).

Costs of Compliance

We estimate that this AD affects 400 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Cleaning the Crew Oxygen System	51 work-hours × \$85 per hour = \$4,335	\$827	\$5,162	\$2,064,800

Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/>

#!documentDetail;D=FAA-2013-0370-0002; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the MCAI, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2013–26–02 Bombardier, Inc.: Amendment 39–17711. Docket No. FAA–2013–0370; Directorate Identifier 2013–NM–034–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective February 3, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL–600–2C10 (Regional Jet Series 700, 701, & 702) airplanes, serial numbers 10002 through 10265 inclusive; and Model CL–600–2D15 (Regional Jet Series 705) and CL–600–2D24 (Regional Jet Series 900) airplanes, serial numbers 15002 through 15153 inclusive, 15156, and 15157; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by a report that traces of oil could be found in the crew oxygen system due to the use of incorrect pressure testing procedures during manufacturing. We are issuing this AD to detect and correct oil contaminants, which could cause an ignition and result in a fire in the oxygen system.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 6,600 flight hours or 36 months after the effective date of this AD, whichever occurs first: Clean the crew oxygen system, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA–35–012, Revision B, including Appendix A, dated May 6, 2013.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA–35–012, dated August 3, 2012; or Bombardier Service Bulletin 670BA–35–012, Revision A, dated November 26, 2012; which are not incorporated by reference in this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District

Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2013–01, dated January 22, 2013, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#/documentDetail;D=FAA-2013-0370-0002>.

(2) Service information identified in this AD that is not incorporated by reference may be obtained at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 670BA–35–012, Revision B, including Appendix A, dated May 6, 2013.

(ii) Reserved.

(3) For service information identified in this AD, Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 11, 2013.

John P. Piccola,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013–30288 Filed 12–27–13; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2013–0304; Directorate Identifier 2013–NM–005–AD; Amendment 39–17713; AD 2013–26–04]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747–400, –400D, and –400F series airplanes. This AD was prompted by a report of water leakage into the main deck cargo wire integration unit (WIU). The water flowed from the main deck floor panels, through disbonded seams in the aft main equipment center (MEC) drip shield gutter, then onto the WIU. This AD requires cleaning the aft MEC drip shield gutter; and doing a one-time general visual inspection for disbonded seams, and repair if necessary. This AD also requires installing a fiberglass reinforcement overcoat to the underside of the bonded seams of the aft MEC drip shield gutters. We are issuing this AD to prevent water penetration into the MEC, which could result in the loss of flight critical systems.

DATES: This AD is effective February 3, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 3, 2014.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.