

FIGURE 1 TO PARAGRAPH (G) OF THIS AD: ENGINE SHUT-OFF VALVE (FUEL SPAR VALVE) MOV ACTUATOR INSPECTION—Continued

AWL No.	Task	Interval	Applicability	Description
				<ol style="list-style-type: none"> <li>1. Make sure both Engine Control Switches are in the CUTOFF position.</li> <li>2. Inspect the left engine fuel spar valve actuator located in the left rear spar.               <ol style="list-style-type: none"> <li>a. Verify the manual override handle on the engine fuel spar valve actuator is in the CLOSED position.</li> <li>b. Repair or replace any MOV actuator that is not in the CLOSED position (refer to Boeing Airplane Maintenance Manual, 28-22-02).</li> </ol> </li> <li>3. Inspect the right engine fuel spar valve actuator located in the right rear spar.               <ol style="list-style-type: none"> <li>a. Verify the manual override handle on the engine fuel spar valve actuator is in the CLOSED position.</li> <li>b. Repair or replace any MOV actuator that is not in the CLOSED position (refer to Boeing Airplane Maintenance Manual, 28-22-02).</li> </ol> </li> </ol>

#### (h) No Alternative Actions and Intervals

After accomplishment of the maintenance or inspection program revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO) FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Related Information

For more information about this AD, contact Rebel Nichols, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: (425) 917-6509; fax: (425) 917-6590; email: [rebel.nichols@faa.gov](mailto:rebel.nichols@faa.gov).

Issued in Renton, Washington, on December 30, 2013.

**John P. Piccola,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-00234 Filed 1-9-14; 8:45 am]

**BILLING CODE 4910-13-P**

#### DEPARTMENT OF TRANSPORTATION

##### Federal Aviation Administration

##### 14 CFR Part 39

[Docket No. FAA-2008-1088; Directorate Identifier 2008-NE-15-AD]

RIN 2120-AA64

##### Airworthiness Directives; Dowty Propellers Propellers

###### Correction

In proposed rule document 2013-30882, appearing on pages 78290-78292, in the issue of Thursday, December 26, 2013, make the following correction:

On page 78290, in the first column, the subject heading is corrected to read as set forth above.

[FR Doc. C1-2013-30882 Filed 1-9-14; 8:45 am]

**BILLING CODE 1505-01-D**

#### DEPARTMENT OF TRANSPORTATION

##### Federal Aviation Administration

##### 14 CFR Part 39

[Docket No. FAA-2013-0164; Directorate Identifier 2013-NE-10-AD]

RIN 2120-AA64

##### Airworthiness Directives; Austro Engine GmbH Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede airworthiness directive (AD) 2013-14-08 that applies to all Austro Engine GmbH model E4 engines. AD 2013-14-08 requires removing from service certain part number (P/N) waste gate controllers. Since we issued AD 2013-14-08 we received several reports of power loss events due to fracture of the waste gate controller lever. This proposed AD would require removing certain P/N waste gate controllers from service. We are proposing this AD to prevent failure of the waste gate controller lever, which could lead to damage to one or more engines, loss of thrust control, and damage to the airplane.

**DATES:** We must receive comments on this proposed AD by March 11, 2014.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Austro Engine GmbH, Rudolf-Diesel-Strasse 11, A-2700 Weiner Neustadt, Austria; phone: +43 2622 23000; fax: +43 2622 23000-2711; Internet: [www.austroengine.at](http://www.austroengine.at). You may

view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2013-0164; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the mandatory continuing airworthiness information, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7779; fax: 781-238-7199; email: [frederick.zink@faa.gov](mailto:frederick.zink@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-0164; Directorate Identifier 2013-NE-10-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

##### Discussion

On July 10, 2013, we issued AD 2013-14-08, Amendment 39-17513 (78 FR 42677, July 17, 2013), ("AD 2013-14-08"), for all Austro Engine GmbH model E4 engines. AD 2013-14-08 requires removing from service certain P/N waste gate controllers. AD 2013-14-08 resulted from several reports of power loss events due to fracture of the waste gate controller lever. We issued AD

2013-14-08 to prevent failure of the waste gate controller lever, which could lead to damage to one or more engines, loss of thrust control, and damage to the airplane.

#### Actions Since AD 2013-14-08 Was Issued

Since we issued AD 2013-14-08, we received notification of additional waste gate controller P/Ns that require removal from service. Also since we issued AD 2013-14-08, the European Aviation Safety Agency (EASA) has issued AD 2013-0213, dated September 13, 2013, which requires removal and replacement of affected waste gate controllers. We also changed the unsafe condition statement in AD 2013-14-08 to clarify the relationship between the unsafe condition and the engine.

#### Relevant Service Information

We reviewed Austro Engine Mandatory Service Bulletin (MSB) No. MSB-E4-007/6, Revision 6, dated September 18, 2013. The service information describes procedures for removal and installation of the waste gate controllers.

#### FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

#### Proposed AD Requirements

This proposed AD would retain all of the requirements of AD 2013-14-08. This proposed AD would expand the applicability by adding additional P/Ns of affected waste gate controllers.

#### Costs of Compliance

We estimate that this proposed AD would affect 128 engines installed on airplanes of U.S. registry. We also estimate that it would take about 0.5 hours per engine to comply with this proposed AD. The average labor rate is \$85 per hour. Required parts cost about \$231 per engine. Based on these figures, we estimate the total cost of this proposed AD to U.S. operators to be \$35,008.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2013-14-08, Amendment 39-17513 (78 FR 42677, July 17, 2013), and adding the following new AD:

**Austro Engine GmbH Engines:** Docket No. FAA-2013-0164; Directorate Identifier 2013-NE-10-AD.

**(a) Comments Due Date**

The FAA must receive comments on this AD action by March 11, 2014.

**(b) Affected ADs**

This AD supersedes AD 2013-14-08, Amendment 39-17513 (78 FR 42677, July 17, 2013).

**(c) Applicability**

This AD applies to all Austro Engine GmbH model E4 engines, with a waste gate controller, part number (P/N) E4A-41-120-000, Revision 060, or lower revision; or a waste gate controller, P/N E4B-41-120-000, Revision 010, or lower revision, installed.

**(d) Unsafe Condition**

This AD was prompted by engine power loss events due to fracture of the waste gate controller lever. We are issuing this AD to prevent failure of the waste gate controller lever, which could lead to damage to one or more engines, loss of thrust control, and damage to the airplane.

**(e) Compliance**

(1) Comply with this AD within the compliance times specified, unless already done.

(2) At the next maintenance action for any reason, or within 110 flight hours after the effective date of this AD, or within three months after the effective date of this AD, whichever occurs first, remove from service waste gate controller, P/N E4A-41-120-000, Revision 060, or lower revision, and waste gate controller, P/N E4B-41-120-000, Revision 010 or lower revision.

**(f) Installation Prohibition**

After the effective date of this AD, do not install any waste gate controller, P/N E4A-41-120-000, Revision 060, or lower revision, or waste gate controller, P/N E4B-41-120-000, Revision 010, or lower revision, onto any engine, nor approve for return to service any engine that has either waste gate controller installed.

**(g) Alternative Methods of Compliance (AMOCs)**

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

**(h) Related Information**

(1) For more information about this AD, contact Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7779; fax: 781-238-7199; email: [frederick.zink@faa.gov](mailto:frederick.zink@faa.gov).

(2) Refer to MCAI European Aviation Safety Agency AD 2013-0213, dated September 13, 2013, for more information. You may examine the MCAI on the Internet at <http://www.regulations.gov/> #!documentDetail;D=FAA-2013-0164-0002.

(3) Austro Engine Mandatory Service Bulletin No. MSB-E4-007/6, Revision 6,

dated September 18, 2013, which is not incorporated by reference in this AD, can be obtained from Austro Engine GmbH, using the contact information in paragraph (h)(4) of this AD.

(4) For service information identified in this AD, contact Austro Engine GmbH, Rudolf-Diesel-Strasse 11, A-2700 Weiner Neustadt, Austria; phone: +43 2622 23000; fax: +43 2622 23000-2711; Internet: [www.austroengine.at](http://www.austroengine.at).

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on December 31, 2013.

**Colleen M. D'Alessandro,**

*Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2014-00169 Filed 1-9-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF JUSTICE**

**Drug Enforcement Administration**

**21 CFR Part 1308**

[Docket No. DEA-385]

**Schedules of Controlled Substances: Temporary Placement of Four Synthetic Cannabinoids Into Schedule I**

**AGENCY:** Drug Enforcement Administration, Department of Justice.  
**ACTION:** Notice of Intent.

**SUMMARY:** The Deputy Administrator of the Drug Enforcement Administration (DEA) is issuing this notice of intent to temporarily schedule four synthetic cannabinoids into Schedule I pursuant to the temporary scheduling provisions of the Controlled Substances Act (CSA). The substances are: quinolin-8-yl 1-pentyl-1*H*-indole-3-carboxylate (PB-22; QUPIC); quinolin-8-yl 1-(5-fluoropentyl)-1*H*-indole-3-carboxylate (5-fluoro-PB-22; 5F-PB-22); *N*-(1-amino-3-methyl-1-oxobutan-2-yl)-1-(4-fluorobenzyl)-1*H*-indazole-3-carboxamide (AB-FUBINACA); and *N*-(1-amino-3,3-dimethyl-1-oxobutan-2-yl)-1-pentyl-1*H*-indazole-3-carboxamide (ADB-PINACA). This action is based on a finding by the Deputy Administrator that the placement of these synthetic cannabinoids into Schedule I of the CSA is necessary to avoid an imminent hazard to the public safety. Any final order will impose the administrative, civil, and criminal sanctions and regulatory controls applicable to Schedule I substances under the CSA on the manufacture, distribution,

possession, importation, exportation, research, and conduct of instructional activities of these synthetic cannabinoids.

**DATES:** January 10, 2014.

**FOR FURTHER INFORMATION CONTACT:** Ruth A. Carter, Acting Chief, Policy Evaluation and Analysis Section, Office of Diversion Control, Drug Enforcement Administration; Mailing Address: 8701 Morrisette Drive, Springfield, Virginia 22152, Telephone (202) 598-6812.

**SUPPLEMENTARY INFORMATION:** Any final order will be published in the **Federal Register** and may not be effective prior to February 10, 2014.

**Background**

Section 201 of the CSA, 21 U.S.C. 811, provides the Attorney General with the authority to temporarily place a substance into Schedule I of the CSA for two years without regard to the requirements of 21 U.S.C. 811(b) if he finds that such action is necessary to avoid imminent hazard to the public safety. 21 U.S.C. 811(h). In addition, if proceedings to control a substance are initiated under 21 U.S.C. 811(a)(1), the Attorney General may extend the temporary scheduling for up to one year. 21 U.S.C. 811(h)(2).

Where the necessary findings are made, a substance may be temporarily scheduled if it is not listed in any other schedule under section 202 of the CSA, 21 U.S.C. 812, or if there is no exemption or approval in effect for the substance under section 505 of the Federal Food, Drug, and Cosmetic Act (FDCA), 21 U.S.C. 355. 21 U.S.C. 811(h)(1); 21 CFR part 1308. The Attorney General has delegated his authority under 21 U.S.C. 811 to the Administrator of the DEA, who in turn has delegated her authority to the Deputy Administrator of the DEA. 28 CFR 0.100, 0.104, Appendix to Subpart R of Part 0, Sec. 12.

Section 201(h)(4) of the CSA (21 U.S.C. 811(h)(4)) requires the Deputy Administrator to notify the Secretary of the Department of Health and Human Services (HHS) of his intention to temporarily place a substance into Schedule I of the CSA.<sup>1</sup> As PB-22, 5F-

<sup>1</sup> Because the Secretary of the HHS has delegated to the Assistant Secretary for Health of the HHS the authority to make domestic drug scheduling recommendations, for purposes of this Notice of Intent, all subsequent references to "Secretary" have been replaced with "Assistant Secretary." As set forth in a memorandum of understanding entered into by HHS, the Food and Drug Administration (FDA), and the National Institute on Drug Abuse (NIDA), FDA acts as the lead agency within HHS in carrying out the Assistant Secretary's scheduling responsibilities under the CSA, with the concurrence of NIDA. 50 FR 9518, Mar. 8, 1985.