

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2014-01-04 Bae Systems (Operations)

Limited: Amendment 39-17727. Docket No. FAA-2013-0793; Directorate Identifier 2012-NM-138-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective March 14, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bae Systems (Operations) Limited Model BAe 146-100A, -200A, and -300A airplanes; and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes; certificated in any category; all models, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire protection.

(e) Reason

This AD was prompted by reports of excess solder deposited during overhaul on the frangible plug of the extinguisher, which prevented the release of the extinguisher. We are issuing this AD to prevent the failure of a fire extinguisher to discharge, which reduces the ability of the fire protection system to extinguish fires in the engine or auxiliary power unit (APU) fire zones, possibly resulting in damage to the airplane and injury to the passengers.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection and Corrective Action

For airplanes equipped with fire extinguishers manufactured by Kidde Graviner Limited having part number (P/N) 57333 (all dash numbers): Within 12 months after the effective date of this AD, do an x-ray inspection to determine if there is solder between the operating head and container of the fire extinguishers in the engine and APU, in accordance with the Accomplishment Instructions of Bae Systems (Operations) Limited Inspection Service Bulletin ISB. 26-078, dated September 21, 2011; or Kidde Graviner Service Bulletin 26-080, Revision 1, dated July 27, 2011; as applicable.

(1) If any solder is found, before further flight, do the action specified in paragraph (g)(1)(i) or (g)(1)(ii) of this AD, in accordance

with the Accomplishment Instructions of Kidde Graviner Service Bulletin 26-080, Revision 1, dated July 27, 2011.

(i) Overhaul the fire extinguisher and install. An overhaul includes the replacement of the operating head.

Replacement of the pressure relief plug assembly only is not considered an overhaul.

(ii) Install a new fire extinguisher.

(2) If no solder is found, no further action is required by this paragraph.

(h) Parts Installation Limitation

As of the effective date of this AD, no person may install a Kidde Graviner Limited fire extinguisher having P/N 57333 (any dash number), on any airplane, unless the fire extinguisher is new, or it has been determined that there is no solder between the operating head and container of the fire extinguishers as required by paragraph (g) of this AD, or has been overhauled in accordance with the Accomplishment Instructions of Kidde Graviner Service Bulletin 26-080, Revision 1, dated July 27, 2011.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency (EASA) Airworthiness Directive 2012-0126R1, dated September 10, 2012, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#/documentDetail;D=FAA-2013-0793-0002>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bae Systems (Operations) Limited Inspection Service Bulletin ISB. 26-078, dated September 21, 2011.

(ii) Kidde Graviner Limited Service Bulletin 26-080, Revision 1, dated July 27, 2011.

(3) For Bae Systems (Operations) Limited service information identified in this AD, contact Bae Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(4) For Kidde Graviner service information identified in this AD, contact Kidde Graviner Limited, Mathisen Way, Colnbrook, Slough, Berkshire, SL3 0HB, United Kingdom; telephone +44 (0) 1753 683245; fax +44 (0) 1753 685040.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 7, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-02451 Filed 2-6-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0997; Directorate Identifier 2012-NM-060-AD; Amendment 39-17729; AD 2014-02-01]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2011-03-

13 for certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, and Model CL-600-2D24 (Regional Jet Series 900) airplanes. AD 2011-03-13 required repetitive inspections of the rudder travel limiter (RTL) return springs and primary actuator, and corrective actions if necessary. This new AD requires replacing certain RTL return springs, including doing related investigative and corrective actions, if necessary; which is terminating action for the repetitive inspections. This new AD also revises the applicability. This AD was prompted by reports of failure of the RTL return spring. We are issuing this AD to prevent failure of the RTL, which would permit an increase of rudder authority beyond normal structural limits and consequently affect the controllability of the airplane.

DATES: This AD becomes effective March 14, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 14, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of March 14, 2011 (76 FR 6539, February 7, 2011).

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2012-0997>; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

FOR FURTHER INFORMATION CONTACT: Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7318; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011). AD 2011-03-13 applied to certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, and Model CL-600-2D24 (Regional Jet Series 900) airplanes. The NPRM published in the **Federal Register** on September 24, 2012 (77 FR 58787). The NPRM was prompted by reports of failure of the RTL return spring. The NPRM proposed to continue to require repetitive inspections of the rudder travel limiter (RTL) return springs and primary actuator, and corrective actions if necessary. The NPRM also proposed to require replacing certain RTL return springs, including doing related investigative and corrective actions, if necessary. The NPRM also proposed to revise the applicability. We are issuing this AD to prevent failure of the RTL, which would permit an increase of rudder authority beyond normal structural limits and consequently affect the controllability of the airplane.

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, has issued Canadian Airworthiness Directive CF-2010-18R1, dated March 19, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Rudder Travel Limiter (RTL) return spring, part number (P/N) E0650-069-2750S, failed prior to completion of the required endurance test. In addition, the replacement RTL return spring, P/N 670-93465-1 (see Note) was found to be susceptible to chafing on the primary actuator, which could also result in eventual dormant spring failure. There are two return springs in the RTL and if both springs failed, a subsequent mechanical disconnect of the RTL components would result in an unannounced failure of the RTL. This, in turn, would permit an increase of rudder authority beyond normal structural limits and, in the event of a strong rudder input, the controllability of the aeroplane could be affected.

Note: RTL return springs, P/N 670-93465-1, were installed in production aeroplanes serial number 10266 (CL-600-2C10) and 15182 (CL-600-2D24) respectively and were introduced in-service by [Bombardier] Service Bulletin (SB) 670BA-27-047. [Bombardier] SB 670BA-27-047 has since been superseded by [Bombardier] SB 670BA-27-055.

This [TCCA] AD mandates repetitive [detailed] visual inspection of the RTL [for

broken] return springs and [damage through the casing or chafing of the casing of the] primary actuator, [and] replacement of parts as necessary.

This revision mandates the installation of the RTL return spring, P/N BA670-93468-1, as a terminating action to this [TCCA] AD.

This AD expands the applicability by adding Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplane, serial number 10002. This AD also reduces the applicability by removing Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes serial numbers 10334 and subsequent; and also removes Model CL-600-2D15, serial numbers 15289 and subsequent. The installation consists of replacing certain RTL return springs with new springs and doing related investigative and corrective actions, if necessary. The related investigative action is a detailed inspection of the casing of the primary actuator for signs of chafing or missing paint. Corrective actions include replacing any broken return spring with a new spring, repairing any chafing of the primary actuator on its casing, and replacing any primary actuator that has damage through its casing with a new actuator. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2012-0997-0003>.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Request To Correct Service Information

Mesa Air Lines Inc. (Mesa) requested that we correct a step sequence in Bombardier Service Bulletin 670BA-27-059, Revision A, dated March 8, 2012. Mesa stated that step (6) of the job set-up section, in Bombardier Service Bulletin 670BA-27-059, Revision A, dated March 8, 2012, specifies installing the rig pin. Mesa stated that it is not until step (10) that Bombardier Service Bulletin 670BA-27-059, Revision A, dated March 8, 2012, specifies removing panels 325DL and 325EL, and that removing these panels is necessary to install the rig pin.

We agree with the commenter's request regarding the incorrect step sequence. The manufacturer has issued Revision B to Bombardier Service Bulletin 670BA-27-059, dated September 26, 2013, which corrects the step sequence. We have revised paragraph (j) of this final rule to reference Bombardier Service Bulletin 670BA-27-059, Revision B, dated September 26, 2013; and added Bombardier Service Bulletin 670BA-27-

059, Revision A, dated March 8, 2012, to paragraph (k)(2) in this final rule to provide credit for the actions required by paragraph (j) of this AD, if those actions were performed before the effective date of this AD.

Request To Clarify Part Information

Mesa observed that Bombardier Service Bulletin 670BA-27-059, Revision A, dated March 8, 2012, does not mention, reference, or address part number (P/N) BA670-93470-5 (rudder travel limiter). Mesa asked whether Bombardier Service Bulletin 670BA-27-059, Revision A, dated March 8, 2012, or the proposed AD (77 FR 58787, September 24, 2012) applies to its airplanes, since the service information does not reference P/N BA670-93470-5.

We agree that clarification is necessary. Only paragraph (j) of this final rule refers to Bombardier Service Bulletin 670BA-27-059, Revision B,

dated September 26, 2013. Paragraph (j) of this final rule affects airplanes having parts identified in paragraphs (j)(1) and (j)(2) of this final rule, and P/N BA670-93470-5 is not identified. Therefore, operators are not required to do the actions specified in paragraph (j) of this final rule on airplanes having P/N BA670-93470-5.

However, airplanes having P/N BA670-93470-5 are still affected by this final rule. This AD applies to airplanes having serial numbers identified in paragraph (c) of this final rule; paragraph (c) of this final rule does not exclude airplanes having specific parts. All operators of the airplanes identified in applicability of this final rule must show compliance with the provisions of this final rule, including a determination that specific paragraphs do not apply. We have not changed this final rule in this regard.

Conclusion

We reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these changes:

- Are consistent with the intent that was proposed in the NPRM (77 FR 58787, September 24, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (77 FR 58787, September 24, 2012).

Costs of Compliance

We estimate that this AD affects 366 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection [actions retained from AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011)].	2 work-hours × \$85 per hour = \$170 per inspection cycle.	\$0	\$170 per inspection cycle	\$62,220 per inspection cycle.
Replacement [new action]	8 work-hours × \$85 per hour = \$680.	1,291	\$1,971	\$721,386.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between

the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2012-0997-0003>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone

(800) 647-5527) is in the ADDRESSES section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011), and adding the following new AD:

2014-02-01 Bombardier, Inc.: Amendment 39-17729. Docket No. FAA-2012-0997; Directorate Identifier 2012-NM-060-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective March 14, 2014.

(b) Affected ADs

This AD supersedes AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011).

(c) Applicability

This AD applies to the Bombardier, Inc. airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, serial numbers 10002 through 10333 inclusive.

(2) Model CL-600-2D15 (Regional Jet Series 705) airplanes; and Model CL-600-2D24 (Regional Jet Series 900) airplanes, serial numbers 15001 through 15288 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports of failure of the rudder travel limiter (RTL) return spring. We are issuing this AD to prevent failure of the RTL, which would permit an increase of rudder authority beyond normal structural limits and consequently affect the controllability of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Initial Inspections and Replacement/Repair for Certain Airplanes

This paragraph restates the requirements of paragraph (g) of AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011). Except for Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplane, serial number 10002, for airplanes that have accumulated 4,000 or less total flight hours as of March 14, 2011 (the effective date of AD 2011-03-13): Before the accumulation of 6,000 total flight hours, do a detailed inspection of the RTL for broken return springs and damage through the casing, or chafing of the casing of the primary actuator, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010. Before further flight, replace any broken return springs with new springs, and repair or replace with a new actuator any chafed or damaged primary actuator, as applicable, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010. Repeat the inspection thereafter at intervals not to exceed 6,000 flight hours. Accomplishment of the actions required by paragraph (j) of this AD terminates the requirements of this paragraph.

(h) Retained Initial Inspections and Replacement/Repair for Certain Higher Flight Time Airplanes

This paragraph restates the requirements of paragraph (h) of AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011). Except for Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplane, serial number 10002, for airplanes that have accumulated more than 4,000 total flight hours as of March 14, 2011 (the effective date of AD 2011-03-13): Within 2,000 flight hours after March 14, 2011 (the effective date of AD 2011-03-13), do a detailed inspection of the RTL for broken return springs and damage through the casing, or chafing of the casing of the primary actuator, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010. Before further flight, replace any broken return springs with new springs, and repair or replace any chafed or damaged primary actuator with a new actuator, as applicable, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010. Repeat the inspection thereafter at intervals not to exceed 6,000 flight hours. Accomplishment of the actions required by paragraph (j) of this AD terminates the requirements of this paragraph.

(i) New RTL Spring Inspection and Replacement for a Certain Airplane

For Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplane, serial number 10002, at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD: Do a detailed inspection of the RTL for broken return springs and damage through the casing, or chafing of the casing of the primary actuator, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010. Before further flight, replace any broken return springs with new springs, and repair or replace with a new actuator any chafed or damaged primary actuator, as applicable, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010. Repeat the inspection thereafter at intervals not to exceed 6,000 flight hours. Accomplishment of the applicable actions required by paragraph (j) of this AD terminates the requirements of this paragraph.

(1) If the airplane has accumulated 4,000 or less total flight hours as of the effective date of this AD: Before the accumulation of 6,000 total flight hours.

(2) If the airplane has accumulated more than 4,000 total flight hours as of the effective date of this AD: Within 2,000 flight hours after the effective date of this AD.

(j) New RTL Spring Replacement

At the applicable time specified in paragraph (j)(1) or (j)(2) of this AD: Replace the RTL return springs with new springs, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-059, Revision B, dated September 26, 2013. Do all applicable

related investigative and corrective actions before further flight. Accomplishment of the applicable actions required by this paragraph terminates the requirements of paragraphs (g), (h), and (i) of this AD.

(1) For airplanes with RTL return springs having part number (P/N) 670-93465-1: Within 6,000 flight cycles after the effective date of this AD.

(2) For airplanes with RTL return springs having P/N E0650-069-2750S: At the applicable time specified in paragraph (j)(2)(i), (j)(2)(ii), or (j)(2)(iii) of this AD.

(i) For airplanes with 15,400 total flight cycles or more as of the effective date of this AD: Within 2,000 flight cycles after the effective date of this AD.

(ii) For airplanes with 5,200 total flight cycles or more, but less than 15,400 total flight cycles as of the effective date of this AD: Within 5,000 flight cycles after the effective date of this AD, but not to exceed 17,400 total flight cycles.

(iii) For airplanes with less than 5,200 total flight cycles as of the effective date of this AD: Before accumulating 10,200 total flight cycles.

(k) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before March 14, 2011 (the effective date of AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011)), using Bombardier Service Bulletin 670BA-27-055, dated May 11, 2010, which is not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions required by paragraph (j) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA-27-059, dated October 12, 2011; or Bombardier Service Bulletin 670BA-27-059, Revision A, dated March 8, 2012; which are not incorporated by reference in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 2011-03-13, Amendment 39-16597 (76 FR 6539, February 7, 2011), are approved as AMOCs for this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they

are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2010-18R1, dated March 19, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/>

#!documentDetail;D=FAA-2012-0997-0003.

(2) Service information identified in this AD that is not incorporated by reference may be obtained at the addresses specified in paragraphs (n)(5) and (n)(6) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on March 14, 2014.

(i) Bombardier Service Bulletin 670BA-27-059, Revision B, dated September 26, 2013.

(ii) Reserved.

(4) The following service information was approved for IBR on March 14, 2011 (76 FR 6539, February 7, 2011).

(i) Bombardier Service Bulletin 670BA-27-055, Revision A, dated August 6, 2010.

(ii) Reserved.

(5) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 10, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-02468 Filed 2-6-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0039; Directorate Identifier 2013-SW-058-AD; Amendment 39-17737; AD 2014-02-09]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France (Eurocopter) Helicopters

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter Model EC225LP and AS332L1 helicopters with emergency floatation gear. The AD requires, before the next overwater flight, inspecting the strap installation on the hinged rods of the emergency floatation gear on both rear cradles for correct installation. If a strap is installed under the hinged rod median plate rather than over it, reinstalling the strap is required. The AD is prompted by incorrect routing of the straps on the hinged rods of the emergency floatation gear rear cradles. The actions are intended to detect incorrect strap installation and prevent failure of the rods or straps upon deployment of the emergency floatation gear, incorrect float position, and subsequent capsizing of the helicopter.

DATES: This AD becomes effective February 24, 2014.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of February 24, 2014.

We must receive comments on this AD by April 8, 2014.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Docket:** Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- **Fax:** 202-493-2251.

- **Mail:** Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.

- **Hand Delivery:** Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>

or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) AD, any incorporated by reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

FOR FURTHER INFORMATION CONTACT: Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email gary.b.roach@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments prior to it becoming effective. However, we invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that resulted from adopting this AD. The most helpful comments reference a specific portion of the AD, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit them only one time. We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this rulemaking during the comment period. We will consider all the comments we receive and may conduct additional rulemaking based on those comments.

Discussion

We are adopting a new AD for Eurocopter Model EC225LP and