

**(e) Required Actions**

(1) Within 5 hours time in service (TIS), and thereafter at intervals not to exceed 25 hours TIS, visually inspect the swashplate outer ring, P/N 412-010-407-105, for a crack, using a 5X or higher power magnifying glass and a bright light and referring to Figures 1 and 2 in AgustaWestland S.p.A. Alert Bollettino Tecnico No. 412-134, dated July 15, 2013. If a crack exists, before further flight, remove the swashplate outer ring from service.

(2) Within 300 hours TIS or 8 months, whichever occurs first, remove the swashplate outer ring, P/N 412-010-407-105, from service.

(3) Do not install a swashplate outer ring, P/N 412-010-407-105, on any helicopter.

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD No. 2013-0152-E, dated July 17, 2013. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2014-0035.

**(h) Subject**

Joint Aircraft Service Component (JASC) Code: 6230, Main Rotor Mast/Swashplate.

**(i) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) AgustaWestland S.p.A. Alert Bollettino Tecnico No. 412-134, dated July 15, 2013.

(ii) Reserved.

(3) For AgustaWestland service information identified in this AD, contact AgustaWestland, Customer Support & Services, Via Per Tornavento 15, 21019 Somma Lombardo (VA) Italy, ATTN: Giovanni Cecchelli; telephone 39-0331-711133; fax 39-0331-711180; or at <http://www.agustawestland.com/technical-bulletins>.

(4) You may view this service information that is incorporated by reference at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the

availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on January 16, 2014.

**Lance T. Gant,**

*Acting Directorate Manager, Rotorcraft Directorate,*

Aircraft Certification Service.  
[FR Doc. 2014-01956 Filed 2-24-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2013-0699; Directorate Identifier 2012-NM-198-AD; Amendment 39-17751; AD 2014-03-13]**

**RIN 2120-AA64**

**Airworthiness Directives; Fokker Services B.V. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes. This AD was prompted by three reports of cracking in the rear pressure bulkhead (RPBH) web. This AD requires inspecting the RPBH web for cracking, and repairing if necessary. We are issuing this AD to detect and correct cracking of the RPBH web, which could result in in-flight decompression of the airplane and possible injury to the occupants.

**DATES:** This AD becomes effective April 1, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 1, 2014.

**ADDRESSES:** You may examine the AD on the Internet at <http://www.regulations.gov> /*#!docketDetail;D=FAA-2013-0699*; or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box

1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email [technicalservices@fokker.com](mailto:technicalservices@fokker.com); Internet <http://www.myfokkerfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes. The NPRM published in the **Federal Register** on August 23, 2013 (78 FR 52465). The NPRM was prompted by three reports of cracking in the rear pressure bulkhead (RPBH) web. The NPRM proposed to require inspecting the RPBH web for cracking, and repairing if necessary. We are issuing this AD to detect and correct cracking of the RPBH web, which could result in in-flight decompression of the airplane and possible injury to the occupants.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2012-0219, dated October 19, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Three reports have been received of a crack in the rear pressure bulkhead (RPBH) web, just below the horizontal beam XI between buttock lines BL425L and BL425R, in the centre web bay below the pressure relief valves.

This condition, if not detected and corrected, could result in an exponential crack growth rate, possibly leading to failure of the affected RPBH web, resulting in in-flight decompression of the aeroplane and possible injury to occupants.

A repetitive inspection requirement has been published in issue 10 of Fokker Services [Airworthiness Limitations Section] ALS Report SE-623 under task number 534106-00-05. The threshold to start this ALS-task is 30,000 [total] flight cycles (FC). However, it is known that many aeroplanes have already exceeded this threshold.

For the reasons described above, this [EASA] AD requires a one-time inspection [detailed visual or high frequency eddy current inspection] of the affected RPBH web for cracks and, depending on findings, accomplishment of a repair. The repair can also be applied at any time as a modification, thereby exempting the aeroplane from (further) repetitive ALS task 534106–00–05 inspections.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0699-0002>.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (78 FR 52465, August 23, 2013) or on the determination of the cost to the public.

**Conclusion**

We reviewed the available data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 52465, August 23, 2013) for correcting the unsafe condition; and

- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 52465, August 23, 2013).

**Costs of Compliance**

We estimate that this AD affects 4 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection .....	5 work-hours X \$85 per hour = \$425 .....	\$0	\$425	\$1,700

We estimate the following costs to do any necessary repairs that would be

required based on the results of the inspection. We have no way of

determining the number of aircraft that might need these repairs:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
On-condition inspection and repair .....	16 work-hours × \$85 per hour = \$1,360 .....	\$0	\$1,360

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**Examining the AD Docket**

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0699>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the MCAI, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647–5527) is in the ADDRESSES section.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new AD:

**2014–03–13 Fokker Services B.V.:**

Amendment 39–17751. Docket No. FAA–2013–0699; Directorate Identifier 2012–NM–198–AD.

**(a) Effective Date**

This airworthiness directive (AD) becomes effective April 1, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category, as identified in Fokker Service Bulletin SBF100–53–120, dated May 15, 2012.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Reason**

This AD was prompted by three reports of cracking in the rear pressure bulkhead (RPBH) web. We are issuing this AD to detect and correct cracking of the RPBH web, which could result in in-flight decompression of the airplane and possible injury to the occupants.

**(f) Compliance**

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**(g) Inspection**

Before the accumulation of 30,000 total flight cycles, or within 12 months after the effective date of this AD, whichever occurs later: Do the actions specified in paragraph (g)(1) or (g)(2) of this AD.

(1) Do a detailed inspection for cracking of the rear side of the RPBH web below beam XI between buttock line (BL) 425L and BL 425R, in accordance with PART 1 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-120, dated May 15, 2012.

(2) Do a high frequency eddy current (HFEC) inspection for cracking of the forward side of the RPBH web below beam XI between BL 425L and BL 425R, in accordance with PART 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-120, dated May 15, 2012.

**Note 1 to paragraph (g) of this AD:** Fokker Services All Operators Message AOF100.176, dated May 15, 2012; and AOF100.178, dated September 10, 2012; provide additional information concerning the subject addressed by this AD.

**(h) On-Condition Inspection and Repair**

(1) If any cracking is found during the inspections specified in paragraph (g)(1) or (g)(2) of this AD: Before further flight, repair the cracking, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-121, dated May 15, 2012.

(2) For any airplane inspected as specified in paragraph (g)(1) of this AD and no cracking was found: Within 12 months after that inspection, do the HFEC inspection specified in PART 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-120, dated May 15, 2012. If any cracking is found: Before further flight, repair the cracking, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-121, dated May 15, 2012.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**(j) Related Information**

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency (EASA) Airworthiness Directive 2012-0219, dated October 19, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0699-0002>.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-53-120, dated May 15, 2012.

(ii) Fokker Service Bulletin SBF100-53-121, dated May 15, 2012.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email [technicalservices@fokker.com](mailto:technicalservices@fokker.com); Internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 29, 2014.

**John P. Piccola,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-02782 Filed 2-24-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2013-0670; Directorate Identifier 2013-NM-081-AD; Amendment 39-17756; AD 2014-03-19]**

**RIN 2120-AA64**

**Airworthiness Directives; the Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -800, -900, and -900ER series airplanes modified by particular supplemental type certificates (STCs). This AD was prompted by reports of cracks found during inspections of the in-flight entertainment system radome assembly. This AD requires repetitive detailed inspections for cracks in the radome assembly, and replacement of the radome if necessary. We are issuing this AD to detect and correct cracks in the in-flight entertainment system radome assembly, which could result in the radome (or pieces) separating from the airplane and striking the tail, and consequently reducing the controllability of the airplane.

**DATES:** This AD is effective April 1, 2014.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 1, 2014.

**ADDRESSES:** For service information identified in this AD, contact Live TV, 8900 Hangar Boulevard, Orlando, FL 32827; phone: 407-812-2600; fax: 407-812-2526; Internet <http://www.livetv.net>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://>