

- Reported thermal damage was limited to melting of the headlamp harness and/or the headlamp housing.
- Frequently, a headlamp would intermittently fail to illuminate or flickered before becoming completely inoperative.

For the seventeen complaints that alleged simultaneous failure of both headlamps while attempting to turn them on or while driving, the headlamp failures likely had occurred one at a time—the subject vehicle's headlamps are connected in a parallel circuit and each circuit is fused independently. Therefore, failure of one headlamp or its harness is very unlikely to affect the other headlamp's operation. Furthermore, during the agency's headlamp failure investigation PE09–019, a random sample of consumers was contacted by ODI in a telephone survey to verify their experiences. Though the consumers stated in complaints to the manufacturer that both headlamps failed at the same time, ODI discovered through its interviews of these complainants that, in fact, one headlamp would begin to flicker and then cut off while the other headlamp remained operational. In a few cases where no action was taken by the complainants, the second headlamp failed several months later; however none of those surveyed could confirm that both headlamps failed to illuminate simultaneously. There is no reason to believe this is not applicable to the subject vehicles as well.

#### Technical Service Bulletin

In May of 2009, General Motors Corporation (GM) issued Technical Bulletin #09–08–42–004 applicable to the MY 2007–2009 Saturn Outlook vehicles. The Subject: “Low Beam Headlamp Replacement/Diagnosis (Inspect Fuse, Bulb, Harness, Replace Harness and Fill Connector Cavity for Low Beam Bulb Connector with Nyogel Grease).” The bulletin provides corrective actions to address the condition that some customers describe as the low beam headlamp bulb being inoperative. A reduction of consumer complaints accompanied release of this bulletin, suggesting that the repair cost concerns on the part of many of the complainants were addressed.

#### Investigation Precedent

ODI previously opened two defect investigations concerning inoperative headlamps due to overheating and melting of headlamp harness—failures very similar to those described by owner of the subject vehicle. Both investigations were closed without a recall because a safety-related defect

trend was not identified. The closing resume summary of PE04–020 stated: “Nissan and Ford found that the original equipment headlight stainless steel bulb terminals may over time cause elevated contact resistance and overheat the electrical connector housing. This can result in a headlight flickering, bulb outage and heat deformation to the headlight connector.

This problem can affect independently either headlight but does not cause simultaneous failure of both headlights. The problem also does not affect front parking lamps. As a result, the complaints typically report single failure of one headlight. There were no crashes or loss of vehicle control reported.”

In another previous investigation of headlamp harness failure (PE05–007), the closing resume summary stated: “Improper installation of the original equipment headlight connector can cause increased terminal resistance and overheat the headlight connector.

This problem can affect independently either headlight but does not cause simultaneous failure of both headlights. The problem also does not affect front parking lamps. As a result, the complaints typically report single failure of one headlight. There were no crashes or loss of vehicle control reported.”

#### Customer Satisfaction Program

In December of 2011, GM issued a Customer Satisfaction Program (CSP), Bulletin No. 11055 that applies to the subject vehicles. GM notified the owners to bring their vehicles to a GM dealer to have the headlamp connectors and the low beam headlamp bulbs replaced at no charge through 2013. Shortly after issuance of the more recent GM bulletin, related complaints to NHTSA decreased significantly from over a hundred annually to 21 for calendar year (CY) 2012, 33 for CY 2013 and only 11 (year-to-date) as of July 16, 2014.

#### Conclusion

Based on the information currently available, NHTSA does not believe that the headlamp condition as alleged by the petitioner indicates the likelihood of a safety-related defect that would warrant a formal investigation. Therefore, in view of the need to allocate and prioritize NHTSA's limited resources to best accomplish the agency's safety mission, the petition is denied.

**Authority:** 49 U.S.C. 30162(d); delegations of authority at CFR 1.50 and 501.8.

**Nancy Lummen Lewis,**

*Associate Administrator for Enforcement.*

[FR Doc. 2014–17984 Filed 7–30–14; 8:45 am]

**BILLING CODE 4910–59–P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

#### Denial of Motor Vehicle Defect Petition, DP13–002

**AGENCY:** National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

**ACTION:** Denial of petition for a defect investigation.

**SUMMARY:** This notice states the reasons for denying a Defect Petition (DP) (DP 13–002) submitted under 49 CFR parts 552 by Ms. Jessie A. Powell of Middleboro, MA (petitioner) in a January, 2013 letter to the Administrator of NHTSA (the “Agency”). The petitioner requested that the Agency open an investigation into software and brake failures on model year (MY) 2012 Toyota Prius C vehicles (the “Subject Vehicles”).

After reviewing materials in-hand, those furnished by the petitioner, and upon completing an inspection of her vehicle, NHTSA sees no indication that additional investigation would lead to a finding that a defect related to motor vehicle safety exists. NHTSA has concluded that further investigation of the issue raised in the petition is not warranted. The Agency accordingly has denied the petition.

**FOR FURTHER INFORMATION CONTACT:** Mr. Jeff Price, Office of Defects Investigation (ODI), NHTSA; 1200 New Jersey Avenue SE., Washington, DC 20590. Telephone: (202) 366–5410. Email: [jeffrey.price@dot.gov](mailto:jeffrey.price@dot.gov).

#### SUPPLEMENTARY INFORMATION:

##### Introduction

Pursuant to 49 CFR 552.1, interested persons may petition NHTSA requesting that the Agency initiate an investigation to determine whether a motor vehicle or item of replacement equipment does not comply with an applicable motor vehicle safety standard or contains a defect that relates to motor vehicle safety. Upon receipt of a properly filed petition, the Agency conducts a technical review (§ 552.6) of the petition, material submitted with the petition, and any appropriate additional information. After considering the technical review and taking into

account appropriate factors, which may include, among others, allocation of Agency resources, Agency priorities, and the likelihood of success in litigation that might arise from a determination of noncompliance or a defect related to motor vehicle safety, the Agency will grant or deny the petition (§ 552.8).

**Background Information**

*Petition Overview*

On January 3, 2013, NHTSA received a letter (ODI No. 10487746) from Ms. Jessie A. Powell petitioning the agency to investigate drivability and braking concerns in the subject vehicle.

*Petition Main Points*

The petition expressed two concerns:

1. "The first software problem was when the vehicle shifted from battery to motor and caused such impact, I initially believed the vehicle had been struck in the rear."
2. "The next more alarming problem was NO BRAKES. The brake pedal traveled to the floor and a dashboard warning light flashed."

This symptom occurred twice, leading to the vehicle being towed to the dealership, the second time in the dealership parking lot after diagnostics of the first incident.

**ODI Analysis of the Defect Petition Request**

ODI's petition review included the following;

- Review of the petition and its enclosures;
- Assessment of petition vehicle history;
- Inspection of the Petitioners vehicle on April 4, 2013;
- Inspection of an additional complaint vehicle in June of 2013; and
- Review of potentially related VOQs.

*Powell Vehicle History*


- Mar 3, 2012—Build Date (DTC History)
- Apr 23, 2012—10 mi Date of First Use (DTC History/Vehicle History Report)
- Apr 27, 2013—110 mi Passed Safety Inspection (Vehicle History Report)
- May 8, 2012—Rough transition from battery to motor (Petition)
- May 15, 2012—Brake pedal to floor, dashboard warning light, behavior repeated at home, and vehicle towed to dealership (Petition)<sup>1</sup>
- May 17, 2012 841 mi—DTC pulled: U0151, U0293, U0100, P3000, U0101 Same brake symptoms as previous, at dealership (Petition)
- Apr 4, 2013 831 mi—Vehicle inspection by NHTSA and Toyota representatives
- On Apr 4, 2013, ODI met with the petitioner, representatives from Toyota, and legal counsel for both parties at a Toyota dealership. Included in the visit were an interview of the petitioner, basic inspection of the subject vehicle, and test drives of the subject vehicle and an exemplar.

Ms. Powell was interviewed to collect specific details concerning her complaint and then accompanied by NHTSA personnel while she test-drove her vehicle in the same dealership

parking lot, duplicating the complaint condition. NHTSA personnel also drove the vehicle with Ms. Powell present and experienced the complaint condition. Specifically, the vehicle was test driven according to the same driving cycle described by the owner. The condition was found to be normal operation of the "hill holder" feature of the vehicle. The dashboard warning light Ms. Powell referred to in her complaint was the flashing light described in the "Hill Holder" operation section of the owner's manual. This function allows the vehicle brake system to apply brakes to keep the vehicle from rolling backwards while on a hill. This vehicle feature was explained to Ms. Powell by NHTSA personnel. Ms. Powell neither accepted nor denied the explanation of what was occurring in her vehicle. At no time was there any "jolt" from the battery during the transition from battery to gas engine operation. The vehicle was then put on a hoist where the vehicle powertrain, brake systems and complete electrical system were checked. All computer systems were checked for Diagnostic Trouble Codes. The codes found were due to a discharged battery. This vehicle had been parked and unused for many months, requiring a jump start to move it into position for the inspection.

Hill Assist Control (HAC), a feature intended to prevent the vehicle from rolling backwards when starting from a stationary position on an incline, is described in the Prius C Quick Start Guide and Owner's Manual:

Quick Start Guide (p. 23):




HAC helps prevent rolling backwards on an incline. To engage, push further down on brake pedal while at a complete stop until a beep sounds and slip indicator illuminates. HAC holds for approximately two seconds after releasing brake pedal. Refer to the *Owner's Manual* for more details.

Owner's Manual (p. 222 – 223):

<sup>1</sup>Note—Improper mileage of 841 entered by Dealership on May 15, 2012. Correct mileage 831

miles on May 15, 2012 and inspection date Apr 4, 2013.

**Assists with starting off and temporarily maintains braking power even if the foot is removed from the brake pedal when starting off on an incline or a slippery slope.**



To engage hill-start assist control, further depress the brake pedal when the vehicle is stopped completely.

A buzzer will sound once to indicate the system is activated. The slip indicator will also start flashing.

#### ■ Hill-start assist control operating conditions

- The system operates in the following situations:
  - The shift lever is in a position other than P.
  - The parking brake is not applied.
  - The accelerator pedal is not depressed.
- Hill-start assist control cannot be operated while the slip indicator light is illuminated.

#### ■ Hill-start assist control

- While hill-start assist control is operating, the brakes remain automatically applied after the driver releases the brake pedal. The stop lights and the high mounted stoplight turn on.
- Hill-start assist control operates for about 2 seconds after the brake pedal is released.
- If the slip indicator does not flash and the buzzer does not sound when the brake pedal is further depressed, slightly reduce the pressure on the brake pedal (do not allow the vehicle to roll backward) and then firmly depress it again. If the system still does not operate, check that the operating conditions explained above have been met.

■ Hill-start assist control buzzer


- When hill-start assist control is activated, the buzzer will sound once.
- In the following situations, hill-start assist control will be canceled and the buzzer will sound twice.
  - No attempt is made to drive the vehicle within approximately 2 seconds of releasing the brake pedal.
  - The shift lever is moved to P.
  - The parking brake is applied.
  - The brake pedal is depressed again.
  - The brake pedal has been depressed for more than approximately 3 minutes.
- If a buzzer other than the hill-start assist control buzzer is sounding, the hill-start assist control buzzer may not sound.

■ If the slip indicator comes on

It may indicate a malfunction in the system. Contact your Toyota dealer.

2

When driving

 **CAUTION**

■ Hill-start assist control

- Do not overly rely on hill-start assist control. Hill-start assist control may not operate effectively on steep inclines and roads covered with ice.
- Unlike the parking brake, hill-start assist control is not intended to hold the vehicle stationary for an extended period of time. Do not attempt to use hill-start assist control to hold the vehicle on an incline, as doing so may lead to an accident.

*VOQs Pertaining to the 2012 Prius*

All 133 consumer complaints filed with NHTSA as of July 16, 2014 for the three MY 2012 Prius variants<sup>2</sup> (only four pertained to the Prius C variant subject to this petition) were reviewed for signs of the jolting symptom cited early in the petition. None of them indicated experiencing jolting sensations in routine driving similar to those reported by the petitioner.

Further review identified no trend of the brake behavior reported by the petitioner (brake pedal to the floor along with the VSC light).

*Discussion*

After a test drive and vehicle inspection, no actionable problem was found within the petitioner’s vehicle.

The braking concern reported turned out to be normal vehicle operation. Broader review of the consumer complaints reported for all variants of the subject vehicle showed no indication that either the reported jolting sensation or the brake performance concerns reported are occurring in this vehicle population at a level that would require investigative action by NHTSA.

The petitioner identified other complaints of poor braking performance and low brake pedal received by NHTSA concerning Prius models. The following recalls by Toyota were to address many of these complaints. Neither of these recalls is applicable to Ms. Powell’s 2012 Prius C.

1. Recall 10V–039 March 5, 2010—Reprogramming ABS ECU—Improve

Antilock brake function over bumpy surfaces.

2. Recall 13V–235 August 7, 2013—Replace Brake Booster/Pump assembly—Low brake pedal due to nitrogen bubble in hydraulic portion of brake system.

**Conclusion**

In the Agency’s view, additional investigation is unlikely to result in a finding that a defect related to motor vehicle safety exists. Therefore, in view of the need to allocate and prioritize NHTSA limited resources to best accomplish the Agency’s safety mission, the petition is denied. This action does not constitute a finding by NHTSA that a safety-related defect does not exist. The Agency will take further action if warranted by future circumstances.

<sup>2</sup>Prius, Prius C, Prius V.

**Authority:** 49 U.S.C. 30162(d); delegations of authority at CFR 1.95 and 501.8.

**Nancy Lummen Lewis,**

*Associate Administrator for Enforcement.*

[FR Doc. 2014-17983 Filed 7-30-14; 8:45 am]

**BILLING CODE 4910-59-P**

---

## DEPARTMENT OF THE TREASURY

### Bureau of the Fiscal Service

#### Proposed Collection of Information: TreasuryDirect System

**ACTION:** Notice and request for comments.

**SUMMARY:** The Department of the Treasury, as part of its continuing effort to reduce paperwork and respondent burden, invites the general public and other Federal agencies to take this opportunity to comment on proposed and/or continuing information collections, as required by the Paperwork Reduction Act of 1995, Public Law 104-13 (44 U.S.C. 3506(c)(2)(A)). Currently the Bureau of the Fiscal Service within the Department of the Treasury is soliciting comments concerning the electronic process for selling/issuing, servicing, and making payments on or redeeming U.S. Treasury securities.

**DATES:** Written comments should be received on or before September 29, 2014 to be assured of consideration.

**ADDRESSES:** Direct all written comments to Bureau of the Fiscal Service, Bruce A. Sharp, 200 Third Street A4-A,

Parkersburg, WV 26106-1328, or [bruce.sharp@fiscal.treasury.gov](mailto:bruce.sharp@fiscal.treasury.gov).

#### FOR FURTHER INFORMATION CONTACT:

Requests for additional information or copies should be directed to Bureau of the Fiscal Service, Helen Reilly, 200 Third Street, Parkersburg, WV 26106-1328, (304) 480-6179, or [helen.reilly@fiscal.treasury.gov](mailto:helen.reilly@fiscal.treasury.gov).

#### SUPPLEMENTARY INFORMATION:

*Title:* TreasuryDirect.

*OMB Number:* 1535-0138.

*Abstract:* The information collected in the electronic system is requested to establish a new account and process any associated transactions.

*Current Actions:* The Bureau of the Fiscal Service (Fiscal Service) offers Americans the opportunity to buy and hold Treasury securities directly with the Department of the Treasury. The retail program is geared toward small investors, most of them individuals who buy savings bonds and marketable Treasury securities. Investors create and manage electronic accounts via the Fiscal Service TreasuryDirect system.

Fiscal Service is exploring a strategy to reach new customers, develop new and innovative product delivery streams, and increase the number of available product offerings. In support of this strategy, Fiscal Service will introduce the Treasury Retail Investment Manager (TRIM) that will eventually replace the current TreasuryDirect system. TRIM will be more flexible and responsive to changing business needs for delivering digital investing needs.

*Type of Review:* Revision of a previously approved collection.

*Affected Public:* Individuals or Households.

*Estimated Number of Respondents:* 2.06 million.

*Estimated Time per Respondent:* 10 minutes.

*Estimated Total Annual Burden Hours:* 97,000De.

*Request For Comments:* Comments submitted in response to this notice will be summarized and/or included in the request for OMB approval. All comments will become a matter of public record. Comments are invited on: (a) Whether the collection of information is necessary for the proper performance of the functions of the agency, including whether the information shall have practical utility; (b) the accuracy of the agency's estimate of the burden of the collection of information; (c) ways to enhance the quality, utility, and clarity of the information to be collected; (d) ways to minimize the burden of the collection of information on respondents, including through the use of automated collection techniques or other forms of information technology; and (e) estimates of capital or start-up costs and costs of operation, maintenance, and purchase of services to provide information.

Dated: July 28, 2014.

**Bruce A. Sharp,**

*Bureau Clearance Officer.*

[FR Doc. 2014-18052 Filed 7-30-14; 8:45 am]

**BILLING CODE 4810-39-P**