

B) of Bombardier Repair Drawing 8/4-32-0160, Issue 6, dated June 27, 2012; and install the repaired cam assembly in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 6, dated June 27, 2012.

(ii) Install a new or serviceable cam assembly, in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 6, dated June 27, 2012.

(3) If the cam mechanism is found damaged or inoperative during the repair specified in paragraph (h)(2)(i) of this AD; or if any discrepancies are found and Bombardier Repair Drawing 8/4-32-0160, Issue 6, dated June 27, 2012, does not specify repairs for those discrepancies; or repairs specified in paragraph (h)(2)(i) of this AD cannot be accomplished: Before further flight, do the applicable actions required by paragraph (h)(3)(i) or (h)(3)(ii) of this AD.

(i) Repair and reinstall using a method approved by the Manager, ANE-170, New York ACO, FAA, or TCCA; or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(ii) Install a new or serviceable cam assembly, in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 6, dated June 27, 2012.

(i) New Credit for Previous Actions for Paragraphs (g) and (h) of This AD

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Repair Drawing 8/4-32-0160, Issue 5, dated June 6, 2012, which is not incorporated by reference in this AD.

(j) New Terminating Action

Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first, replace any MLG AES cam mechanism assembly having P/N 48510-1 or P/N 48510-3 with a new MLG AES cam mechanism assembly having P/N 48510-5, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-32-100, Revision A, dated August 30, 2012. Accomplishing this replacement terminates the repetitive inspections required by this AD.

(k) New Credit for Previous Actions for Paragraph (j) of This AD

This paragraph provides credit for actions required by paragraph (j) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84-32-100, dated August 15, 2012, which is not incorporated by reference in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District

Office, as appropriate. ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or TCCA; or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2011-01R2, dated May 21, 2013, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0129>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(5) and (n)(6) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on September 23, 2014.

(i) Bombardier Repair Drawing 8/4-32-0160, Issue 6, dated June 27, 2012. The issue dates for this document are identified only on sheets 1 and 1A of this document.

(ii) Bombardier Service Bulletin 84-32-100, Revision A, dated August 30, 2012.

(4) The following service information was approved for IBR on August 2, 2011 (76 FR 42033, July 18, 2011).

(i) Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011. The issue dates for this document are identified only on the first page of this document.

(ii) Reserved.

(5) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 30, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-19150 Filed 8-18-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0250; Directorate Identifier 2013-NM-165-AD; Amendment 39-17930; AD 2014-16-06]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes. This AD was prompted by reports of in-flight uncommanded rudder movements. This AD requires revising the airplane flight manual (AFM) to incorporate an uncommanded yaw motion procedure. We are issuing this AD to prevent in-flight uncommanded rudder movements, which could lead to structural failure and subsequent loss of the airplane.

DATES: This AD becomes effective September 23, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 23, 2014.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0250> or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>;

www.bombardier.com. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

FOR FURTHER INFORMATION CONTACT:

Luke Walker, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7363; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes. The NPRM published in the *Federal Register* on April 21, 2014 (79 FR 22069). The NPRM was prompted by reports of in-flight uncommanded rudder movements. The NPRM proposed to require revising the AFM to incorporate an uncommanded yaw motion procedure. We are issuing this AD to prevent in-flight uncommanded rudder movements, which could lead to structural failure and subsequent loss of the airplane.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2013-22, dated August 12, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes. The MCAI states:

There have been several reported incidents where Bombardier Regional Jet aeroplanes experienced in-flight uncommanded rudder movements. Investigation revealed that a failure of the voltage regulator inside the yaw damper actuator could lead to uncommanded yaw movement. If not corrected, this condition could lead to structural failure and the subsequent loss of the aeroplane.

Since the Challenger 604 aeroplanes have the same system, and can also experience a similar problem of uncommanded yaw movement, Transport Canada is issuing this [Canadian] AD that mandates the introduction of an emergency procedure to the Aeroplane Flight Manual (AFM) to address the above-mentioned unsafe condition.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov>#!/documentDetail;D=FAA-2014-0250-0002.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (79 FR 22069, April 21, 2014) or on the determination of the cost to the public.

“Contacting the Manufacturer” Paragraph in This AD

Since late 2006, we have included a standard paragraph titled “Airworthy Product” in all MCAI ADs in which the FAA develops an AD based on a foreign authority’s AD.

We have become aware that some operators have misunderstood or misinterpreted the Airworthy Product paragraph to allow the owner/operator to use messages provided by the manufacturer as approval of deviations during the accomplishment of an AD-mandated action. The Airworthy Product paragraph does not approve messages or other information provided by the manufacturer for deviations to the requirements of the AD-mandated actions. The Airworthy Product paragraph only addresses the requirement to contact the manufacturer for corrective actions for the identified unsafe condition and does not cover deviations from other AD requirements. However, deviations to AD-required actions are addressed in 14 CFR 39.17, and anyone may request the approval for an alternative method of compliance to the AD-required actions using the procedures found in 14 CFR 39.19.

To address this misunderstanding and misinterpretation of the Airworthy Product paragraph, we have changed the paragraph and retitled it “Contacting the Manufacturer.” This paragraph now clarifies that for any requirement in this AD to obtain corrective actions from a manufacturer, the actions must be accomplished using a method approved by the FAA, TCCA, or Bombardier, Inc.’s TCCA Design Approval Organization (DAO).

The Contacting the Manufacturer paragraph also clarifies that, if approved by the DAO, the approval must include the DAO-authorized signature. The DAO signature indicates that the data and information contained in the document are TCCA-approved, which is also FAA-approved. Messages and other information provided by the manufacturer that do not contain the DAO-authorized signature approval are not TCCA-approved, unless TCCA directly approves the manufacturer’s message or other information.

This clarification does not remove flexibility previously afforded by the Airworthy Product paragraph. Consistent with long-standing FAA

policy, such flexibility was never intended for required actions. This is also consistent with the recommendation of the Airworthiness Directive Implementation Aviation Rulemaking Committee to increase flexibility in complying with ADs by identifying those actions in manufacturers’ service instructions that are “Required for Compliance” with ADs. We continue to work with manufacturers to implement this recommendation. But once we determine that an action is required, any deviation from the requirement must be approved as an alternative method of compliance.

We also have decided not to include a generic reference to either the “delegated agent” or “design approval holder (DAH) with State of Design Authority design organization approval,” but instead we have provided the specific delegation approval granted by the State of Design Authority for the DAH throughout this AD.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (79 FR 22069, April 21, 2014) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (79 FR 22069, April 21, 2014).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Costs of Compliance

We estimate that this AD affects 116 airplanes of U.S. registry.

We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$9,860, or \$85 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0250>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the ADDRESSES section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-16-06 Bombardier, Inc.: Amendment 39-17930. Docket No. FAA-2014-0250; Directorate Identifier 2013-NM-165-AD.

(a) Effective Date

This AD becomes effective September 23, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes, certificated in any category, serial numbers (S/Ns) 5301 through 5665 inclusive, and 5701 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 22, Autopilot System; and Code 27, Rudder Actuator.

(e) Reason

This AD was prompted by reports of in-flight uncommanded rudder movements. We are issuing this AD to prevent in-flight uncommanded rudder movements, which could lead to structural failure and subsequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual (AFM) Revision

Within 30 days after the effective date of this AD, revise the Emergency Procedures Section of the applicable Bombardier AFM to incorporate the uncommanded yaw motion procedure specified in paragraph (g)(1) or (g)(2) of this AD, as applicable.

(1) For Model CL-600-2B16 (CL-604 Variant) airplanes having S/Ns 5301 through 5665 inclusive: Procedure 1.C., Uncommanded Yaw Motion, of Section 03-06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL-604 AFM, PSP 604-1, Revision 89, dated July 8, 2013.

(2) For Model CL-600-2B16 (CL-604 Variant) airplanes having S/Ns 5701 and subsequent: Procedure 1.C., Uncommanded Yaw Motion, of Section 03-06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL-605 AFM, PSP 605-1, Revision 25, dated July 8, 2013.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, FAA, New York

Aircraft Certification Office (ACO), ANE-170, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA) or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2013-22, dated August 12, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0250-0002>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Procedure 1.C., Uncommanded Yaw Motion, of Section 03-06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL-604 Airplane Flight Manual, PSP 604-1, Revision 89, dated July 8, 2013.

(ii) Procedure 1.C., Uncommanded Yaw Motion, of Section 03-06, Automatic Flight Control System, of Chapter 3—Emergency Procedures, of the Bombardier Challenger CL-605 Airplane Flight Manual, PSP 605-1, Revision 25, dated July 8, 2013.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the

National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 30, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2014-19152 Filed 8-18-14; 8:45 am]

BILLING CODE 4910-13-P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Parts 240, 241, and 250

[Release No. 34-72472; File No. S7-02-13]

RIN 3235-AL25

Application of “Security-Based Swap Dealer” and “Major Security-Based Swap Participant” Definitions to Cross-Border Security-Based Swap Activities; Republication

Correction

In rule document R1-2014-15337 beginning on page 47278 in the issue of Tuesday, August 12, 2014, make the following correction:

On page 47278, in the first column, in the eleventh through seventeenth lines, and on page 47372, in the third column, in the eighth through fourteenth lines, the editorial notes should read as follows:

Editorial Note: Rule document 2014-15337 was originally published on pages 39067 through 39162 in the issue of Wednesday, July 9, 2014. In that publication the footnotes contained erroneous entries. The corrected document is republished in its entirety.

[FR Doc. C1-2014-15337 Filed 8-18-14; 8:45 am]

BILLING CODE 1505-01-D

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 100

[Docket Number USCG-2014-0705]

RIN 1625-AA08

Special Local Regulations for Marine Events, Atlantic Ocean; Ocean City, NJ

AGENCY: Coast Guard, DHS.

ACTION: Temporary final rule.

SUMMARY: The Coast Guard is temporarily changing the enforcement

date of the special local regulation for the recurring air show event known as the Ocean City Air Show, held over the waters of the Atlantic Ocean, adjacent to Ocean City, New Jersey. The change of enforcement date for the special local regulation is necessary to provide for the safety of life on navigable waters during the event. This action will restrict vessel traffic in the waters of the Atlantic Ocean adjacent to Ocean City, New Jersey, during the event.

DATES: This rule is effective August 19, 2014 until 2:30 p.m. on September 14, 2014, and will be enforced from 11:00 a.m. to 2:30 p.m. on September 14, 2014.

ADDRESSES: Documents mentioned in this preamble are part of docket [USCG-2014-0705]. To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type the docket number in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rulemaking. You may also visit the Docket Management Facility in Room W12-140 on the ground floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this temporary rule, call or email Lieutenant Brennan Dougherty, U.S. Coast Guard, Sector Delaware Bay, Chief Waterways Management Division, Coast Guard; telephone (215) 271-4851, email Brennan.P.Dougherty@uscg.mil. If you have questions on viewing or submitting material to the docket, call Cheryl Collins, Program Manager, Docket Operations, telephone (202) 366-9826.

SUPPLEMENTARY INFORMATION:

Table of Acronyms

DHS Department of Homeland Security
FR Federal Register
NPRM Notice of Proposed Rulemaking

A. Regulatory History and Information

The regulation for this marine event may be found at 33 CFR 100.501, Table to § 100.501, section (a), line “13”.

The Coast Guard is issuing this final rule pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b) and (d)(3)), which authorizes an agency to issue a rule without prior notice and opportunity to comment, and to take effect in less than 30 days, when the agency for good cause finds that those procedures are “impracticable, unnecessary, or contrary to the public

interest.” The Coast Guard finds that good cause exists for not publishing a notice of proposed rulemaking (NPRM) with respect to this rule because immediate action is needed to minimize potential danger to the public during the event. The potential dangers posed by air shows make this change to the special local regulation necessary to provide for the safety of participants, spectator craft, and other vessels transiting the event area. For the safety concerns noted, it is in the public interest to have this regulation in effect during the event. The Coast Guard will issue broadcast notice to mariners to advise vessel operators of navigational restrictions. On scene Coast Guard and local law enforcement vessels will also provide actual notice to mariners. For the same reasons, the Coast Guard finds that good cause exists for making this rule effective less than 30 days after publication in the **Federal Register**. Delaying the effective date would be contrary to the public interest, because immediate action is needed to ensure the safety of the event. However, notifications will be made to users of the affected area near Ocean City, NJ, via marine information broadcasts and a local notice to mariners.

B. Basis and Purpose

The legal basis and authorities for this rulemaking establishing a special local regulation are found in 33 U.S.C. 1233, which authorize the Coast Guard to establish and define special local regulations. The Captain of the Port Delaware Bay is establishing a special local regulation for the waters of the Atlantic Ocean, near Ocean City, NJ, to protect event participants, spectators and transiting vessels. Entry into this area is prohibited unless specifically authorized by the Captain of the Port Delaware Bay or designated representative.

C. Discussion of the Final Rule

The City of Ocean City sponsors an annual Air Show usually held on the third Sunday in September over the waters of the Atlantic Ocean adjacent to Ocean City, New Jersey.

The regulation listing annual marine events within the Fifth Coast Guard District and special local regulation locations is 33 CFR 100.501. The Table to § 100.501 identifies special local regulations by COTP zone, with the COTP Delaware Bay zone listed in section “(a.)” of the Table. The Table to § 100.501, at section (a.) event Number “13”, describes the enforcement date and regulated location for this marine event.