

Requirements, Revision 04, dated August 27, 2013, except as provided by paragraph (k)(2) of this AD, accomplish all applicable maintenance tasks. Accomplishing these actions terminates the requirements of paragraphs (g), (h), (i), and (j) of this AD.

(2) Where paragraph 3 of the "Record of Revisions" section of Airbus A330 ALS Part 3—Certification Maintenance Requirements, Revision 04, dated August 27, 2013, specifies accomplishing the actions "from 27 August 2013," this AD requires compliance within the specified compliance time after the effective date of this AD.

#### (l) No Alternative Inspections or Intervals

After accomplishing the action required by paragraph (k)(1) of this AD, no alternative inspections or inspection intervals may be used, other than those specified in Airbus A330 ALS, Part 3—Certification Maintenance Requirements, Revision 04, dated August 27, 2013, except as provided by paragraph (k)(2) of this AD, unless the inspections or intervals are approved as an AMOC in accordance with the procedures specified in paragraph (m) of this AD.

#### (m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0245, dated October 2, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0587.

(2) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email [airworthiness.A330@airbus.com](mailto:airworthiness.A330@airbus.com); Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 18, 2014.

Kevin Hull,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-20257 Filed 8-25-14; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2014-0585; Directorate Identifier 2013-NM-248-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Airbus Model A318, A319, and A321 series airplanes; and Model A320-211, -212, -214, -231, -232, and -233 airplanes. This proposed AD was prompted by a report of corrosion found during the manufacturing process for some oxygen pipe assemblies that are used to supply oxygen to the flight crew. This proposed AD would require an inspection to determine the batch number or installation date of the oxygen pipe assembly that is installed at the end of the right-hand crew distribution line, and, if necessary, replacement of the pipe. We are proposing this AD to detect and correct corrosion, which could lead to blocked or reduced oxygen supply to a flight crew member during a decompression event or a smoke/fire event in the cockpit. Under certain conditions, corrosion particles could increase the risk of fire in the cockpit.

**DATES:** We must receive comments on this proposed AD by October 10, 2014.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: (202) 493-2251.

- *Mail*: U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0585; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0585; Directorate Identifier 2013-NM-248-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2013-0278, dated November 26, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A318, A319, and A321 series airplanes; and Model A320-211, -212, -214, -231, -232, and -233 airplanes. The MCAI states:

Some oxygen pipe assemblies, Part Number (P/N) D3511032000640, have been found corroded during manufacturing at supplier level. The affected pipe assembly is installed at the end of the right hand (RH) crew distribution line, just upstream of the First Officer and RH Observer oxygen mask boxes.

The investigation showed that the affected pipes had been heat treated just 4 weeks before the summer factory closure and were only cleaned after re-opening of the factory. During this interruption, corrosion developed in these pipes.

This condition, if not detected and corrected, could lead to blocked or reduced oxygen supply to one flight crew member in case of decompression or smoke/fire in the cockpit. In addition, the presence of particles in oxygen lines, under certain conditions, increases the risk of fire in the cockpit.

The parts manufacturer identified the batch numbers of the potentially affected pipes that were manufactured in a specific period in 2011. Based on that information, Airbus has identified the aeroplanes on which those pipes have been installed on the production line and has issued Service Bulletin (SB) A320-35-1069, containing instructions to remove the affected pipes from service.

For the reasons described above, this [EASA] AD requires the identification of the affected oxygen pipes P/N D3511032000640, and for those included in the affected batches, replacement of the oxygen pipe. This [EASA] AD also prohibits installation of any of the affected pipes on other aeroplanes.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2014-0585.

#### Relevant Service Information

Airbus has issued Service Bulletin A320-35-1069, dated April 26, 2013. The actions described in this service information are intended to correct the

unsafe condition identified in the MCAI.

#### FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### “Contacting the Manufacturer” Paragraph in This Proposed AD

Since late 2006, we have included a standard paragraph titled “Airworthy Product” in all MCAI ADs in which the FAA develops an AD based on a foreign authority’s AD.

The MCAI or referenced service information in an FAA AD often directs the owner/operator to contact the manufacturer for corrective actions, such as a repair. Briefly, the Airworthy Product paragraph allowed owners/operators to use corrective actions provided by the manufacturer if those actions were FAA-approved. In addition, the paragraph stated that any actions approved by the State of Design Authority (or its delegated agent) are considered to be FAA-approved.

In an NPRM having Directorate Identifier 2012-NM-101-AD (78 FR 78285, December 26, 2013), we proposed to prevent the use of repairs that were not specifically developed to correct the unsafe condition, by requiring that the repair approval provided by the State of Design Authority or its delegated agent specifically refer to the FAA AD. This change was intended to clarify the method of compliance and to provide operators with better visibility of repairs that are specifically developed and approved to correct the unsafe condition. In addition, we proposed to change the phrase “its delegated agent” to include a design approval holder (DAH) with State of Design Authority design organization approval (DOA), as applicable, to refer to a DAH authorized to approve required repairs for the proposed AD.

One commenter to the NPRM having Directorate Identifier 2012-NM-101-AD (78 FR 78285, December 26, 2013) stated the following: “The proposed wording, being specific to repairs, eliminates the interpretation that Airbus messages are

acceptable for approving minor deviations (corrective actions) needed during accomplishment of an AD mandated Airbus service bulletin.”

This comment has made the FAA aware that some operators have misunderstood or misinterpreted the Airworthy Product paragraph to allow the owner/operator to use messages provided by the manufacturer as approval of deviations during the accomplishment of an AD-mandated action. The Airworthy Product paragraph does not approve messages or other information provided by the manufacturer for deviations to the requirements of the AD-mandated actions. The Airworthy Product paragraph only addresses the requirement to contact the manufacturer for corrective actions for the identified unsafe condition and does not cover deviations from other AD requirements. However, deviations to AD-required actions are addressed in 14 CFR 39.17, and anyone may request the approval for an alternative method of compliance to the AD-required actions using the procedures found in 14 CFR 39.19.

To address this misunderstanding and misinterpretation of the Airworthy Product paragraph, we have changed the paragraph and retitled it “Contacting the Manufacturer.” This paragraph now clarifies that for any requirement in this proposed AD to obtain corrective actions from a manufacturer, the actions must be accomplished using a method approved by the FAA, the European Aviation Safety Agency (EASA), or Airbus’s EASA DOA.

The Contacting the Manufacturer paragraph also clarifies that, if approved by the DOA, the approval must include the DOA-authorized signature. The DOA signature indicates that the data and information contained in the document are EASA-approved, which is also FAA-approved. Messages and other information provided by the manufacturer that do not contain the DOA-authorized signature approval are not EASA-approved, unless EASA directly approves the manufacturer’s message or other information.

This clarification does not remove flexibility previously afforded by the Airworthy Product paragraph. Consistent with long-standing FAA policy, such flexibility was never intended for required actions. This is also consistent with the recommendation of the Airworthiness Directive Implementation Aviation Rulemaking Committee to increase flexibility in complying with ADs by identifying those actions in manufacturers’ service instructions that are “Required for Compliance” with

ADs. We continue to work with manufacturers to implement this recommendation. But once we determine that an action is required, any deviation from the requirement must be approved as an alternative method of compliance.

#### Costs of Compliance

We estimate that this proposed AD affects 2 airplanes of U.S. registry.

We also estimate that it would take about 2 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$340, or \$170 per product.

In addition, we estimate that any necessary follow-on actions would take about 5 work-hours, for a cost of \$425 per product. We have no way of determining the number of aircraft that might need this action.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. Amend § 39.13 by adding the following new airworthiness directive (AD):

**Airbus:** Docket No. FAA-2014-0585; Directorate Identifier 2013-NM-248-AD.

#### (a) Comments Due Date

We must receive comments by October 10, 2014.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1) through (c)(4) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Model A318-111, -112, -121, and -122 airplanes.

(2) Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.

(3) Model A320-211, -212, -214, -231, -232, and -233 airplanes.

(4) Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

#### (e) Reason

This AD was prompted by a report of corrosion found during the manufacturing process for some oxygen pipe assemblies that are used to supply oxygen to the flight crew. We are issuing this AD to detect and correct corrosion, which could lead to blocked or reduced oxygen supply to a flight crew member during a decompression event or a smoke/fire event in the cockpit. Under certain conditions, corrosion particles could increase the risk of fire in the cockpit.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspecting for Part Numbers and Replacement

For airplanes identified in paragraph 1.A. of Airbus Service Bulletin A320-35-1069, dated April 26, 2013: Within 7,500 flight hours or 26 months after the effective date of this AD, whichever occurs first, inspect the crew oxygen pipe, having part number (P/N) D3511032000640, to determine the batch number of that pipe, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-35-1069, dated April 26, 2013. A review of airplane maintenance records is acceptable in lieu of this inspection if the batch number of the pipe can be conclusively determined from that review. If the batch number of the oxygen pipe is 19356252, 40008586, 40076689, 40187414, 40292749, 40405164, 40649383, 40724994, 40820410, or 40911832, within 7,500 flight hours or 26 months after the effective date of this AD, whichever occurs first, replace the oxygen pipe with a serviceable part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-35-1069, dated April 26, 2013.

#### (h) Inspection for Part Number of Crew Oxygen Pipe

For airplanes not identified in paragraph 1.A. of Airbus Service Bulletin A320-35-1069, dated April 26, 2013: Within 7,500 flight hours or 26 months after the effective date of this AD, whichever occurs first, inspect the crew oxygen pipe to determine whether P/N D3511032000640 was installed after June 2011. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number and installation date of the pipe can be conclusively determined from that review. If the pipe was installed after June 2011, or the date cannot be conclusively determined, before further flight, do the actions required in paragraph (g) of this AD.

#### (i) Parts Installation Prohibition

As of the effective date of this AD, do not install, on any airplane, a crew oxygen pipe P/N D3511032000640, that is identified as belonging to batch number 19356252, 40008586, 40076689, 40187414, 40292749, 40405164, 40649383, 40724994, 40820410, or 40911832.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer,

International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0278, dated November 26, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2014-0585.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 15, 2014.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-20261 Filed 8-25-14; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2014-0575; Directorate Identifier 2014-NM-086-AD]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all The

Boeing Company Model 747-8F and 747-8 series airplanes. This proposed AD was prompted by reports of delamination damage to leading edge (LE) variable camber krueger (VCK) flaps. This proposed AD would require repetitive inspections to detect delamination damage of the lightning strike applique (LSA) on the LE VCK flaps, and corrective actions if necessary. We are proposing this AD to detect and correct delamination damage to the LE VCK flaps, which can reduce the lightning strike protection capability on the LE VCK flaps and result in an uncommanded motion of the trailing edge flap system. Such uncommanded flap motion, without shutdown of the trailing edge or leading edge flaps, may cause unexpected changes in lift, potentially resulting in asymmetric lift and loss of control of the airplane.

**DATES:** We must receive comments on this proposed AD by October 10, 2014.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0575; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The

street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Kenneth Frey, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6468; fax: 425-917-6190; email: [kenneth.frey@faa.gov](mailto:kenneth.frey@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0575; Directorate Identifier 2014-NM-086-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

We have received multiple reports of damage to the LSA on the LE VCK flaps found during ground inspections on Model 747-8F and 747-8 series airplanes. The damage included delamination of topcoat and metal foil layers from the underlying dielectric layer of the LSA. In some cases, the LSA damage was incorrectly identified as missing or peeling paint.

Excessive delamination damage can reduce the lightning strike protection capability on LE VCK flaps. Loss of lightning strike protection could expose the electrical traces of the leading edge failure indication (LEFI) system on the back side of the LE VCK flaps to a direct lightning strike. A direct lightning strike to the LE VCK flaps with existing LSA damage could result in direct lightning attachment to the high lift flap control units (FCUs), potentially resulting in an uncommanded motion of the trailing edge flap system. Such uncommanded flap motion, without shutdown of the trailing edge or leading edge flaps, may cause unexpected changes in lift, potentially resulting in asymmetric lift and loss of control of the airplane.