

originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a need to incorporate new revisions into the aircraft maintenance manual (AMM) or in the Limitations document of the FAA-approved maintenance program. The limitations were revised to incorporate new life limits for the fire extinguisher. These actions are required to ensure the continued operational safety of the affected airplanes.

#### (f) Actions and Compliance

(1) *Actions retained from AD 2013-11-08, Amendment 39-17468 (78 FR 37701; June 24, 2013) for all airplanes in the Applicability section of this AD:* If the flap actuator has accumulated 3,500 hours time-in-service (TIS) or more since new or last overhauled or 7 years or more since new or last overhauled, whichever occurs first, replacement of the flap actuator (except part numbers 978.73.14.101 and 978.73.14.103) is required within 350 hours TIS after July 29, 2013, (the effective date retained from AD 2013-11-08) or 6 months after July 29, 2013, (the effective date retained from AD 2013-11-08), whichever occurs first. Flap actuators with less than 3,500 hours TIS or 7 years since new or last overhauled are covered by the airworthiness limitations document (ALS) requirement.

(2) *Actions new to this AD for all affected Models PC-6/B2-H2 and PC-6/B2-H4 airplanes:* Before further flight after January 16, 2015 (the effective date of this AD) incorporate the maintenance requirements as specified in Section 04-00-00, Airworthiness Limitations, of Chapter 04, Airworthiness Limitations, of the Pilatus PC-6 Maintenance Manual, document number 01975, Revision 19, dated May 31, 2014, into your FAA-accepted maintenance program (maintenance manual).

(3) *Actions new to this AD for all airplanes in the Applicability section of this AD except for the Models PC-6/B2-H2 and PC-6/B2-H4 airplanes:* Before further flight after January 16, 2015 (the effective date of this AD) incorporate the maintenance requirements as specified in Pilatus ALS, document number 02334, Revision 4, dated May 31, 2014, into your FAA-accepted maintenance program (maintenance manual).

(4) *Actions new to this AD for all airplanes in the Applicability section of this AD:*

(i) For airplanes with Halon Fire Extinguishers that have not yet reached the 10 year life limit after January 16, 2015 (the effective date of this AD), when the Halon Fire Extinguisher reaches its life limit of 10 years, before further flight, replace with an airworthy Halon Fire Extinguisher following Section 04-00-00, Airworthiness Limitations, of Chapter 04, Airworthiness Limitations, of the Pilatus PC-6 Maintenance Manual, document number 01975, Revision 19, dated May 31, 2014; or Pilatus ALS document number 02334, Revision 4, dated May 31, 2014; as applicable.

(ii) For airplanes with Halon Fire Extinguishers that have reached the 10 year life limit on or before January 16, 2015 (the effective date of this AD), within the next 6 months after January 16, 2015 (the effective

date of this AD), replace with an airworthy Halon Fire Extinguisher following Section 04-00-00, Airworthiness Limitations, of Chapter 04, Airworthiness Limitations, of the Pilatus PC-6 Maintenance Manual, document number 01975, Revision 19, dated May 31, 2014; or Pilatus ALS document number 02334, Revision 4, dated May 31, 2014; as applicable.

(iii) Repetitively, after replacing the airplanes Halon Fire Extinguisher as required in paragraphs (f)(4)(i) or (f)(4)(ii), within 10 years after each last replacement, replace with an airworthy Halon Fire Extinguisher.

#### (g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: [doug.rudolph@faa.gov](mailto:doug.rudolph@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### (h) Related Information

Refer to European Aviation Safety Agency (EASA) AD No.: 2014-0181, dated July 31, 2014, for related information. The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#/docketDetail;D=FAA-2014-0717>.

#### (i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pilatus Airworthiness Limitations document number 02334, Revision 4, dated May 31, 2014. The revision level of this document is indicated only in the Record of Revisions.

(ii) Section 04-00-00, Airworthiness Limitations, of Chapter 04, Airworthiness Limitations, of the Pilatus PC-6 Maintenance Manual, document number 01975, Revision 19, dated May 31, 2014.

(3) For Pilatus Aircraft Limited service information identified in this AD, contact PILATUS AIRCRAFT LTD., Customer Liaison Manager, CH-6371 STANS, Switzerland; telephone: +41 (0) 41 619 65 80; fax: +41 (0) 41 619 65 76; Internet: <http://www.pilatus->

[aircraft.com](http://www.pilatus-aircraft.com); email: [fodermatt@pilatus-aircraft.com](mailto:fodermatt@pilatus-aircraft.com).

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on December 2, 2014.

**Robert Busto,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-28730 Filed 12-11-14; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2014-0053; Directorate Identifier 2013-NM-174-AD; Amendment 39-18047; AD 2014-25-05]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 777 airplanes. This AD was prompted by reports of corroded, migrated, or broken spring pins of the girt bar floor fitting; in one case the broken pins prevented a door escape slide from deploying during a maintenance test. This AD requires replacing the existing spring pins at each passenger entry door at both girt bar floor fittings with new spring pins. We are issuing this AD to prevent broken or migrated spring pins of the girt bar floor fittings, which could result in improper deployment of the escape slide/raft and consequent delay and injury during evacuation of passengers and crew from the cabin in the event of an emergency.

**DATES:** This AD is effective January 16, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 16, 2015.

**ADDRESSES:** For service information identified in this AD, contact Boeing

Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0053; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Ana Martinez Hueto, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6592; fax: 425-917-6591; email: [ana.m.hueto@faa.gov](mailto:ana.m.hueto@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 777 airplanes. The NPRM published in the **Federal Register** on February 6, 2014 (79 FR 7103). The NPRM was prompted by reports of corroded, migrated, or broken spring pins of the girt bar floor fitting; in one case the broken pins prevented a door escape slide from deploying during a maintenance test. The NPRM proposed to require replacing the existing spring pins at each passenger entry door at both girt bar floor fittings with new spring pins. We are issuing this AD to prevent broken or migrated spring pins of the girt bar floor fittings, which could result in improper deployment of the escape slide/raft and consequent delay and injury during evacuation of passengers and crew from the cabin in the event of an emergency.

#### Revised Service Information

Since publication of the NPRM (79 FR 7103, February 6, 2014), Boeing has issued Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014. That revision states that no more work is necessary on airplanes changed in accordance with the original issue (Boeing Alert Service Bulletin 777-52A0050, dated June 18, 2013), which was specified as the appropriate source of service information in the NPRM.

We have changed paragraphs (c) and (g) of this AD to specify Boeing Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014; added a new paragraph (h) to this AD to give credit for actions done before the effective date of this AD using Boeing Alert Service Bulletin 777-52A0050, dated June 18, 2013; and redesignated subsequent paragraphs accordingly.

#### Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM (79 FR 7103, February 6, 2014) and the FAA's response to each comment.

#### Request To Change Compliance Time

Boeing asked that we change the compliance time in paragraph (g) of the NPRM (79 FR 7103, February 6, 2014) from 36 months to 1,175 days. Boeing stated that 1,175 days (3 years, 80 days) is consistent with the compliance time specified in Boeing Alert Service Bulletin 777-52A0050, dated June 18, 2013. Boeing noted that this compliance time encompasses the 777 maintenance planning document C-check inspection interval of 1,125 days (3 years, 30 days) for structural items. Boeing added that this change is not significant.

American Airlines (AA) asked that we change the compliance time to match the Maintenance Review Board (MRB) limit of 1,125 days, which would allow AA's maintenance to be scheduled at regular maintenance visits without any undue burden on current flight schedules.

We agree with changing the compliance time to coincide with regular maintenance inspection intervals. However, instead of specifying 1,175 days, we worked in conjunction with Boeing to determine that a 37-month compliance time is appropriate. We have changed paragraph (g) of this AD accordingly.

#### Request To Limit Parts Installation Prohibition

Delta Airlines (Delta) asked that we revise paragraph (h) of the NPRM (79 FR 7103, February 6, 2014), which is

paragraph (i) of this AD, to prohibit installation of the specified spring pins only in the locations being addressed by this AD. Delta stated that this clarification would allow the use of part number (P/N) MS39086-261 or P/N MS16562-252 in locations not subject to the actions in the NPRM. Delta added that the proposed language would prevent the use of these pins anywhere on the applicable Model 777 airplanes.

We agree to specify the location on the airplane where installation of the spring pins is prohibited. We have changed paragraph (i) of this AD accordingly.

#### Request To Revise Parts Installation Prohibition to Pertain to Unmodified Airplanes Only

AA asked that we prohibit installation of spring pins only on airplanes modified in accordance with Boeing Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014, and allow installation of the spring pins on unmodified airplanes. AA added that the Boeing Model 777 Illustrated Parts Catalog (IPC) currently identifies spring pins having P/N MS16562-252 as valid parts for installation on unmodified airplanes. AA added that, since the analysis of broken spring pins has shown that they have failed due to stress corrosion, it should be acceptable to install a new pin in an unmodified airplane because the airplane will be modified within a set amount of time.

We do not agree to allow installation of the spring pins having part number MS39086-261 or MS16562-252 on unmodified airplanes. In general, once we have determined that an unsafe condition exists, we do not allow that condition to be introduced into the fleet. In developing the technical information on which every AD is based, we consider the availability of replacement parts that the AD will require to be installed. Since we have determined that replacement parts are available to operators, this AD prohibits installation of the unsafe parts. We have not changed this AD in this regard.

#### Request To Define Configuration/Parts Control

Singapore Airlines asked for an explanation of how Boeing ensures that the affected spring pins are not delivered to operators since the girt bar assembly includes the spring pins.

FedEx asked that we revise the NPRM (79 FR 7103, February 6, 2014) either to specifically state that no reidentification of the floor fitting assemblies is required, or to provide a specific reidentification process. FedEx Express also asked that the issue of parts

identification as specified in the referenced service information (Boeing Alert Service Bulletin 777-52A0050, dated June 18, 2013), be resolved. FedEx noted “a vague requirement” to identify accomplishment of the service bulletin on the part but there are no specific instructions. FedEx stated this could result in the part being inadvertently returned to a pre-modification condition. FedEx recognized that ensuring compliance lies in the control of the spring pins, not the floor fitting assemblies. FedEx stated that there is no value added by identifying the part after the change is made because Boeing did not provide a step in the Work Instructions with a location to apply this identification.

We acknowledge the commenter’s concerns. Since issuance of the NPRM (79 FR 7103, February 6, 2014), Boeing has updated its IPC and Boeing Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014, to clarify appropriate parts installation. In addition, Boeing Service Bulletin 777-

52A0050, Revision 1, dated August 7, 2014, includes Work Instructions for applying the part identification. We have not changed this AD in this regard.

**Concern Regarding Parts Availability**

FedEx expressed concern about the ability of operators to obtain the required parts since Boeing currently restricts the part’s availability. FedEx noted that it has an adequate supply.

We consider the compliance times in this AD to be adequate to allow operators to acquire parts to have on hand for replacing the affected spring pins. Therefore, we have determined that, due to the safety implications and consequences associated with corroded, migrated, or broken spring pins, the existing pins must be replaced within 37 months after the effective date of this AD. We have not changed this AD regarding this issue.

**Conclusion**

We reviewed the relevant data, considered the comments received, and

determined that air safety and the public interest require adopting this AD with the changes described previously, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (79 FR 7103, February 6, 2014) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (79 FR 7103, February 6, 2014).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

**Costs of Compliance**

We estimate that this AD affects 189 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement .....	Up to 40 work-hours × \$85 per hour = Up to \$3,400.	\$0	Up to \$3,400 .....	Up to \$642,600.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2014-25-05** The Boeing Company: Amendment 39-18047 ; Docket No. FAA-2014-0053; Directorate Identifier 2013-NM-174-AD.

**(a) Effective Date**

This AD is effective January 16, 2015.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes, certificated in any category, as identified in Boeing Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014.

**(d) Subject**

Air Transport Association (ATA) of America Code 52, Doors.

**(e) Unsafe Condition**

This AD was prompted by reports of corroded, migrated, or broken spring pins of the girt bar floor fitting; in one case the broken pins prevented a door escape slide from deploying during a maintenance test. We are issuing this AD to prevent broken or migrated spring pins of the girt bar floor fittings, which could result in improper deployment of the escape slide/raft and consequent delay and injury during evacuation of passengers and crew from the cabin in the event of an emergency.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Spring Pin Replacement**

Within 37 months after the effective date of this AD: Replace the spring pin at both girt bar floor fittings at each passenger entry door with a new spring pin, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014.

**(h) Credit for Previous Actions**

This paragraph provides credit for the action specified in paragraph (g) of this AD, if that action was performed before the effective date of this AD using Boeing Alert Service Bulletin 777-52A0050, dated June 18, 2013, which is not incorporated by reference in this AD.

**(i) Parts Installation Prohibition**

As of the effective date of this AD, no person may install a spring pin having part number MS39086-261 or MS16562-252 at a girt bar floor fitting at a passenger entry door on any airplane.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

**(k) Related Information**

(1) For more information about this AD, contact Ana Martinez Hueto, Aerospace

Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6592; fax: 425-917-6591; email: [ana.m.hueto@faa.gov](mailto:ana.m.hueto@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses in paragraphs (l)(3) and (l)(4) of this AD.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 777-52A0050, Revision 1, dated August 7, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, WA, on November 28, 2014.

**John P. Piccola, Jr.,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-28916 Filed 12-11-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2013-1029; Directorate Identifier 2013-NM-177-AD; Amendment 39-18042; AD 2014-25-01]**

**RIN 2120-AA64**

**Airworthiness Directives; Bombardier, Inc. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are superseding Airworthiness Directive (AD) 2010-13-04 for certain Bombardier, Inc. Model

DHC-8-400 series airplanes. AD 2010-13-04 required modifying the nose landing gear (NLG) trailing arm. This new AD requires installing a new pivot pin retention mechanism. This new AD also adds airplanes to the applicability. This AD was prompted by a report of several missing or damaged pivot pin retention bolts. We are issuing this AD to prevent failure of the pivot pin retention bolt, which could result in a loss of directional control or loss of a NLG tire during take-off or landing.

**DATES:** This AD becomes effective January 16, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 16, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of July 28, 2010 (75 FR 35622, June 23, 2010).

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-1029>; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

**FOR FURTHER INFORMATION CONTACT:**

Ricardo Garcia, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7331; fax 516-794-5531.

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2010-13-04, Amendment 39-16335 (75 FR 35622, June 23, 2010). AD 2010-13-04 applied to certain Bombardier, Inc. Model DHC-8-400 series airplanes. The NPRM published in the **Federal Register** on December 24, 2013 (78 FR 77615).