

Revision 2, dated January 23, 2014, for accomplishing the actions in this paragraph.

(j) New Inspection and Corrective Action

For airplanes on which the system disconnect assembly has been replaced in accordance with Part 4 of the Accomplishment Instructions of Boeing Service Bulletin 777-54A0024, dated April 1, 2010; or Revision 1, dated November 4, 2010: Within 1,125 days after the effective date of this AD, do a detailed inspection of the cover plate fasteners to determine if all cover plate attach fasteners are installed, in accordance with Part 5 of the Accomplishment Instructions of Boeing Service Bulletin 777-54A0024, Revision 2, dated January 23, 2014. If any fastener is missing, before further flight, install fasteners (including doing a detailed inspection for damage of the electrical components and repairing any damaged components), in accordance with Part 6 of the Accomplishment Instructions of Boeing Service Bulletin 777-54A0024, Revision 2, dated January 23, 2014.

(k) Credit for Previous Actions

This paragraph restates the credit provided by paragraph (j) of AD 2011-09-11, Amendment 39-16673 (76 FR 24354, May 2, 2011). This paragraph provides credit for the corresponding actions required by paragraphs (g), (h), and (i) of this AD, if those actions were performed before June 6, 2011 (the effective date of AD 2011-09-11) using Boeing Service Bulletin 777-54A0024, dated April 1, 2010, which is not incorporated by reference in this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(m) Related Information

(1) For more information about this AD, contact Kevin Nguyen, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356;

phone: 425-917-6501; fax: 425-917-6590; email: kevin.nguyen@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(5) and (n)(6) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on February 26, 2015.

(i) Boeing Service Bulletin 777-54A0024, Revision 2, dated January 23, 2014.

(ii) Reserved.

(4) The following service information was approved for IBR on June 6, 2011 (76 FR 24354, May 2, 2011).

(i) Boeing Service Bulletin 777-54A0024, Revision 1, dated November 4, 2010.

(ii) Reserved.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 22, 2014.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-00009 Filed 1-21-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0925; Directorate Identifier 2014-NM-229-AD; Amendment 39-18066; AD 2014-25-52]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A330-200 Freighter, -200, and -300 series airplanes and Model A340-200, -300, -500, and -600 series airplanes. This emergency AD was sent previously to all known U.S. owners and operators of these airplanes. This AD requires revising the airplane flight manual to advise the flightcrew of emergency procedures for abnormal Alpha Protection (Alpha Prot). This AD was prompted by a report of Angle of Attack (AoA) probes jamming on an in-service Airbus Model A321 airplane. We are issuing this AD to ensure that the flightcrew has procedures to counteract the pitch down order due to abnormal activation of the Alpha Prot. An abnormal Alpha Prot, if not corrected, could result in loss of control of the airplane.

DATES: This AD is effective February 6, 2015 to all persons except those persons to whom it was made immediately effective by Emergency AD 2014-25-52, issued on December 10, 2014, which contained the requirements of this amendment.

We must receive comments on this AD by March 9, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0925; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116,

Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

On December 10, 2014, we issued Emergency AD 2014-25-52, which requires revising the airplane flight manual to advise the flightcrew of emergency procedures for abnormal Alpha Prot. This emergency AD was sent previously to all known U.S. owners and operators of these airplanes.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued Emergency Airworthiness Directive 2014-0267-E, dated December 9, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition on all Airbus Model A330-200 Freighter, -200, and -300 series airplanes and Model A340-200, -300, -500, and -600 series airplanes. The MCAI states:

An occurrence was reported where an Airbus A321 aeroplane encountered a blockage of two Angle of Attack (AoA) probes during climb, leading to activation of the Alpha Protection (Alpha Prot) while the Mach number increased. The flightcrew managed to regain full control and the flight landed uneventfully.

When Alpha Prot is activated due to blocked AoA probes, the flight control laws order a continuous nose down pitch rate that, in a worst case scenario, cannot be stopped with backward sidestick inputs, even in the full backward position. If the Mach number increases during a nose down order, the AoA value of the Alpha Prot will continue to

decrease. As a result, the flight control laws will continue to order a nose down pitch rate, even if the speed is above minimum selectable speed, known as VLS.

This condition, if not corrected, could result in loss of control of the aeroplane.

As the same systems are installed on A330 and A340 airplanes, to address this unsafe condition, Airbus * * * [has] developed a specific Aircraft Flight Manual (AFM) procedure, which has been published in AFM Temporary Revision (TR) No. 528 for A330 aeroplanes and AFM TR No. 529 for A340 aeroplanes, as applicable to aeroplane type and model.

For the reasons described above, this AD requires amendment of the applicable AFM [to advise the flightcrew of emergency procedures for abnormal Alpha Prot].

This is considered to be an interim action and further [EASA] AD action may follow.

FAA’s Determination and AD Requirements

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

FAA’s Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this

rule because an abnormal Alpha Prot, if not corrected, could result in loss of control of the airplane. Therefore, we find that notice and opportunity for prior public comment are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2014-0925 and Directorate Identifier 2014-NM-229-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 91 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
AFM revision	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$7,735

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations

for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014–25–52 Airbus: Amendment 39–18066; Docket No. FAA–2014–0925; Directorate Identifier 2014–NM–229–AD.

(a) Effective Date

This AD is effective February 6, 2015 to all persons except those persons to whom it was

made immediately effective by Emergency AD 2014–25–52, issued on December 10, 2014, which contained the requirements of this amendment.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes, certificated in any category, identified in paragraphs (c)(1) through (c)(6) of this AD.

- (1) All Model A330–223F and –243F airplanes.
- (2) All Model A330–201, –202, –203, –223, and –243 airplanes.
- (3) All Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes.
- (4) All Model A340–211, –212, and –213 airplanes.
- (5) All Model A340–311, –312, and –313 airplanes.
- (6) All Model A340–541 and A340–642 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Unsafe Condition

This AD was prompted by a report of Angle of Attack (AoA) probes jamming on an

in-service Airbus Model A321 airplane. We are issuing this AD to ensure the flightcrew has procedures to counteract the pitch down order due to abnormal activation of the Alpha Prot. An abnormal Alpha Prot, if not corrected, could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Airplane Flight Manual (AFM)

Within 2 days after the effective date of this AD, revise the AFM to incorporate procedures to address undue activation of Alpha Prot by inserting the text specified in figure 1 to paragraph (g) of this AD into the Emergency Procedures section of the applicable AFM, to advise the flightcrew of emergency procedures for abnormal Alpha Prot. This may be accomplished by inserting a copy of this AD into the AFM. When a statement identical to the text specified in figure 1 to paragraph (g) of this AD is included in the general revisions of the AFM, the general revisions may be inserted in the AFM, and the text specified in figure 1 to paragraph (g) of this AD may be removed.

FIGURE 1 TO PARAGRAPH (g) OF THIS AD—AFM PROCEDURE

- **If the Alpha Prot strip (black and amber) completely and permanently hides the VLS strip (amber) in a stabilized wings-level flight path (without an increase in the load factor):**

Keep on one ADR.

Turn off two ADRs.

In case of dispatch with one ADR inoperative, switch only one ADR to OFF.

CAUTION RISK OF ERRONEOUS DISPLAY OF THE VSW STRIP (RED AND BLACK) AND RISK OF UNDUE STALL WARNING

Do not increase speed.

Consider using the Flight Path Vector (FPV).

Recover affected DU by using associated DMC switching.

When at or above safety altitude, level off.

- **At any time, with a speed above VLS, if the aircraft goes to a continuous nose down pitch rate that cannot be stopped with backward sidestick inputs, immediately:**

Keep on one ADR.

Turn off two ADRs.

(h) Special Flight Permits

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(i) Other FAA Provisions

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1138; fax 425–227–1149. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal

inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1138; fax 425–227–1149.

(k) Material Incorporated by Reference

None.

Issued in Renton, Washington, on January 7, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–00713 Filed 1–21–15; 8:45 am]

BILLING CODE 4910–13–P