

compliance time listed in paragraph (f)(3)(i) or (f)(3)(ii) of this AD, as applicable.

(i) For MLG configuration equipped with DTD5094 cylinder: Within the next 200 flight cycles after April 24, 2015 (the effective date of this AD) or within the next 2 months after the effective date of this AD, whichever occurs first.

(ii) For MLG configuration equipped with L161 cylinder: Within the next 600 flight cycles after April 24, 2015 (the effective date of this AD) or within the next 6 months after April 24, 2015 (the effective date of this AD), whichever occurs first.

(4) If evidence of migration of the special washer was detected during the inspection required in paragraph (f)(3) of this AD, within the applicable compliance time specified in paragraph (f)(3)(i) or (f)(3)(ii) of this AD, do the corrective actions on the LH or RH MLG, as applicable, following Part 2 of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-A-JA140940, Original Issue, dated October 3, 2014.

(5) If no evidence of migration of the special washer was detected during the inspection required in paragraph (f)(3) of this AD, before further flight, apply a witness paint over the special washer tab and onto the MLG spigot housing (LH and RH MLG) following Part 1 of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-A-JA140940, Original Issue, dated October 3, 2014.

(6) For airplanes that, before April 24, 2015 (the effective date of this AD), have been modified following British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JM7862, Revision 1, dated May 7, 2013, do all of the actions on the MLG cylinder (LH and/or RH, as applicable) following the instructions in Part 2 of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-A-JA140940, Original Issue, dated October 3, 2014, at the compliance time listed in paragraph (f)(6)(i) or (f)(6)(ii), as applicable.

(i) For MLG configuration equipped with DTD5094 cylinder: Within the next 200 flight cycles after April 24, 2015 (the effective date of this AD) or within the next 2 months after April 24, 2015 (the effective date of this AD), whichever occurs first.

(ii) For MLG configuration equipped with L161 cylinder: Within the next 600 flight cycles after April 24, 2015 (the effective date of this AD) or within the next 6 months after April 24, 2015 (the effective date of this AD), whichever occurs first.

(7) If any wear, corrosion, or damage is detected during the inspection required in either paragraph (f)(3) or (f)(6), as applicable, of this AD, before further flight, do all of the corrective actions (including application of the a witness paint) following the instructions in Part 2 of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-A-JA140940, Original Issue, dated October 3, 2014.

(8) Between 30 and 45 days after doing the action required in either paragraph (f)(3) or (f)(6) of this AD or between the next 20 to 30 flight cycles after doing the action required in either paragraph (f)(3) or (f)(6) of this AD, whichever occurs first, inspect the witness paint applied as required in either

paragraph (f)(5) or (f)(7) of this AD following the instructions in Part 3 of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-A-JA140940, Original Issue, dated October 3, 2014.

(9) If any damaged paint is detected during the inspection required in paragraph (f)(8) of this AD, before further flight, contact British Aerospace Regional Aircraft to obtain FAA-approved repair instructions approved specifically for this AD and incorporate those instructions. You may find the contact information for British Aerospace Regional Aircraft in paragraph (h) of this AD.

(10) As of April 24, 2015 (the effective date of this AD), do not install a LH or RH MLG on any of the applicable airplanes unless it has passed all of the inspections required by this AD.

(11) For all airplanes: The compliance times for paragraphs (f)(3)(i), (f)(3)(ii), (f)(6)(i), (f)(6)(ii), and (f)(8) of this AD are presented in flight cycles (landings). If the total flight cycles have not been kept, multiply the total number of airplane hours time-in-service (TIS) by 0.75 to calculate the cycles. You may use the following as an example for this AD:

- (i) 200 hours TIS \times .75 = 150 cycles; or
- (ii) 600 hours TIS \times .75 = 450 cycles.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: taylor.martin@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI found in the European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, AD No. 2014-0239, dated November 3, 2014; and British Aerospace Jetstream Series 3100 & 3200 Service Bulletin SB 32-JA851226, Revision 5, dated April 30, 2013; British Aerospace Jetstream and British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JM7862, Revision 1, dated May 7, 2013, for related information. The MCAI can be found in the AD docket on the Internet at <http://www.regulations.gov/#/documentDetail;D=FAA-2014-1093-0002>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) British Aerospace Jetstream Series 3100 and 3200 Service Bulletin No. 32-JM7862, Revision 3, dated October 3, 2014.

(ii) British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-A-JA140940, Original Issue, dated October 3, 2014.

(3) For service information identified in this AD, contact BAE Systems (Operations) Ltd, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; phone: +44 1292 675207, fax: +44 1292 675704; email: RAPublications@baesystems.com; Internet: <http://www.jetstreamcentral.com>.

(4) You may view this service information the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1093.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 10, 2015.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-06053 Filed 3-19-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-1123; Directorate Identifier 2014-CE-037-AD; Amendment 39-18120; AD 2015-06-02]

RIN 2120-AA64

Airworthiness Directives; GA 8 Airvan (Pty) Ltd Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for GA 8 Airvan (Pty) Ltd Model GA8-TC320 airplanes. This AD results from

mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as missing required engine mount fire seal washers, which could reduce the engine retention capability in the event of a fire. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective April 24, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of April 24, 2015.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123; or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact GA 8 Airvan (Pty) Ltd, c/o GippsAero Pty Ltd, Attn: Technical Services, P.O. Box 881, Morwell Victoria 3840, Australia; telephone: +61 03 5172 1200; fax: +61 03 5172 1201; email: techpubs@gippsaero.com; Internet: <http://www.gippsaero.com/customer-support/technical-publications.aspx>. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123.

FOR FURTHER INFORMATION CONTACT: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to add an AD that would apply to GA 8 Airvan (Pty) Ltd Model GA8-TC320 airplane. The NPRM was published in the **Federal Register** on January 6, 2015 (80 FR 419). The NPRM proposed to correct an unsafe condition for the specified products and was based on mandatory continuing airworthiness information (MCAI)

originated by an aviation authority of another country. The MCAI states:

A recent review of the engine mount installation on the GA8-TC 320 aircraft has highlighted the omission of engine mount fire seal washers during the assembly process.

The current engine mount configuration does not meet the certification basis for the aircraft, specifically regulation 23.865 of the Federal Aviation Regulations of the United States of America, where engine mounts located in designated fire zones are required to be suitably shielded so that they are capable of withstanding the effects of a fire.

The Gippsland Aeronautics GA8-TC 320 aircraft require the installation of an approved steel washer at each of the engine mount locations to address a potential risk of reduced engine retention capability in the event of a fire.

The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2014-1123-0002>.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (80 FR 419, January 6, 2015) or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (80 FR 419, January 6, 2015) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (80 FR 419, January 6, 2015).

Related Service Information Under 1 CFR Part 51

We reviewed GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014. The GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014 describes procedures for inspecting the orientation of the engine isolator mounts to verify proper installation, re-installing if necessary, and installing steel washers on the forward side of each side of the engine isolator mounts. This service information is reasonably available; see **ADDRESSES** for ways to access this service information.

Costs of Compliance

We estimate that this proposed AD will affect 13 products of U.S. registry.

We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$10 per product.

Based on these figures, we estimate the cost of this AD on U.S. operators to be \$5,655, or \$435 per product.

According to the manufacturer, all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2015-06-02 GA 8 Airvan (Pty) Ltd:
Amendment 39-18120; Docket No. FAA-2014-1123; Directorate Identifier 2014-CE-037-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective April 24, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to GA8 Airvan (Pty) Ltd GA8-TC320 airplanes, all serial numbers affected, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 71: Power Plant.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as missing required engine mount fire seal washers, which could reduce the engine retention capability in the event of a fire. We are issuing this AD to detect and correct the omission of steel washers at each isolator mount location, which, if not corrected,

could result in reduced engine retention capability in the event of a fire.

(f) Actions and Compliance

Unless already done, comply with this AD within the compliance times specified in paragraphs (f)(1) through (f)(4) of this AD:

(1) Within the next 300 hours time-in-service after April 24, 2015 (the effective date of this AD) or within the next 12 months after April 24, 2015 (the effective date of this AD), whichever occurs first, inspect the orientation of the engine isolator mounts to verify that the mounts have been installed properly following the Accomplishment Instructions in GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014.

(2) Before reinstalling the engine isolator mounts following the inspection required in paragraph (f)(1) of this AD, before further flight, install a part number J-2218-61 steel washer on the forward side of each of the four engine isolator mounts, following the Accomplishment Instructions in GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014.

(3) If during the inspection required in paragraph (f)(1) of this AD, any of the engine isolator mounts are found to not comply with the specifications found in the Accomplishment Instructions of GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014, before further flight, re-install the isolators to the correct orientation, or if damage is found, replace with airworthy parts.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information

collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI Civil Aviation Safety Authority (CASA) AD No. AD/GA8/8, dated November 24, 2014. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) GippsAero Mandatory Service Bulletin SB-GA8-2014-115, Issue 1, dated October 6, 2014.

(ii) Reserved.

(3) For GippsAero service information identified in this AD, contact GA 8 Airvan (Pty) Ltd, c/o GippsAero Pty Ltd, Attn: Technical Services, P.O. Box 881, Morwell Victoria 3840, Australia; telephone: + 61 03 5172 1200; fax: +61 03 5172 1201; email: techpubs@gippsaero.com; Internet: <http://www.gippsaero.com/customer-support/technical-publications.aspx>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1123.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 12, 2015.

Robert Busto,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-06234 Filed 3-19-15; 8:45 am]

BILLING CODE 4910-13-P