

**Conclusion**

This action affects only certain novel or unusual design features on the Gulfstream Model GVII series airplanes. It is not a rule of general applicability.

**List of Subjects in 14 CFR Part 25**

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

**The Special Conditions**

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued, in lieu of § 25.397(c), as part of the type-certification basis.

For Gulfstream Model GVII series airplanes equipped with side-stick controls designed for forces to be applied by one wrist and not arms, the limit pilot forces are as follows.

1. For all components between and including the side-stick control-assembly handle and its control stops:

| Pitch                  | Roll                 |
|------------------------|----------------------|
| Nose up, 200 lbf ..... | Nose left, 100 lbf.  |
| Nose down, 200 lbf ... | Nose right, 100 lbf. |

2. For all other components of the side-stick control assembly, but excluding the internal components of the electrical sensor assemblies, to avoid damage to the control system as the result of an in-flight jam:

| Pitch                  | Roll                |
|------------------------|---------------------|
| Nose up, 125 lbf ..... | Nose left, 50 lbf.  |
| Nose down, 125 lbf ... | Nose right, 50 lbf. |

Issued in Renton, Washington, on June 2, 2015.

**Jeffrey E. Duven,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-14904 Filed 6-16-15; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2006-23706; Directorate Identifier 2006-NE-03-AD; Amendment 39-18177; AD 2014-12-04]

**RIN 2120-AA64**

**Airworthiness Directives; Honeywell International Inc. Turboprop Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are superseding airworthiness directive (AD) 2006-15-08 for all Honeywell International Inc. TPE331-1, -2, -2UA, -3U, -3UW, -5, -5A, -5AB, -5B, -6, -6A, -10, -10AV, -10GP, -10GT, -10P, -10R, -10T, -10U, -10UA, -10UF, -10UG, -10UGR, -10UR, -11U, -12JR, -12UA, -12UAR, and -12UHR turboprop engines with certain Honeywell part numbers (P/Ns) of Woodward fuel control unit (FCU) assemblies, installed. AD 2006-15-08 required initial and repetitive dimensional inspections of the fuel control drives for wear, and replacement of the FCU and fuel pump. This new AD requires initial and repetitive dimensional inspections of the affected fuel control drives and insertion of certain airplane operating procedures into the applicable flight manuals. This AD was prompted by reports of loss of the fuel control drive, leading to engine overspeed, overtorque, overtemperature, uncontained rotor failure, and asymmetric thrust in multi-engine airplanes. We are issuing this AD to prevent failure of the fuel control drive that could result in damage to the engine and airplane.

**DATES:** This AD is effective July 22, 2015.

**ADDRESSES:** For service information identified in this AD, contact Honeywell International Inc., 111 S 34th Street, Phoenix, AZ 85034-2802; phone: 800-601-3099; Internet: <https://myaerospace.honeywell.com/wps/portal/lut/>. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2006-23706; or in person at the Docket

Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712-4137; phone: 562-627-5246; fax: 562-627-5210; email: [joseph.costa@faa.gov](mailto:joseph.costa@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2006-15-08, Amendment 39-14688 (71 FR 41121, July 20, 2006), (“AD 2006-15-08”). AD 2006-15-08 applied to all Honeywell International Inc. TPE331-1, -2, -2UA, -3U, -3UW, -5, -5A, -5AB, -5B, -6, -6A, -10, -10AV, -10GP, -10GT, -10P, -10R, -10T, -10U, -10UA, -10UF, -10UG, -10UGR, -10UR, -11U, -12JR, -12UA, -12UAR, and -12UHR turboprop engines with certain Honeywell part numbers (P/Ns) of Woodward FCU assemblies, installed. The NPRM published in the **Federal Register** on March 19, 2014 (79 FR 15261). The NPRM was prompted by reports of loss of the fuel control drive, leading to engine overspeed, overtorque, overtemperature, uncontained rotor failure, and asymmetric thrust in multi-engine airplanes. The NPRM proposed to continue to require initial and repetitive dimensional inspections of the affected fuel control drives but would no longer require the installation of a modified FCU. The NPRM also proposed to require insertion of certain airplane operating procedures into the applicable flight manuals. We are issuing this AD to prevent failure of the fuel control drive that could result in damage to the engine and airplane.

**Comments**

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM (79 FR 15261, March 19, 2014) and the FAA’s response to each comment.

### Disagreement With the Elimination of Requirement To Install a Modified FCU

Honeywell International Inc. (Honeywell) and an individual commenter indicated that the NPRM should mandate the installation of the FCU because of the benefits it provides. In addition, both commenters disagreed with the FAA that the modified FCU contributed to the rate of in-flight shutdowns (IFSDs) and that the inherent risk of repetitive inspections does not support the elimination of the overspeed governor (OSG) modification requirement of AD 2006–15–08.

We disagree. We eliminated the mandatory installation of recently certified, modified FCUs due to the numerous reports of unscheduled removals and the IFSDs caused by the recent design changes incorporated in the modified FCU. We did not change this AD.

### Request Change to Costs of Compliance

Honeywell indicated that the cost for repetitive inspections is not accurate. Honeywell estimates that, without a change in design, a limitless number of inspections would be needed over the life of the engine.

We agree. Numerous fuel control drive inspections could be needed over the life of the engine. The Costs of Compliance paragraph was changed to reflect an annual cost of compliance which was based on the fleet costs as reflected in the NPRM.

### Request To Change the Applicability

Honeywell requested that engines in Group #4 reflect the engines associated with FCU assembly P/Ns being added to the Applicability paragraph for added clarity.

We agree. We changed Table 1 to paragraph (c) of this AD to clarify the Group #4 engine models as follows: “Group #4 TPE331–3U, –3UW, –5, –5B, –6, –6A, and –10T”.

### Request To Change the Applicability

Honeywell requested that clarification be provided for FCU P/Ns of Woodward fuel control units. The Applicability paragraph refers to P/Ns as Woodward P/Ns when the listed P/Ns are Honeywell P/Ns for Woodward FCUs.

We agree. We changed paragraph (c) of this AD to read, “. . . turboprop engines with Honeywell part numbers (P/Ns) for Woodward fuel control unit (FCU) assemblies listed in Table 1 to paragraph (c) of this AD, installed.”

### Request Redundant Term Be Removed From the Compliance

Honeywell requested that “spline” be removed from the fuel control drive

inspection as stated in the Compliance paragraph. This change is consistent with the Compliance and the Definitions paragraphs in AD 2006–15–08.

We agree. We changed paragraphs (e)(1)(i) and (e)(2)(ii) to read: “Inspect the fuel control drive for wear.”

### Request To Change Related Information

Honeywell requested that the publications listed in Related Information, paragraph (i)(2), be referred to as airplane publications and not as obtainable from Honeywell International. The reason for this request is that the Airplane Flight Manual (AFM), the Pilot Operating Handbook (POH), and the Manufacturer’s Operating Manual (MOM) are airplane publications and cannot be obtained from Honeywell.

We agree that the AFM, POH, and the MOM are airplane manuals. As a result of reviewing this comment, we decided that mentioning all applicable owners of airplane manuals is unnecessary in the related information section of this AD.

### Request To Change Airplane Operating Procedures

Honeywell requested that reference to the “Loss of Fuel Control Drive” be changed to “Loss of the drive between the engine driven fuel pump and the fuel control governor.” This change would eliminate confusion between the loss of the accessory drive gearing to the fuel pump with the loss of the fuel control drive.

We agree that the term “fuel control drive” is not a term used in airplane operating procedures. We removed the term “fuel control drive” from the Airplane Operating Procedures in this AD and made other changes to simplify and clarify Figure 1 to paragraph (e) of this AD.

### Request To Change Airplane Operating Procedures

One commenter requested a revision of the Operating Procedure “Warnings” in the NPRM to clearly address overspeed during start and immediately after start before the propeller has been removed from the start locks. This change would provide clarification and enhance safety.

We disagree. The Loss of Fuel Control Drive causing rapid, uncommanded acceleration during engine start is as unsafe as the Loss of Fuel Control Drive immediately after start when the engine is stable before the propeller is removed from the start locks. However, since the observed effects for these two conditions are the same, we combined both instances as “Rapid,

Uncommanded Acceleration During Engine Start”.

### Request To Change Airplane Operating Procedures

The commenter requested changing the operating procedures for when the propeller is off the start locks to address the rapid uncommanded, uncontrolled increase in revolutions-per-minute (RPM). The commenter believes that if the fuel control drive fails when the propeller is off the start locks the engine’s propeller governor will control and stabilize the engine RPM.

We disagree with the commenter’s justification because test data has shown that the engine propeller governor will not control and stabilize the engine RPM if the fuel control drive fails when the propeller is off the start locks. A rapid, uncommanded, uncontrolled increase in RPM is most evident during partial or full reverse. We simplified the operating procedure by removing the statement “Power—Move power lever to or toward flight idle as required to maintain engine limits” with the propeller off the start locks as proposed in the NPRM. We changed Figure 1 to paragraph (e) of this AD by adding the following: “Engine shut down—Move condition lever to EMERGENCY STOP”.

### Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

### Costs of Compliance

We estimate that this AD will affect 2,250 engines installed on airplanes of U.S. registry. We estimate that it will take 8 hours per engine to perform an FCU inspection. The average labor rate is \$85 per hour. Due to the more frequent inspections proposed by this AD, we estimate 10% of affected engines will require FCU assembly stub shaft replacement, and fuel pump or fuel control repair. We also estimate that repairs will not exceed \$10,000 per engine. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$525,587 per year.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

Authority 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2006–15–08, Amendment 39–14688 (71 FR 41121, July 20, 2006), and adding the following new AD:

**2015–12–04 Honeywell International Inc.:**  
Amendment 39–18177454851; Docket No. FAA–2006–23706; Directorate Identifier 2006–NE–03–AD.

**(a) Effective Date**

This AD is effective July 22, 2015.

**(b) Affected ADs**

This AD replaces AD 2006–15–08, Amendment 39–14688 (71 FR 41121, July 20, 2006).

**(c) Applicability**

This AD applies to all Honeywell International Inc. TPE331–1, –2, –2UA, –3U, –3UW, –5, –5A, –5AB, –5B, –6, –6A, –10, –10AV, –10GP, –10GT, –10P, –10R, –10T, –10U, –10UA, –10UF, –10UG, –10UGR, –10UR, –11U, –12JR, –12UA, –12UAR, and –12UHR turboprop engines with Honeywell part numbers (P/Ns) for Woodward fuel control unit (FCU) assemblies listed in Table 1 to paragraph (c) of this AD, installed.

TABLE 1 TO PARAGRAPH (c)—AFFECTED FCU ASSEMBLY P/Ns

| Group No. | Engine   | FCU assembly P/Ns  |
|-----------|--|--|
| 1 .....   | TPE331–1, –2, and –2UA .....   | P/N 869199–13, –20, –21, –22, –23, –24, –25, –26, –27, –28, –29, –31, –32, –33, –34, and –35.  |
| 2* .....  | TPE331–1, –2, and –2UA .....   | P/N 869199–9, –10, –11, –12, –14, –16, –17, and –18.   |
| 3 .....   | TPE331–3U, –3UW, –5, –5A, –5AB, –5B, –6, –6A, –10AV, –10GP, –10GT, –10P, and –10T.                 | P/N 893561–7, –8, –9, –10, –11, –14, –15, –16, –20, –26, –27, and –29; or P/N 897770–1, –3, –7, –9, –10, –11, –12, –14, –15, –16, –25, –26, and –28.   |
| 4* .....  | TPE331–3U, –3UW, –5, –5B, –6, –6A, and –10T.   | P/N 893561–4, –5, –12, and –13 or P/N 897770–5, –8, and –13.   |
| 5 .....   | TPE331–10, –10R, –10U, –10UA, –10UF, –10UG, –10UGR, –10UR, –11U, –12JR, –12UA, –12UAR, and –12UHR. | P/N 897375–2, –3, –4, –5, –8, –9, –10, –11, –12, –13, –14, –15, –16, –17, –19, –21, –24, –25, –26, and –27; or P/N 897780–1, –2, –3, –4, –5, –6, –7, –8, –9, –10, –11, –14, –15, –16, –17, –18, –19, –20, –21, –22, –23, –24, –25, –26, –27, –30, –32, –34, –36, –37, and –38; or P/N 893561–17, –18, and –19. |

\* New/added FCU assembly P/Ns

**(d) Unsafe Condition**

We are issuing this AD to prevent failure of the fuel control drive that could result in damage to the engine and airplane.

**(e) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(1) Inspection of Engines With FCU Assembly P/Ns in Groups 2 and 4**

For FCU assembly P/Ns in Groups 2 and 4 listed in Table 1 to paragraph (c) of this AD:

- (i) At the next scheduled inspection of the fuel control drive, or within 500 hours-in-

service (HIS) after the effective date of this AD, whichever occurs first, inspect the fuel control drive for wear.

- (ii) Thereafter, re-inspect the fuel control drive within every 1,000 HIS since-last-inspection (SLI).

**(2) Inspection of Engines With FCU Assembly P/Ns in Groups 1, 3, and 5**

For FCU assembly P/Ns in Groups 1, 3, or 5 listed in Table 1 to paragraph (c) of this AD:

- (i) If on the effective date of this AD the FCU assembly has 950 or more HIS SLI, inspect the fuel control drive for wear within 50 HIS from the effective date of this AD.

(ii) If on the effective date of this AD the FCU assembly has fewer than 950 HIS SLI, inspect the fuel control drive for wear before reaching 1,000 HIS.

- (iii) Thereafter, re-inspect the fuel control drive for wear within every 1,000 HIS SLI.

**(3) Airplane Operating Procedures**

Within 60 days after the effective date of this AD, insert the information in Figure 1 to paragraph (e) of this AD, into the Emergency Procedures Section of the Airplane Flight Manual (AFM), Pilot Operating Handbook (POH), and the Manufacturer’s Operating Manual (MOM).

**Figure 1 to Paragraph (e) – Airplane Operating Procedures**

NOTE

Procedures in dotted line boxes are immediate action items to be performed by the pilot / flight crew.

RAPID, UNCOMMANDED ACCELERATION DURING  
ENGINE START (Propeller ON Start Locks)

- Engine Start – Abort Immediately – Move condition lever to EMERGENCY STOP.

WARNING

Do not attempt to re-start engine. Report to maintenance.

ON GROUND or IN FLIGHT:

RAPID, UNCOMMANDED INCREASE IN RPM, TORQUE,  
FUEL FLOW AND/OR TURBINE TEMPERATURE  
(Propeller OFF Start Locks)

- Identify Malfunctioning Engine (multi-engine airplane) – Cross check for high torque, RPM, fuel flow, and turbine temperatures.
- Engine shut down - Move condition lever to EMERGENCY STOP.

WARNING

Never retard the power levers aft of flight idle in flight or on the ground.

WARNING

Do not attempt an engine re-start. Report to maintenance.

**(f) Optional Terminating Action**

Replacing the affected FCU assembly with an FAA-approved FCU assembly P/N not listed in this AD is terminating action for the initial and repetitive inspections required by this AD, and for inserting the information in Figure 1 to paragraph (e) of this AD into the AFM, POH, and MOM.

**(g) Definitions**

For the purposes of this AD:

(1) The “fuel control drive” is a series of mating splines located between the fuel pump and fuel control governor.

(2) The fuel control drive consists of four drive splines: The fuel pump internal spline, the fuel control external “quill shaft” spline, and the stub shaft internal and external splines.

**(h) Alternative Methods of Compliance (AMOCs)**

The Manager, Los Angeles Aircraft Certification Office, FAA, may approve

AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

**(i) Related Information**

(1) For more information about this AD, contact Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712–4137; phone: 562–627–5246; fax: 562–627–5210; email: [joseph.costa@faa.gov](mailto:joseph.costa@faa.gov).

(2) Information pertaining to operating recommendations for affected engines after a fuel control drive failure is contained in Honeywell International Inc., Operating Information Letter (OIL) OI331–12R6, dated May 26, 2009, for multi-engine airplanes; and in OIL OI331–18R4, dated May 26, 2009, for single-engine airplanes. Information on fuel control drive inspection can be found in Section 72–00–00 of the applicable TPE331 maintenance manuals. These Honeywell International Inc., OILs and the TPE331 maintenance manuals, which are not incorporated by reference in this AD, can be

obtained from Honeywell International Inc., using the contact information in paragraph (i)(3) of this AD.

(3) For service information identified in this AD, contact Honeywell International Inc., 111 S. 34th Street, Phoenix, AZ 85034–2802; Internet: <https://myaerospace.honeywell.com/wps/portal/lut>; phone: 800–601–3099.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

**(j) Material Incorporated by Reference**

None.

Issued in Burlington, Massachusetts, on June 5, 2015.

**Ann C. Mollica,**

*Acting Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2015-14694 Filed 6-16-15; 8:45 am]

**BILLING CODE 4910-13-P**

## EQUAL EMPLOYMENT OPPORTUNITY COMMISSION

### 29 CFR Part 1611

#### Privacy Act Regulations

##### *CFR Correction*

■ In Title 29 of the Code of Federal Regulations, Parts 900 to 1899, revised as of July 1, 2014, on page 257, in § 1611.3, in paragraph (b)(3), the address “1801 L Street NW.” is corrected to read “131 M Street NE.”.

[FR Doc. 2015-14654 Filed 6-16-15; 8:45 am]

**BILLING CODE 1505-01-D**

## ENVIRONMENTAL PROTECTION AGENCY

### 40 CFR Part 52

#### Approval and Promulgation of Implementation Plans

##### *CFR Correction*

In Title 40 of the Code of Federal Regulations, Part 52 (§§ 52.1019 to 52.2019), revised as of July 1, 2014, on page 649, in § 52.1881, paragraph (b) is removed and reserved.

[FR Doc. 2015-14652 Filed 6-16-15; 8:45 am]

**BILLING CODE 1505-01-D**

## DEPARTMENT OF COMMERCE

### National Oceanic and Atmospheric Administration

#### 50 CFR Part 622

[Docket No. 120815345-3525-02]

RIN 0648-XD988

#### Snapper-Grouper Fishery of the South Atlantic; 2015 Commercial Accountability Measure and Closure for the South Atlantic Lesser Amberjack, Almaco Jack, and Banded Rudderfish Complex

**AGENCY:** National Marine Fisheries Service (NMFS), National Oceanic and Atmospheric Administration (NOAA), Commerce.

**ACTION:** Temporary rule; closure.

**SUMMARY:** NMFS implements accountability measures (AMs) for the commercial sector for the lesser amberjack, almaco jack, and banded rudderfish complex in the South Atlantic for the 2015 fishing year through this temporary rule. Commercial landings for the lesser amberjack, almaco jack, and banded rudderfish complex, as estimated by the Science and Research Director, are projected to reach their combined commercial annual catch limit (ACL) on June 23, 2015. Therefore, NMFS closes the commercial sector for this complex on June 23, 2015, through the remainder of the fishing year in the exclusive economic zone (EEZ) of the South Atlantic. This closure is necessary to protect the lesser amberjack, almaco jack, and banded rudderfish resources.

**DATES:** This rule is effective 12:01 a.m., local time, June 23, 2015, until 12:01 a.m., local time, January 1, 2016.

**FOR FURTHER INFORMATION CONTACT:** Catherine Hayslip, NMFS Southeast Regional Office, telephone: 727-824-5305, email: [catherine.hayslip@noaa.gov](mailto:catherine.hayslip@noaa.gov).

**SUPPLEMENTARY INFORMATION:** The snapper-grouper fishery of the South Atlantic, which includes the lesser amberjack, almaco jack, and banded rudderfish complex, is managed under the Fishery Management Plan for the Snapper-Grouper Fishery of the South Atlantic Region (FMP). The FMP was prepared by the South Atlantic Fishery Management Council and is implemented under the authority of the Magnuson-Stevens Fishery Conservation and Management Act (Magnuson-Stevens Act) by regulations at 50 CFR part 622.

The combined commercial ACL for the lesser amberjack, almaco jack, and banded rudderfish complex is 189,422 lb (85,920 kg), round weight. Under 50 CFR 622.193(l)(1)(i), NMFS is required to close the commercial sector for the lesser amberjack, almaco jack, and banded rudderfish complex when the commercial ACL has been reached, or is projected to be reached, by filing a notification to that effect with the Office of the Federal Register. NMFS has determined that the commercial sector for this complex is projected to reach the ACL on June 23, 2015. Therefore, this temporary rule implements an AM to close the commercial sector for the lesser amberjack, almaco jack, and banded rudderfish complex in the South Atlantic, effective 12:01 a.m., local time June 23, 2015.

The operator of a vessel with a valid commercial vessel permit for South Atlantic snapper-grouper having lesser

amberjack, almaco jack, or banded rudderfish on board must have landed and bartered, traded, or sold such species prior to 12:01 a.m., local time, June 23, 2015. During the closure, the bag limit specified in 50 CFR 622.187(b)(8) and the possession limits specified in 50 CFR 622.187(c) apply to all harvest or possession of lesser amberjack, almaco jack, or banded rudderfish in or from the South Atlantic EEZ. These bag and possession limits apply in the South Atlantic on board a vessel for which a valid Federal commercial or charter vessel/headboat permit for South Atlantic snapper-grouper has been issued, without regard to where such species were harvested, *i.e.*, in state or Federal waters. During the closure, the sale or purchase of lesser amberjack, almaco jack, or banded rudderfish taken from the EEZ is prohibited. The prohibition on sale or purchase does not apply to the sale or purchase of lesser amberjack, almaco jack, or banded rudderfish that were harvested, landed ashore, and sold prior to 12:01 a.m., local time, June 23, 2015, and were held in cold storage by a dealer or processor.

#### Classification

The Regional Administrator, Southeast Region, NMFS, has determined this temporary rule is necessary for the conservation and management of the lesser amberjack, almaco jack, and banded rudderfish complex, a component of the South Atlantic snapper-grouper fishery, and is consistent with the Magnuson-Stevens Act and other applicable laws.

This action is taken under 50 CFR 622.193(l)(1)(i) and is exempt from review under Executive Order 12866.

These measures are exempt from the procedures of the Regulatory Flexibility Act because the temporary rule is issued without opportunity for prior notice and comment.

This action responds to the best scientific information available. The Assistant Administrator for Fisheries, NOAA (AA), finds that the need to immediately implement this action to close the commercial sector for the lesser amberjack, almaco jack, and banded rudderfish complex constitutes good cause to waive the requirements to provide prior notice and opportunity for public comment pursuant to the authority set forth in 5 U.S.C. 553(b)(B), as such procedures are unnecessary and contrary to the public interest. Such procedures are unnecessary because the rule itself has been subject to notice and comment, and all that remains is to notify the public of the closure. Such procedures are contrary to the public