

positive account balance will be considered enrolled prior to September 5, 2015 for purposes of this paragraph;

(5) All deposits made on behalf of a participant first enrolled on or after September 5, 2015 who does not have a contribution allocation in effect will be invested in the age-appropriate TSP Lifecycle Fund; and

(6) Once a contribution allocation becomes effective, it remains in effect until it is superseded by a subsequent contribution allocation or the participant's account balance is reduced to zero. If a rehired participant has a positive account balance and a contribution allocation in effect, then the participant's contribution allocation will remain in effect until a new allocation is made. If, however, the participant has a zero account balance, then the participant's contributions will be allocated to the age-appropriate TSP Lifecycle Fund until a new allocation is made.

* * * * *

§ 1601.22 [Amended]

■ 5. Amend § 1601.22 by removing paragraph (a)(3).

■ 6. Amend § 1601.33 by revising the first sentence of paragraph (a), to read as follows:

§ 1601.33 Acknowledgement of risk.

(a) A uniformed services participant or a participant enrolled prior to September 5, 2015 who wants to invest in a TSP Fund other than the G Fund must execute an acknowledgement of risk for that fund. * * *

* * * * *

PART 1651—DEATH BENEFITS

■ 7. The authority citation for part 1651 continues to read as follows:

Authority: 5 U.S.C. 8424(d), 8432d, 8432(j), 8433(e), 8435(c)(2), 8474(b)(5) and 8474(c)(1).

■ 8. Amend § 1651.2 by revising the last sentence of paragraph (d) to read as follows:

§ 1651.2 Entitlement to funds in a deceased participant's account.

* * * * *

(d) * * * The account will accrue earnings at the G Fund rate in accordance with 5 CFR part 1645 until it is paid out or a beneficiary participant account is established under this part.

■ 3. Amend § 1651.19, by revising the first sentence of paragraph (a) to read as follows:

§ 1651.19 Beneficiary participant accounts.

* * * * *

(a) * * * Regardless of the allocation of the deceased participant's account balance at the time of his or her death, each beneficiary participant account, once established, will be allocated 100 percent to the age-appropriate TSP Lifecycle Fund based on the beneficiary participant's date of birth. * * *

* * * * *

[FR Doc. 2015-21302 Filed 8-27-15; 8:45 am]

BILLING CODE 6760-01-P

DEFENSE NUCLEAR FACILITIES SAFETY BOARD

10 CFR Part 1703

FOIA Fee Schedule Update

AGENCY: Defense Nuclear Facilities Safety Board.

ACTION: Establishment of FOIA Fee Schedule.

SUMMARY: The Defense Nuclear Facilities Safety Board is publishing its Freedom of Information Act (FOIA) Fee Schedule Update pursuant to the Board's regulations.

DATES: Effective September 1, 2015.

FOR FURTHER INFORMATION CONTACT:

Mark T. Welch, General Manager, Defense Nuclear Facilities Safety Board, 625 Indiana Avenue NW., Suite 700, Washington, DC 20004-2901, (202) 694-7060.

SUPPLEMENTARY INFORMATION: The FOIA requires each Federal agency covered by the Act to specify a schedule of fees applicable to processing of requests for agency records. 5 U.S.C. 552(a)(4)(A)(i). On July 9, 2015 the Board published for comment in the **Federal Register** its Proposed FOIA Fee Schedule, 80 FR 39389. No comments were received in response to that notice, and the Board is now establishing the Fee Schedule.

Pursuant to 10 CFR 1703.107(b)(6) of the Board's regulations, the Board's General Manager will update the FOIA Fee Schedule once every 12 months. The previous Fee Schedule Update went into effect on June 1, 2014. 79 FR 31848.

Board Action

Accordingly, the Board issues the following schedule of updated fees for services performed in response to FOIA requests:

DEFENSE NUCLEAR FACILITIES SAFETY BOARD SCHEDULE OF FEES FOR FOIA SERVICES

[Implementing 10 CFR 1703.107(b)(6)]

Search or Review Charge	\$85.00 per hour.
Copy Charge (paper)	\$.05 per page, if done in-house, or generally available commercial rate approximately \$.10 per page).
Electronic Media	\$5.00 per electronic media.
Copy Charge (audio and video cassette)	Actual commercial rates.
Duplication of DVD	\$25.00 for each individual DVD; \$16.50 for each duplicate DVD.
Copy Charge for large documents (e.g., maps, diagrams)	Actual commercial rates.

Dated: August 21, 2015.

Mark T. Welch,
General Manager.

[FR Doc. 2015-21413 Filed 8-27-15; 8:45 am]

BILLING CODE 3670-01-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-0822; Directorate Identifier 2014-NM-210-AD; Amendment 39-18248; AD 2015-17-15]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, Model CL-600-2D24 (Regional Jet Series 900) airplanes, and Model CL-600-2E25 (Regional Jet Series 1000) airplanes. This AD was prompted by results of a design review indicating that the burst pressure of the flexible hose, used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard, was lower than the opening pressure of the high-pressure relief valve, which could cause the flexible hose to burst before it can vent the excess oxygen overboard. This AD requires replacing the oxygen hose assembly with a new, improved assembly. We are issuing this AD to prevent the accumulation of oxygen in an enclosed space, which could result in an uncontrolled oxygen-fed fire if an ignition source is nearby.

DATES: This AD becomes effective October 2, 2015.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 2, 2015.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> #!docketDetail;D=FAA-2015-0822 or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view

this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0822.

FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7318; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, Model CL-600-2D24 (Regional Jet Series 900) airplanes, and Model CL-600-2E25 (Regional Jet Series 1000) airplanes. The NPRM published in the **Federal Register** on April 13, 2015 (80 FR 19574).

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, has issued Canadian Airworthiness Directive CF-2014-37, dated October 17, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, Model CL-600-2D15 (Regional Jet Series 705) airplanes, Model CL-600-2D24 (Regional Jet Series 900) airplanes, and Model CL-600-2E25 (Regional Jet Series 1000) airplanes. The MCAI states:

Design review found that the burst pressure of the flexible hose, used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard, is lower than the opening pressure of the high-pressure relief valve. This could cause the flexible hose to burst before it is able to vent the excess oxygen overboard. If an ignition source is present, the accumulation of oxygen in an enclosed space may result in an uncontrolled oxygen-fed fire.

This [Canadian] AD mandates the replacement of the oxygen hose assembly with a new design oxygen hose assembly.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov>

#!documentDetail;D=FAA-2015-0822-0004.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM (80 FR 19574, April 13, 2015) and the FAA's response to each comment.

Request To Change the Compliance Time

Mesa Airlines and Envoy Air Inc. asked that the compliance time specified in paragraph (g) of the proposed AD (80 FR 19574, April 13, 2015) be changed.

Mesa Airlines stated that the current compliance time would immediately ground 78 airplanes on the effective date of the AD, and with increased demand for replacement parts it would be difficult to recover. Mesa Airlines asked that we change the compliance time to "Within 6,000 flight hours, or within 44 months after the effective date of this AD, whichever occurs first." Mesa Airlines added that this would allow for scheduling with heavy maintenance inspection and parts procurement.

Envoy Air Inc. stated that a large number of affected airplanes have flown more than 5,800 total flight hours. Envoy Air Inc. noted that the proposed compliance time "before the accumulation of 5,800 total flight hours" would mean that most of the affected airplanes would be required to comply with this AD prior to the effective date to remain in compliance. Envoy Air Inc. asked that we change the compliance time to "Within 5,800 flight hours or 44 months, whichever occurs first, from the effective date of the AD." Envoy Air Inc. stated that this would more clearly communicate the desired compliance time for this AD.

We partially agree with the requests. We have changed the compliance time in paragraph (g) of this AD to "Within 5,800 flight hours or 44 months after the effective date of this AD, whichever occurs first." This change matches the compliance time listed in the MCAI, and will allow operators to remain in compliance.

We do not agree that the compliance time should be extended to "Within 6,000 flight hours, or within 44 months after the effective date of this AD, whichever occurs first." After