provide adequate clearance to prevent chafing between the high voltage electrical lines and the hydraulic hoses. This condition could result in a fire in an area of the helicopter without extinguishing capability and subsequent loss of control of the helicopter.

#### (c) Affected ADs

This AD supersedes AD 2014-07-04R1, Amendment 39-17964 (79 FR 54893, September 15, 2014).

#### (d) Comments Due Date

We must receive comments by November 24, 2015.

### (e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (f) Required Actions

Within 150 hours time-in-service, reroute the left hand and right hand upper deck wiring system by complying with the Instructions, paragraph B, of Sikorsky Aircraft Corporation Special Service Instructions SSI No. 92–070A, Revision A, dated April 25, 2014.

# (g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Boston Aircraft Certification Office, FAA, may approve AMOCs for this AD. Send your proposal to: Ian Lucas, Aviation Safety Engineer, Engine & Propeller Directorate, FAA, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238– 7757; email ian.lucas@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

### (h) Additional Information

Sikorsky Aircraft Corporation Alert Service Bulletin ASB 92–20–003, Basic Issue, dated May 5, 2014, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Sikorsky Aircraft Corporation, Customer Service Engineering, 124 Quarry Road, Trumbull, CT 06611; telephone 1–800-Winged-S or 203–416–4299; email sikorskywcs@sikorsky.com.

You may review the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, Texas 76177.

## (i) Subject

Joint Aircraft Service Component (JASC) Code: 2910 Main Hydraulic System. Issued in Fort Worth, Texas, on September 17, 2015.

#### James A. Grigg,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service. [FR Doc. 2015–24148 Filed 9–24–15; 8:45 am]

#### BILLING CODE 4910-13-P

### **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2015-3956; Directorate Identifier 2015-CE-032-AD]

#### RIN 2120-AA64

# Airworthiness Directives; Alpha Aviation Concept Limited Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Alpha Aviation Concept Limited Model R2160 airplanes that would supersede AD 2008–09–01. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a need to revise the maintenance program to include the revised airworthiness limitations for the internal wing structure and wing attachment inspections. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by November 9, 2015. **ADDRESSES:** You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to http://www.regulations.gov. Follow the instructions for submitting comments.
  - Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M— 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M— 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Alpha

Aviation Holdings Limited, Steele Road, RD 2 Hamilton Airport, Hamilton 3282, New Zealand, telephone: +64 7 843 9877; fax: +64 7 929 2878; Internet: http://www.alphaaviation.co.nz/. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

## **Examining the AD Docket**

You may examine the AD docket on the Internet at http:// www.regulations.gov by searching for and locating Docket No. FAA-2015-3956; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4123; fax: (816) 329–4090; email: karl.schletzbaum@faa.gov.

# SUPPLEMENTARY INFORMATION:

### **Comments Invited**

relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-3956; Directorate Identifier 2015-CE-032-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this

We invite you to send any written

We will post all comments we receive, without change, to <a href="http://regulations.gov">http://regulations.gov</a>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

proposed AD because of those

# Discussion

comments.

On April 11, 2008, we issued AD 2008–09–01, Amendment 39–15481 (73

FR 21519; April 22, 2008) ("AD 2008–09–01"). That AD required actions intended to address an unsafe condition on certain Alpha Aviation Concept Limited Model R2160 airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2008–09–01, Alpha Aviation Concept Limited developed a longer life limit for the wing structure and wing attachments and transferred the life limit information from the related service information to the airplane maintenance manual. Subsequently, Alpha Aviation Concept Limited discovered that the analysis that allowed the life limit increase was incorrect and the previous life limit and inspection provisions of the related service bulletin should be retained.

The Civil Aviation Authority (CAA), which is the aviation authority for New Zealand, has issued AD DCA/R2000/43, dated August 7, 2015 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

This AD introduces a change to the airworthiness limitations for the internal wing structure and wing attachment inspections. These inspection intervals were increased and added to Section 3.2— Airworthiness Limitations of the applicable Service Manual in January 2015. Section 3.2 of the respective Service Manuals has now been revised to revert to the original inspection intervals.

You may examine the MCAI on the Internet at http://www.regulations.gov by searching for and locating Docket No. FAA-2015-3956.

# **Related Service Information Under 1** CFR Part 51

Alpha Aviation Concept Limited has issued Alpha Aviation APEX R2000 Service Manual, S/N 001 to 378, and Alpha Aviation R2000 Service Manual. These service manuals include a revision to Section 3: Airworthiness Limitations, Time Limits, & Maintenance Inspections, Issued August 2015. These revisions now include periodic internal wing structure and wing attachment inspections. A copy of these revisions to the Airworthiness Limitations section of the applicable service manuals are reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of this NPRM.

# FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

### **Costs of Compliance**

We estimate that this proposed AD will affect 9 products of U.S. registry. We also estimate that it would take about 3 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$2,295, or \$255 per product.

In addition, we estimate that any necessary follow-on actions would take about 12 work-hours and require parts costing \$1,326, for a cost of \$2,346 per product. We have no way of determining the number of products that may need these actions.

## **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## **Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national

Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

## § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39–15481 (73 FR 21519; April 22, 2008), and adding the following new AD:

**Alpha Aviation Concept Limited:** Docket No. FAA–2015–3956; Directorate Identifier 2015–CE–032–AD.

## (a) Comments Due Date

We must receive comments by November 9, 2015.

### (b) Affected ADs

This AD supersedes AD 2008–09–01, Amendment 39–15481 (73 FR 21519; April 22, 2008) ("AD 2008–09–01").

## (c) Applicability

This AD applies to Alpha Aviation Concept Limited Model R2160 airplanes, serial numbers (S/Ns) 001 through 378, and 160A–06001 and subsequent, certificated in any category.

#### (d) Subject

Air Transport Association of America (ATA) Code 5: Time Limits.

#### (e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a need to revise the maintenance program to include the revised airworthiness limitations for the internal wing structure and wing attachment inspections. We are issuing this AD to prevent failure of the wing structure and fuselage attachment due to undetected fatigue and corrosion.

### (f) Actions and Compliance

Unless already done, before further flight after the effective date of this AD, insert the following into the Airworthiness Limitations section of the FAA-approved maintenance program (e.g., maintenance manual). These revisions to the Limitations sections incorporate the wing spar inspection upon the accumulation of 3,500 hours time-inservice (TIS) and requires a repetitive inspection thereafter every 750 hours TIS (the requirements of AD 2008–09–01):

- (1) For S/Ns 001 through 378: Insert paragraph 3.4.9, Wing 3500 hr Inspection, on pages 3–3 and 3–4, dated August 2015, of Section 3: Airworthiness Limitations, Time Limits, & Maintenance Inspections, dated August 2015, of the APEX R2000 Service Manual S/N 001 to 378, Alpha Aviation Ltd.
- (2) For S/Ns 160A–06001 and subsequent: Insert paragraph 3.4.9, Wing 3500 hr Inspection, on pages 3–3 and 3–4, dated August 2015, of Section 3: Airworthiness Limitations, Time Limits, & Maintenance Inspections, all dated August 2015, of the R2000 Service Manual, Alpha Aviation Ltd.

## (g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4146; fax: (816) 329–4090; email: karl.schletzbaum@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

## (h) Related Information

Refer to MCAI Civil Aviation Authority (CAA) AD DCA/R2000/43, dated August 7, 2015, for related information. You may examine the MCAI on the Internet at http://www.regulations.gov by searching for and locating Docket No. FAA-2015-3956. For service information related to this AD, contact Alpha Aviation Holdings Limited, Steele Road, RD 2 Hamilton Airport, Hamilton 3282, New Zealand, telephone: +64 7 843 9877; fax: +64 7 929 2878; Internet:

http://www.alphaaviation.co.nz/. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on September 17, 2015.

#### Melvin Johnson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–24149 Filed 9–24–15; 8:45 am] BILLING CODE 4910–13–P

### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No.FAA-2015-3084; Airspace Docket No. 15-AGL-13]

# Proposed Establishment of Class E Airspace; International Falls, MN

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM), correction.

**SUMMARY:** This action makes a correction to the NPRM published in the **Federal Register** of August 27, 2015, proposing to establish Class E en route domestic airspace in the International Falls, MN area. Exclusionary reference to Canadian airspace was omitted from the regulatory text.

**DATES:** Comments due date remains October 13, 2015.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2015-3084/Airspace Docket No. 15-AGL-13, at the beginning of your comments. You may also submit comments through the Internet at http://www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800– 647–5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Y, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at <a href="http://www.faa.gov/air\_traffic/publications/">http://www.faa.gov/air\_traffic/publications/</a>. For further information, you can contact the Airspace Policy and Regulations Group, Federal Aviation

Administration, 800 Independence Avenue SW., Washington, DC, 20591; telephone: 202–267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to <a href="http://www.archives.gov/federal\_register/code\_of\_federal-regulations/ibr locations.html">http://www.archives.gov/federal\_register/code\_of\_federal-regulations/ibr locations.html</a>.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Raul Garza, Jr., Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: 817–868–2927.

#### SUPPLEMENTARY INFORMATION:

History. A notice of proposed rulemaking was published in the **Federal Register** of August 27, 2015 (80 FR 51972). In the regulatory text of the proposed rule, exclusionary language was inadvertently omitted from the legal description of the airspace. This action makes the correction. The legal description is rewritten for clarity.

#### **Proposed Amendment Correction**

Accordingly, pursuant to the authority delegated to me, in the **Federal Register** of August 27, 2015 (80 FR 51972), FR Docket 2015–21087, the legal description on page 51973, column 2, beginning at line 31, is corrected to read as follows:

### §71.1 [Amended]

# AGL MN E6 International Falls, MN [Corrected]

That airspace extending upward from 1,200 feet above the surface within an area bounded by lat. 49°00′00″ N., long. 095°00′00″ W.; to lat. 49°00′00″ N., long. 093°30′00″ W.; to lat. 48°06′30″ N., long. 090°06′00″ W.; to lat. 48°34′00″ N., long. 090°55′00″ W.; to lat. 48°34′00″ N., long. 094°00′00″ W.; to lat. 48°40′00″ N., long. 095°00′00″ W., thence to the point of beginning, excluding that airspace within Federal airways and within Canadian airspace.

Issued in Fort Worth, TX, on September 9, 2015.

## Robert W. Beck,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2015–24159 Filed 9–24–15; 8:45 am]

BILLING CODE 4910-13-P