

directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-31R2, dated November 14, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-1985-0003.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 8-24-84, Revision D, dated April 10, 2014.

(ii) Bombardier Service Bulletin 8-24-89, Revision C, dated November 4, 2014.

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 6, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-26218 Filed 10-19-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0442; Directorate Identifier 2007-SW-24-AD; Amendment 39-18291; AD 2015-20-12]

RIN 2120-AA64

Airworthiness Directives; Various Sikorsky-Manufactured Transport and Restricted Category Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 98-26-02 for certain Sikorsky Aircraft Corporation (Sikorsky) Model S-61A, D, E, L, N, NM, R, and V helicopters. AD 98-26-02 required determining whether the main rotor shaft (MRS) was used in repetitive external lift (REL) operations, performing a nondestructive inspection (NDI) for cracks, replacing any unairworthy MRS, and establishing retirement lives for each REL MRS. This new AD retains some of the requirements of AD 98-26-02 but determines a new retirement life for each MRS, expands the applicability to include additional helicopters, and requires removing from service any MRS with oversized dowel pin bores. This AD was prompted by the manufacturer's reevaluation of the retirement life for the MRS based on torque, ground-air-ground (GAG) cycle, and fatigue testing. We are issuing this AD to prevent MRS structural failure, loss of power to the main rotor, and subsequent loss of control of the helicopter.

DATES: This AD is effective November 24, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 24, 2015.

ADDRESSES: For service information identified in this AD, contact Sikorsky Aircraft Corporation, Attn: Manager, Commercial Technical Support, mailstop s581a, 6900 Main Street, Stratford, Connecticut, telephone (203) 383-4866, email [\[www.sikorsky.com\]\(http://www.sikorsky.com\), or at <http://www.regulations.gov>. You may view this referenced service information at the FAA, Office of the Regional Counsel, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.](mailto:tsslibrary@</p>
</div>
<div data-bbox=)

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> in Docket No. FAA-2008-0442; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any incorporated-by-reference information, the economic evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Tracy Murphy, Aviation Safety Engineer, Boston Aircraft Certification Office, Engine & Propeller Directorate, FAA, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238-7172; email tracy.murphy@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On April 10, 2008, we issued a notice of proposed rulemaking (NPRM) (73 FR 21556, April 22, 2008) proposing to amend 14 CFR part 39 by adding an AD for Sikorsky Aircraft Corporation Model S-61A, D, E, L, N, NM, R, and V; Croman Corporation Model SH-3H; Carson Helicopters, Inc., Model S-61L; Glacier Helicopters, Inc., Model CH-3E; Robinson Air Crane, Inc., Model CH-3E, CH-3C, HH-3C and HH-3E; and Siller Helicopters Model CH-3E and SH-3A helicopters. The NPRM proposed superseding AD 98-26-02 (63 FR 69177, December 16, 1998), which required determining whether the MRS was used in REL operations, performing an NDI for cracks, replacing any unairworthy MRS, and establishing retirement lives for each REL MRS. The NPRM proposed to retain some of the requirements of AD 98-26-02 but also proposed a new retirement life determination for each MRS, removing from service any MRS with oversized dowel pin bores, and expanding the applicability to include certain restricted category models. The NPRM was prompted by the manufacturer's reevaluation of the retirement life for the MRS based on torque, GAG cycle, and fatigue testing.

Those proposals were intended to prevent MRS structural failure, loss of power to the main rotor, and subsequent loss of control of the helicopter.

On April 16, 2013, we issued a supplemental NPRM (SNPRM) (78 FR 24363, April 25, 2013) that proposed to revise the NPRM based on comments received on the NPRM and a reevaluation of the relevant data. The SNPRM proposed retaining the proposals in the NPRM but extending the hours TIS required for identifying the MRS as an REL MRS to coincide with the NDI to prevent repeated disassembly of the shaft. The SNPRM also proposed to extend the time required to replace the MRS and revise calculations for establishing the retirement life.

On September 19, 2014, we issued a second SNPRM (79 FR 60789, October 8, 2014). In addition to retaining previously-proposed requirements, the second SNPRM revised the Cost of Compliance section to reflect an increased cost for parts to replace an MRS and clarified some of the wording for complying with the AD.

Since the SNPRM (79 FR 60789, October 8, 2014) was issued, the FAA Southwest Regional Office has relocated. We have revised the physical address to reflect the new address.

Comments

We gave the public the opportunity to participate in developing this AD, but we did not receive any comments on the second SNPRM (79 FR 60789, October 8, 2014).

FAA's Determination

We have reviewed the relevant information and determined that an unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed except for a minor change. Sikorsky Aircraft was inadvertently omitted as one of the current type certificate holders of some of the applicable model helicopters; we are correcting that error in this AD. This change is consistent with the intent of the proposals in the SNPRM (79 FR 60789, October 8, 2014) and will not increase the economic burden on any operator nor increase the scope of the AD.

Related Service Information Under 14 CFR Part 51

Sikorsky issued Alert Service Bulletin No. 61B35-69, dated April 19, 2004, which provides procedures for determining REL and Non-REL status,

assigns new REL and Non-REL MRS retirement lives, and provides a method for marking the REL MRS. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this AD.

Other Related Service Information

Sikorsky issued Customer Service Notice (CSN) No. 6135-10, dated March 18, 1987, and Service Bulletin (SB) No. 61B35-53, dated December 2, 1981, both revised with Revision A on April 19, 2004, for Model S-61L, N, and NM (serial number (S/N) 61454), and R series transport category helicopters; and S-61A, D, E, and V series restricted category helicopters. CSN 6135-10A specifies replacing the planetary assembly and MRS assembly attaching hardware with high strength hardware. CSN 6135-10A also specifies reworking the dowel retainer to increase hole chamfer and related countersink diameters. SB 61B35-53A specifies replacing the existing planetary matching plates with new steel matching plates during overhaul at the operator's discretion.

Sikorsky Aircraft Corporation also issued an All Operators Letter CCS-61-AOL-04-0005, dated May 18, 2004, which contains an example and additional information about tracking cycles and the moving average procedure.

Costs of Compliance

We estimate that this AD affects 60 helicopters of U.S. Registry. We estimate that operators may incur the following costs in order to comply with this AD. It will take about 2.2 work-hours to NDI an REL MRS at \$85 per work-hour plus a \$50 consumable cost, for a total estimated cost of \$237 per helicopter and \$14,220 for the U.S. fleet. It will take about 2.2 work-hours to replace an MRS at \$85 per work-hour plus parts cost of \$81,216, for a total estimated cost of \$81,403 per helicopter.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that a regulatory distinction is required, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 98-26-02, Amendment 39-10943 (63 FR 69177, December 16, 1998), and adding the following new AD:

2015-20-12 Sikorsky Aircraft Corporation; Sikorsky Aircraft; Croman Corporation; Carson Helicopters, Inc.; Glacier Helicopters, Inc.; Robinson Air Crane, Inc.; and Siller Helicopters: Amendment 39-18291; Docket No. FAA-2008-0442; Directorate Identifier 2007-SW-24-AD.

(a) Applicability

This AD applies to Model S-61A, D, E, L, N, NM (serial number (S/N) 61454), R, V, CH-3C, CH-3E, HH-3C, HH-3E, SH-3A, and SH-3H helicopters with main rotor shaft (MRS), part number S6135-20640-001, S6135-20640-002, or S6137-23040-001, installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as MRS structural failure, loss of power to the main rotor, and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 98-26-02, Amendment 39-10943 (63 FR 69177, December 16, 1998).

(d) Effective Date

This AD becomes effective November 24, 2015.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) Within 10 hours time-in-service (TIS):

(i) Create a component history card or equivalent record for each MRS.

(ii) If there is no record of the hours TIS on an individual MRS, substitute the helicopter's hours TIS or the helicopter's transmission hours TIS if both the shaft and transmission were installed new at the same time.

(iii) If the record of external lift cycles (lift cycles) on an individual MRS is incomplete, add the known number of lift cycles to a number calculated by multiplying the number of hours TIS of the individual MRS by the average lift cycles calculated according to the instructions in Section I of Appendix 1 of this AD or by a factor of 13.6, whichever is higher. An external lift cycle is defined as a flight cycle in which an external load is picked up, the helicopter is repositioned (through flight or hover), and the helicopter hovers and releases the load and departs or lands and departs.

(iv) At the end of each day's operations, record the number of lift cycles performed and the hours TIS.

(2) Within 250 hours TIS, determine whether the MRS is a repetitive external lift (REL) or Non-REL MRS.

(i) Calculate the first moving average of lift cycles by following the instructions in Section I of Appendix 1 of this AD.

(A) If the calculation results in 6 or more lift cycles per hour TIS, the MRS is an REL-MRS.

(B) If the calculation results in less than 6 lift cycles per hour TIS, the MRS is a Non-REL MRS.

(ii) If the MRS is a Non-REL MRS based on the calculation performed in accordance with paragraph (f)(2)(i) of this AD, thereafter at intervals of 50 hour TIS, recalculate the average lift cycles per hour TIS by following the instructions in Section II of Appendix 1 of this AD.

(iii) Once an MRS is determined to be an REL MRS, you no longer need to perform the 250-hour TIS moving average calculation, but you must continue to count and record the lift cycles and number of hours TIS.

(iv) If an MRS is determined to be an REL MRS, it remains an REL MRS for the rest of its service life and is subject to the retirement times for an REL MRS.

(3) Within 1,100 hours TIS:

(i) Conduct a Non-Destructive Inspection for a crack on each MRS. If there is a crack in an MRS, before further flight, replace it with an airworthy MRS.

(ii) If an MRS is determined to be an REL MRS, identify it as an REL MRS by etching "REL" on the outside diameter of the MRS near the part S/N by following the Accomplishment Instructions, paragraph 3.C., of Sikorsky Alert Service Bulletin No. 61B35-69, dated April 19, 2004.

(4) Replace each MRS with an airworthy MRS on or before reaching the revised retirement life as follows:

(i) For an REL MRS that is not modified by following Sikorsky Customer Service Notice (CSN) No. 6135-10, dated March 18, 1987, and Sikorsky Service Bulletin (SB) No. 61B35-53, dated December 2, 1981 (unmodified REL MRS), the retirement life is 30,000 lift cycles or 1,500 hours TIS, whichever occurs first.

(ii) For an REL MRS that is modified by following Sikorsky CSN No. 6135-10, dated March 18, 1987, and Sikorsky SB No. 61B35-53 dated December 2, 1981; or Sikorsky CSN No. 6135-10A and Sikorsky SB No. 61B35-53A, both Revision A, and both dated April 19, 2004 (modified REL MRS), the retirement life is 30,000 lift cycles or 5,000 hours TIS, whichever occurs first.

(iii) For a Non-REL MRS, the retirement life is 13,000 hours TIS.

(5) Establish or revise the retirement lives of the MRS as indicated in paragraphs (f)(4)(i) through (f)(4)(iii) of this AD by recording the new or revised retirement life on the MRS component history card or equivalent record.

(6) Within 50 hours TIS, remove from service any MRS with oversized (0.8860" or greater diameter) dowel pin bores.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Boston Aircraft Certification Office, FAA, may approve AMOCs for this AD. Send your proposal to: Tracy Murphy, Aviation Safety Engineer, Boston Aircraft Certification Office, Engine & Propeller Directorate, FAA, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238-7172; email tracy.murphy@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

Sikorsky Aircraft Corporation All Operators Letter CCS-61-AOL-04-0005,

dated May 18, 2004; Sikorsky Customer Service Notice (CSN) No. 6135-10, dated March 18, 1987; Sikorsky CSN No. 6135-10A, Revision A, dated April 19, 2004; Sikorsky Service Bulletin (SB) No. 61B35-53, dated December 2, 1981; and Sikorsky SB No. 61B35-53A, Revision A, dated April 19, 2004, which are not incorporated by reference, contain additional information about the subject of this AD. For more information about these documents, contact Sikorsky Aircraft Corporation, Attn: Manager, Commercial Technical Support, mailstop s581a, 6900 Main Street, Stratford, Connecticut, telephone (203) 383-4866, email tsslibrary@sikorsky.com, or at <http://www.sikorsky.com>. You may review a copy of the referenced service information at the FAA, Office of the Regional Counsel, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Sikorsky Alert Service Bulletin No. 61B35-69, dated April 19, 2004.

(ii) Reserved.

(3) For Sikorsky service information identified in this AD, contact Sikorsky Aircraft Corporation, Attn: Manager, Commercial Technical Support, mailstop s581a, 6900 Main Street, Stratford, Connecticut, telephone (203) 383-4866, email tsslibrary@sikorsky.com, or at <http://www.sikorsky.com>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Appendix 1 to AD 2015-20-12**Section I: The First Moving Average of External Lift Cycles (Lift Cycles) per Hour Time-in-Service (TIS)**

The first moving average calculation is performed on the main rotor shaft (MRS) assembly when the external lift component history card record reflects that the MRS assembly has reached its first 250 hours TIS. To perform the calculation, divide the total number of lift cycles performed during the first 250 hours TIS by 250. The result will be the first moving average calculation of lift cycles per hour TIS.

Section II: Subsequent Moving Average of Lift Cycles per Hour TIS

Subsequent moving average calculations are performed on the MRS assembly at intervals of 50 hour TIS after the first moving average calculation. Subtract the total number of lift cycles performed during the first 50-hour TIS interval used in the previous moving average calculation from the total number of lift cycles performed on the MRS assembly during the previous 300 hours TIS. Divide this result by 250. The result will be the next or subsequent moving average calculation of lift cycles per hour TIS.

Section III: Sample Calculation for Subsequent 50 Hour TIS Intervals

Assume the total number of lift cycles for the first 50 hour TIS interval used in the previous moving average calculation = 450 lift cycles and the total number of lift cycles for the previous 300 hours TIS = 2700 lift cycles. The subsequent moving average of lift cycles per hour TIS = (2700 - 450) divided by 250 = 9 lift cycles per hour TIS.

Issued in Fort Worth, Texas, on October 4, 2015.

Lance T. Gant,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2015-25976 Filed 10-19-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2015-1832; Airspace Docket No. 14-ACE-10]

Establishment of Class E Airspace; Wakeeney, KS

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace at Wakeeney, KS. Controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Trego Wakeeney Airport. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) operations at the airport. The airport name also is correctly noted in the airspace description.

DATES: Effective 0901 UTC, December 10, 2015. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.9Z, Airspace Designations and Reporting

Points, and subsequent amendments can be viewed on line at http://www.faa.gov/air_traffic/publications. For further information, you can contact the Airspace Policy and ATC Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 29591; telephone: 202-267-8783. The order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/code-of-federal-regulations/ibr-locations.html>.

FAA Order 7400.9, Airspace Designations and Reporting Points is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT:

Rebecca Shelby, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone: 817-222-5857.

SUPPLEMENTARY INFORMATION:**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace at Trego Wakeeney Airport, Wakeeney, KS.

History

On June 25, 2015, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to propose Class E airspace extending upward from 700 feet above the surface at Trego Wakeeney Airport, Wakeeney, KS, (80 FR 36495). The airport name is corrected in the airspace description from Sheridan Municipal Airport to Trego Wakeeney Airport. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA

Order 7400.9Z, dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR part 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends Title 14, Code of Federal Regulations (14 CFR), Part 71 by establishing Class E airspace extending upward from 700 feet above the surface within a 6.0-mile radius of Trego Wakeeney Airport, Wakeeney, KS, to accommodate new Standard Instrument Approach Procedures for IFR operations at the airport. The correct airport name is noted in the airspace description, changing it from Sheridan Municipal Airport.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures" paragraph 311a. This airspace action is