

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Turbomeca S.A.: Docket No. FAA-2015-8257; Directorate Identifier 2015-NE-36-AD.

(a) Comments Due Date

We must receive comments by May 10, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Turbomeca S.A. MAKILA 2A and MAKILA 2A1 turboshaft engine models with a high-pressure (HP) gas generator module (M03) that has modification (mod) TU 52 installed.

(d) Reason

This AD was prompted by two occurrences of crack initiation on a ferrule of the diffuser, which propagated and led to the ferrule rupture. We are issuing this AD to prevent rupture of the ferrule of the diffuser, which could result in engine fire and damage to the helicopter.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Borescope inspect the centrifugal diffuser ferrule, part number (P/N) 0298210100, prior to the ferrule accumulating 700 hours, time since new or time since replacement or within 30 hours from the effective date of this AD, whichever is later. Use Accomplishment Instructions,

paragraphs 2.4.1 through 2.4.2.2.1, of Turbomeca S.A. Alert Mandatory Service Bulletin (MSB) No. 298 72 2832, Version B, dated October 12, 2015, to do the borescope inspections required by this AD.

(2) Repeat the borescope inspection required by this AD every 50 hours since last inspection.

(3) If any crack, loss of contact between the ferrule and diffuser axial vane, or any contact between the injection manifold supply pipe and the diffuser ferrule is found, remove the diffuser case and replace the ferrule with a part eligible for installation.

(f) Credit for Previous Actions

You may take credit for the actions required by paragraph (e) of this AD if you performed Turbomeca S.A. MSB No. 298 72 2832, Version A, dated September 3, 2015 before the effective date of this AD.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Brian Kierstead, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: brian.kierstead@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2015-0209, dated October 16, 2015, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2015-8257.

(3) Turbomeca S.A. Alert MSB No. A298 72 2832, Version B, dated October 12, 2015, can be obtained from Turbomeca S.A., using the contact information in paragraph (h)(5) of this proposed AD.

(4) Turbomeca S.A. Service Bulletin (SB) No. 298 72 2833, Version A, dated July 29, 2015, can be obtained from Turbomeca S.A., using the contact information in paragraph (h)(5) of this proposed AD.

(5) For service information identified in this proposed AD, contact Turbomeca S.A., 40220 Tarnos, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15.

(6) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on February 29, 2016.

Colleen M. D'Alessandro,

Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2016-05465 Filed 3-10-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-6033; Directorate Identifier 2015-SW-019-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Airbus Helicopters Model AS 365 N3 helicopters. This proposed AD would require inspecting the cabin and cockpit for labels, placards, or markings that provide jettison procedure instructions for cabin doors, removing any labels, placards, or markings that are in an incorrect location, and installing placards where they are missing. This proposed AD is prompted by the determination that placards had not been installed according to specifications on newly manufactured helicopters. The proposed actions are intended to provide exit procedures during an emergency.

DATES: We must receive comments on this proposed AD by May 10, 2016.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202-493-2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.
- *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-6033; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and other

information. The street address for the Docket Operations Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT:

David Hatfield, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email david.hatfield@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2015-0068-E, dated April 29, 2015, to correct an unsafe condition for Airbus Helicopters Model AS 365 N3 helicopters without external life rafts installed, except those helicopters

modified in accordance with Airbus Helicopters modification (MOD) 0711B68, and Model AS 365 N3 helicopters with external life rafts installed, except those helicopters modified in accordance Airbus Helicopters MOD 0711B67 and MOD 0711B68. EASA advises that, during helicopter delivery after manufacturing, Airbus Helicopters identified that placards providing jettison procedure instructions for the cabin doors were not systematically installed or not installed in a proper location. This condition, if not corrected, could prevent the timely evacuation of the helicopter during an emergency. The EASA AD consequently requires determining whether any placards are missing or incorrectly located, installing any missing placards, and replacing any incorrectly located placards.

FAA's Determination

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, EASA, its technical representative, has notified us of the unsafe condition described in its AD. We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition is likely to exist or develop on other products of the same type design.

Related Service Information Under 1 CFR Part 51

We reviewed Airbus Helicopters Alert Service Bulletin No. AS365-11.00.02, Revision 2, dated April 23, 2015 (ASB). The service information describes procedures for replacing and installing cabin internal evacuation markings. The ASB reports that deviations in the locations of the cabin internal evacuation markings and missing markings were noted during the delivery of new helicopters. The ASB provides instructions about the locations of, characteristics of, and information contained in the markings.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Proposed AD Requirements

This proposed AD would require, within 50 hours time-in-service (TIS), inspecting the cabin and cockpit for labels, placards, or markings that provide jettison procedure instructions for cabin doors in certain locations. If a label, placard, or marking is not located as required or is not visible and legible

to every occupant, this proposed AD would require installing a placard in the required locations before further flight.

Differences Between This Proposed AD and the EASA AD

The EASA AD requires compliance within 14 days after the effective date of the EASA AD. This AD requires compliance within 50 hours TIS.

Costs of Compliance

We estimate that this proposed AD would affect 15 helicopters of U.S. Registry and that labor costs would average \$85 a work-hour. Based on these estimates, we expect that inspecting the helicopter to determine the proper location and presence of cabin door jettison procedure placards and replacing and installing them would require 4 work hours and a parts cost of \$70. We estimate a total cost of \$410 per helicopter, and \$6,150 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus Helicopters: Docket No. FAA–2015–6033; Directorate Identifier 2015–SW–019–AD.

(a) Applicability

This AD applies to Airbus Helicopters Model AS 365 N3 helicopters, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as missing or incorrectly located information for exiting a helicopter. This condition could result in failure to jettison cabin doors during an emergency, resulting in death or injury of helicopter occupants.

(c) Comments Due Date

We must receive comments by May 10, 2016.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 50 hours time-in-service:

(1) Inspect the cabin and cockpit for labels, placards, and markings that provide jettison procedure instructions for cabin doors.

(2) For the left and right side, remove any existing label, placard, and marking and install placards in accordance with the Accomplishment Instructions, paragraph 3.B.2 and Figures 1 through 6, of Airbus Helicopters Alert Service Bulletin No.

AS365–11.00.02, Revision 2, dated April 23, 2015.

(f) Credit for Previously Completed Actions

Actions accomplished before the effective date of this AD in accordance with Airbus Helicopters Modification (MOD) 0711B68 for helicopters without external life rafts or MOD 0711B68 and MOD 0711B67 for helicopters with external life rafts are considered acceptable for compliance with this AD.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: David Hatfield, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222–5110; email 9–ASW–FTW–AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD No. 2015–0068–E, dated April 29, 2015. You may view the EASA AD on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA–2015–6033.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 1100, Placards and Markings.

Issued in Fort Worth, Texas, on February 29, 2016.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2016–05369 Filed 3–10–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–4278; Directorate Identifier 2012–SW–022–AD]

RIN 2120–AA64

Airworthiness Directives; AgustaWestland S.p.A. (Agusta) Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain

Agusta Model AB139 and AW139 helicopters. This proposed AD would require performing operational checks of both hydraulic systems. This proposed AD is prompted by an assessment of the hydraulic systems of the helicopter following an accident. The proposed actions are intended to prevent loss of hydraulic power to the flight controls and subsequent loss of control of the helicopter.

DATES: We must receive comments on this proposed AD by May 10, 2016.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Docket:** Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- **Fax:** 202–493–2251.

- **Mail:** Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590–0001.

- **Hand Delivery:** Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket number FAA–2016–4278 or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D’Angelo; telephone 39–0331–664757; fax 39 0331–664680; or at <http://www.agustawestland.com/technical-bulletins>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Fort Worth, Texas 76177.

FOR FURTHER INFORMATION CONTACT: Matt Wilbanks, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Parkway, Fort Worth, Texas 76177; telephone (817) 222–5110; email matt.wilbanks@faa.gov.