

numbers (type certificate previously held by Cessna Aircraft Company) that are certificated in any category.

(1) Airplanes previously affected by AD 2008–15–06

Model	Serial Nos.	Year manufactured
(1) 175	55001 through 55703.	1958.
(2) 175	55704 through 56238.	1959.
(3) 175	28700A, 626, and 640.	1958 and 1959.
(4) 175A	56239 through 56777.	1960.

(2) New airplane affected by this AD:

Model	Serial Nos.	Year manufactured
175A	619	1960.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 71, Power Plant.

(e) Unsafe Condition

This AD was prompted by the determination that an airplane needs to be added to the Applicability section and an airplane needs to be removed from the Applicability section. We are issuing this AD to detect and correct cracks in the engine mounting brackets, which could result in failure of the engine mounting bracket. This failure could lead to the engine detaching from the firewall.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Logbook Check

(1) Check the airplane logbook to determine if all four of the original engine mounting brackets have been replaced. Do the logbook check at the following compliance time, as applicable. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action.

(i) *For airplanes previously affected by AD 2008–15–06:* Within the next 30 days after September 2, 2008 (the effective date retained from AD 2008–15–06).

(ii) *For the new airplane affected by this AD:* Within the next 30 days after the effective date of this AD.

(2) If you can positively determine that all four of the original engine mounting brackets have been replaced, no further action is required. Make an entry into the aircraft logbook showing compliance with this portion of the AD in accordance with 14 CFR 43.9. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action.

(3) If you cannot positively determine that all four of the original engine mounting brackets have been replaced, inspect each of the upper and lower engine mounting brackets on both the left and right sides for cracks following Cessna Single Engine Service Bulletin SEB07–2, Revision 2, dated June 18, 2007. Do the inspections at the following compliance times, as applicable.

(i) *For airplanes previously affected by AD 2008–15–06:* Initially inspect within the next 12 months after September 2, 2008 (the effective date retained from AD 2008–15–06). If no cracks are found, repetitively inspect thereafter at intervals not to exceed 500 hours time-in-service (TIS) until all four of the original engine mounting brackets are replaced.

(ii) *For the new airplane affected by this AD:* Initially inspect within the next 12 months after the effective date of this AD. If no cracks are found, repetitively inspect thereafter at intervals not to exceed 500 hours TIS until all four of the original engine mounting brackets are replaced.

(h) Engine Mounting Bracket Replacement

For all airplanes affected by this AD: If cracks are found in any of the engine mounting brackets during any inspection required in paragraph (g)(3) of this AD, including all subparagraphs, before further flight after the inspection in which cracks are found, replace the cracked engine mounting bracket(s) following Cessna Single Engine Service Bulletin SEB07–2, Revision 2, dated June 18, 2007. Replacing the cracked engine mounting bracket terminates the repetitive inspections required in paragraphs (g)(3)(i) and (g)(3)(ii) of this AD only for the replaced engine mounting bracket.

(i) Terminating Action

To terminate the repetitive inspections required in paragraphs (g)(3)(i) and (g)(3)(ii) of this AD, you may replace all four original engine mounting brackets following Cessna Single Engine Service Bulletin SEB07–2, Revision 2, dated June 18, 2007, at the following compliance times, as applicable.

(1) *For airplanes previously affected by AD 2008–15–06:* At any time before or after the initial inspection required in paragraph (g)(3)(i) of this AD.

(2) *For the new airplane affected by this AD:* At any time before or after the initial inspection required in paragraph (g)(3)(ii) of this AD.

(j) Engine Mounting Bracket Disposal

For all airplanes affected by this AD: Before further flight after the engine mounting bracket is removed for replacement, dispose of every replaced bracket following 14 CFR 43.10, paragraph (c)(6), which states the following: “Mutilation. The part may be mutilated to deter its installation in a type certificated product. The mutilation must render the part beyond repair and incapable of being reworked to appear to be airworthy.”

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if

requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved for AD 2008–15–06 are approved as AMOCs for the corresponding provisions of this AD.

(l) Related Information

(1) For more information about this AD, contact Gary Park, Aerospace Engineer, Wichita ACO, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946–4123; fax: (316) 946–4107, email: gary.park@faa.gov.

(2) For service information identified in this AD, contact Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517–5800; fax: (316) 942–9006; Internet: www.cessna.txtav.com. You may view this referenced service information at the FAA, FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on April 4, 2016.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–08259 Filed 4–11–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–5463; Directorate Identifier 2016–NM–013–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL–600–2C10 (Regional Jet Series 700, 701, & 702), Model CL–600–2D15 (Regional Jet Series 705), Model CL–600–2D24 (Regional Jet Series 900), and Model CL–600–2E25 (Regional Jet Series 1000) airplanes. This proposed AD was prompted by reports of corrosion found on the slat and flap torque tubes in the

slat and flap control system. This proposed AD would require replacement of the slat and flap torque tubes in the slat and flap control system. We are proposing this AD to prevent rupture of a corroded slat or flap torque tube. This condition could result in an inoperative slat or flap system and consequent reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by May 27, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; Internet: <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5463; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in

the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516-228-7318; fax: 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2016-5463; Directorate Identifier 2016-NM-013-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2016-03R1, dated February 18, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), Model CL-600-2D24 (Regional Jet Series 900), and Model CL-600-2E25 (Regional Jet Series 1000) airplanes. The MCAI states:

There have been a number of reports of corrosion found on the torque tubes in the slat and flap control system. Investigation revealed that the current design of the flap and slat torque tubes do not have proper corrosion protection and are not entirely

sealed which leads to moisture ingress and internal corrosion. A corroded tube may rupture resulting in an inoperative slat or flap system, or in a worst case scenario, could result in reduced controllability of the aeroplane. This [Canadian] AD mandates the replacement of affected slat and flap system torque tubes with [new or] modified torque tubes.

This [Canadian] AD was revised to add the statement that accomplishment of the initial Service Bulletin (SB) 670BA-27-067, dated 15 January 2015 also meets the requirements of this AD and to correct the editorial error for the release date of SB 670BA-27-067, Revision A.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5463.

Related Service Information Under 1 CFR Part 51

We reviewed Bombardier Service Bulletin 670BA-27-067, Revision A, dated February 23, 2015. This service information describes procedures for replacement of the slat and flap torque tubes in the slat and flap control system. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Costs of Compliance

We estimate that this proposed AD affects 509 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement of the slat and flap torque tubes	34 work-hours × \$85 per hour = \$2,890	\$105,000	\$107,890	\$54,916,010

According to the parts manufacturer, some of the costs of this proposed AD

may be covered under warranty, thereby reducing the cost impact on affected

individuals. We do not control warranty coverage for affected individuals. As a

result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2016-5463; Directorate Identifier 2016-NM-013-AD.

(a) Comments Due Date

We must receive comments by May 27, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), (c)(3), and (c)(4) of this AD.

(1) Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, serial numbers 10002 through 10342 inclusive.

(2) Bombardier, Inc. Model CL-600-2D15 (Regional Jet Series 705) airplanes, serial numbers 15001 through 15361 inclusive.

(3) Bombardier, Inc. Model CL-600-2D24 (Regional Jet Series 900) airplanes, serial numbers 15001 through 15361 inclusive.

(4) Bombardier, Inc. Model CL-600-2E25 (Regional Jet Series 1000) airplanes, serial numbers 19001 through 19041 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports of corrosion found on the slat and flap torque tubes in the slat and flap control system. We are issuing this AD to prevent rupture of a corroded slat or flap torque tube. This condition could result in an inoperative slat or flap system and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replace Slat and Flap Torque Tubes in the Slat and Flap Control System

Within the compliance times specified in paragraph (g)(1), (g)(2), or (g)(3) of this AD, as applicable: Replace the slat and flap torque tubes in the slat and flap control system with new or modified slat and flap torque tubes, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-27-067, Revision A, dated February 23, 2015.

(1) For airplanes that have accumulated 28,000 total flight hours or less as of the effective date of this AD, or with 137 months or less since the date of issuance of the original Canadian certificate of airworthiness or date of issuance of the original Canadian export certificate of airworthiness as of the effective date of this AD: Before the accumulation of 34,000 total flight hours or within 167 months since the date of issuance

of the original Canadian certificate of airworthiness or date of issuance of the original Canadian export certificate of airworthiness, whichever occurs first.

(2) For airplanes that have accumulated more than 28,000 total flight hours but not more than 36,000 total flight hours as of the effective date of this AD, and with more than 137 months but not more than 176 months since the date of issuance of the original Canadian certificate of airworthiness or date of issuance of the original Canadian export certificate of airworthiness as of the effective date of this AD: At the earlier of the times specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD.

(i) Within 6,000 flight hours or 30 months, whichever occurs first, after the effective date of this AD.

(ii) Before the accumulation of 38,000 total flight hours, or within 186 months since the date of issuance of the original Canadian certificate of airworthiness or date of issuance of the original Canadian export certificate of airworthiness, whichever occurs first.

(3) For airplanes that have accumulated more than 36,000 total flight hours as of the effective date of this AD, or with more than 176 months since the date of issuance of the original Canadian certificate of airworthiness or date of issuance of the original Canadian export certificate of airworthiness as of the effective date of this AD: Within 2,000 flight hours or 10 months, whichever occurs first, after the effective date of this AD.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA-27-067, dated January 15, 2015, which is not incorporated by reference in this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation

(TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2016-03R1, dated February 18, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5463.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; Internet: <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on March 31, 2016.

Victor Wicklund,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-08250 Filed 4-11-16; 8:45 am]

BILLING CODE 4910-13-P

POSTAL REGULATORY COMMISSION

39 CFR Part 3020

[Docket No. RM2016-8; Order No. 3213]

Mail Classification Schedule

AGENCY: Postal Regulatory Commission.

ACTION: Proposed rulemaking.

SUMMARY: The Commission is proposing rules which amend existing rules related to the Mail Classification Schedule and its associated product lists. The proposed rules revise some existing rules in order to better conform with current Commission practices related to the Mail Classification Schedule. The Commission invites public comment on the proposed rules.

DATES: *Comments are due:* May 12, 2016.

FOR FURTHER INFORMATION CONTACT: David A. Trissell, General Counsel, at 202-789-6820.

SUPPLEMENTARY INFORMATION:

Table of Contents

- I. Introduction
- II. History
- III. Rule Modifications
- IV. Public Representative
- V. Invitation of Comments
- VI. Ordering Paragraphs

I. Introduction

This rulemaking is initiated by the Postal Regulatory Commission

(Commission) to fulfill its responsibilities under the Postal Accountability and Enhancement Act (PAEA), Public Law 109-435, 120 Stat. 3198 (2006). The proposed rules amend existing rules concerning the Mail Classification Schedule (MCS) and the associated market dominant and competitive product lists. The proposals amend existing rules to conform to the current practice of publishing the MCS on the Commission's Web site at www.prc.gov, noticing changes to the market dominant and competitive product lists in the **Federal Register**, and publishing the market dominant and competitive product lists in the *Code of Federal Regulations* (CFR).

The proposed rules replace existing 39 CFR part 3020, subpart A in its entirety. Conforming changes also are proposed for 39 CFR part 3020, subparts B, C, and D. The proposed text for these rules appears after the signature of this Order.

II. History

On October 29, 2007, the Commission issued Order No. 43, which in part established rules concerning the MCS, and the market dominant and competitive product lists.¹ It also directed publication of an MCS outline in the CFR that was limited to a table of contents and the market dominant and competitive product lists. Order No. 43, Appendix A. These rules, including the appendix, were codified at 39 CFR part 3020.

The Commission, in Docket No. RM2007-1, also began the process of developing a comprehensive MCS.² This task was not complete at the time the Commission issued Order No. 43.

When an initial proposed MCS was complete, the Commission initiated Docket No. RM2011-8 to incorporate it into the CFR.³ The proposed MCS was to replace the existing outline of the MCS. The Commission solicited and received comments on both the proposed MCS and the corresponding rules. The suggestions provided in the

¹ Docket No. RM2007-1, Order Establishing Ratemaking Regulations for Market Dominant and Competitive Products, October 29, 2007, at 99-108, 138-154 (Order No. 43); 72 FR 64155, November 15, 2007.

² Docket No. RM2007-1, Order No. 26, Order Proposing Regulations to Establish a System of Ratemaking, August 15, 2007, at 2, 82-83; 72 FR 50744, September 4, 2007. *See also* Order No. 43 at 99.

³ Docket No. RM2011-8, Order No. 666, Notice of Proposed Rulemaking Concerning Mail Classification Schedule, February 7, 2011; Docket No. RM2011-8, Order No. 758, Notice of Proposed Rulemaking Concerning Mail Classification Schedule (Revising Order No. 666), July 12, 2011; 76 FR 51311 (Aug. 18, 2011) (to be codified at 39 CFR part 3020, subpart A).

comments were extremely helpful in further developing the MCS and have been incorporated into the rule proposals appearing in the instant rulemaking.

From an administrative perspective, the rulemaking also required the Commission to develop internal procedures for implementing the proposed rules. This included procedures for publishing timely updates to the MCS and the associated product lists appearing in the CFR. Because of the continuous flow of Postal Service proposals to add or modify products, the Commission recognized that keeping the CFR-published MCS and the associated product lists current would require updates on a weekly, if not daily, basis. With the procedures envisioned and the anticipated frequency of updates, the Commission concluded that it would incur prohibitive publication costs and challenging resource burdens.⁴

In the interim, the Postal Service and the Commission each maintained versions of the MCS. The Postal Service used its version when presenting price and classification proposals to the Commission for evaluation. This required the Commission to first resolve any differences between the Commission's version of the MCS and the Postal Service's version of the MCS before considering the Postal Service's proposals.

On April 1, 2013, the Commission published its version of the MCS to the Commission's Web site.⁵ This provided visibility to all interested persons participating in Commission proceedings as to current prices and classifications. From this point forward, the Postal Service submitted its proposed price and classification changes based on this version of the MCS.

The Commission developed internal procedures for updating the draft MCS appearing on its Web site on approximately a monthly basis. The Commission displays all changes in redline, as had been requested by the Postal Service. The redline changes are incorporated, and a new baseline MCS created, at the conclusion of major price or classification proceedings. All prior versions of the MCS are archived and available on the Web site for reference.

⁴ The Commission also explored a "publication by reference" approach with the **Federal Register**. This approach presented an equal number of challenges to the Commission and was dropped from consideration.

⁵ Notice of Posting Draft Mail Classification Schedule to the Commission's Web site, April 1, 2013. At this stage in the development of the MCS, the Commission's version and the Postal Service's version were nearly identical.