

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA–2016–6414; Directorate Identifier 2015–NM–175–AD.

(a) Comments Due Date

We must receive comments by June 24, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers 7003 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by two in-service incidents of a loss of all air data information in the flight deck. We are issuing this AD to prevent loss of control when a loss of all air data information has occurred in the flight deck.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual Revision

Within 30 days after the effective date of this AD, revise the emergency procedures section of the airplane flight manual (AFM) by incorporating Section 03–19, Unreliable Airspeed, Revision 63, dated February 13, 2015, of Chapter 3, Emergency Procedures, in the Bombardier CRJ Series Regional Jet Model CL–600–2B19 Airplane Flight Manual CSP A–012, Revision 64B, dated December 8, 2015.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2015–12, dated June 23, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by

searching for and locating Docket No. FAA–2016–6414.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on April 28, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–10732 Filed 5–9–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–6551; Directorate Identifier 2013–SW–070–AD]

RIN 2120–AA64

Airworthiness Directives; Bell Helicopter Textron Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bell Helicopter Textron (Bell) Model 430 helicopters. This proposed AD would require establishing a life limit for a certain main rotor hub attachment bolt (bolt) and removing from service each bolt that has met or exceeded its life limit. This proposed AD is prompted by a documentation error that omitted the life limit of a certain part-numbered bolt from the Airworthiness Limitations section of the maintenance manual. The proposed actions are intended to establish a life limit for a certain part-numbered bolt to prevent failure of a bolt, failure of a main rotor hub, and subsequent loss of control of a helicopter.

DATES: We must receive comments on this proposed AD by July 11, 2016.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202–493–2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket

Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.

- **Hand Delivery:** Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6551; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Bell Helicopter Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; telephone (450) 437-2862 or (800) 363-8023; fax (450) 433-0272; or at <http://www.bellcustomer.com/files/>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive

public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

Discussion

Transport Canada, which is the aviation authority for Canada, has issued AD No. CF-2013-26, dated September 24, 2013, to correct an unsafe condition for certain serial-numbered Bell Model 430 helicopters. Transport Canada advises that bolt part number (P/N) MS21250-08083, which replaced bolt P/N 20-065-08083 in 2009, has a retirement life of 5,000 hours. However, the retirement life for the replacement bolt was inadvertently omitted from the limitations section of the Bell 430 maintenance manual. Transport Canada advises that this situation, if not corrected, could result in failure of a bolt and loss of control of the helicopter. Transport Canada AD No. CF-2013-26 requires reviewing the helicopter records to determine if bolt P/N MS21250-08083 is installed, creating a historical service record, and establishing an airworthiness life of 5,000 hours air time.

FAA's Determination

This helicopter has been approved by the aviation authority of Canada and is approved for operation in the United States. Pursuant to our bilateral agreement with Canada, Transport Canada, its technical representative, has notified us of the unsafe condition described in its AD. We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition is likely to exist or develop on other products of the same type design.

Related Service Information

We reviewed Bell Helicopter Alert Service Bulletin 430-12-47, dated November 14, 2012 (ASB). The ASB states that original bolt P/N 20-065-08083 has a retirement life of 5,000 hours but has been replaced by standard bolt P/N MS21250-08083, which does not have a life limit listed in the maintenance manual. The purpose of the ASB is to establish a life limit of 5,000 hours for the replacement bolt. Bell specifies reviewing the aircraft records back to January 2009 to determine which part-numbered bolts are installed. If a replacement bolt P/N

MS21250-08083 is installed, the ASB specifies using data from aircraft records to create a historical service record for the replacement bolts and reflecting the 5,000 hours life limit. The ASB also specifies updating the Bell 430 maintenance manual.

Proposed AD Requirements

This proposed AD would require within 10 hours time-in-service (TIS), revising the Airworthiness Limitations section of the applicable maintenance manual or Instructions for Continued Airworthiness (ICA) by establishing a life limit of 5,000 hours TIS for each bolt P/N MS21250-08083. This proposed AD would also require determining the number of hours TIS for each bolt and using the helicopter's hours if the hours TIS of a bolt is unknown. This proposed AD would also require removing from service each bolt that has reached or exceeded its life limit.

Differences Between This Proposed AD and the Transport Canada AD

The proposed AD would require compliance within 10 hours TIS, while the Transport Canada AD requires compliance within 60 days.

Costs of Compliance

We estimate that this proposed AD would affect 43 helicopters of U.S. Registry. We estimate that operators may incur the following costs in order to comply with this AD. At an average labor cost of \$85 per work-hour, we estimate reviewing and revising the records would require 1 work-hour for a cost of about \$85 per helicopter and \$3,655 for the U.S. fleet. We estimate replacing a bolt that has exceeded its life limit would require 0.5 work-hour plus \$290 for a replacement bolt, for a total cost of \$333 per bolt.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bell Helicopter Textron: Docket No. FAA–2016–6551; Directorate Identifier 2013–SW–070–AD.

(a) Applicability

This AD applies to Model 430 helicopters, serial number 49001 through 49129, with a main rotor head attachment bolt (bolt) part number MS21250–08083 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a bolt remaining in service beyond its fatigue life. This condition could result in failure of a bolt, failure of the main rotor hub and subsequent loss of control of a helicopter.

(c) Comments Due Date

We must receive comments by July 11, 2016.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 10 hours time-in-service (TIS):

(1) Revise the Airworthiness Limitations section of the applicable maintenance manual or Instructions for Continued Airworthiness (ICA) to establish a life limit of 5,000 hours TIS for each bolt P/N MS21250–08083.

(2) Determine the number of hours TIS for each bolt and update the helicopter's historical records. If the hours TIS is unknown, calculate the number of hours TIS by counting the helicopter's hours TIS beginning January 1, 2009.

(3) Remove from service each bolt that has reached or exceeded its life limit.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222–5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Bell Helicopter Alert Service Bulletin 430–12–47, dated November 14, 2012, which is not incorporated by reference, contains additional information about the subject of this proposed rule. For service information identified in this proposed rule, contact Bell Helicopter Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; telephone (450) 437–2862 or (800) 363–8023; fax (450) 433–0272; or at <http://www.bellcustomer.com/files/>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in Transport Canada AD No. CF–2013–26, dated September 24, 2013. You may view the Transport Canada AD on the Internet at <http://www.regulations.gov> in the AD Docket.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6220 Main Rotor Head.

Issued in Fort Worth, Texas, on April 27, 2016.

James A. Grigg,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2016–10860 Filed 5–9–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–6415; Directorate Identifier 2015–NM–178–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL–600–2C10 (Regional Jet Series 700, 701, & 702) airplanes. This proposed AD was prompted by two in-service incidents of a loss of all air data information in the flight deck. This proposed AD would require a revision of the airplane flight manual (AFM) emergency procedures section to provide procedures to guide the crew on how to stabilize the airplane airspeed and attitude for continued safe flight when a loss of all air data information has occurred in the flight deck. We are proposing this AD to prevent loss of control when a loss of all air data information has occurred in the flight deck.

DATES: We must receive comments on this proposed AD by June 24, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202–493–2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.