

Issued in Renton, Washington, on June 16, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-14965 Filed 6-27-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-7269; Directorate Identifier 2015-NM-198-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A300 series airplanes; Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. This proposed AD was prompted by a report indicating that during inspections to detect corrosion of the bulk cargo doors, several cracks were discovered. This proposed AD would require a general visual inspection of the bulk cargo door frame to identify any structural repairs, a detailed visual inspection of the frame at the repaired area for any cracking if necessary, and corrective actions if necessary. We are proposing this AD to detect and correct cracking of the bulk cargo doors; such cracking could result in rapid airplane decompression or possible loss of the bulk cargo door.

DATES: We must receive comments on this proposed AD by August 12, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7269; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2016-7269; Directorate Identifier 2015-NM-198-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness

Directive 2015-0238, dated December 18, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for Airbus Model A300 series airplanes; Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. The MCAI states:

During inspections to detect corrosion on the Bulk Cargo Doors of Airbus A300 family aeroplanes, several cracks were discovered. Investigations revealed that a set of SRM [structural repair manual] repair solutions was defined in 1993, and was classified as permanent and without limitation. As of 2011, this set of repair solutions was revised and classified permanent, but with post-repair required actions.

This condition, if not detected and corrected, could result in rapid decompression events or even loss of the bulk cargo door.

As per Ageing Aircraft rules, it was determined that new inspections have to be completed on the Bulk Cargo Door Frames to detect potential fatigue damages on repaired structures or to perform a new repair scheme.

Based on the fact that several aeroplanes could potentially be flying with potential fatigue damages on repaired structures, Airbus was requested to issue Alert Operator Transmission (AOT) A53W010-15 to provide fleet-wide inspection instructions to address this condition.

For the reasons describes above, this [EASA] AD requires a one-time inspection of the bulk cargo door frame to determine whether a repair has been accomplished and, depending on findings, accomplishment of applicable corrective action(s).

The required actions in this NPRM include a detailed visual inspection of the bulk cargo door frame at the repaired area for any cracking, repair of cracks, and post-repair inspections of crack-free frames. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7269.

Related Service Information Under 14 CFR Part 51

We reviewed Airbus Alert Operators Transmission A53W010-15, Revision 00, including Appendixes 1, 2, and 3, dated December 15, 2015. The service information describes a general visual inspection of the bulk cargo door frame to identify any structural repairs, and a detailed visual inspection of the frame at the repaired area. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of

Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or

develop on other products of these same type designs.

Costs of Compliance

We estimate that this proposed AD affects 135 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$11,475

We have received no definitive data that would enable us to provide cost

estimates for the on-condition actions specified in this proposed AD, except

for the cost of reporting, specified as follows:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Reporting	1 work-hour × \$85 per hour = \$85	\$0	\$85

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120–0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that

section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2016–7269; Directorate Identifier 2015–NM–198–AD.

(a) Comments Due Date

We must receive comments by August 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes; Model A300 B4–601, B4–603, B4–620, B4–622, B4–605R, B4–622R, F4–605R, and F4–622R airplanes, and Model A300 C4–605R Variant F airplanes; and Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes, certificated in any category, that have accumulated more than 14,600 total flight cycles as of the effective date of this AD.

Note 1 to paragraph (c) of this AD: For airplanes that have accumulated 14,600 total flight cycles or fewer as of the effective date of this AD, no actions are required by this AD.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report indicating that during inspections to detect corrosion of the bulk cargo doors, several cracks were discovered. We are issuing this AD to detect and correct cracking of the bulk cargo doors; such cracking could result in rapid airplane decompression or possible loss of the bulk cargo door.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 250 flight cycles or 6 months after the effective date of this AD, whichever occurs first, do a general visual inspection of the bulk cargo door frame to identify the existence of any structural repairs, in accordance with the instructions of Airbus Alert Operators Transmission (AOT) A53W010-15, Revision 00, including Appendixes 1, 2, and 3, dated December 15, 2015.

(h) Detailed Visual Inspection

If, during the general visual inspection required in paragraph (g) of this AD, any repair is found on the bulk cargo door frame: Before further flight, do a detailed visual inspection for cracking of the frame at the repaired area, in accordance with the instructions of Airbus AOT A53W010-15, Revision 00, including Appendixes 1, 2, and 3, dated December 15, 2015.

(i) Crack Repair

If any cracking is found during the detailed visual inspection required by paragraph (h) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA Design Organization Approval (DOA).

(j) Post-Repair Actions for Crack-Free Frames

If no cracking is found during the detailed visual inspection required by paragraph (h) of this AD: Do the actions in paragraphs (j)(1) and (j)(2) of this AD.

(1) At the applicable time specified in paragraph (j)(1)(i) or (j)(1)(ii) of this AD: Send a report of the inspection results to Airbus Service Bulletin Reporting Online Application on Airbus World (<https://w3.airbus.com/>).

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 60 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 60 days after the effective date of this AD.

(2) Within 2,800 flight cycles after the detailed visual inspection required by paragraph (h) of this AD: Do applicable post-repair inspections and repairs, using a method approved by the Manager, International Branch, ANM-116, Transport

Airplane Directorate, FAA; or EASA; or Airbus's EASA Design Organization Approval (DOA).

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0238, dated December 18, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7269.

(2) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 10, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-14968 Filed 6-27-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-7270; Directorate Identifier 2015-NM-116-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-700 and -700C series airplanes. This proposed AD was prompted by a report that for airplanes with blended winglets, the nose-up pitch trim limit and associated warning for the horizontal stabilizer control system will allow take-off with incorrect trim settings. This proposed AD would require, depending on airplane configuration, replacing the pitch trim light plates on the flight deck control stand, relocating the position warning horn switches of the horizontal stabilizer, revising the software, removing the placard, and doing related investigative and corrective actions if necessary. We are proposing this AD to prevent take-off with incorrect settings of the horizontal stabilizer pitch trim system. Settings outside of the appropriate pitch trim limits could result in loss of controllability of the airplane during take-off.

DATES: We must receive comments on this proposed AD by August 12, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For Aviation Partners Boeing service information identified in this NPRM, contact Aviation Partners Boeing, 2811 South 102nd Street, Suite 200, Seattle, WA 98168; phone: 206-830-7699; fax: 206-767-3355; email: leng@aviationpartners.com; Internet: <http://www.aviationpartnersboeing.com>.