

c. in the event of emergency not limited to smoke and fire detected in the cargo compartment.

5. A placard stating, "Do Not Enter During Taxi, Takeoff, Landing, or Emergency" (or similar wording) must be located outside of, and on or near the access hatch of, the aft lower-deck Class C cargo compartment.

6. The airplane must be operated as private, not for hire, not for common carriage. This provision does not preclude the operator from receiving remuneration to the extent consistent with 14 CFR parts 125 and 91, subpart F, as applicable.

7. Use of the access hatch, and access to the aft Class C cargo compartment, is limited to the crew only. A placard stating, "Crew Only Access" must be located outside of, and on or near the access hatch of, the aft lower-deck Class C cargo compartment.

8. The Airplane Flight Manual must instruct the crew to close the access hatch when crew are not accessing the aft lower-deck Class C cargo compartment.

9. Special conditions 4, 6, and 7 must be documented in the Limitations section of the Airplane Flight Manual.

Note: The airplane owner or operator must contact the Transport Security Administration (TSA) prior to operating within United States airspace to ensure that this design, and related operational procedures, comply with TSA requirements.

Issued in Renton, Washington, on October 14, 2016.

Michael Kaszycki,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-25810 Filed 10-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9300; Directorate Identifier 2016-NM-124-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model DC-6, DC-6A, C-118A, R6D-1, DC-6B, and R6D-1Z airplanes. This proposed AD was

prompted by a report of a fuel leak in a Model C-118A airplane that resulted from a crack in the wing lower skin. This proposed AD would require repetitive radiographic, electromagnetic testing high frequency (ETHF), and electromagnetic testing low frequency (ETLF) inspections for cracking of the wing lower skin, and repairs if necessary. We are proposing this AD to detect and correct fatigue cracking in the wing lower skin, which could adversely affect the structural integrity of the wing.

DATES: We must receive comments on this proposed AD by December 12, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9300.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9300; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be

available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Haytham Alaidy, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5224; fax: 562-627-5210; email: haytham.alaidy@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-9300; Directorate Identifier 2016-NM-124-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of a fuel leak in a Model C-118A airplane. The fuel leak, discovered during a post-flight inspection, resulted from a crack in the wing lower skin just inboard of the number 2 nacelle attach angle at wing station 175.

Related AD 80-12-02 R1, Amendment 39-5499, applies to Model DC-6, DC-6A, DC-6B, R6D, and C-118 series airplanes. AD 80-12-02 R1 requires repetitive inspections for cracking of the left and right wing lower skin at certain locations. Although wing station 175 is covered by the inspection mandated in AD 80-12-02 R1, the crack was missed during an AD-required inspection.

Boeing Alert Service Bulletin DC6-57A001, dated April 28, 2016 ("ASB DC6-57A001, Revision 0") is an alternative method of compliance (AMOC) to the inspections required by paragraph (c)(1) of AD 80-12-02 R1. This AMOC only applies to the areas inspected in accordance with ASB DC6-57A001, Revision 0. The service information referenced in this NPRM contains revised inspection procedures for crack detection in the area around wing station 175. Such cracking in the

wing lower skin could adversely affect the structural integrity of the wing.

Related Service Information Under 14 CFR Part 51

We reviewed ASB DC6-57A001, Revision 0. The service information describes procedures for radiographic, ETHEF, and ETLF inspections for cracking of the wing lower skin at station 175, and repairs. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or

develop in other products of these same type designs.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between this Proposed AD and the Service Information." For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9300.

Differences Between This Proposed AD and the Service Information

ASB DC6-57A001, Revision 0, specifies to contact the manufacturer for certain instructions, but this proposed

AD would require accomplishment of repair methods, modification deviations, and alteration deviations in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD affects 36 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections	17 work-hours × \$85 per hour = \$1,445 per inspection cycle.	\$0	\$1,445 per inspection cycle	\$52,020 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2016-9300; Directorate Identifier 2016-NM-124-AD.

(a) Comments Due Date

We must receive comments by December 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model DC-6, DC-6A, DC-6B, C-118A, R6D-1, and R6D-1Z airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of a fuel leak in a Model C-118A airplane that resulted from a crack in the wing lower skin just inboard of the number 2 nacelle attach angle at wing station 175. We are issuing this AD to detect and correct fatigue cracking in the wing lower skin, which could adversely affect the structural integrity of the wing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Except as specified in paragraph (i) of this AD: At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin DC6-57A001, dated April 28, 2016 ("ASB DC6-57A001, Revision 0"), do radiographic, electromagnetic testing high frequency (ETHF), and electromagnetic testing low frequency (ETLF) inspections for cracking of the wing lower skin at station 175, in accordance with the Accomplishment Instructions of ASB DC6-57A001, Revision 0. Repeat the radiographic, ETHF, and ETLF inspections of any unrepaired areas thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of ASB DC6-57A001, Revision 0.

(h) Repairs

If any cracking is found during any inspection required by this AD: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Service information Exception

Where paragraph 1.E., "Compliance," of ASB DC6-57A001, Revision 0, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC

requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Haytham Alaidy, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5224; fax: 562-627-5210; email: haytham.alaidy@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on October 13, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-25663 Filed 10-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-9298; Directorate Identifier 2015-NM-161-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A300 series airplanes. This AD was prompted by an evaluation by the design approval holder (DAH) that indicates a section of the wing and aft fuselage is subject to widespread fatigue damage (WFD). This proposed AD would require an inspection to determine if certain modifications have been done. For airplanes on which the specified modifications have not been done, this proposed AD would require

accomplishing those modifications, including doing related investigative and corrective actions if necessary. We are proposing this AD to prevent reduced structural integrity of these airplanes due to the failure of certain structural components.

DATES: We must receive comments on this proposed AD by December 12, 2016.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office-EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: continued.airworthiness-wb.external@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9298; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION: