

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement of fuel manifold	2 work-hours × \$85 per hour = \$170	\$16,000	\$16,170	\$1,762,530

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

General Electric Company: Docket No. FAA–2017–0016; Directorate Identifier 2016–NE–31–AD.

(a) Comments Due Date

We must receive comments by April 14, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all GENx–1B64, –1B64/P1, –1B64/P2, –1B67, –1B67/P1, –1B67/P2, –1B70, –1B70/75/P1, –1B70/75/P2, –1B70/P1, –1B70/P2, –1B70C/P1, –1B70C/P2, –1B74/75/P1, –1B74/75/P2, –1B76A/P2 engines with outer left side signal fuel manifold, part number (P/N) 2403M46G01, and CAGE code 05813, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7313, Fuel Injector Nozzle.

(e) Unsafe Condition

This AD was prompted by fracture of the fuel manifold which led to an in-flight shutdown of the engine. We are issuing this AD to prevent fracture of the fuel manifold, engine fire, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Inspect the outer left side signal fuel manifold, P/N 2403M46G01 and CAGE code 05813, to determine if the part has additional marking “XB,” “INS,” or “KB” adjacent to part number. If the part is marked with “XB,” “INS,” or “KB,” then no further action is required.

(2) For parts without additional marking “XB,” “INS,” or “KB” adjacent to the part number, within 12 months after the effective date of this AD, replace the outer left side signal fuel manifold with a part eligible for installation.

(g) Installation Prohibition

After the effective date of this AD, do not install an outer left side signal fuel manifold,

P/N 2403M46G01, and CAGE code 05813, onto an engine, unless additional marking “XB,” “INS,” or “KB” is adjacent to the part number.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(i) Related Information

(1) For more information about this AD, contact Christopher McGuire, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7120; fax: 781–238–7199; email: chris.mcguire@faa.gov.

(2) GE GENx–1B Service Bulletin (SB) 73–0051 R00, dated November 4, 2016; GE GENx–1B SB 73–0052 R00, dated October 28, 2016; and GE GENx–1B SB 73–0053 R00, dated November 15, 2016, can be obtained from GE using the contact information in paragraph (i)(3) of this AD. These SBs, respectively, describe procedures for inspection, repair, and replacement of the outer left side signal fuel manifold.

(3) For service information identified in this proposed AD, contact General Electric Company, GE-Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215, phone: 513–552–3272; fax: 513–552–3329; email: geae.aoc@ge.com.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

Issued in Burlington, Massachusetts, on February 14, 2017.

Carlos A. Pestana,

Acting Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2017–03740 Filed 2–27–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–0124; Directorate Identifier 2016–NM–166–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model BD-100-1A10 airplanes. This proposed AD was prompted by several reports of nose wheel steering failures in service. This proposed AD would require a part verification and replacement of certain steering manifolds. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by April 14, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0124; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the

regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Assata Dessaline, Aerospace Engineer, Avionics and Services Branch, ANE-172, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7301; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0124; Directorate Identifier 2016-NM-166-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2016-24, dated August 19, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model BD-100-1A10 airplanes. The MCAI states:

Several cases of nose wheel steering failures have been reported in service. In one case, the aeroplane experienced uncommanded nose wheel steering, resulting in a runway excursion.

Investigations found the presence of moisture inside the electrical stage of the electro-hydraulic servo valve (EHSV) unit, which resulted in low insulation resistance and corrosion. This condition, in combination with a steering selector valve failure, could result in uncommanded nose wheel steering, which could lead to a runway excursion at high speed.

This [Canadian] AD mandates the replacement of the steering manifold to provide better moisture ingress protection of the EHSV.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0124.

Related Service Information Under 1 CFR Part 51

We reviewed Bombardier Service Bulletin 100-32-25, Revision 01, dated June 30, 2015. This service information describes procedures for a one-time verification of the steering manifold part number and replacement of the steering manifold and mod plate. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 161 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Steering manifold part verification	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$13,685
Replacement of steering manifold	Up to 4 work-hours × \$85 per hour = \$340.	Up to \$18,522	Up to \$18,862	Up to \$3,036,782

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2017-0124; Directorate Identifier 2016-NM-166-AD.

(a) Comments Due Date

We must receive comments by April 14, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-100-1A10 airplanes, certificated in any category, as identified in Bombardier Service Bulletin 100-32-25, Revision 01, dated June 30, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by several reports of nose wheel steering failures in service. We are issuing this AD to prevent moisture from entering the electrical stage of the electro-hydraulic servo valve (EHSV), which could lead to uncommanded nose wheel steering, and a consequent runway excursion at high speed.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Verification and Replacement of Steering Manifold

Within 48 months after the effective date of this AD, do a one-time inspection to determine the part number of the steering manifold, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100-32-25, Revision 01, dated June 30, 2015.

(1) If the airplane has steering manifold part number (P/N) 40750-103, within 48 months after the effective date of this AD, write "SB100-32-018" on the nose landing gear (NLG) mod plate. If the mod plate is missing or full, within 48 months after the effective date of this AD, install a new plate, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100-32-25, Revision 01, dated June 30, 2015.

(2) If the airplane has steering manifold P/N 40750-101, within 48 months after the effective date of this AD, replace it in accordance with the Accomplishment Instructions of Bombardier Service Bulletin

100-32-25, Revision 01, dated June 30, 2015, and write "SB100-32-018" on the NLG mod plate. If the mod plate is missing or full, within 48 months after the effective date of this AD, install a new plate, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100-32-25, Revision 01, dated June 30, 2015.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 100-32-25, dated September 24, 2014.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install a steering manifold, P/N 40750-101, on the nose landing gear assembly of any airplane.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2016-24, dated August 19, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0124.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on February 15, 2017.

Thomas Groves,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-03712 Filed 2-27-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0123; Directorate Identifier 2016-NM-033-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Defense and Space S.A. Model CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes. This proposed AD was prompted by a reported inability to extend the external handle of the emergency door from its recess due to a jammed spring mechanism. This proposed AD would require a one-time functional check of each emergency door handle, and corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by April 14, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact EADS-CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain;

telephone: +34 91 585 55 84; fax: +34 91 585 55 05; email:

MTA.TechnicalService@casa.eads.net;

Internet: <http://www.eads.net>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0123; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1112; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2017-0123; Directorate Identifier 2016-NM-033-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2016-0051, dated March 11, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition

for all Airbus Defense and Space S.A. Model CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes. The MCAI states:

Failure to extend the external handle of emergency door from its recess was reported. As a consequence, it was impossible to open the rear emergency door from outside. Subsequent investigation determined that jamming of the door spring mechanism led to failure pushing out the emergency door external handle from its position normally aligned with the door skin.

This condition, if not detected and corrected, could lead to failure to open the emergency door from outside in an emergency.

To address this potential unsafe condition, Airbus Defence&Space (D&S) issued Alert Operators Transmission (AOT) AOT-CN235-52-0001 and AOT-C295-52-0001 to provide inspection instructions [and corrective actions if necessary].

For the reasons described above, this [EASA] AD requires a one-time functional check of [each of] the affected emergency door external handle[s] and, depending on findings, [detailed visual inspection for damage or unexpected material and] corrective action [repair]. This [EASA] AD also requires reporting the check result.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0123.

Related Service Information Under 14 CFR Part 51

We reviewed the following Airbus Defense and Space service information.

- Airbus Defense and Space Alert Operators Transmission (AOT) AOT-CN235-52-0001, dated September 4, 2014.
- Airbus Defense and Space AOT-C295-52-0001, dated September 4, 2014.

The service information describes procedures for a one-time functional check of each emergency door handle and corrective actions if necessary. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this