

Given that the United States domestic annual production volume of RTE fully-cooked poultry is about 12,325 million pounds,<sup>7</sup> the projected cooked poultry products from the PRC would only be about 2.6 percent of total United States production in the next five years.<sup>8</sup> The immediate impact on the United States consumers and domestic processors is likely to be minor, as the low volume of trade is likely to have little effect on supply, demand, and prices.

#### Expected Effects on Small Entities

The FSIS Administrator has made a preliminary determination that this proposed rule will not have a significant impact on a substantial number of small entities, as defined by the Regulatory Flexibility Act (5 U.S.C. 601). The expected trade volume will be small, with little or no effect on all U.S. establishments, regardless of size.

#### Executive Order 12988

This proposed rule has been reviewed under Executive Order 12988, Civil Justice Reform. If this proposed rule is adopted: (1) All State and local laws and regulations that are inconsistent with this rule will be preempted; (2) No retroactive effect will be given to this rule; and (3) Administrative proceedings will not be required before parties may file suit in court challenging this rule.

#### Paperwork Reduction Act

No new paperwork requirements are associated with this proposed rule. Foreign countries wanting to export poultry and poultry products to the United States are required to provide information to FSIS certifying that their inspection systems provide standards equivalent to those of the United States, and that the legal authority for the system and their implementing regulations are equivalent to those of the United States. FSIS provided the PRC with questionnaires asking for detailed information about the country's inspection practices and procedures to assist that country in organizing its materials. This information collection

the People's Republic of China, November 2015. The projected annual production of the mentioned chicken and duck products at these five processing establishments will be about 838 million pounds per year, which could be sold in the PRC or to other foreign countries.

<sup>7</sup> Calculated from PHIS data in November 2015. This number cannot be divided by species. If we adjusted it by the proportions of chicken and ducks in total domestic slaughtered poultry, which is 88.3 percent, the volume would be about 10,833 million pounds per year.

<sup>8</sup> If we use 10,833 million pounds (see previous footnote) as the denominator, the projected PRC export would be about 3 percent of United States domestic production of fully-cooked chicken and duck.

was approved under OMB control number 0583-0094. The proposed rule contains no other paperwork requirements.

#### E-Government Act

FSIS and USDA are committed to achieving the purposes of the E-Government Act (44 U.S.C. 3601, *et seq.*) by, among other things, promoting the use of the Internet and other information technologies and providing increased opportunities for citizen access to Government information and services, and for other purposes.

#### Additional Public Notification

FSIS will officially notify the World Trade Organization's Committee on Sanitary and Phytosanitary Measures (WTO/SPS Committee) in Geneva, Switzerland, of this proposal and will announce it on-line through the FSIS Web page located at: [http://www.fsis.usda.gov/regulations\\_&\\_policies/Proposed\\_Rules/index.asp](http://www.fsis.usda.gov/regulations_&_policies/Proposed_Rules/index.asp). FSIS also will make copies of this **Federal Register** publication available through the FSIS Constituent Update, which is used to provide information regarding FSIS policies, procedures, regulations, **Federal Register** notices, FSIS public meetings, and other types of information that could affect or would be of interest to our constituents and stakeholders. The Update is available on the FSIS Web page. Through the Web page, FSIS is able to provide information to a much broader, more diverse audience. In addition, FSIS offers an email subscription service which provides automatic and customized access to selected food safety news and information. This service is available at: <http://www.fsis.usda.gov/subscribe>. Options range from recalls to export information, regulations, directives, and notices. Customers can add or delete subscriptions themselves, and have the option to password protect their accounts.

#### USDA Non-Discrimination Statement

No agency, officer, or employee of the USDA, on the grounds of race, color, national origin, religion, sex, gender identity, sexual orientation, disability, age, marital status, family/parental status, income derived from a public assistance program, or political beliefs, shall exclude from participation in, deny the benefits of, or subject to discrimination, any person in the United States under any program or activity conducted by the USDA.

#### How To File a Complaint of Discrimination

To file a complaint of discrimination, complete the USDA Program Discrimination Complaint Form, which may be accessed online at [http://www.ocio.usda.gov/sites/default/files/docs/2012/Complain\\_combined\\_6\\_8\\_12.pdf](http://www.ocio.usda.gov/sites/default/files/docs/2012/Complain_combined_6_8_12.pdf), or write a letter signed by you or your authorized representative.

Send your completed complaint form or letter to USDA by mail, fax, or email:

**Mail:** U.S. Department of Agriculture, Director, Office of Adjudication, 1400 Independence Avenue SW., Washington, DC 20250-9410.

**Fax:** (202) 690-7442.

**Email:** [program.intake@usda.gov](mailto:program.intake@usda.gov).

Persons with disabilities who require alternative means for communication (Braille, large print, audiotape, etc.), should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD).

#### List of Subjects in 9 CFR Part 381

Imported products.

For the reasons set out in the preamble, FSIS is proposing to amend 9 CFR part 381 as follows:

#### PART 381—POULTRY PRODUCTS INSPECTION REGULATIONS

■ 1. The authority citation for Part 381 continues to read as follows:

**Authority:** 7 U.S.C. 138f, 450; 21 U.S.C. 451-470; 7 CFR 2.7, 2.18, 2.53.

#### § 381.196 [Amended]

■ 2. Amend § 381.196(b) by removing footnote 2 after "People's Republic of China."

Done at Washington, DC, on June 12, 2017.

**Alfred V. Almanza,**  
Administrator.

[FR Doc. 2017-12554 Filed 6-15-17; 8:45 am]

**BILLING CODE 3410-DM-P**

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2017-0490; Directorate Identifier 2017-NE-13-AD]

RIN 2120-AA64

#### Airworthiness Directives; Ipeco Holdings Ltd. Pilot and Co-Pilot Seats

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain

Ipeco Holdings Ltd. (Ipeco) pilot and co-pilot seats. This proposed AD was prompted by reports of unexpected movement of pilot and co-pilot seats on takeoff and landing. This proposed AD would require modification and reidentification of the affected seats. We are proposing this AD to correct the unsafe condition on these products.

**DATES:** We must receive comments on this NPRM by July 31, 2017.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Mail:** Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- **Fax:** 202-493-2251.

For service information identified in this proposed AD, contact Ipeco Holdings Ltd., Aviation Way, Southend on Sea, SS2 6UN, United Kingdom; phone: 44 1702 549371; fax: 44 1702 540782; email: [sales@Ipeco.com](mailto:sales@Ipeco.com). You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0490; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments

will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Neil Doh, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7757; fax: 781-238-7199; email: [neil.doh@faa.gov](mailto:neil.doh@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0490; Directorate Identifier 2017-NE-13-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD.

**Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2016-0256, dated December 16, 2016 (referred to hereinafter as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Occurrences have been reported of pilot/co-pilot unexpected rearward movement during take-off and landing. Investigations determined that horizontal guide block wear, presence of burrs on horizontal centre track, and horizontal track lock system weakness (spring tension too low) were various causes which contributed to the seat not being correctly locked.

This condition, if not corrected, could lead to further cases of unwanted flight crew seat

movement, possibly resulting in reduced control of the aeroplane.

You may obtain further information by examining the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0490.

**Related Service Information Under 1 CFR Part 51**

Ipeco has issued Service Bulletin (SB) 063-25-08, Revision 00; SB 063-25-09, Revision 00; and SB 063-25-10, Revision 00; all dated May 31, 2016. These SBs provides instructions, differentiated by the part numbers of the affected pilot and co-pilot seats, for the modification and reidentification of these seats. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of the United Kingdom, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This proposed AD would require modification and reidentification of the affected pilot and co-pilot seats.

**Costs of Compliance**

We estimate that this proposed AD affects an unknown number of pilot and co-pilot seats installed on 55 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modify crew seats .....	2 work-hours × \$85 per hour = \$170 .....	\$125	\$295	\$16,225

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Ipeco Holdings Ltd.:** Docket No. FAA-2017-0490; Directorate Identifier 2017-NE-13-AD.

#### (a) Comments Due Date

We must receive comments by July 31, 2017.

#### (b) Affected ADs

None.

### (c) Applicability

(1) This AD applies to Ipeco Holdings Ltd. (Ipeco) pilot and co-pilot crew seats with a part number (P/N) listed in the Planning Information section of Ipeco Service Bulletins (SBs) 063-25-08, Revision 00, dated May 31, 2016; 063-25-09, Revision 00, dated May 31, 2016; and 063-25-10, Revision 00, dated May 31, 2016.

(2) These seats are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR 42 and ATR 72 airplanes.

### (d) Subject

Joint Aircraft System Component (JASC) Code 2510, Flight Compartment Equipment.

### (e) Reason

This AD was prompted by reports of unexpected movement of pilot and co-pilot seats on takeoff and landing. We are issuing this AD to prevent unexpected movement of pilot and co-pilot seats on takeoff and landing. The unsafe condition, if not corrected, could result in reduced control of the airplane.

### (f) Compliance

(1) Comply with this AD within the compliance times specified, unless already done.

(2) Within 2 years after the effective date of this AD, modify and reidentify each affected pilot and co-pilot seat. Use the Accomplishment Instructions of Ipeco SB 063-25-08, Revision 00, dated May 31, 2016; Ipeco SB 063-25-09, Revision 00, dated May 31, 2016; or Ipeco SB 063-25-10, Revision 00, dated May 31, 2016; as appropriate, to do the modification and reidentification.

### (g) Installation Prohibition

Do not install any pilot or co-pilot seat identified in paragraph (c) of this AD unless the seat is modified and reidentified as specified in paragraph (f)(2) of this AD.

### (h) Alternative Methods of Compliance (AMOCs)

The Manager, Boston Aircraft Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

### (i) Related Information

(1) For more information about this AD, contact Neil Doh, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7757; fax: 781-238-7199; email: [neil.doh@faa.gov](mailto:neil.doh@faa.gov).

(2) Refer to MCAI European Aviation Safety Agency AD 2016-0256, dated December 16, 2016, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-0490.

(3) Ipeco SB 063-25-08, Revision 00, dated May 31, 2016; Ipeco SB 063-25-09, Revision 00, dated May 31, 2016; and Ipeco SB 063-25-10, Revision 00, dated May 31, 2016, can be obtained from Ipeco, using the contact information in paragraph (i)(4) of this proposed AD.

(4) For service information identified in this proposed AD, contact Ipeco Holdings Ltd., Aviation Way, Southend on Sea, SS26UN, United Kingdom; phone: 44 1702 549371; fax: 44 1702 540782; email: [sales@Ipeco.com](mailto:sales@Ipeco.com).

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on June 9, 2017.

**Robert J. Ganley,**

*Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2017-12305 Filed 6-15-17; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2017-0555; Directorate Identifier 2016-NM-183-AD]

RIN 2120-AA64

### Airworthiness Directives; Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2013-02-12, which applies to all EADS CASA (now Airbus Defense and Space S.A.) Model CN-235, CN-235-100, CN-235-200, and CN-235-300 airplanes. AD 2013-02-12 currently requires a one-time inspection to identify the correct polarity for each pair of electrical connectors on each engine fire extinguisher cartridge, and repair if necessary. Since we issued AD 2013-02-12, we have determined it is necessary to add a requirement for modifying the installation of the fire extinguisher circuit harness. This proposed AD would continue to require identifying the correct polarity of each pair of electrical connectors of the affected engine fire extinguisher cartridge, and doing a repair if necessary. This proposed AD would also require modifying the installation of the fire extinguisher circuit harnesses. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by July 31, 2017.