

**(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-57-027, Revision 2, dated December 11, 2013.

(ii) Fokker Service Bulletin SBF100-57-028, Revision 2, dated December 11, 2013.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone: +31 (0)88-6280-350; fax: +31 (0)88-6280-111; email: [technicalservices@fokker.com](mailto:technicalservices@fokker.com); Internet: <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 3, 2017.

**Dionne Palermo,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017-14583 Filed 7-18-17; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2016-9506; Directorate Identifier 2016-NM-090-AD; Amendment 39-18957; AD 2017-14-13]**

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. This AD was prompted by a report of an aborted takeoff because the rudder pedals were not operating correctly. Investigation revealed a protruding screw in the rudder pedal heel rest adjacent to the pedals. This AD requires a torque check of the screws in

the cover assembly of the heel rest for both the Captain and the First Officer's rudder pedals, and corrective action if necessary. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective August 23, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 23, 2017.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9506.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9506; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6490; fax: 425-917-6590; email: [Kelly.McGuckin@faa.gov](mailto:Kelly.McGuckin@faa.gov).

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. The NPRM published in the **Federal**

**Register** on December 20, 2016 (81 FR 92753). The NPRM was prompted by a report of an aborted takeoff because the rudder pedals were not operating correctly. Investigation revealed a protruding screw in the rudder pedal heel rest adjacent to the pedals. It was determined that the screws in the cover assembly of the heel rest for both the Captain and the First Officer's rudder pedals might not have been properly torqued. The NPRM proposed to require a torque check of the screws in the cover assembly of the heel rest for both the Captain and the First Officer's rudder pedals, and corrective action if necessary. We are issuing this AD to detect and correct a protruding screw in the cover assembly of the heel rest of a rudder pedal. A protruding screw could restrict rudder pedal motion and reduce differential braking control during takeoff or landing, which could cause a high speed runway excursion.

**Comments**

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA's response to each comment.

**Support for the NPRM**

Boeing, Air Line Pilots Association, International, and Tyler Myers supported the intent of the NPRM.

**Request To Allow Credit for Previously Accomplished Actions**

United Airlines noted that the NPRM did not address whether or not the final rule would allow operators to take credit for accomplishment of the actions in Boeing Alert Service Bulletin 737-25A1732, Revision 1, dated August 15, 2016 ("BASB 737-25A1732, Revision 1"), if completed prior to the effective date of the final rule. We infer that the commenter is requesting that the final rule include a statement that accomplishment of the actions specified in BASB 737-25A1732, Revision 1, prior to the effective date of the final rule is acceptable for compliance with the requirements of the final rule.

We agree with the commenter that operators should be able to take credit for accomplishment of the actions in BASB 737-25A1732, Revision 1, prior to the effective date of this AD. This allowance was provided in paragraph (f) of the proposed AD in the statement "Comply with this AD within the compliance times specified unless already done." However, since the NPRM was issued, Boeing has published, and we have reviewed, Boeing Alert Service Bulletin 737-25A1732, Revision 2, dated April 13,

2017 (“BASB 737–25A1732, Revision 2”). BASB 737–25A1732, Revision 2, provides clarification of the actions described in the work instructions by providing supplementary details and including additional descriptive figures. No additional work is necessary and the scope of this AD is not expanded.

We have revised paragraphs (c), (g), and (h) of this AD to refer to BASB 737–25A1732, Revision 2. We have also added paragraph (i) to this AD to give credit for actions accomplished using the work instructions in BASB 737–25A1732, Revision 1; and redesignated the subsequent paragraphs accordingly.

**Effect of Winglets on Accomplishment of the Proposed Actions**

Aviation Partners Boeing stated that the installation of winglets per Supplemental Type Certificate (STC) ST00830SE does not affect the

accomplishment of the manufacturer’s service instructions.

We agree with the commenter that STC ST00830SE does not affect the accomplishment of the manufacturer’s service instructions. Therefore, the installation of STC ST00830SE does not affect the ability to accomplish the actions required by this AD. We have not changed this AD in this regard.

**Conclusion**

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Torque check .....	2 work-hours × \$85 per hour = \$170 .....	\$0	\$170	\$201,790

We have received no definitive data that will enable us to provide cost estimates for the on-condition actions specified in this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on

the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Related Service Information Under 14 CFR Part 51**

We reviewed Boeing Alert Service Bulletin 737–25A1732, Revision 2, dated April 13, 2017. The service information describes procedures for a torque check of the screws in the cover assembly of the heel rest for both the Captain and the First Officer’s rudder pedals, and corrective action. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

We estimate that this AD affects 1,187 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2017–14–13 The Boeing Company:**  
Amendment 39–18957; Docket No. FAA–2016–9506; Directorate Identifier 2016–NM–090–AD.

**(a) Effective Date**

This AD is effective August 23, 2017.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737–25A1732, Revision 2, dated April 13, 2017.

**(d) Subject**

Air Transport Association (ATA) of America Code 25, Equipment and Furnishings.

**(e) Unsafe Condition**

This AD was prompted by a report of an aborted takeoff because the rudder pedals were not operating correctly. Investigation revealed a protruding screw in the rudder pedal heel rest adjacent to the pedals. It was determined that the screws in the cover assembly of the heel rest for both the Captain and the First Officer’s rudder pedals might

not have been properly torqued. We are issuing this AD to detect and correct a protruding screw in the cover assembly of the heel rest of a rudder pedal. A protruding screw could restrict rudder pedal motion and reduce differential braking control during takeoff or landing, which could cause a high speed runway excursion.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Torque Check

Within 21 months after the effective date of this AD: Do a one-time torque check of the screws in the cover assembly of the heel rest for both the Captain and the First Officer's rudder pedals, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-25A1732, Revision 2, dated April 13, 2017.

#### (h) Corrective Action

If the results of the torque check required by paragraph (g) of this AD indicate that any screw does not hold torque to the required value, before further flight, replace the affected screw and associated nutplate, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-25A1732, Revision 2, dated April 13, 2017.

#### (i) Credit for Actions Accomplished Previously

This paragraph provides credit for the actions specified in paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737-25A1732, Revision 1, dated August 15, 2016.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or sub-step is labeled "RC Exempt," then the RC requirement is removed from that step or sub-step. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (k) Related Information

(1) For more information about this AD, contact Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6490; fax: 425-917-6590; email: [Kelly.McGuckin@faa.gov](mailto:Kelly.McGuckin@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-25A1732, Revision 2, dated April 13, 2017.

(ii) Reserved.

(iii) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 29, 2017.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017-14584 Filed 7-18-17; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Part 300

[TD 9820]

RIN 1545-BN09

#### Special Enrollment Examination User Fee for Enrolled Agents

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Final regulation.

**SUMMARY:** This document contains a final regulation changing the amount of the user fee for the special enrollment examination to become an enrolled agent. The charging of user fees is authorized by the Independent Offices Appropriations Act of 1952. The final regulation affects individuals taking the enrolled agent special enrollment examination.

#### **DATES:**

*Effective date:* This regulation is effective August 18, 2017.

*Applicability date:* For the date of applicability, see § 300.4(d).

#### **FOR FURTHER INFORMATION CONTACT:**

Jonathan R. Black, (202) 317-6845 (not a toll-free number).

#### **SUPPLEMENTARY INFORMATION:**

#### **Background and Explanation of Provisions**

This document contains amendments to 26 CFR part 300 regarding user fees. On January 26, 2016, a notice of proposed rulemaking (REG-134122-15) proposing to change the amount of the Enrolled Agent Special Enrollment Examination (EA-SEE) user fee was published in the **Federal Register** (81 FR 4221) (January 26, 2016 proposed rule). On October 25, 2016, a second notice of proposed rulemaking (REG-134122-15) withdrawing the January 26, 2016 proposed rule and proposing a smaller change to the EA-SEE user fee was published in the **Federal Register** (81 FR 73363) (October 25, 2016 proposed rule). Comments responding to each proposed rule were received, and a public hearing on the second proposed rule was held on December 29, 2016. After consideration of the comments, this Treasury decision adopts the regulations proposed by the October 25, 2016 proposed rule without change.

#### *A. Enrolled Agents and the Special Enrollment Examination*

Section 330 of title 31 of the United States Code authorizes the Secretary of the Treasury to regulate the practice of