

phone: 562-627-5239; fax: 562-627-5210; email: chandraduth.ramdoss@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on July 18, 2017.

Victor Wicklund,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-15554 Filed 7-26-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0708; Directorate Identifier 2017-NM-035-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede Airworthiness Directive (AD) AD 2016-20-11, for certain Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Airbus Model A310 series airplanes. AD 2016-20-11 requires repetitive inspections of the external area of the aft cargo door sill beam for cracking, repetitive inspections for fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, and repair if necessary. Since we issued AD 2016-20-11, we have determined that reinforcement of the aft cargo door sill beam area is necessary to address the unsafe condition, which constitutes terminating action for the repetitive inspections. This proposed AD would retain the inspections for cracking, and repair if necessary; and require reinforcement of the aft cargo door sill beam area. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 11, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0708; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0708; Directorate Identifier 2017-NM-035-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory,

economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On September 28, 2016, we issued AD 2016-20-11, Amendment 39-18677 (81 FR 85837, November 29, 2016) (“AD 2016-20-11”), for certain Airbus Model A300-600 series airplanes; and Airbus Model A310 series airplanes. AD 2016-20-11 was prompted by reports of fatigue cracks on the cargo door sill beam, lock fitting, and torsion box plate. AD 2016-20-11 requires repetitive ultrasonic and detailed inspections of the external area of the aft cargo door sill beam for cracking, repetitive high frequency eddy current (HFEC) inspections for fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, and repair if necessary. We issued AD 2016-20-11 to detect and correct fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, which could result in the loss of the door locking function and subsequently, loss of the cargo door in flight and rapid decompression.

Since we issued AD 2016-20-11, Airbus has developed a reinforcement modification of the aft cargo door sill beam area, which constitutes terminating action for the repetitive inspections. We have determined the reinforcement of the aft cargo door sill beam area is necessary to address the unsafe condition.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0048, dated March 15, 2017; corrected April 20, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus Model A300-600 series airplanes; and Airbus Model A310 series airplanes. The MCAI states:

In the frame of the widespread fatigue damage (WFD) compliance study and after an in-service occurrence, the area of the aft cargo door sill beam and adjacent structure was identified as sensitive to the fatigue loads.

This condition, if not detected and corrected, could lead to failure of multiple lock fittings, possibly resulting in loss of the cargo door in flight and consequent explosive decompression of the aeroplane.

To address this potential unsafe condition, Airbus issued Alert Operators Transmission (AOT) A53W005-14 providing inspection instructions and, consequently, EASA issued Emergency AD 2014-0097-E [which corresponded to FAA AD 2014-12-06] to require repetitive ultrasonic inspections (US) or detailed inspections (DET) of the aft cargo door sill beam area [and corrective actions if necessary].

After that [EASA] AD was issued, further analysis indicated that repetitive high frequency eddy current (HFEC) inspections needed to be introduced, and Airbus published Service Bulletin (SB) A310-53-2139 and SB A300-53-6179 to provide instructions. Prompted by this determination, EASA issued AD 2015-0150, retaining the requirements of EASA Emergency AD 2014-0097-E, which was superseded, and required repetitive HFEC inspections of the concerned areas. The first HFEC inspection terminated the repetitive US/DET inspections. That [EASA] AD also required the inspection results to be reported.

Since that [EASA] AD was issued, Airbus developed a reinforcement modification of the aft cargo door sill beam area, and published Airbus SB A310-53-2141 and SB A300-53-6181, which were revised lately, to make this available for in-service application.

For the reasons described above, this [EASA] AD retains the requirements of EASA AD 2015-0150 [which corresponded to FAA AD 2016-20-11], which is superseded, and requires modification [reinforcement] of the aft cargo door sill beam, which constitutes

terminating action for the repetitive inspections.

This [EASA] AD is re-published to correct the compliance time description in Table 4.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0708.

Related Service Information Under 1 CFR Part 51

Airbus has issued Airbus Service Bulletin A300-53-6181, Revision 01, dated July 2, 2015; and A310-53-2141, Revision 01, dated July 2, 2015. This service information describes procedures for reinforcing the aft cargo door sill beam. These service bulletins are distinct since they apply to different airplane models.

Airbus has issued Airbus Service Bulletin A300-53-6179, dated December 12, 2014; and A310-53-2139, dated December 12, 2014. This service information describes procedures for repetitive HFEC inspections of the cargo door sill beam, lock fitting, and torsion box plate. These service bulletins are distinct since they apply to different airplane models.

Airbus has also issued AOT A53W005-14, Revision 01, dated April

29, 2014, which describes procedures for doing an ultrasonic inspection or detailed inspection of the aft cargo door sill beam external area for cracking.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this AD affects 75 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection (retained actions from AD 2016-20-11).	12 work-hours × \$85 per hour = \$1,020 per inspection cycle.	N/A	\$1,020 per inspection cycle ...	\$76,500 per inspection cycle.
Modification (new proposed action).	40 work-hours × \$85 per hour = \$3,400.	\$96,890	\$100,290	\$7,521,750.
Reporting (retained action from AD 2016-20-11).	1 work-hour × \$85 per hour = \$85 per inspection cycle.	0	\$85 per inspection cycle	\$6,375 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120-0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing

instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a

substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2016–20–11, Amendment 39–18677 (81 FR 85837, November 29, 2016), and adding the following new AD:

Airbus: Docket No. FAA–2017–0708; Directorate Identifier 2017–NM–035–AD.

(a) Comments Due Date

We must receive comments by September 11, 2017.

(b) Affected ADs

This AD replaces AD 2016–20–11, Amendment 39–18677 (81 FR 85837, November 29, 2016) (“AD 2016–20–11”).

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1) through (c)(5) of this AD, certificated in any category, all manufacturer serial numbers on which Airbus Modification 05438 has been embodied in production, except those on which Airbus Modification 12046 has been embodied in production.

- (1) Airbus Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.
- (2) Airbus Model A300 B4–605R and B4–622R airplanes.
- (3) Airbus Model A300 F4–605R and F4–622R airplanes.

(4) Airbus Model A300 C4–605R Variant F airplanes.

(5) Airbus Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of fatigue cracks on the cargo door sill beam, lock fitting, and torsion box plate. We are issuing this AD to prevent fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, which could result in the loss of the door locking function and subsequently, loss of the cargo door in flight and rapid decompression.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2016–20–11, with no changes. Within the compliance time identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD, as applicable: Do an ultrasonic inspection or detailed inspection of the aft cargo door sill beam external area for cracking, in accordance with Airbus Alert Operators Transmission (AOT) A53W005–14, dated April 22, 2014; or Airbus AOT A53W005–14, Revision 01, dated April 29, 2014. Repeat the inspection thereafter at intervals not to exceed 275 flight cycles. As of January 3, 2017 (the effective date of AD 2016–20–11), use only AOT A53W005–14, Revision 01, dated April 29, 2014, to comply with the requirements of this paragraph.

(1) For airplanes that have accumulated 30,000 flight cycles or more since the airplane’s first flight as of July 2, 2014 (the effective date of AD 2014–12–06, Amendment 39–17867, (79 FR 34403, June 17, 2014) (“AD 2014–12–06”)): Within 50 flight cycles after July 2, 2014.

(2) For airplanes that have accumulated 18,000 flight cycles or more, but fewer than 30,000 flight cycles since the airplane’s first flight as of July 2, 2014 (the effective date of AD 2014–12–06): Within 275 flight cycles after July 2, 2014.

(3) For airplanes that have accumulated fewer than 18,000 flight cycles since the airplane’s first flight as of July 2, 2014 (the effective date of AD 2014–12–06): Before exceeding 18,275 flight cycles since the airplane’s first flight.

(h) Retained Optional Terminating Action, With No Changes

This paragraph restates the provisions of paragraph (h) of AD 2016–20–11, with no changes. Accomplishment of a high frequency eddy current (HFEC) inspection for cracking, in accordance with Airbus AOT A53W005–14, dated April 22, 2014; or AOT A53W005–14, Revision 01, dated April 29, 2014; terminates the repetitive inspections required by paragraph (g) of this AD for that airplane. If any cracking is found during the HFEC inspection, before further flight, repair using a method approved by the Manager,

International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus’s EASA Design Organization Approval (DOA).

(i) Retained Reporting Requirement, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2016–20–11, with no changes. Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g) of this AD to “Airbus Service Bulletin Reporting Online Application” on Airbus World (<https://w3.airbus.com/>), at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the inspection results, including no findings.

(1) If the inspection was done on or after January 3, 2017 (the effective date of AD 2016–20–11): Submit the report within 30 days after the inspection.

(2) If the inspection was done before January 3, 2017 (the effective date of AD 2016–20–11): Submit the report within 30 days after January 3, 2017.

(j) Retained Definition of Airplane Groups, With No Changes

This paragraph restates the definitions specified in paragraph (j) of AD 2016–20–11, with no changes. Paragraphs (k)(1), (k)(2), and (k)(3) of this AD refer to airplane groups, as identified in paragraphs (j)(1), (j)(2), and (j)(3) of this AD.

(1) Airplanes on which an HFEC inspection was accomplished as specified in Airbus AOT A53W005–14.

(2) Airplanes on which no HFEC inspection was accomplished as specified in Airbus AOT A53W005–14, that have accumulated more than 18,000 total flight cycles as of January 3, 2017 (the effective date of AD 2016–20–11).

(3) Airplanes on which no HFEC inspection was accomplished as specified in Airbus AOT A53W005–14, that have accumulated 18,000 total flight cycles or fewer as of January 3, 2017 (the effective date of AD 2016–20–11).

(k) Retained Repetitive HFEC Inspections, With No Changes

This paragraph restates the requirements of paragraph (k) of AD 2016–20–11, with no changes. At the applicable time specified in paragraph (k)(1), (k)(2), or (k)(3) of this AD: Do an HFEC inspection for fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, in accordance with Airbus Service Bulletin A300–53–6179, dated December 12, 2014; or Airbus Service Bulletin A310–53–2139, dated December 12, 2014; as applicable. Repeat the HFEC inspection thereafter at intervals not to exceed 4,600 flight cycles.

(1) For airplanes identified in paragraph (j)(1) of this AD: Inspect within 4,600 flight cycles after the most recent HFEC inspection specified in Airbus AOT A53W005–14.

(2) For airplanes identified in paragraph (j)(2) of this AD: Inspect within 2,000 flight cycles after January 3, 2017 (the effective date of AD 2016–20–11).

(3) For airplanes identified in paragraph (j)(3) of this AD: Inspect before exceeding 13,000 total flight cycles since the airplane’s

first flight, or within 2,000 flight cycles after January 3, 2017 (the effective date of AD 2016–20–11), whichever occurs later.

(l) Retained Corrective Action, With No Changes

This paragraph restates the requirements of paragraph (l) of AD 2016–20–11, with no changes. If any crack is found during any inspection required by paragraph (g) or (k) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA.

(m) Retained Terminating Action for Repetitive Inspections in Paragraph (g) of This AD, With No Changes

This paragraph restates the terminating action of paragraph (m)(1) of AD 2016–20–11, with no changes. For any airplane identified in paragraphs (j)(2) and (j)(3) of this AD, accomplishment of the initial inspection required by paragraph (k) of this AD terminates the repetitive inspections required by paragraph (g) of this AD.

(n) New Cargo Door Reinforcement

At the latest of the applicable times specified in paragraphs (n)(1), (n)(2), and (n)(3) of this AD: Reinforce the aft cargo door sill beam area, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310–53–2141, Revision 01, dated July 2, 2015; or Airbus Service Bulletin A300–53–6181, Revision 01, dated July 2, 2015; as applicable.

(1) Before exceeding 19,600 flight cycles since first flight of the airplane.

(2) Within 2,300 flight cycles after the last HFEC or detailed inspection required by this AD that was accomplished before the effective date of this AD.

(3) Within 12 months after the effective date of this AD.

(o) New Terminating Action

Modification of an airplane as required by paragraph (n) of this AD constitutes terminating action for the repetitive inspections required by paragraphs (g) and (k) of this AD for that airplane.

(p) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (n) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A300–53–6181, dated June 26, 2015; or Airbus Service Bulletin A310–53–2141, dated June 26, 2015; as applicable.

(q) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the

attention of the person identified in paragraph (r)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2016–20–11 are approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(4) *Required for Compliance (RC)*: Except as required by paragraph (l) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(r) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017–0048, dated March 15, 2017; corrected April 20, 2017, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0708.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind

Avenue SW., Renton, WA 98057–3356; telephone 425–227–2125; fax 425–227–1149. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 14, 2017.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–15553 Filed 7–26–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF COMMERCE

Bureau of Economic Analysis

15 CFR Part 801

[Docket No.: 170322304–7304–01]

RIN 0691–AA86

Direct Investment Surveys: BE–12, Benchmark Survey of Foreign Direct Investment in the United States

AGENCY: Bureau of Economic Analysis, Commerce.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule would amend regulations of the Department of Commerce's Bureau of Economic Analysis (BEA) to set forth the reporting requirements for the 2017 BE–12, Benchmark Survey of Foreign Direct Investment in the United States. The BE–12 survey is conducted every five years; the prior survey covered 2012. The benchmark survey covers the universe of foreign direct investment in the United States and is BEA's most detailed survey of such investment. For the 2017 benchmark survey, BEA proposes changes in data items collected, the design of the survey forms, and the reporting requirements for the survey to satisfy changing data needs, improve data quality and the effectiveness and efficiency of data collection.

DATES: Comments on this proposed rule will receive consideration if submitted in writing on or before 5 p.m. September 25, 2017.

ADDRESSES: You may submit comments, identified by RIN 0691–AA86, and referencing the agency name (Bureau of Economic Analysis), by any of the following methods: