

paragraph (i)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) Refer to MCAI EASA AD 2015–0126, dated July 1, 2015, for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0029.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW, Renton, WA 98057–3356; telephone: 425–227–1138; fax: 425–227–1149.

(j) Material Incorporated by Reference

None.

Issued in Renton, Washington, on January 25, 2018.

Michael Kaszycki,

*Acting Director, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2018–02350 Filed 2–6–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0030; Product Identifier 2014–NM–161–AD; Amendment 39–19180; AD 2018–03–07]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A330–202, –203, –223, and –243 airplanes; and Model A340–211, –212, –311, and –313 airplanes. This AD requires contacting the FAA to obtain instructions for addressing the unsafe condition on these products, and doing the actions specified in those instructions. This AD was prompted by a report of a hard contact that was found between the constant speed motor/generator feeder line route 6G/6E and the optional cabin temperature control pipe on the upper shell between certain frames. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective February 22, 2018.

We must receive comments on this AD by March 26, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0030; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW, Renton, WA 98057–3356; telephone: 425–227–1138; fax: 425–227–1149.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2014–0161, dated July 10, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus Model A330–202, –203, –223, and –243 airplanes; and Model A340–211, –212, –311, and –313 airplanes. The MCAI states:

A hard contact was found on an A330 aeroplane during production between the Constant Speed Motor/Generator (CSM/G) feeder line route 6G/6E (Functional Item Number 1526VB) and the optional cabin temperature control pipe on the upper shell between Frame (FR)37.4 and FR38 on stringer 5, right hand (RH) side.

This condition, if not corrected, may lead to chafing and, consequently, a short circuit when the emergency generation is activated, resulting in the loss of emergency generation. The loss of normal generation combined with the loss of emergency generation jeopardizes the aeroplane safe flight.

To address this potential unsafe condition, Airbus developed a modification to provide adequate clearance between harness 1526VB and the affected (optional) air-conditioning temperature control pipe. A340–200/–300 aeroplanes equipped with this optional cabin temperature control pipe are also affected by this issue. The modification can be embodied in service through Airbus Service Bulletin (SB) A330–92–3125, or SB A340–92–4097, as applicable.

For the reasons described above, this [EASA] AD requires modification of the CSM/G mounting with installation of new stacking and/or longer bracket, depending on aeroplane configuration.

You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0030.

FAA’s Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of these same type designs.

FAA’s Determination of the Effective Date

Since there are currently no domestic operators of this product, we find good cause that notice and opportunity for prior public comment are unnecessary. In addition, for the reason(s) stated above, we find that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–0030; Product Identifier 2014–NM–161–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments

received by the closing date and may amend this AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We

will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

Currently, there are no affected U.S.-registered airplanes. This AD requires contacting the FAA to obtain

instructions for addressing the unsafe condition, and doing the actions specified in those instructions. Based on the actions specified in the MCAI AD, we are providing the following cost estimates for an affected airplane that is placed on the U.S. Register in the future:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product
Modification	Up to 17 work-hours × \$85 per hour = \$1,445 ...	Up to \$256	Up to \$1,701.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;

2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018-03-07 Airbus: Amendment 39-19180; Docket No. FAA-2018-0030; Product Identifier 2014-NM-161-AD.

(a) Effective Date

This AD becomes effective February 22, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Airbus Model A330-202, -203, -223, and -243 airplanes, all manufacturer serial numbers on which Airbus modification 45775, 45790, 45795, 46165, 46779, 48099, 48454, 52131, 52802, 53730, 53819, 54310, 54410, 54420, 54530, 55231, 55630, 56080, 56260, 56620, 57186, 57430, 200774, 201071,

201298, 201888, 202558, or 203045 has been embodied in production, except those on which Airbus modification 203395 has been embodied in production.

(2) Airbus Model A340-211, -212, -311, and -313 airplanes, all manufacturer serial numbers on which Airbus modification 40413, 40550, 40901, 42021, 43590, or 46487 has been embodied in production, except those on which Airbus modification 203395 has been embodied in production.

(d) Subject

Air Transport Association (ATA) of America Code 92, Electrical system installation.

(e) Reason

This AD was prompted by a report of a hard contact that was found between the constant speed motor/generator feeder line route 6G/6E and the optional cabin temperature control pipe on the upper shell between certain frames. We are issuing this AD to prevent chafing, which can lead to a short circuit when the emergency generation is activated and a consequent loss of emergency generation. The loss of normal generation combined with the loss of emergency generation could adversely affect the airplane’s continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Action(s)

Within 30 days after the effective date of this AD, request instructions from the Manager, International Section, Transport Standards Branch, FAA, to address the unsafe condition specified in paragraph (e) of this AD; and accomplish the action(s) at the times specified in, and in accordance with, those instructions. Guidance can be found in Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency (EASA) AD 2014-0161, dated July 10, 2014.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19,

send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (i)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) Refer to MCAI EASA AD 2014-0161, dated July 10, 2014, for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0030.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW, Renton, WA 98057-3356; telephone: 425-227-1138; fax: 425-227-1149.

(j) Material Incorporated by Reference

None.

Issued in Renton, Washington, on January 26, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-02354 Filed 2-6-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Part 11

[Docket No. RM11-6-000]

Annual Update to Fee Schedule for the Use of Government Lands by Hydropower Licensees; Correction

AGENCY: Federal Energy Regulatory Commission,DOE.

ACTION: Correcting amendment.

SUMMARY: This document contains corrections to the final rule (RM11-6-000) which published in the **Federal Register** on Tuesday, March 7, 2017 (82 FR 12717). The Final Rule provided the annual update to the fee schedule in Appendix A to Part 11, which lists per-acre rental fees by county (or other geographic area) for use of government lands by hydropower licensees and updated Appendix A to Part 11 with the fee schedule of per-acre rental fees by county (or other geographic area) from October 1, 2016, through September 30, 2017 (Fiscal Year 2017).

DATES: Effective February 7, 2018, and is applicable beginning October 1, 2016.

FOR FURTHER INFORMATION CONTACT: Norman Richardson, Financial Management Division, Office of the Executive Director, Federal Energy Regulatory Commission, 888 First Street

NE, Washington, DC 20426, (202) 502-6219, Norman.Richardson@ferc.gov.

SUPPLEMENTARY INFORMATION:

On February 28, 2017, the Commission issued an *Annual Update to Fee Schedule for the Use of Government Lands for Hydropower Licensees* in the above-captioned proceeding. Pursuant to *Annual Charges for the Use of Government Lands in Alaska*, Order No. 838, 83 FR 1 (Jan. 2, 2018), FERC Stats. & Regs. ¶ 61,281 (2017), this document updates the per-acre rental fees for the State of Alaska, as reflected in the caption below.

List of Subjects in 18 CFR Part 11

Public lands.

Accordingly, 18 CFR part 11 is corrected by making the following correcting amendment:

PART 11—[AMENDED]

■ 1. The authority citation for part 11 continues to read as follows:

Authority: 16 U.S.C. 792-828c; 42 U.S.C. 7101-7352.

■ 2. Appendix A to Part 11 is amended by:

■ a. Revising the entries under “Alaska”; and

■ b. Removing footnote 1.

The revisions read as follows:

Appendix A to Part 11—Fee Schedule for FY 2017

State	County	Fee/acre/yr
Alaska	Aleutian Islands Area	\$1.02
	Statewide per-acre	\$36.53

Issued: February 1, 2018.

Kimberly D. Bose,

Secretary.

[FR Doc. 2018-02412 Filed 2-6-18; 8:45 am]

BILLING CODE 6717-01-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 100

[Docket No. USCG-2018-0013]

Special Local Regulation; Black Warrior River, Tuscaloosa, AL

AGENCY: Coast Guard, DHS.

ACTION: Notice of enforcement of regulation.

SUMMARY: The Coast Guard will enforce a special local regulation on the Black Warrior River extending the entire width of the channel from mile marker 339.0 to mile marker 341.5 in Tuscaloosa, AL on March 24, 2018, to provide for the safety of life on navigable waterways during the Rowing Competition marine event. Our regulation for Recurring Marine Events in Captain of the Port Sector Mobile Zone identifies the regulated area for this rowing event. During the enforcement period, no vessel may transit this regulated area without approval from the Captain of the Port

Sector Mobile or a designated representative.

DATES: The regulation in 33 CFR 100.801, Table 7, line 4, will be enforced from 6 a.m. through 4:30 p.m. on March 24, 2018.

FOR FURTHER INFORMATION CONTACT: If you have questions about this notice of enforcement, call or email call or email LT Kyle D. Berry, Sector Mobile, Waterways Management Division, U.S. Coast Guard; telephone 251-441-5940, email Kyle.D.Berry@uscg.mil.

SUPPLEMENTARY INFORMATION: The Coast Guard will enforce a special local regulation for the annual “Rowing Competition/University of South Alabama”, listed in 33 CFR 100.801, Table 7, line 4, from 6 a.m. through 4:30 p.m. on March 24, 2018. This action is