

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0084; Product Identifier 2018-NE-02-AD; Amendment 39-19212; AD 2018-05-03]

RIN 2120-AA64

Airworthiness Directives; Safran Helicopter Engines, S.A., Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Safran Helicopter Engines, S.A., Arrius 2F turboshaft engines. This AD requires inspection and replacement of the magnetic heads installed on oil system electrical magnetic plugs. This AD was prompted by reports from the manufacturer of a batch of non-conforming magnetic heads installed on electrical magnetic plugs. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective March 21, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 21, 2018.

We must receive comments on this AD by April 20, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Safran Helicopter Engines, S.A., 40220 Tarnos, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15. You may view this service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803.

For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0084.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0084; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Robert Green, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2018-0012-E, dated January 16, 2018 (referred to hereinafter as “the MCAI”), to address an unsafe condition for the specified products. The MCAI states:

Flaking of the cadmium coating of electrical magnetic plugs head Part Number (P/N) 9 520 01 154 5 was detected. Investigation results indicate that this was the result of manufacturing deficiency. This part is installed on electrical magnetic plugs (front and rear position) of the engine, providing warning signals for early detection of internal part(s) structural degradation, propagating in form of presence of metal particles in the lubrication system. The subsequent investigation identified the batch of affected magnetic plugs heads by serial number (s/n).

This condition, if not detected and corrected, could lead to reduced capability of the particle detection system to identify internal structural failures and consequent in-flight shut-down, resulting in forced landing with possible damage to the helicopter and injury to occupants.

To address this potential unsafe condition, Safran Helicopter Engines issued Alert Mandatory Service Bulletin (MSB) A319 79 4840 and Alert MSB A319 79 4841 to provide inspection and replacement instructions.

You may obtain further information by examining the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2018-0084.

Related Service Information Under 14 CFR Part 51

We reviewed Safran Helicopter Engines Alert Mandatory Service Bulletin (MSB) No. A319 79 4840, Version A, dated November 27, 2017, and Safran Helicopter Engines Alert MSB No. A319 79 4841, Version A, dated November 20, 2017. The MSBs describe procedures, respectively, for inspecting and replacing the magnetic heads installed on the electrical magnetic plugs. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by France and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

AD Requirements

This final rule requires inspection and replacement of the magnetic heads installed on oil system electrical magnetic plugs.

FAA’s Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because the compliance time for the action is less than the time required for public comment. Therefore, we find good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reason stated above, we find that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about

this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2018-0084 and Product Identifier 2018-NE-02-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. We will

consider all comments received by the closing date and may amend this final rule because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this final rule.

Costs of Compliance

We estimate that this AD affects 105 engines installed on helicopters of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
ARRIUS 2F Rear Electrical Mag Plug Inspection	2 work-hours × \$85 per hour = \$170 ...	\$0	\$170	\$17,850
ARRIUS 2F Front and Rear Electrical Mag Plug Mag Head Replacement.	4 work-hours × \$85 per hour = \$340 ...	3,061	3,401	357,105

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018-05-03 Safran Helicopter Engines (Type Certificate previously held by Turbomeca, S.A.): Amendment 39-19212; Docket No. FAA-2018-0084; Product Identifier 2018-NE-02-AD.

(a) Effective Date

This AD is effective March 21, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Safran Helicopter Engines, S.A., Arrius 2F turboshaft engines, with an oil system electrical magnetic plug magnetic head, part number (P/N) 9520011545, with serial numbers (S/Ns) DU4621 through DU5053 inclusive, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7900, Engine Oil System (Airframe Furnished).

(e) Unsafe Condition

This AD was prompted by reports from the manufacturer of a batch of non-conforming magnetic heads installed on electrical oil debris magnetic plugs. We are issuing this AD to prevent failure of the engine oil debris detection system. This unsafe condition, if not addressed, could result in the inability to detect engine bearing failures, failure of the engine, in-flight shutdown, and loss of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 15 flight hours or 30 days, whichever occurs first after the effective date of this AD, and then after each flight, inspect the magnetic head installed on the rear electrical magnetic plug in accordance with the Accomplishment Instructions, paragraph 2.4.5, of Safran Helicopter Engines Alert Mandatory Service Bulletin (MSB) A319 79 4840, Version A, dated November 27, 2017.

(2) Within 60 days after the effective date of this AD, replace each affected magnetic head, installed on the front or the rear electrical magnetic plug, with a part eligible for installation in accordance with the Accomplishment Instructions, paragraph 2.4.2, of Safran Helicopter Engines Alert MSB A319 79 4841, Version A, dated November 20, 2017.

(3) After replacement of the magnetic head installed on the rear electrical magnetic plug, as required by paragraph (g)(2) of this AD, the repetitive inspections required by paragraph (g)(1) of this AD are no longer required.

(h) Installation Prohibition

After the effective date of this AD, except as part of the inspection required by paragraph (g)(1) of this AD, do not install a magnetic head, P/N 9520011545, with an S/N DU4621 up to and including DU5053 on any engine.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2018-0012-E, dated January 16, 2018, for more information. You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2018-0084.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Safran Helicopter Engines Alert Mandatory Service Bulletin (MSB) A319 79 4840, Version A, dated November 27, 2017.

(ii) Safran Helicopter Engines Alert MSB A319 79 4841, Version A, dated November 20, 2017.

(3) For Safran Helicopter Engines service information identified in this AD, contact Safran Helicopter Engines, S.A., 40220 Tarnos, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15.

(4) You may view this service information at FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on February 23, 2018.

Karen M. Grant,

Acting Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2018-04439 Filed 3-5-18; 8:45 am]

BILLING CODE 4910-13-P

COMMODITY FUTURES TRADING COMMISSION**17 CFR Part 143**

RIN 3038-AE58

Annual Adjustment of Civil Monetary Penalties to Reflect Inflation—2018

AGENCY: Commodity Futures Trading Commission.

ACTION: Final rule.

SUMMARY: The Commodity Futures Trading Commission (Commission) is amending Rule 143.8, its rule that governs the maximum amount of civil monetary penalties, to adjust for inflation. This rule sets forth the maximum, inflation-adjusted dollar amount for civil monetary penalties (CMPs) assessable for violations of the Commodity Exchange Act (CEA) and Commission rules, regulations and orders thereunder. The rule, as amended, implements the Federal Civil Penalties Inflation Adjustment Act of 1990, as amended.

DATES: This rule is effective on March 6, 2018 and is applicable to penalties assessed after March 6, 2018.

FOR FURTHER INFORMATION CONTACT: Edward J. Riccobene, Associate Chief Counsel, Division of Enforcement, at (202) 418-5327 or ericcobene@cftc.gov, Commodity Futures Trading Commission, 1155 21st Street NW, Washington, DC 20581.

SUPPLEMENTARY INFORMATION:**I. Background**

The Federal Civil Penalties Inflation Adjustment Act of 1990 (FCPIAA)¹ requires the head of each Federal agency to periodically adjust for inflation the minimum and maximum amount of CMPs provided by law within the jurisdiction of that agency.² A 2015

¹ The FCPIAA, Public Law 101-410 (1990), as amended, is codified at 28 U.S.C. 2461 note. The FCPIAA states that the purpose of the FCPIAA is to establish a mechanism that (1) allows for regular adjustment for inflation of civil monetary penalties; (2) maintains the deterrent effect of civil monetary penalties and promote compliance with the law; and (3) improves the collection by the Federal Government of civil monetary penalties.

² For the relevant CMPs within the Commission's jurisdiction, the Act provides only for maximum

amendment to the FCPIAA³ required agencies to make an initial "catch-up" adjustment to its civil monetary penalties effective no later than August 1, 2016.⁴ For every year thereafter effective not later than January 15, the FCPIAA, as amended, requires agencies to make annual adjustments for inflation, with guidance from the Director of the Office of Management and Budget.⁵

II. Commodity Exchange Act Civil Monetary Penalties

The following sections of the CEA provide for CMPs that meet the FCPIAA definition⁶ and these CMPs are, therefore, subject to the inflation adjustment: Sections 6(c), 6b, and 6c of the CEA.⁷

III. Annual Inflation Adjustment for Commodity Exchange Act Civil Monetary Penalties**A. Methodology**

The FCPIAA annual inflation adjustment, in the context of the CFTC's CMPs, is determined by increasing the maximum penalty by a "cost-of-living adjustment", rounded to the nearest multiple of one dollar.⁸ Annual inflation adjustments are based on the percent change between the October Consumer Price Index for all Urban Consumers (CPI-U) preceding the date of the adjustment, and the prior year's October CPI-U.⁹ In this case, October 2017 CPI-U (246.663)/October 2015 CPI-U (241.729) = 1.02041.¹⁰ In order to

amounts that can be assessed for each violation of the Act or the rules, regulations and orders promulgated thereunder; the Act does not set forth any minimum penalties. Therefore, the remainder of this release will refer only to CMP maximums.

³ Federal Civil Penalties Inflation Adjustment Act Improvements Act of 2015, Public Law 114-74, 129 Stat. 584 (2015) (2015 Act), title VII, Section 701.

⁴ FCPIAA Sections 4 and 5. See also, Adjustment of Civil Monetary Penalties for Inflation, 81 FR 41435 (June 27, 2016).

⁵ FCPIAA Sections 4 and 5. See also, Executive Office of the President, Office of Management and Budget Memorandum, M-18-03, Implementation of Penalty Inflation Adjustments for 2018, Pursuant to the Federal Civil Penalties Inflation Adjustment Act Improvements Act of 2015 (Dec. 15, 2017) (2017 OMB Guidance) (<https://www.whitehouse.gov/wp-content/uploads/2017/11/M-18-03.pdf>).

⁶ FCPIAA Section 3(2).

⁷ 7 U.S.C. 9, 13a-1, 13b. Criminal authorities may also seek fines for criminal violations of the CEA (see 7 U.S.C. 13, 13(c), 13(d), 13(e), and 13b). The FCPIAA does not affect the amounts of these criminal penalties.

⁸ FCPIAA Sections 4 and 5.

⁹ FCPIAA Section 5(b)(1).

¹⁰ The CPI-U is published by the Department of Labor. Interested parties may find the relevant Consumer Price Index on the internet. To access this information, go to the Consumer Price Index Home Page at: <http://www.bls.gov/cpi/>. Click the "CPI Data/Databases" heading, and select "All Urban Consumers (Current Series)", "Top Picks."