

(Approved by the Office of Management and Budget under control numbers 0579-0190, 0579-0439, 0579-0454, 0579-0458, and 0579-0463)

Done in Washington, DC, this 9th day of March 2018.

Kevin Shea,

Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 2018-05267 Filed 3-14-18; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0778; Product Identifier 2017-NM-038-AD; Amendment 39-19228; AD 2018-06-08]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 757-200 series airplanes. This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the side panel-to-frame attachments and frames of the aft cargo compartment are subject to widespread fatigue damage (WFD). This AD requires an inspection of the side panel-to-frame attachments and frames to verify that certain modifications have been done, and applicable on-condition actions. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 19, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 19, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching

for and locating Docket No. FAA-2017-0778.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0778; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Peter Jarzomb, Aerospace Engineer, Airframe Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5234; fax: 562-627-5210; email: peter.jarzomb@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 757-200 series airplanes. The NPRM published in the **Federal Register** on August 25, 2017 (82 FR 40508). The NPRM was prompted by an evaluation by the DAH indicating that the side panel-to-frame attachments and frames of the aft cargo compartment are subject to WFD. The NPRM proposed to require an inspection of the side panel-to-frame attachments and frames to verify that certain modifications have been done, and applicable on-condition actions. We are issuing this AD to prevent fatigue cracking at the attachment points of the side panel-to-frame attachments of the aft cargo compartment, which could result in reduced structural integrity of the body frames, and consequent rapid decompression of the airplane.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Support for the NPRM

Boeing and United Airlines agreed with the content of the NPRM.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that accomplishing the supplemental type certificate (STC) ST01518SE does not affect the actions specified in the NPRM.

We concur with the commenter. We have redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01518SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01518SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

Request To Provide Instructions for Previously Repaired Areas

FedEx Express asked that instructions to address previously repaired areas on which the modification has not been incorporated be added to Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017, before issuing the proposed AD.

We do not agree with the commenter's request. To wait for Boeing to update the service bulletin, as requested, would delay the issuance of the final rule. However, to delay this action would be inappropriate since we have determined that an unsafe condition exists and that the actions required by this AD must be done to ensure continued safety. If a previously repaired area does not incorporate the modification required by this AD, and the modification cannot be done on the previously repaired area, operators must request an alternative method of compliance (AMOC) using the procedures specified in paragraph (j) of this AD. We have made no change to this AD in this regard.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017. The service information describes procedures for a general visual inspection of the side panel-to-frame attachments and frames to verify that certain modifications have

been done. The service information also describes procedures for on-condition actions, which include repetitive inspections for cracking, repairs, and modifications. This service information is reasonably available because the interested parties have access to it through their normal course of business

or by the means identified in the ADDRESSES section.

Costs of Compliance

We estimate that this AD affects 13 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
General visual inspection	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$1,105

We estimate the following costs to do any necessary on-condition actions that are required. We have no way of determining the number of aircraft that might need these on-condition actions.

ESTIMATED COSTS OF ON-CONDITION ACTIONS *

Labor cost	Parts cost	Cost per product
Up to 45 work-hours × \$85 per hour = Up to \$3,825	Unavailable	Up to \$3,825.

* The costs in the table do not include the cost estimate for on-condition repairs. We have received no definitive data that would enable us to provide cost estimates for the on-condition repairs specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018-06-08 The Boeing Company:
Amendment 39-19228; Docket No. FAA-2017-0778; Product Identifier 2017-NM-038-AD.

(a) Effective Date

This AD is effective April 19, 2018.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 757-200 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017.

(2) Installation of Supplemental Type Certificate (STC) ST01518SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rqstc.nsf/0/312bc296830a925c86257c85006d1b1f/\\$FILE/ST01518SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rqstc.nsf/0/312bc296830a925c86257c85006d1b1f/$FILE/ST01518SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01518SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder indicating that the side panel-to-frame attachments and frames of the aft cargo compartment are subject to widespread fatigue damage. We are issuing this AD to prevent fatigue cracking at the attachment points of the side panel-to-frame attachments of the aft cargo compartment, which could result in reduced structural integrity of the body frames, and consequent rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One-Time General Visual Inspection and Corrective Actions

Except as required by paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017, uses the phrase "the Revision 1 date of this service bulletin," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017, specifies contacting Boeing, and specifies that action as RC: This AD requires repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Terminating Action for Inspections

Accomplishment of a modification in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017, terminates the inspections required by paragraph (g) of this AD at the modified location only.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Peter Jarzomb, Aerospace Engineer, Airframe Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5234; fax: 562-627-5210; email: peter.jarzomb@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 757-53A0012, Revision 1, dated January 25, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on

the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 2, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-05015 Filed 3-14-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2017-0695; Product Identifier 2016-NM-173-AD; Amendment 39-19223; AD 2018-06-03]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2009-18-16, which applied to certain Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes. AD 2009-18-16 required an inspection for cracking of certain fastener holes on certain frames, and related investigative and corrective actions if necessary; and modification of certain fastener holes. This new AD reduces the compliance times. This AD was prompted by the identification of a structural modification that falls within the scope of the work related to the extension of the service life of the affected airplanes and widespread fatigue damage evaluations. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 19, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 19, 2018.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; internet: <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200