

**Subpart F—Grade Requirements**

Dated: March 30, 2018.

**Bruce Summers,**

*Acting Administrator, Agricultural Marketing Service.*

[FR Doc. 2018–06882 Filed 4–5–18; 8:45 am]

BILLING CODE 3410–02–P

**NATIONAL CREDIT UNION ADMINISTRATION****12 CFR Part 741**

RIN 3133–AE77

**Requirements for Insurance; National Credit Union Share Insurance Fund Equity Distributions; Correction**

**AGENCY:** National Credit Union Administration (NCUA).

**ACTION:** Final rule; correcting amendment.

**SUMMARY:** On February 23, 2018, the NCUA Board (Board) published a final rule adopting amendments to its share insurance requirements rule to provide stakeholders with greater transparency regarding the calculation of each eligible financial institution's pro rata share of a declared equity distribution from the National Credit Union Share Insurance Fund (NCUSIF). A clerical error appeared that resulted in an incorrect amendatory instruction. This document corrects that error.

**DATES:** This correction is effective April 6, 2018.

**FOR FURTHER INFORMATION CONTACT:** Benjamin M. Litchfield, Staff Attorney, Office of General Counsel, the National Credit Union Administration, at 1775 Duke Street, Alexandria, Virginia 22314–3428, or by telephone at (703) 518–6540.

**SUPPLEMENTARY INFORMATION:** On February 23, 2018, at 83 FR 7954, the Board published a final rule adopting amendments to 12 CFR part 741. Amendatory instruction 2.a.iv. called for revising the definition of “equity ratio” in § 741.4. However, the final rule did not set out regulatory text for the revised definition of “equity ratio.” This was an inadvertent drafting error. This document corrects that error by amending the final rule to supply a revised definition for “equity ratio.”

**List of Subjects in 12 CFR Part 741**

Bank deposit insurance, Credit unions, Reporting and recordkeeping requirements.

By the National Credit Union Administration Board on April 2, 2018.

**Gerard Poliquin,**

*Secretary of the Board.*

For the reasons discussed above, the Board amends 12 CFR part 741 as follows:

**PART 741—REQUIREMENTS FOR INSURANCE**

■ 1. The authority citation for part 741 continues to read as follows:

**Authority:** 12 U.S.C. 1757, 1766(a), 1781–1790, and 1790d; 31 U.S.C. 3717.

■ 2. Amend § 741.4 in paragraph (b), by revising the definition of “equity ratio” to read as follows:

**§ 741.4 Insurance premium and one percent deposit.**

\* \* \* \* \*

(b) \* \* \*

\* \* \* \* \*

*Equity ratio* means the ratio of:  
(i) The amount determined by subtracting—

(A) Direct liabilities of the NCUSIF and contingent liabilities for which no provision for losses has been made from

(B) The sum of all one percent deposits made by federally insured credit unions pursuant to paragraph (c) of this section and the retained earnings balance of the NCUSIF, to

(ii) The aggregate amount of insured shares in all federally insured credit unions.

\* \* \* \* \*

[FR Doc. 2018–07068 Filed 4–5–18; 8:45 am]

BILLING CODE 7535–01–P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2017–0668; Product Identifier 2017–NE–17–AD; Amendment 39–19236; AD 2018–07–05]

RIN 2120–AA64

**Airworthiness Directives; General Electric Company Turbofan Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all General Electric Company (GE) CF6–80A, –80A1, –80A2, and –80A3 turbofan engines. This AD was prompted by high cycle fatigue (HCF) cracking of the low-pressure turbine (LPT) stage 3 nozzles. This AD requires

replacement of the LPT stage 3 nozzles, part numbers (P/Ns) 9290M52P05 and 9290M52P06, installed. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 11, 2018.

**ADDRESSES:** For service information identified in this final rule, contact General Electric Company, GE-Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215, phone: 513–552–3272; fax: 513–552–3329; email: [geae.aoc@ge.com](mailto:geae.aoc@ge.com). You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781–238–7759. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0668.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0668; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800–647–5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Herman Mak, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7147; fax: 781–238–7199; email: [herman.mak@faa.gov](mailto:herman.mak@faa.gov).

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all GE CF6–80A, –80A1, –80A2, and –80A3 turbofan engines. The NPRM published in the **Federal Register** on September 12, 2017 (82 FR 42752) and an NPRM correction published on September 21, 2017 (82 FR 44127). The NPRM was prompted by an LPT uncontainment on a GE CF6–80A2 engine. An investigation determined the uncontainment was the result of HCF cracking of the LPT stage 3 nozzles. The NPRM proposed to require replacement of the LPT stage 3 nozzles. We are