

Proposed Rules

Federal Register

Vol. 83, No. 72

Friday, April 13, 2018

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Agricultural Marketing Service

7 CFR Part 205

[Doc. No. AMS–NOP–14–0079; NOP–14–05]

RIN 0581–AD44

National Organic Program (NOP); Amendments to the National List of Allowed and Prohibited Substances (Crops, Livestock and Handling); Reopening of Comment Period

AGENCY: Agricultural Marketing Service, USDA.

ACTION: Proposed rule; Reopening of the public comment period.

SUMMARY: The Agricultural Marketing Service (AMS) published a proposed rule in the **Federal Register** on January 18, 2018, which describes 35 amendments to the National List of Allowed and Prohibited Substances (Crops, Livestock and Handling). The public comment period closed on March 19, 2018. This document reopens the comment period on the proposed rule for an additional 30 days. Multiple stakeholders requested that AMS extend the comment period to provide more time to develop comments on the proposed rule.

DATES: Comments must be received by May 14, 2018.

ADDRESSES: Interested parties may submit written comments on the Amendments to the National List of Allowed and Prohibited Substances (Crops, Livestock and Handling) proposed rule using one of the following methods:

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* Robert Pooler, Standards Division, National Organic Program, USDA–AMS–NOP, Room 2646–So., Ag Stop 0268, 1400 Independence Ave. SW, Washington, DC 20250–0268.

Instructions: All submissions received must include the docket number AMS–NOP–14–0079; NOP–14–05PR, and/or

Regulatory Information Number (RIN) 0581–AD60 for this rulemaking. Commenters should identify the topic and section of the proposed rule to which their comment refers. All commenters should refer to the GENERAL INFORMATION section in the Notice of Proposed Rulemaking for more information on preparing your comments. All comments received will be posted without change to <http://www.regulations.gov>.

Docket: For access to the docket, including background documents and comments received, go to <http://www.regulations.gov>. Comments submitted in response to this proposed rule will also be available for viewing in person at USDA–AMS, National Organic Program, Room 2642–South Building, 1400 Independence Ave. SW, Washington, DC, from 9 a.m. to 12 noon and from 1 p.m. to 4 p.m., Monday through Friday (except official Federal holidays). Persons wanting to visit the USDA South Building to view comments received in response to this proposed rule are requested to make an appointment in advance by calling (202) 720–3252.

FOR FURTHER INFORMATION CONTACT: Robert Pooler, Standards Division. Telephone: (202) 720–3252; Fax: (202) 260–9151.

SUPPLEMENTARY INFORMATION: This document reopens the public comment period for the proposed rule published in the **Federal Register** on January 18, 2018 (83 FR 2498), Amendments to the National List of Allowed and Prohibited Substances (Crops, Livestock and Handling). In the proposed rule, AMS solicits public comments generally and requests comments on specific topics. AMS is reopening the comment period, which ended on March 19, 2018, for 30 days based on multiple stakeholder requests that AMS extend the comment period to provide more time to develop comments on the proposed rule.

AMS is proposing to amend the National List of Allowed and Prohibited Substances by: Changing the use restrictions for seventeen substances allowed for organic production or handling; adding sixteen new substances for use in organic production or handling; listing rotenone as a prohibited substance in organic crop production; and removing ivermectin as an allowed parasiticide for use in organic livestock production.

To submit comments, or access the proposed rule docket, please follow the instructions provided under the **ADDRESSES** section. If you have questions, consult the person listed under **FOR FURTHER INFORMATION CONTACT**.

Authority: 7 U.S.C. 6501–6522.

Dated: April 10, 2018.

Bruce Summers,
Acting Administrator, Agricultural Marketing Service.

[FR Doc. 2018–07719 Filed 4–12–18; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0273; Product Identifier 2018–NM–017–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes. This proposed AD was prompted by several reports of cracks in a certain floor beam lower chord at stop fitting Number 1 of the forward airstair door cutout. This proposed AD would require repetitive inspections for any cracks and applicable on-condition actions. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by May 29, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0273.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0273; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Galib Abumeri, Aerospace Engineer, Airframe Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0273; Product Identifier 2018-NM-017-AD” at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received several reports of cracks in the station (STA) 312 floor beam lower chord at stop fitting No. 1 of the forward airstair door cutout. One operator found multiple cracks in the STA 312 floor beam lower chord in the fillet radii and the two inboard attachment fasteners at stop fitting No. 1 of the forward airstair door cutout. Cracks have also been found in the STA 312 floor beam lower chord fillet radii, with no cracks in the lower chord at the two inboard attach fastener holes common to stop fitting No. 1. In addition, other airplanes have had cracks in the STA 312 floor beam lower chord, at the two inboard attach fastener holes. Cracks in the STA 312 floor beam lower chord supporting the forward airstair stop loads may lead to cracks developing in the adjacent airstair support structure. This condition, if not addressed, could result in the inability of a principal structural element to sustain limit loads and possible rapid decompression.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Requirements Bulletin 737-53A1370 RB, dated December 13, 2017. The service information describes procedures for repetitive high frequency eddy current inspections of the STA 312 floor beam lower chord, and door stop fittings No. 2, No. 5 and No. 8 on the forward airstair door for any cracks and applicable on-condition actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified in Boeing Alert Requirements Bulletin 737-53A1370 RB, dated December 13, 2017, described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0273.

Explanation of Requirements Bulletin

The FAA worked in conjunction with industry, under the Airworthiness Directives Implementation Aviation Rulemaking Committee (AD ARC), to enhance the AD system. One enhancement is a process for annotating which steps in the service information are “required for compliance” (RC) with an AD. Boeing has implemented this RC concept into Boeing service bulletins.

In an effort to further improve the quality of ADs and AD-related Boeing service information, a joint process improvement initiative was worked between the FAA and Boeing. The initiative resulted in the development of a new process in which the service information more clearly identifies the actions needed to address the unsafe condition in the “Accomplishment Instructions.” The new process results in a Boeing Requirements Bulletin, which contains only the actions needed to address the unsafe condition (*i.e.*, only the RC actions).

Costs of Compliance

We estimate that this proposed AD affects 67 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	Up to 11 work-hours × \$85 per hour = \$935 per inspection cycle.	\$0	Up to \$935 per inspection cycle ...	Up to \$62,645 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2018–0273; Product Identifier 2018–NM–017–AD.

(a) Comments Due Date

We must receive comments by May 29, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes with a forward airstair door installed, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors; 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by several reports of cracks in the station (STA) 312 floor beam lower chord at stop fitting No. 1 of the forward airstair door cutout. We are issuing this AD to address such cracking, which could result in the inability of a principal structural element to sustain limit loads and possible rapid decompression.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For airplanes identified as Group 1 in Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017: Within 120 days after the effective date of this AD, inspect the STA 312 floor beam lower chord and door stop fittings No. 2, No. 5 and No. 8 for any cracks and do applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(2) Except as required by paragraph (h) of this AD: For airplanes identified as Group 2 in Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017, at the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017.

Note 1 to paragraph (g)(2) of this AD: Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–53A1370, dated December 13, 2017, which is referred to in Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017, uses the phrase "the original issue date of Requirements Bulletin 737–53A1370 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 737–53A1370 RB, dated December 13, 2017, specifies contacting Boeing, this AD requires repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5324; fax: 562–627–5210; email: galib.abumeri@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on March 29, 2018.

Chris Spangenberg,

*Acting Director, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2018-07632 Filed 4-12-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0274; Product Identifier 2017-NM-128-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This proposed AD was prompted by reports of fire incidents of the auxiliary power unit (APU) inlet, which caused tail cone damage after an initial failed APU start followed by two or more in-flight APU start attempts. This proposed AD would require modification of the APU electronic control unit (ECU) wiring harness. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by May 29, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0274; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Assata Dessaline, Aerospace Engineer, Avionics and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7301; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0274; Product Identifier 2017-NM-128-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2017-26,

dated July 31, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model BD-100-1A10 airplanes. The MCAI states:

APU inlet fire incidents causing tail cone damage have been reported after an initial failed APU start followed by two or more in-flight APU start attempts. Bombardier Inc. (BA) has determined that the in-flight negative pressure differential at the APU inlet allows flash fires of residual fuel in the APU combustor to exit through the APU inlet.

As an interim mitigating action, BA has revised the affected aeroplane Aircraft Flight Manual (AFM) procedure for in-flight APU start to limit the number of APU start attempts.

To further address the safety concerns associated with in-flight APU inlet fire, BA is introducing a modification to the APU Electronic Control Unit (ECU) wiring harness that will prevent a second attempt to start the APU following a failed start in flight. This [Canadian] AD is issued to mandate compliance with BA Service Bulletin (SB) 100-49-04 or SB 350-49-001, as applicable, on affected aeroplanes.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0274.

Related Service Information Under 14 CFR Part 51

Bombardier, Inc., has issued Service Bulletin 100-49-04, dated March 29, 2017; and Service Bulletin 350-49-001, dated March 29, 2017. This service information describes a modification of the APU ECU harness. These documents are distinct since they apply to different airplane models in different configurations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.